



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
052500E	AIRCRAFT WEIGHT AND BALANCE CHECK ESGP				MTH 16-May-2014 HRS 2463.4 LDG 2244		48		31-May-2018	15 m 29 d
052501A	INSPECT FIRST AID KIT INSPECTION				MTH 28-Mar-2016 HRS 3132.9 LDG 2877		12		31-Jan-2017	-2 d <b>Over Due</b>
055601	INSPECT WINDSHIELD SURFACE RE-SEAL *CF				MTH 07-Jun-2006		O/C			
055602	INSPECT HUMP SEAL REPAIR *CF				MTH 07-Jun-2006		O/C			
A530016	GENERAL VISUAL INSPECTION OF THE TAILCONE UNDER FLOOR AREA AND TAILCONE STINGER GVI: PHASE 21 ESGP				MTH 25-Nov-2015 HRS 3054.9 LDG 2805		24		30-Nov-2017	9 m 28 d
5-92-01	INSPECTION DOCUMENT 1 ESGP				MTH 14-Mar-2016 HRS 3113.1 LDG 2859		12 600		31-Mar-2017 3713.1	1 m 29 d 340.6
5-92-02	INSPECTION DOCUMENT 2 ESGP				MTH 14-Mar-2016 HRS 3113.1 LDG 2859		12		31-Mar-2017	1 m 29 d
5-92-03	INSPECTION DOCUMENT 3 ESGP				MTH 14-Mar-2016 HRS 3113.1 LDG 2859		24 1200		31-Mar-2018 4313.1	13 m 29 d 940.6
5-92-04	INSPECTION DOCUMENT 4 ESGP				MTH 14-Mar-2016 HRS 3113.1 LDG 2859		24		31-Mar-2018	13 m 29 d
5-92-05	INSPECTION DOCUMENT 5 ESGP				MTH 14-Mar-2016 HRS 3113.1 LDG 2859		48 1200		31-Mar-2020 4313.1	37 m 29 d 940.6
5-92-06	INSPECTION DOCUMENT 6 ESGP				MTH 14-Mar-2016 HRS 3113.1 LDG 2859		36 1800		31-Mar-2019 4913.1	25 m 29 d 1540.6
5-92-07	INSPECTION DOCUMENT 7 ESGP				MTH 14-Mar-2016 HRS 3113.1 LDG 2859		36		31-Mar-2019	25 m 29 d
5-92-08 MSG -3 Program Applied	INSPECTION DOCUMENT 8				MTH 14-Mar-2016 HRS 3113.1 LDG 2859	-1155 -1126	48 2400		31-Jan-2017 4387.1	-2 d 1014.6 <b>Over Due</b>
5-92-09	INSPECTION DOCUMENT 9 ESGP				MTH 14-Mar-2016 HRS 3113.1 LDG 2859		48 1200		31-Mar-2020 4313.1	37 m 29 d 940.6
5-92-10 MSG -3 Program Applied	INSPECTION DOCUMENT 10				MTH 14-Mar-2016 HRS 3113.1 LDG 2859	-1155	48		31-Jan-2017	-2 d <b>Over Due</b>
5-92-11 MSG -3 Program Applied	INSPECTION DOCUMENT 11				MTH 14-Mar-2016 HRS 3113.1 LDG 2859	-1155	48		31-Jan-2017	-2 d <b>Over Due</b>
5-92-12	INSPECTION DOCUMENT 12				MTH 14-Mar-2016 HRS 3113.1 LDG 2859	-149	3000		5964.1	2591.6 <b>Over Due</b>



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Maintenance Inspections

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
5-92-13	INSPECTION DOCUMENT 13		MTH 14-Mar-2016 HRS 3113.1 LDG 2859		72			
D291100	DISCARD HYDRAULIC SYSTEM FILTERS: INSPECTION DOCUMENT 13		MTH 14-Mar-2016 HRS 3113.1 LDG 2859	-38	72		31-Jan-2019	23 m 29 d
D324010	DISCARD BRAKE SYSTEMS FILTERS: INSPECTION DOCUMENT 13		MTH 14-Mar-2016 HRS 3113.1 LDG 2859	-38	72		31-Jan-2019	23 m 29 d
5-92-14	INSPECTION DOCUMENT 14 MSG -3 Program Applied		MTH 14-Mar-2016 HRS 3113.1 LDG 2859	-1155	96		31-Jan-2021	47 m 29 d
5-92-15	INSPECTION DOCUMENT 15 MSG -3 Program Applied		MTH 14-Mar-2016 HRS 3113.1 LDG 2859	-1155	144		31-Jan-2025	95 m 29 d
5-92-16	INSPECTION DOCUMENT 16 ESGP		MTH 07-Jun-2016 HRS 3195.3 LDG 2938 APUH 1687 APUS 3470	-23	12 400		31-May-2017 3595.3	3 m 29 d 222.8
5-92-17	INSPECTION DOCUMENT 17 MSG -3 Program Applied		MTH 14-Mar-2016 HRS 3113.1 LDG 2859 APUH 1636	-365 -78	24 500		31-Mar-2017 2058	1 m 29 d 295
5-92-18	INSPECTION DOCUMENT 18 MSG -3 Program Applied		MTH 14-Mar-2016 HRS 3113.1 LDG 2859 APUH 1636	-365 -78	24 1000		31-Mar-2017 2558	1 m 29 d 795
5-92-19	INSPECTION DOCUMENT 19 ESGP		MTH 14-Mar-2016 HRS 3113.1 LDG 2859		24 2400		31-Mar-2018 5513.1	13 m 29 d 2140.6
5-92-22	INSPECTION DOCUMENT 22		DAYS 07-Jun-2006 HRS 3113.1 LDG 2859		A/R			
5-92-23	INSPECTION DOCUMENT 23 ESGP		MTH 01-Nov-2016 HRS 3329 LDG 3059 APUH 1763 APUS 3762		100			
B245001	FUNCTIONAL CHECK MAIN SHIP (UY006) BATTERY (CAPACITY CHECK) MARATHON NI-CAD: INSPECTION DOCUMENT 23 ESGP	30978-002 10800920	MTH 01-Nov-2016 HRS 3329 LDG 3059		12 100		30-Nov-2017 3429	9 m 28 d 56.5
5-92-24	INSPECTION DOCUMENT 24		MTH 14-Mar-2016 HRS 3113.1 LDG 2859		N/A			
5-92-25	INSPECTION DOCUMENT 25 ESGP		MTH 15-Jul-2016 HRS 3240.4 LDG 2975 APUH 1687 APUS 3470		300		3540.4	167.9
5-92-26	INSPECTION DOCUMENT 26		MTH 14-Mar-2016 HRS 3113.1 LDG 2859 APUH 1636	-313	500		1823	60

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Maintenance Inspections

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
A801103 APU	DETAILED INSPECTION STARTER/GENERATOR : INSPECTION DOCUMENT 26	300SGL138Q-6 3203XL	MTH 14-Mar-2016 HRS 3113.1 LDG 2859 APUH 1636	-313	500		1823	60
5-92-27	INSPECTION DOCUMENT 27		MTH 14-Mar-2016 HRS 3113.1 LDG 2859	-149	600		3564.1	191.6
5-92-30	INSPECTION DOCUMENT 30		MTH 14-Mar-2016 HRS 3113.1 LDG 2859 APUH 1636	-78	1000		2558	795
5-92-34	INSPECTION DOCUMENT 34 GSE		MTH 29-Sep-2016 HRS 3305.4 LDG 3034 APUH 1748 APUS 3724		6			
B342006	OPERATIONAL CHECK L3 COM STANDBY BATTERY PACK (PERIODIC CHECK): INSPECTION DOCUMENT 34 GSE		MTH 29-Sep-2016 HRS 3305.4 LDG 3034 APUH 1748 APUS 3724	-15	6		31-Mar-2017	1 m 29 d
B342007 STANDBY	OPERATIONAL CHECK SECURAPLANE BATTERY (ENERGY LEVEL): INSPECTION DOCUMENT 34 GSE	100-2410-04 1038	MTH 29-Sep-2016 HRS 3305.4 LDG 3034 APUH 1748 APUS 3724	-15	6		31-Mar-2017	1 m 29 d
5-92-35	INSPECTION DOCUMENT 35 ESGP		MTH 14-Mar-2016 HRS 3113.1 LDG 2859		12			
B342005	FUNCTIONAL CHECK L3 COM STANDBY BATTERY PACK(CAPACITY CHECK): INSPECTION DOCUMENT 35		MTH 14-Mar-2016 HRS 3113.1 LDG 2859		12		31-Mar-2017	1 m 29 d
5-92-36	INSPECTION DOCUMENT 36		MTH 14-Mar-2016 HRS 3113.1 LDG 2859		24			
B237006	FUNCTIONAL CHECK CVR UNDERWATER LOCATOR BEACON COCKPIT VOICE RECORDER UNDERWATER LOCATING DEVICE (ULD): INSPECTION DOCUMENT 36	DK120 SC20671	MTH 14-Mar-2016 HRS 3113.1 LDG 2859	-4	24		30-Nov-2017	9 m 28 d
B313003	FUNCTIONAL CHECK FDR UNDERWATER LOCATOR BEACON FLIGHT DATA RECORDER UNDERWATER LOCATING DEVICE(ULD): INSPECTION DOCUMENT 36	DK120 DU15507	MTH 14-Mar-2016 HRS 3113.1 LDG 2859	-4	24		30-Nov-2017	9 m 28 d
5-92-37	INSPECTION DOCUMENT 37 (NOT CURRENTLY USED)		MTH 14-Mar-2016 HRS 3113.1 LDG 2859		36			
5-92-40 MSG -3 Program Applied	INSPECTION DOCUMENT 40		MTH 14-Mar-2016 HRS 3113.1 LDG 2859	-1308 -1349	72 2400		31-Aug-2018 4164.1	18 m 29 d 791.6



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
5-92-43	INSPECTION DOCUMENT 43				MTH 14-Mar-2016 HRS 3113.1 LDG 2859		A/R			
A324006 LEFT	NON DESTRUCTIVE TEST MAIN WHEEL ASSEMBLY : INSPECTION DOCUMENT 43			3-1571-6 0533	MTH		A/R			
A324006 NOSE	NON DESTRUCTIVE TEST WHEEL ASSEMBLY : INSPECTION DOCUMENT 43			3-1418 4537	MTH 14-Mar-2016 HRS 3113.1 LDG 2859		A/R			
A324006 RIGHT	NON DESTRUCTIVE TEST MAIN WHEEL ASSEMBLY : INSPECTION DOCUMENT 43			3-1571-6 3476	MTH 14-Mar-2016 HRS 3113.1 LDG 2859		A/R			
5-92-44	INSPECTION DOCUMENT 44 (14 CFR 91.207) ESGP				MTH 14-Mar-2016 HRS 3113.1 LDG 2859		12		31-Mar-2017	1 m 29 d
5-92-45	INSPECTION DOCUMENT 45 ESGP				MTH 15-Jul-2016 HRS 3240.4 LDG 2975 APUH 1687 APUS 3470		24			
B238002 NO. 1	CALIBRATION TEST ATC TRANSPONDER (FAR 91.413): INSPECTION DOCUMENT 45	ESGP		7517400-922 0601A483	MTH 14-Jul-2016		24		31-Jul-2018	17 m 29 d
B238002 NO. 2	CALIBRATION TEST ATC TRANSPONDER (FAR 91.413): INSPECTION DOCUMENT 45	ESGP		7517400-922 0601A481	MTH 14-Jul-2016		24		31-Jul-2018	17 m 29 d
B341100 NO. 1	CALIBRATION TEST (PILOT) AIR DATA COMPUTER (FAR 91.411) : INSPECTION DOCUMENT 45	ESGP		7030700-71703 06010808	MTH 14-Jul-2016		24		31-Jul-2018	17 m 29 d
B341100 NO. 2	CALIBRATION TEST (COPILOT) AIR DATA COMPUTER (FAR 91.411) : INSPECTION DOCUMENT 45	ESGP		7030700-71703 06010822	MTH 14-Jul-2016		24		31-Jul-2018	17 m 29 d
B341100 RVSM	INSPECT SKIN WAVINESS: INSPECTION DOCUMENT 45	ESGP			MTH 15-Jul-2016 HRS 3240.4 LDG 2975 APUH 1687 APUS 3470		24		31-Jul-2018	17 m 29 d
B341100 SECONDARY	CALIBRATION TEST ADU (FAR 91.411) : INSPECTION DOCUMENT 45	ESGP		501-1890-02 1565	MTH 14-Jul-2016		24		31-Jul-2018	17 m 29 d
5-92-47	INSPECTION DOCUMENT 47						N/A			
5-92-48	INSPECTION DOCUMENT 48				MTH 14-Mar-2016 HRS 3113.1 LDG 2859	-206	500		3407.1	34.6
5-92-50	INSPECTION DOCUMENT 50 GSE				MTH 29-Sep-2016 HRS 3305.4 LDG 3034 APUH 1748 APUS 3724	-15	6		31-Mar-2017	1 m 29 d
5-92-52	INSPECTION DOCUMENT 52				MTH 07-Jun-2006 HRS 0		6000		6000	2627.5



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Maintenance Inspections

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
5-92-MD	INSPECTION DOCUMENT MD	MTH 07-Jun-2016	120				30-Jun-2026	112 m 28 d
	ESGP	HRS 3195.3	2400				5595.3	2222.8
		LDG 2938						
		APUH 1687						
		APUS 3470						
5-92-ME	INSPECTION DOCUMENT ME	MTH 14-Mar-2016						
		HRS 3113.1	-3113.1	15000			15000	11627.5
		LDG 2859						
5-92-MF	INSPECTION DOCUMENT MF	MTH 14-Mar-2016						
		HRS 3113.1	-3113.1	7500			7500	4127.5
		LDG 2859						
5-92-MJ	INSPECTION DOCUMENT MJ	MTH 14-Mar-2016						
		HRS 3113.1	-3113.1	13000			13000	9627.5
		LDG 2859						
5-92-ML	INSPECTION DOCUMENT ML	MTH 14-Mar-2016						
		HRS 3113.1	-3113.1	11500			11500	8127.5
		LDG 2859						
5-92-MM	INSPECTION DOCUMENT MM	MTH 14-Mar-2016						
		HRS 3113.1	-3113.1	11000			11000	7627.5
		LDG 2859						
5-92-MN	INSPECTION DOCUMENT MN	MTH 14-Mar-2016						
		HRS 3113.1	-3113.1	9000			9000	5627.5
		LDG 2859						
5-92-MO	INSPECTION DOCUMENT MO	MTH 14-Mar-2016						
		HRS 3113.1	-3113.1	12500			12500	9127.5
		LDG 2859						
057109	OIL FILTER CHANGE	MTH 15-Jul-2016						
E1	ESGP	HRS 3305.3		24			31-Jul-2018	17 m 29 d
		LDG 3045		900			(4140.4)4205.3	832.8
057109	OIL FILTER CHANGE	MTH 29-Sep-2016						
E2	ESGP	HRS 3305.4		24			30-Sep-2018	19 m 28 d
		LDG 3034		900			(4205.4)4205.4	832.9
057120	INSPECTION LOW UTILIZATION	MTH 14-Mar-2016						
E1	ESGP	HRS 3178		24			31-Mar-2018	13 m 29 d
		LDG 2929						
057120	INSPECTION LOW UTILIZATION	MTH 14-Mar-2016						
E2	ESGP	HRS 3113.1		24			31-Mar-2018	13 m 29 d
		LDG 2859						
057159	MINOR INSPECTION	MTH 14-Mar-2016						
E1	ESGP	HRS 3178		12			31-Mar-2017	1 m 29 d
		LDG 2929		600			(3713.1)3778	405.5
057159	MINOR INSPECTION	MTH 14-Mar-2016						
E2	ESGP	HRS 3113.1		12			31-Mar-2017	1 m 29 d
		LDG 2859		600			(3713.1)3713.1	340.6
A262003	RESTORATION PORTABLE HALON FIRE EXTINGUISHER (INTERNAL INSPECTION)							
CABIN		C352TS	MTH 14-Mar-2016	-47	72		30-Apr-2018	14 m 28 d
MSG -3 Program Applied		Y-95677	HRS 3113.1					
		LDG 2859						
A262003	RESTORATION PORTABLE HALON FIRE EXTINGUISHER (INTERNAL INSPECTION)							
COCKPIT		C352TS	MTH 14-Mar-2016	-47	72		30-Apr-2018	14 m 28 d
MSG -3 Program Applied		Y-95678	HRS 3113.1					
		LDG 2859						
B262004	RESTORATION (HYDROSTATIC TEST) PORTABLE HALON FIRE EXTINGUISHER							
CABIN		C352TS	MTH 14-Mar-2016	-53	144		31-Oct-2023	80 m 29 d
MSG -3 Program Applied		Y-95677	HRS 3113.1					
		LDG 2859						

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Maintenance Inspections

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
B262004	RESTORATION (HYDROSTATIC TEST) PORTABLE HALON FIRE EXTINGUISHER							
COCKPIT		C352TS	MTH 14-Mar-2016	-53	144		31-Oct-2023	80 m 29 d
MSG -3 Program Applied		Y-95678	HRS 3113.1 LDG 2859					
B262005	RESTORATION (HYDROSTATIC TEST) FIRE BOTTLE							
APU		9914513-7	MTH 14-Mar-2016	-3	60		31-Dec-2020	46 m 29 d
MSG -3 Program Applied		37317A1	HRS 3113.1 LDG 2859					
B262008	RESTORATION (HYDROSTATIC TEST) ENGINE FIRE BOTTLE							
AFT		30400037-1	MTH 14-Mar-2016	-6	60		30-Sep-2020	43 m 28 d
MSG -3 Program Applied		45532B1	HRS 3113.1 LDG 2859					
B262008	RESTORATION (HYDROSTATIC TEST) ENGINE FIRE BOTTLE							
FORWARD		30400037-1	MTH 14-Mar-2016	-15	60		31-Dec-2019	34 m 29 d
MSG -3 Program Applied		51165B1	HRS 3113.1 LDG 2859					
B320900	RESTORATION PNEUMATIC BLOWDOWN/EMERGENCY BRAKE BOTTLE (HYDROSTATIC TEST)							
		40005347-3	MTH 14-Mar-2016	-19	36		31-Aug-2017	6 m 29 d
		4384	HRS 3113.1 LDG 2859					
350000	RESTORATION (HYDROSTATIC TEST) OXYGEN CYLINDER							
MSG -3 Program Applied		804882-14	MTH 14-Mar-2016	-27	60		31-Dec-2018	22 m 29 d
		ALT281-11393	HRS 3113.1 LDG 2859					
350010	RESTORATION (HYDROSTATIC TEST) OXYGEN (DOT-3AA) CYLINDER							
PORTABLE		PN	MTH 14-Mar-2016		60			
		SN-UNKNOWN	HRS 3113.1 LDG 2859					
054906	REPLACE FUEL NOZZLE ASSEMBLY		07-Jun-2006					
	*CF		APUS 0	7	4000	7	4000	238
710060	CLEAN/INSPECT/TEST ENGINE WIRING HARNESS CONNECTORS							
E1	ESGP		MTH 31-Oct-2014					
			HRS 2751.8		900		(3586.9)3651.8	279.3
			LDG 2486					
710060	CLEAN/INSPECT/TEST ENGINE WIRING HARNESS CONNECTORS							
E2	ESGP		MTH 31-Oct-2014					
			HRS 2686.9		900		(3586.9)3586.9	214.4
			LDG 2416					
720010	OVERHAUL-ENGINE							
E1	*CF		MTH 07-Jun-2006					
			HRS 64.9		5000		(5000)5064.9	1692.4
720010	OVERHAUL-ENGINE							
E2	*CF		MTH 07-Jun-2006					
			HRS 0		5000		(5000)5000	1627.5
720045	INSPECTION REMOVE ENGINE BLEED VALVE, INSPECT FOR CORROSION AND REAPPLY SILICONE GREASE							
E1	ESGP		MTH 14-Mar-2016		12		31-Mar-2017	1 m 29 d
			HRS 3178		600		(3713.1)3778	405.5
			LDG 2929					
720045	INSPECTION REMOVE ENGINE BLEED VALVE, INSPECT FOR CORROSION AND REAPPLY SILICONE GREASE							
E2	ESGP		MTH 14-Mar-2016		12		31-Mar-2017	1 m 29 d
			HRS 3113.1		600		(3713.1)3713.1	340.6
			LDG 2859					
720060	HOT SECTION INSPECTION							
E1	ESGP		MTH 25-Jul-2014					
			HRS 2610.2		2500		(5045.3)5110.2	1737.7
			LDG 2369					
720060	HOT SECTION INSPECTION							
E2	ESGP		MTH 25-Jul-2014					
			HRS 2545.3		2500		(5045.3)5045.3	1672.8
			LDG 2299					
731030	INSTALL NEW FUEL FILTER ELEMENT							
E1	ESGP		MTH 25-Nov-2015		24		30-Nov-2017	9 m 28 d
			HRS 3119.8		900		(3954.9)4019.8	647.3
			LDG 2875					

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Maintenance Inspections

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
731030 E2	INSTALL NEW FUEL FILTER ELEMENT	ESGP	MTH 25-Nov-2015 HRS 3054.9 LDG 2805		24 900		30-Nov-2017 (3954.9)3954.9	9 m 28 d 582.4
731100 E1	INSPECT EMERGENCY FUEL SHUTOFF LEVER AND CABLE	ESGP	MTH 15-Jul-2016 HRS 3305.3 LDG 3045		24 900		31-Jul-2018 (4140.4)4205.3	17 m 29 d 832.8
731100 E2	INSPECT EMERGENCY FUEL SHUTOFF LEVER AND CABLE	ESGP	MTH 15-Jul-2016 HRS 3240.4 LDG 2975		24 900		31-Jul-2018 (4140.4)4140.4	17 m 29 d 767.9
740010 E1	CHECK SPARK IGNITERS FOR CLEANLINESS AND EROSION	ESGP	MTH 14-Mar-2016 HRS 3178 LDG 2929		600		(3713.1)3778	405.5
740010 E2	CHECK SPARK IGNITERS FOR CLEANLINESS AND EROSION	ESGP	MTH 14-Mar-2016 HRS 3113.1 LDG 2859		600		(3713.1)3713.1	340.6
751030 E1	REPLACE INTERCOMPRESSORBLEEDVALVE SERVOVALVE		MTH 07-Jun-2006		-			
751030 E2	REPLACE INTERCOMPRESSORBLEEDVALVE SERVOVALVE		MTH 22-Jun-2011 HRS 1419.3 LDG 1262		-			
790020 E1	CHANGE OIL	ESGP	MTH 25-Jul-2014 HRS 2610.2 LDG 2369		A/R			
790020 E2	CHANGE OIL	ESGP	MTH 25-Jul-2014 HRS 2545.3 LDG 2299		A/R			
790030 E1	MONITOR OIL QUALITY		MTH 07-Jun-2006		O/C			
790030 E2	MONITOR OIL QUALITY		MTH 07-Jun-2006		O/C			



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
211002	EMERGENCY PRESSURIZATION FLOW (UY005) VALVE	*CF 4713-19 0622	MTH 07-Jun-2006		O/C			
211120 LEFT	BI LEVEL VALVE 9912492-1	*CF 1988-00-3 1898	MTH 07-Jun-2006		O/C			
211120 RIGHT	BI LEVEL VALVE 9912492-1	GSE 1988-00-3 2201	MTH 23-Oct-2007 HRS 504		O/C	0		
212200	MOTOR AND BLOWER ASSEMBLY	*CF 7003-400 0598	MTH 07-Jun-2006		O/C			
213005	MANUAL TOGGLE VALVE 9912409-12	*CF 52773-114 1295	MTH 07-Jun-2006		O/C			
213006	CABIN ALTITUDE (U1005) CONTROLLER 9912409-13	*CF F 52770-116 2383	MTH 07-Jun-2006		O/C			
213007 PRIMARY	OUTFLOW VALVE 9912409-19	*CF A 52771-314 1020B	MTH 07-Jun-2006		O/C			
213007 SECONDARY	OUTFLOW VALVE 9912409-11	*CF H 52772-114 1227B	MTH 07-Jun-2006		O/C			
213101	ALT PRESSURE SWITCH 9910095-6	GSE GB300NA161 0832342	MTH 01-Oct-2009 HRS 846		O/C	0		
215001	ENVIRONMENTAL CONTROL UNIT 9912493-8	*CF 2215460-3 707	MTH 07-Jun-2006		O/C			
215004	PAC OVERHEAT SWITCH 1173T0570	*CF 927223-2-2 0144	MTH 07-Jun-2006		O/C			
215005	ACM COOLING TURBINE	*CF 2206610-1 692	MTH 07-Jun-2006		O/C			
215006	HEAT EXCHANGER	*CF 2340594-6 757	MTH 07-Jun-2006		O/C			
215100	WATER SPRAY ECU ASPIRATOR 9912493-3	*CF 2215605-1 SN-UNKNOWN	MTH 07-Jun-2006		O/C			
215101	WATER SEPARATOR TEMP 1 SENSOR 9914130-20	*CF 1E62-1 11BA131	MTH 07-Jun-2006		O/C			
216002	ENVIRONMENTAL TEMP CONTROLLER 9912518-5	*CF M2 1E64-2 11BA59	MTH 07-Jun-2006		O/C			
216003 NO. 1	CABIN TEMP SENSOR 9914130-3	*CF 1E47-1 1BB10	MTH 07-Jun-2006		O/C			
216003 NO. 2	CABIN TEMP SENSOR 9914130-3	*CF 1E47-1 1BB7	MTH 07-Jun-2006		O/C			





## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
216009 CABIN	ZONE TEMPERATURE (UC021) SENSOR 9914130-6	*CF 1E46-1 1BB10	MTH 07-Jun-2006		O/C			
216009 COCKPIT	ZONE TEMPERATURE (UF029) SENSOR 9914130-6	*CF 1E46-1 10BA248	MTH 07-Jun-2006		O/C			
216099 216100	ECU TEMP CONTROL VALVE 9912518-2	*CF 27241287-14 12BA330A	MTH 07-Jun-2006		O/C			
216100 LEFT	CABIN TEMPERATURE CONTROL (VT029) VALVE 9912518-2	*CF 27241287-14 1BB25A	MTH 07-Jun-2006		O/C			
216100 RIGHT	COCKPIT TEMPERATURE CONTROL (VT030) VALVE 9912518-2	ESGP 27241287-14 7AY117F	MTH 05-Jan-2013 LDG 1764		O/C	0 0 0		
216101 LEFT	CABIN DUCT OVERHEAT (SC013) SWITCH 9912518-2	*CF 1173T42 3026	MTH 07-Jun-2006		O/C			
216101 RIGHT	COCKPIT DUCT OVERHEAT (SF034) SWITCH 9912518-2	*CF 1173T42 3024	MTH 07-Jun-2006		O/C			
217001	WATER SEPARATOR 9912493-7	*CF 2341316-2 619	MTH 07-Jun-2006		O/C			
217101 LEFT	OZONE CONVERTER 9914523-2	*CF D 31A437-1 0960/1831	MTH 07-Jun-2006		O/C			
217101 RIGHT	OZONE CONVERTER 9914523-2	*CF D 31A437-1 0965/1836	MTH 07-Jun-2006		O/C			
221009	AUTOPILOT (PC400) CONTROLLER PC-400	*CF A 7003897-923 06023450	MTH 07-Jun-2006		O/C			
221010 AILERON	DRIVE SERVO 9914523-2	*CF 4006719-921 05109830	MTH 07-Jun-2006		O/C			
221010 ELEVATOR	DRIVE SERVO 9914523-2	*CF 4006719-921 05109831	MTH 07-Jun-2006		O/C			
221010 RUDDER	DRIVE SERVO 9914523-2	*CF 4006719-922 05109797	MTH 07-Jun-2006		O/C			
231003	HIGH FREQUENCY RECEIVER/EXCITER HONEYWELL KHF-1050 RX 1053	*CF 064-01073-0101 1370	MTH 07-Jun-2006		O/C			
231004	HF POWER AMP HONEYWELL KHF-1050 KPA 1052	*CF 064-01072-0101 1381	MTH 07-Jun-2006		O/C			
231005	H.F. CONTROL HEAD HONEYWELL PS-440	*CF C 071-01605-0101 341	MTH 07-Jun-2006		O/C			
231006	H.F. ANTENNA COUPLER 9914523-2	*CF 2 064-01074-0101 1498	MTH 07-Jun-2006		O/C			



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
231501	FLITEPHONE VI ASSEMBLY ANTENNA IRIDIUM	*CF S67-1575-109 5199	MTH 07-Jun-2006		O/C			
232003 NO. 1	COMM ANTENNA	*CF S65-8282-1 1743	MTH 07-Jun-2006		O/C			
232003 NO. 2	COMM ANTENNA	*CF 21-38-1RF/36 10033	MTH 07-Jun-2006		O/C			
232004	FLITEPHONE 800 RADIOTELEPHONE (RT800) TRANCEIVER ST3100	*CF 400-10680-001 1068011891	MTH 07-Jun-2006		O/C			
232008 NO. 1	HONEYWELL PRIMUS II SRZ850 INTEGRATED (RCZ851) COMMUNICATION UNIT RCZ-833K	*CF AT 7510700-665 0602A335	MTH 07-Jun-2006		O/C			
232008 NO. 2	HONEYWELL PRIMUS II SRZ850 INTEGRATED (RCZ851) COMMUNICATION UNIT RCZ-833K	*CF AT 7510700-665 0602A336	MTH 07-Jun-2006		O/C			
232010 NO. 1	COMM TRANSCEIVER TR-833	*CF 7510763-901 0602A339	MTH 07-Jun-2006		O/C			
232010 NO. 2	COMM TRANSCEIVER TR-833	*CF 7510763-901 0602A355	MTH 07-Jun-2006		O/C			
232011	SELCAL DECODER CSD-714	*CF C 1200008-000 4759	MTH 07-Jun-2006		O/C			
232013 NO. 1	CLUSTER COMM MODULE XC-833	*CF K 7510784-835 0602A364	MTH 07-Jun-2006		O/C			
232013 NO. 2	CLUSTER COMM MODULE XC-833	*CF K 7510784-835 0601A342	MTH 07-Jun-2006		O/C			
235001 NO. 1	AUDIO CONTROL PANEL AMPLIFIER AV-850A	*CF AC 7511001-915 0512A702	MTH 07-Jun-2006		O/C			
235001 NO. 2	AUDIO CONTROL PANEL AMPLIFIER AV-850A	*CF AC 7511001-915 0512A705	MTH 07-Jun-2006		O/C			
237001	COCKPIT VOICE RECORDER FA2100	ESGP 2100-1020-02 000460602	MTH 02-May-2011 HRS 1342 LDG 1203		O/C			
237002	CVR GRAVITY SWITCH	*CF 6895D1-X-5-5 5097	MTH 07-Jun-2006		O/C			
237004	CVR CONTROL UNIT	*CF 4 S251-1120-00 000361246	MTH 07-Jun-2006		O/C			
237006	CVR UNDERWATER LOCATOR BEACON ESGP	DK120 SC20671	MTH 02-May-2011 HRS 1342 LDG 1203		O/C			
237006A	CVR UNDERWATER LOCATOR BEACON BATTERY 266-E0305-00	ESGP 810-2008/K SN-UNKNOWN	MTH 11-Oct-2013 HRS 2283.9 LDG 2052		DUE DUE DUE DUE	0 0 0 0	31-Jul-2019	29 m 29 d

Expiration Date: 31-Jul-2019

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Components

Item Code	Description	City	Mod Lvl	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #			Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
238001	STDBY CONTROL UNIT CD-850	*CF	G	7513000-835 06013126	MTH 07-Jun-2006		O/C			
240001 LEFT	POWER CONTROL (UD015) UNIT 9914216-6	*CF		91479-1 1300	MTH 07-Jun-2006		O/C			
240001 RIGHT	POWER CONTROL (UE016) UNIT 9914216-6	*CF		91479-1 1297	MTH 07-Jun-2006		O/C			
242050 LEFT	AC (UD017) GENERATOR 9914435-8	*CF		91372-3 1028	MTH 07-Jun-2006		O/C			
242050 RIGHT	AC (UE018) GENERATOR 9914435-8	GSE		91372-3 511	MTH 01-Oct-2009 HRS 846		O/C	0		
242100	STORMSCOPE INVERTER DO-160	*CF		SPC5 N/A	MTH 07-Jun-2006		O/C			
243003 APU	GENERATOR (UT032) CONTROL UNIT	*CF		51525-001F P2249	MTH 07-Jun-2006		O/C			
243003 LEFT	GENERATOR (UT007) CONTROL UNIT	*CF		51525-001F P2185	MTH 07-Jun-2006		O/C			
243003 RIGHT	GENERATOR (UT008) CONTROL UNIT	*CF		51525-001F P2231	MTH 07-Jun-2006		O/C			
243004 LEFT	DC (EI011) AMMETER S3439-1	*CF		MD144-1 L0512214	MTH 07-Jun-2006		O/C			
243004 RIGHT	DC (EI010) AMMETER S3439-1	*CF		MD144-1 K0510809	MTH 07-Jun-2006		O/C			
243005	DC (EI009) VOLTMETER MD129-1	*CF		C662502-0101 L0511491	MTH 07-Jun-2006		O/C			
243007	MAIN SHIP (UY006) BATTERY 9914058-6	ESGP		30978-002 10800920	MTH 01-Nov-2016 HRS 3329 LDG 3059 APUH 1763 APUS 3762		O/C			
243008	OVERHEAT MONITOR	*CF		1529-1 4487	MTH 07-Jun-2006		O/C			
243009	BATTERY TEMP INDICATOR	*CF		1229-1 3336	MTH 07-Jun-2006		O/C			
243010	BATTERY TEMP SENSOR	*CF		19504 SN-UNKNOWN	MTH 07-Jun-2006		O/C			
243015	BATTERY DISCONNECT (KY001) RELAY	*CF		A876K CP26875	MTH 07-Jun-2006		O/C			
243016	OVERVOLTAGE (UZ003) MONITOR	*CF		1645-1-3 3829	MTH 07-Jun-2006		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Components

Item Code	Description	City	Mod Lvl	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #			Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
245079 LEFT	START CNTL NZ013 PCB	*CF		6318324-5 SN-UNKNOWN	MTH 07-Jun-2006		O/C			
245079 RIGHT	START CNTL NZ012 PCB	*CF		6318324-5 SN-UNKNOWN	MTH 07-Jun-2006		O/C			
245080	TRIM NZ001 PCB	*CF		6518351-7 0921	MTH 07-Jun-2006		O/C			
245081	PRESS NZ002 PCB	*CF		6518352-5 SN-UNKNOWN	MTH 07-Jun-2006		O/C			
245082	DIMMING NZ023 PCB	*CF		6518366-3 0333	MTH 07-Jun-2006		O/C			
245083 LEFT	EEC INTERFACE NZ021 PCB	*CF		6618002-4 0195	MTH 07-Jun-2006		O/C			
245083 RIGHT	EEC INTERFACE NZ020 PCB	*CF		6618002-4 0210A	MTH 07-Jun-2006		O/C			
245084	LANDING GEAR NZ004 PCB	*CF		6618704-6 0660	MTH 07-Jun-2006		O/C			
245086	SQUAT SW NZ006 PCB	*CF		6618706-1 0615	MTH 07-Jun-2006		O/C			
245087	CABIN DOOR NZ007 PCB	*CF		6618707-26 0132A	MTH 07-Jun-2006		O/C			
245088	LANDING GEAR CONT NZ009 PCB	*CF		6618735-1 0225	MTH 07-Jun-2006		O/C			
245091	NO TAKE-OFF NZ008 PCB FDR OPTION	*CF		6618708-6 0246	MTH 07-Jun-2006		O/C			
245092 LEFT	FUEL NZ015 PCB	*CF		6618714-11 0120	MTH 07-Jun-2006		O/C			
245092 RIGHT	FUEL NZ014 PCB	*CF		6618714-11 0123	MTH 07-Jun-2006		O/C			
245094	HYD NZ016 PCB	*CF		6618723-5 0223	MTH 07-Jun-2006		O/C			
245095	POS TAIL NZ017 PCB	*CF		6618721-1 0617	MTH 07-Jun-2006		O/C			
245096 LEFT	ANTI ICE NZ019 PCB	*CF		6618718-1 1095	MTH 07-Jun-2006		O/C			
245096 RIGHT	ANTI-ICE NZ018 PCB	*CF		6618718-1 1094	MTH 07-Jun-2006		O/C			



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Components

Item Code	Description	City	Mod Lvl	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #			Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
245098	RUDDER BIAS NZ029 PCB	*CF		6618812-1 0629	MTH 07-Jun-2006		O/C			
245103	APU NZ025 PCB	*CF		6618808-26 0302	MTH 07-Jun-2006		O/C			
245104	APU NZ026 PCB	*CF		6618809-1 0575	MTH 07-Jun-2006		O/C			
245105	TAIL DEICE CONT NZ031 PCB	*CF		6618730-1 0223	MTH 07-Jun-2006		O/C			
245106	TAIL DEICE MON NZ033 PCB	*CF		6618731-1 0224	MTH 07-Jun-2006		O/C			
245107	MISCELLANEOUS NZ035 PCB	*CF		6618732-1 0196A	MTH 07-Jun-2006		O/C			
250002	AV VISOR PLUS PROCESSOR	ESGP		90008-0031 43B00581	MTH 09-Sep-2013 HRS 2237.1 LDG 2009		O/C			
250003	AV VISOR DISPLAY	*CF		15004-00300 136713	MTH 07-Jun-2006		O/C			
251007 NO. 1	PBE	ESGP		E28180-20-0006 A5CF05078	MTH 29-Sep-2016 HRS 3305.4 LDG 3034 APUH 1763 APUS 3762		120	2	31-Jul-2026	113 m 29 d
252003	TEMPERATURE PROBE	*CF		102DB1AG A62821	MTH 07-Jun-2006		O/C			
252010 CABIN	BREIFER CONTROL	*CF	D	PBS250-2G5 252001599	MTH 07-Jun-2006		O/C			
252010	COMPUTER-CABIN BRIEFER -- S2800-420	GSE		PBS250-1-S8 251000133	MTH 12-Oct-2007 HRS 497		O/C	0		
252525	EXTERNALLY SERVICABLE TOILET	ESGP		15900-021 183	MTH 20-Oct-2011 HRS 1557.4 LDG 1374		O/C	0		
256001 NO. 10	LIFE JACKET	ESGP		P01074-207 SN-UNKNOWN	MTH 14-Mar-2016 HRS 3113.1 LDG 2859		60	1	28-Feb-2021	48 m 26 d
256001 NO. 1	LIFE JACKET	ESGP		P01074-207 SN-UNKNOWN	MTH 14-Mar-2016 HRS 3113.1 LDG 2859		60	1	28-Feb-2021	48 m 26 d
256001 NO. 2	LIFE JACKET	ESGP		P01074-207 SN-UNKNOWN	MTH 14-Mar-2016 HRS 3113.1 LDG 2859		60	1	28-Feb-2021	48 m 26 d
256001 NO. 3	LIFE JACKET	ESGP		P01074-207 SN-UNKNOWN	MTH 14-Mar-2016 HRS 3113.1 LDG 2859		60	1	28-Feb-2021	48 m 26 d
256001 NO. 4	LIFE JACKET	ESGP		P01074-207 SN-UNKNOWN	MTH 14-Mar-2016 HRS 3113.1 LDG 2859		60	1	28-Feb-2021	48 m 26 d

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Components

Item Code	Description	City	Mod Lvl	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #			Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
256001 NO. 5	LIFE JACKET	ESGP		P01074-207 SN-UNKNOWN	MTH 14-Mar-2016 HRS 3113.1 LDG 2859		60	1	28-Feb-2021	48 m 26 d
256001 NO. 6	LIFE JACKET	ESGP		P01074-207 SN-UNKNOWN	MTH 14-Mar-2016 HRS 3113.1 LDG 2859		60	1	28-Feb-2021	48 m 26 d
256001 NO. 7	LIFE JACKET	ESGP		P01074-207 SN-UNKNOWN	MTH 14-Mar-2016 HRS 3113.1 LDG 2859		60	1	28-Feb-2021	48 m 26 d
256001 NO. 8	LIFE JACKET	ESGP		P01074-207 SN-UNKNOWN	MTH 14-Mar-2016 HRS 3113.1 LDG 2859		60	1	28-Feb-2021	48 m 26 d
256001 NO. 9	LIFE JACKET	ESGP		P01074-207 SN-UNKNOWN	MTH 14-Mar-2016 HRS 3113.1 LDG 2859		60	1	28-Feb-2021	48 m 26 d
256002	EMERGENCY LOCATOR TRANSMITTER C406N	*CF		453-5060 01792	MTH 07-Jun-2006		O/C			
256003	EMERGENCY LOCATOR BEACON BATTERY PACK	ESGP		452-0133 365273-091	MTH 11-Jan-2016 HRS 3109.1 LDG 2853		60	13	31-Dec-2019	34 m 29 d
256004	ELT ANTENNA	*CF		110-328-01 5042207	MTH 07-Jun-2006		O/C			
261002 LEFT	ENGINE FIRE DETECT (UT021) CONTROL UNIT	*CF		377-02838 0542175	MTH 07-Jun-2006		O/C			
261002 RIGHT	ENGINE FIRE DETECT (UT020) CONTROL UNIT	*CF		377-02838 0542171	MTH 07-Jun-2006		O/C			
262001 AFT	ENGINE FIRE BOTTLE	ESGP		30400037-1 45532B1	MTH 05-Oct-2015 HRS 3020.2 LDG 2760		O/C			
262001 APU	FIRE BOTTLE	ESGP		9914513-7 37317A1	MTH 14-Mar-2016 HRS 3113.1 LDG 2859		O/C			
262001 FORWARD	ENGINE FIRE BOTTLE	ESGP		30400037-1 51165B1	MTH 17-Mar-2015 HRS 2805.3 LDG 2549		O/C	0		
262002 CABIN	PORTABLE HALON FIRE EXTINGUISHER	ESGP		C352TS Y-95677	MTH 25-Apr-2012 HRS 1689.4 LDG 1522		O/C	0		
262002 COCKPIT	PORTABLE HALON FIRE EXTINGUISHER	ESGP		C352TS Y-95678	MTH 25-Apr-2012 HRS 1689.4 LDG 1522		O/C	0		5
263004 262003 : APU	APU FIRE BOTTLE CARTRIDGE	ESGP		13083-5 ESD14G540-001	MTH 14-Mar-2016 HRS 3113.1 LDG 2859		72	20	31-Jul-2020	41 m 29 d
Manufacture Date: 31-Jul-2014										
263006 262003 : FL	FORWARD ENGINE BOTTLE FORWARD CARTRIDGE	ESGP		13083-5 ESD14M564-001	MTH 17-Mar-2015 HRS 2805.3 LDG 2549		72		31-Dec-2020	46 m 29 d
Manufacture Date: 01-Dec-2014										



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
263008	FORWARD ENGINE BOTTLE AFT CARTRIDGE		MTH 17-Mar-2015		72	0	31-Dec-2020	46 m 29 d
<i>262003 : FR</i>		ESGP 13083-5 ESD10G376-001	HRS 2805.3 LDG 2549					
Manufacture Date: 01-Dec-2014								
263010	AFT ENGINE BOTTLE FORWARD CARTRIDGE		MTH 05-Oct-2015		72		28-Feb-2018	12 m 26 d
<i>262003 : AL</i>		ESGP 13083-5 ESD12B424-001	HRS 3020.2 LDG 2760					
Manufacture Date: 28-Feb-2012								
263012	AFT ENGINE BOTTLE AFT CARTRIDGE		MTH 05-Oct-2015		72		31-Oct-2018	20 m 29 d
<i>262003 : AR</i>		ESGP 13083-5 ESD12K451-001	HRS 3020.2 LDG 2760					
Manufacture Date: 31-Oct-2012								
272001	RUDDER BIAS SHUTOFF VALVE		MTH 07-Jun-2006		O/C			
	*CF	5307-1 0917C						
272002	STICK SHAKER (MC001) UNIT		MTH 07-Jun-2006		O/C			
<i>LEFT</i>	*CF A	201 6633						
272002	STICK SHAKER (MF004) UNIT		MTH 07-Jun-2006		O/C			
<i>RIGHT</i>	*CF A	201 6653						
272003	RUDDER BIAS ACTUATOR		MTH 07-Jun-2006		O/C			
	*CF	6660613-12 SN-UNKNOWN						
273004	SERVO ACTUATOR		MTH 09-Dec-2009		O/C			
	ESGP	44430-3739 T723	HRS 907 LDG 793					
273020	AFT ELEVATOR TRIM CABLE ASSEMBLY		MTH 07-Jun-2006			0		
		PN SN-UNKNOWN	HRS 0		4800	0	4800	1427.5
273201	ELEV TRIM SWITCH		MTH 07-Jun-2006		O/C			
	*CF	8-405-04 B60878						
274000	HORIZONTAL STABILIZER ACTUATOR		MTH 07-Jun-2006		O/C			
	9912548-6 *CF	41011680-107 0548						
274001	HYDRAULIC MANIFOLD ASSEMBLY		MTH 07-Jun-2006		O/C			
	9912625-17 *CF	8244-1 134						
274013	HORIZONTAL STABILIZER ISOLATION (UY015) VALVE		MTH 07-Jun-2006		O/C			
	9912625-13 *CF	4220-1 0138						
274044	HORIZONTAL STAB VALVE ASSY		MTH 07-Jun-2006		O/C			
	9912625-12 *CF	4218-1 0139						
275001	FLAP CONTROL (UY024) VALVE		MTH 07-Jun-2006		O/C			
	9912625-5 *CF	4216-3 0139						
275003	FLAP ACTUATOR		MTH 07-Jun-2006		O/C			
<i>LEFT</i>	9912007-1 *CF	1535000-1 2218						
275003	FLAP ACTUATOR		MTH 01-Oct-2009		O/C			
<i>RIGHT</i>	9912007-2 GSE	1535000-3 3015	HRS 846			0		



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Components

Item Code	Description	City	Mod Lvl	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #			Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
275004 LEFT WING LEFT INBOARD	AFT FLAP ROLLER CF-2920	*CF		S3049-5F8 SN-UNKNOWN	MTH 07-Jun-2006 LDG 0		5000	0	5000	1888
275004 LEFT WING LEFT OUTBOARD	AFT FLAP ROLLER CF-2920	*CF		S3049-5F8 SN-UNKNOWN	MTH 07-Jun-2006 LDG 0		5000	0	5000	1888
275004 LEFT WING RIGHT INBOARD	AFT FLAP ROLLER CF-2920	ESGP		S3049-5F8 SN-UNKNOWN	MTH 14-Mar-2016 HRS 3113.1 LDG 2859		5000	0	7859	4747
275004 LEFT WING RIGHT OUTBOARD	AFT FLAP ROLLER CF-2920	*CF		S3049-5F8 SN-UNKNOWN	MTH 07-Jun-2006 LDG 0		5000	0	5000	1888
275004 RIGHT WING LEFT INBOARD	AFT FLAP ROLLER CF-2920	*CF		S3049-5F8 SN-UNKNOWN	MTH 07-Jun-2006 LDG 0		5000	0	5000	1888
275004 RIGHT WING LEFT OUTBOARD	AFT FLAP ROLLER CF-2920	*CF		S3049-5F8 SN-UNKNOWN	MTH 07-Jun-2006 LDG 0		5000	0	5000	1888
275004 RIGHT WING RIGHT INBOARD	AFT FLAP ROLLER CF-2920	*CF		S3049-5F8 SN-UNKNOWN	MTH 07-Jun-2006 LDG 0		5000	0	5000	1888
275004 RIGHT WING RIGHT OUTBOARD	AFT FLAP ROLLER CF-2920	*CF		S3049-5F8 SN-UNKNOWN	MTH 07-Jun-2006 LDG 0		5000	0	5000	1888
275005 LEFT WING LEFT INBOARD	FORWARD FLAP ROLLER CF-2920	*CF		S3049-5F8 SN-UNKNOWN	MTH 07-Jun-2006 LDG 0		5000	0	5000	1888
275005 LEFT WING LEFT OUTBOARD	FORWARD FLAP ROLLER CF-2920	*CF		S3049-5F8 SN-UNKNOWN	MTH 07-Jun-2006 LDG 0		5000	0	5000	1888
275005 LEFT WING RIGHT INBOARD	FORWARD FLAP ROLLER CF-2920	*CF		S3049-5F8 SN-UNKNOWN	MTH 07-Jun-2006 LDG 0		5000	0	5000	1888
275005 LEFT WING RIGHT OUTBOARD	FORWARD FLAP ROLLER CF-2920	*CF		S3049-5F8 SN-UNKNOWN	MTH 07-Jun-2006 LDG 0		5000	0	5000	1888
275005 RIGHT WING LEFT INBOARD	FORWARD FLAP ROLLER CF-2920	*CF		S3049-5F8 SN-UNKNOWN	MTH 07-Jun-2006 LDG 0		5000	0	5000	1888
275005 RIGHT WING LEFT OUTBOARD	FORWARD FLAP ROLLER CF-2920	*CF		S3049-5F8 SN-UNKNOWN	MTH 07-Jun-2006 LDG 0		5000	0	5000	1888
275005 RIGHT WING RIGHT INBOARD	FORWARD FLAP ROLLER CF-2920	*CF		S3049-5F8 SN-UNKNOWN	MTH 07-Jun-2006 LDG 0		5000	0	5000	1888
275005 RIGHT WING RIGHT OUTBOARD	FORWARD FLAP ROLLER CF-2920	*CF		S3049-5F8 SN-UNKNOWN	MTH 07-Jun-2006 LDG 0		5000	0	5000	1888
276001 LEFT	SPEED BRAKE ACTUATOR 9912344-1	*CF		1535500-1 2994	MTH 07-Jun-2006		O/C			
276001 RIGHT	SPEED BRAKE ACTUATOR 9912344-1	*CF		1535500-1 2971	MTH 07-Jun-2006		O/C			





## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
276002	SPEED BRAKE CONTROL VALVE 9912625-6	*CF 4216-2 0142	MTH 07-Jun-2006		O/C			
276003	SPEED BRAKE SAFETY VALVE 9912625-7	*CF 4217-1 0142	MTH 07-Jun-2006		O/C			
280003 LEFT	FUEL RELIEF VALVE ASSY 9912501-2	*CF 840203-105 4142	MTH 07-Jun-2006		O/C			
280003 RIGHT	FUEL RELIEF VALVE ASSY 9912501-2	*CF 840203-105 4189	MTH 07-Jun-2006		O/C			
280004 LEFT	HIGH LVL FUEL VALVE 9914107-1	*CF 61087 4165	MTH 07-Jun-2006		O/C			
280004 RIGHT	HIGH LVL FUEL VALVE 9914107-1	*CF 61087 4023	MTH 07-Jun-2006		O/C			
281101 LEFT	FUEL VENT FLOAT VALVE 9914268-5	*CF 60221-4 1346	MTH 07-Jun-2006		O/C			
281101 RIGHT	FUEL VENT FLOAT VALVE 9914268-5	*CF 60221-4 1373	MTH 07-Jun-2006		O/C			
282011 LEFT AFT	SCAVENGE FUEL EJECTOR PUMP 9912483-2	*CF 2950024-101 3130	MTH 07-Jun-2006		O/C			
282011 LEFT FORWARD	SCAVENGE FUEL EJECTOR PUMP 9912483-2	*CF 2950024-101 3145	MTH 07-Jun-2006		O/C			
282011 LEFT MID	SCAVENGE FUEL EJECTOR PUMP 9912483-2	*CF 2950024-101 3121	MTH 07-Jun-2006		O/C			
282011 RIGHT AFT	SCAVENGE FUEL EJECTOR PUMP 9912483-2	*CF 2950024-101 3135	MTH 07-Jun-2006		O/C			
282011 RIGHT FORWARD	SCAVENGE FUEL EJECTOR PUMP 9912483-2	*CF 2950024-101 3125	MTH 07-Jun-2006		O/C			
282011 RIGHT MID	SCAVENGE FUEL EJECTOR PUMP 9912483-2	*CF 2950024-101 3134	MTH 07-Jun-2006		O/C			
282012 LEFT <i>282012A : L</i>	FUEL BOOST CARTRIDGE	*CF LR55505-2 D1193	MTH 07-Jun-2006		O/C			
282012 LEFT WING	BOOST FUEL ELECTRIC PUMP 9914421-4	*CF LR55540A B1127	MTH 07-Jun-2006		O/C			
282012 RIGHT <i>282012A : R</i>	FUEL BOOST CARTRIDGE	*CF LR55505-2 D1196	MTH 07-Jun-2006		O/C			
282012 RIGHT WING	BOOST FUEL ELECTRIC PUMP 9914421-4	*CF LR55540A B1124	MTH 07-Jun-2006		O/C			



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
282013 LEFT WING	PRIMARY MOTIVE FLOW EJECTOR PUMP 9912483-1	*CF 2950023-101 1083	MTH 07-Jun-2006		O/C			
282013 RIGHT WING	PRIMARY MOTIVE FLOW EJECTOR PUMP 9912483-1	*CF 2950023-101 1087	MTH 07-Jun-2006		O/C			
282014	FUEL CROSSFEED ACTUATOR 9914423-2	*CF MA20A1029-1 AA63843	MTH 07-Jun-2006		O/C			
282100 LEFT WING	SINGLE PT REFUEL/DEFUEL SHUTOFF VALVE 9914423-4	*CF 80002-101 1784	MTH 07-Jun-2006		O/C			
282100 RIGHT WING	SINGLE PT REFUEL/DEFUEL SHUTOFF VALVE 9914423-4	*CF 80002-101 1755	MTH 07-Jun-2006		O/C			
282106	FUEL CROSSFEED VALVE 9914423-4	*CF 125838AW AA64475	MTH 07-Jun-2006		O/C			
282108 LEFT	MOTIVE FLOW SHUTOFF (UY009) VALVE 9914423-4	*CF 4151 999	MTH 07-Jun-2006		O/C			
282108 RIGHT	MOTIVE FLOW SHUTOFF (UY008) VALVE 9914423-4	*CF 4151 1052	MTH 07-Jun-2006		O/C			
282118 LEFT	FUEL SHUT-OFF VALVE 9914094-1	*CF 71498 AA37423	MTH 07-Jun-2006		O/C			
282118 RIGHT	FUEL SHUT-OFF VALVE 9914094-1	*CF 71498 AA41856	MTH 07-Jun-2006		O/C			
282200 LEFT	LOW LEVEL VALVE ASSY 9914427-2	*CF 726400-1 1025	MTH 07-Jun-2006		O/C			
282200 RIGHT	LOW LEVEL VALVE ASSY 9914427-2	*CF 726400-1 1004	MTH 07-Jun-2006		O/C			
282201	VALVE-REFUEL/DEFUEL 9914427-2	*CF 9036-351-2 1110	MTH 07-Jun-2006		O/C			
282202 LEFT	FUEL VALVE ASSY 9914427-2	*CF 750800-2 1125	MTH 07-Jun-2006		O/C			
282202 RIGHT	FUEL VALVE ASSY 9914427-2	*CF 750800-2 1121	MTH 07-Jun-2006		O/C			
284012 LEFT	LOW FUEL LEVEL SENSOR 9914427-2	*CF GIF5400-43 2186	MTH 07-Jun-2006		O/C			
284012 RIGHT	LOW FUEL LEVEL SENSOR 9914427-2	GSE GIF5400-43 742	MTH 01-Oct-2009 HRS 846		O/C	0		
284013 LEFT WING	FUEL QTY W0 PROBE 9912498-8	*CF 10634T07Y00 MN00644	MTH 07-Jun-2006		O/C			



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Components

Item Code	Description	City	Mod Lvl	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #			Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
284013 RIGHT WING	FUEL QTY W0 PROBE 9912498-8	*CF		10634T07Y00 MN00599	MTH 07-Jun-2006		O/C			
284014 LEFT WING	FUEL QTY W1 PROBE 9912498-1	*CF		10634T02Y00 1475	MTH 07-Jun-2006		O/C			
284014 RIGHT WING	FUEL QTY W1 PROBE 9912498-1	*CF		10634T02Y00 1480	MTH 07-Jun-2006		O/C			
284015 LEFT WING	FUEL QTY W2 PROBE 9912498-2	*CF		10634T03Y00 MN00325	MTH 07-Jun-2006		O/C			
284015 RIGHT WING	FUEL QTY W2 PROBE 9912498-2	*CF		10634T03Y00 MN00502	MTH 07-Jun-2006		O/C			
284016 LEFT WING	FUEL QTY W3 PROBE 9912498-3	*CF		10634T04Y00 MN00401	MTH 07-Jun-2006		O/C			
284016 RIGHT WING	FUEL QTY W3 PROBE 9912498-3	*CF		10634T04Y00 MN00369	MTH 07-Jun-2006		O/C			
284017 LEFT WING	FUEL QTY W4 PROBE 9912498-4	*CF		10634T05Y00 1768	MTH 07-Jun-2006		O/C			
284017 RIGHT WING	FUEL QTY W4 PROBE 9912498-4	*CF		10634T05Y00 MN00465	MTH 07-Jun-2006		O/C			
284018 LEFT WING	FUEL QTY W5 PROBE 9912498-5	*CF		10634T01Y00 MN00067	MTH 07-Jun-2006		O/C			
284018 RIGHT WING	FUEL QTY W5 PROBE 9912498-5	*CF		10634T01Y00 MN00236	MTH 07-Jun-2006		O/C			
284019 LEFT WING	FUEL QTY W6 PROBE 9912498-6	*CF		10634T06Y00 MN00572	MTH 07-Jun-2006		O/C			
284019 RIGHT WING	FUEL QTY W6 PROBE 9912498-6	*CF		10634T06Y00 MN00669	MTH 07-Jun-2006		O/C			
284196	FUEL QUANTITY SIGNAL CONDITIONER 9912498-7	*CF		10635B01Y01 06011180	MTH 07-Jun-2006		O/C			
291001	HYDRAULIC RESERVOIR 9912542-1	GSE		7470 539	MTH 01-Oct-2009 HRS 846		O/C	0		
291002 LEFT	HYDRAULIC PUMP 9912062-4	*CF		24195-LAA 4613	MTH 07-Jun-2006		O/C			
291002 RIGHT	HYDRAULIC PUMP 9912062-4	*CF		24195-LAA 4653	MTH 07-Jun-2006		O/C			
291005 LEFT	HYDRAULIC FLOW SWITCH 9912194-3	*CF		3520020100-4 06581	MTH 07-Jun-2006		O/C			



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
291005 RIGHT	HYDRAULIC FLOW SWITCH 9912194-3	*CF 3520020100-4 06568	MTH 07-Jun-2006		O/C			
291008	SPEED BRAKE THERMAL RELIEF VALVE 9912625-8	*CF 2664 0136	MTH 07-Jun-2006		O/C			
291010	HYD PRESS SWITCH 9912625-3	*CF 80637 0410	MTH 07-Jun-2006		O/C			
291013 LEFT	FIREWALL HYD SHUTOFF VALVE *CF	AV24B1325C5 AA64135	MTH 07-Jun-2006		O/C			
291013 RIGHT	FIREWALL HYD SHUTOFF VALVE *CF	AV24B1325C5 AA62484	MTH 07-Jun-2006		O/C			
301001 LEFT WING	ANTI-ICE BLEED AIR UNDER TEMP SL013 SWITCH *CF	1173T42-4 2975	MTH 07-Jun-2006		O/C			
301001 RIGHT WING	ANTI-ICE BLEED AIR UNDER TEMP SR016 SWITCH *CF	1173T42-4 2963	MTH 07-Jun-2006		O/C			
301002	ISOLATION VALVE 9912403-2	*CF 2602-36 1390	MTH 07-Jun-2006		O/C			
301008 LEFT	DEICE TAIL VALVE *CF	3D2353-06 N051831	MTH 07-Jun-2006		O/C			
301008 RIGHT	DEICE TAIL VALVE *CF	3D2353-06 N052543	MTH 07-Jun-2006		O/C			
301020	WINDSHIELD RAIN REMOVAL MN001 FAN *CF	011598-501 C06030414	MTH 07-Jun-2006		O/C			
301137 LEFT WING	INLET ANTI-ICE PRESSURE REG SHUTOFF VD001 VALVE 9912495-1	GSE 1962-00-7 2918	MTH 13-Jul-2007 HRS 392		O/C	0		
301137 RIGHT WING	INLET ANTI-ICE PRESSURE REG SHUTOFF VE002 VALVE 9912495-1	GSE 1962-00-7 2735	MTH 13-Jul-2007 HRS 392		O/C	392		
301201 LEFT	TAIL DEICE PRESSURE SV005 SWITCH ESGP	1106P55-1 8179A	MTH 25-Apr-2016 HRS 3161.5 LDG 2909 APUH 1687 APUS 3470		O/C	0	0	
301201 RIGHT	TAIL DEICE PRESSURE SV004 SWITCH *CF	1106P55-1 3158A	MTH 07-Jun-2006		O/C			
301202 LEFT	HORIZ STAB DEICE BOOT ESGP	P29S4D5280-11 NBY5320	MTH 23-Jan-2015 HRS 2767 LDG 2503		O/C	0	0	0
301202 RIGHT	HORIZ STAB DEICE BOOT ESGP	P29S4D5280-12 NCC0500	MTH 23-Jan-2015 HRS 2767 LDG 2503		O/C	0	0	0
302101 LEFT	PRESSURE REG VALVE 9912495-4	*CF 1946-00-19 3459	MTH 07-Jun-2006		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Components

Item Code	Description	City	Mod Lvl	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #			Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
302101 RIGHT	PRESSURE REG VALVE 9912495-4	*CF		1946-00-19 3458	MTH 07-Jun-2006		O/C			
302104 LEFT	NACELLE INLET SWITCH	*CF		1173T0759 3264	MTH 07-Jun-2006		O/C			
302104 RIGHT	NACELLE INLET SWITCH	*CF		1173T0759 3239	MTH 07-Jun-2006		O/C			
303001 LEFT	PITOT TUBE	*CF		PH1100-1-VCW C3745	MTH 07-Jun-2006		O/C			
303001 RIGHT	PITOT TUBE	*CF		PH1100-1-VCW C3738	MTH 07-Jun-2006		O/C			
303001 STANDBY	PITOT TUBE	*CF		PH1100-1-RCDW C3782	MTH 07-Jun-2006		O/C			
304100 LEFT	WINDSHIELD CONTROLLER 9914411-1	*CF		856-1-1 205520323	MTH 07-Jun-2006		O/C			
304100 RIGHT	WINDSHIELD CONTROLLER 9914411-1	*CF		856-1-1 205520324	MTH 07-Jun-2006		O/C			
302005 E1	ANTI-ICING VALVE 31J2879-04	*CF		540-0406-4 3784	MTH 07-Jun-2006		O/C			
302005 E2	ANTI-ICING VALVE 31J2879-04	*CF		540-0406-4 3762	MTH 07-Jun-2006		O/C			
312001 LEFT HAND	DIGITAL CLOCK	*CF		M877A5V 17041	MTH 07-Jun-2006		O/C			
313001	FDR ACCELEROMETER	*CF		3001-01-111-3 12058740	MTH 07-Jun-2006		O/C			
313002	FDR MFDAU UNIT	*CF	C	2231230-5A 01424	MTH 07-Jun-2006		O/C			
313003 LEFT	ENGINE ACCELEROMETER	*CF		6222SM15 20374	MTH 07-Jun-2006		O/C			
313003 RIGHT	ENGINE ACCELEROMETER	*CF		6222SM15 20434	MTH 07-Jun-2006		O/C			
313006	FLIGHT DATA RECORDER	*CF		980-4700-025 12069	MTH 07-Jun-2006		O/C			
313007	FDR UNDERWATER LOCATOR BEACON	*CF		DK120 DU15507	MTH 07-Jun-2006		O/C	0		
313007A	FDR BATTERY	ESGP		810-2008/K MAY2018	MTH 25-Apr-2012 HRS 1689.4 LDG 1522		72	0	30-Apr-2018	14 m 28 d



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Components

Item Code	Description	City	Mod Lvl	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #			Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
313008	FDR IMPACT SWITCH	*CF		6895-D-1-X-5-5 5742	MTH 07-Jun-2006		O/C			
315001	FDR FAIL ANNUNCIATOR 9912504-17	*CF		1304-1-17 205490309	MTH 07-Jun-2006		O/C			
315101 LEFT	WARNING GEN/MIXER UNIT	*CF		1287-1-2 205470206	MTH 07-Jun-2006		O/C			
315101 RIGHT	WARNING GEN/MIXER UNIT	ESGP		1287-1-2 205470217	MTH 01-Nov-2016 HRS 3329 LDG 3059 APUH 1763 APUS 3762		O/C			
316001	TILT INDICATOR	*CF		3001J72 23331	MTH 07-Jun-2006		O/C			
321003 LEFT MAIN LANDING GEAR	TRUNNION	ESGP		6641630-41 25078551	MTH 24-Aug-2015 HRS 2964.8 LDG 2709		33300	0	36009	32897
321003 RIGHT MAIN LANDING GEAR	TRUNNION	ESGP		6641630-42 24998516	MTH 24-Aug-2015 HRS 2964.8 LDG 2709		33300	0	36009	32897
321004 LEFT MAIN LANDING GEAR	TRAILING LINK	*CF		6641648-15 SN-UNKNOWN	MTH 07-Jun-2006 LDG 0		40300	0	40300	37188
321004 RIGHT MAIN LANDING GEAR	TRAILING LINK	*CF		6641648-14 SN-UNKNOWN	MTH 07-Jun-2006 LDG 0		40300	0	40300	37188
321011 LEFT MAIN LANDING GEAR	TRAILING LINK SPACER	*CF		6641533-1 SN-UNKNOWN	MTH 07-Jun-2006 LDG 0		33300	0	33300	30188
321011 RIGHT MAIN LANDING GEAR	TRAILING LINK SPACER	*CF		6641533-1 SN-UNKNOWN	MTH 07-Jun-2006 LDG 0		33300	0	33300	30188
321020 LEFT MAIN LANDING GEAR	BREATHER VENT	ESGP		QSB-5-SS SN-UNKNOWN	MTH 07-Jun-2016 HRS 3195.3 LDG 2938 APUH 1687 APUS 3470		12 600	0 0	30-Jun-2017 3795.3	4 m 28 d 422.8
321020 RIGHT MAIN LANDING GEAR	BREATHER VENT	ESGP		QSB-5-SS SN-UNKNOWN	MTH 07-Jun-2016 HRS 3195.3 LDG 2938 APUH 1687 APUS 3470		12 600	0 0	30-Jun-2017 3795.3	4 m 28 d 422.8
322001 NOSE	LANDING GEAR ASSEMBLY	*CF		6642614-1-5 11	MTH 07-Jun-2006 LDG 0		33300	0	33300	30188
322002 NOSE GEAR	SHIMMY DAMPER	ESGP		5543001-12 042-12X	MTH 24-Oct-2012 HRS 1963.9 LDG 1742		O/C			
322007 NOSE GEAR	TRUNNION	*CF		6642611-9 SN-UNKNOWN	MTH 07-Jun-2006		O/C			
323001 LEFT MAIN LANDING GEAR	ACTUATOR 9912537-3	*CF		1550000-3 1062B	MTH 07-Jun-2006 LDG 0		70200	0	70200	67088

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Components

Item Code	Description	City	Mod Lvl	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #			Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
323001	ACTUATOR RIGHT MAIN LANDING GEAR	*CF		1550000-4 1059	MTH 07-Jun-2006 LDG 0		70200	0	70200	67088
323002 : R										
323003	ACTUATOR NOSE LANDING GEAR	*CF		1549300-9 0510	MTH 07-Jun-2006 LDG 0		33300	0	33300	30188
323004	UPLOCK ACTUATOR LEFT	*CF		5527504-3 3481	MTH 07-Jun-2006		O/C			
323004	UPLOCK ACTUATOR NOSE	*CF		5527504-3 3437	MTH 07-Jun-2006		O/C			
323004	UPLOCK ACTUATOR RIGHT	*CF		5527504-3 3487	MTH 07-Jun-2006		O/C			
323005	PRESSURE EMER GEAR GAUGE GSE			19940929-1 45184D	MTH 01-Oct-2009 HRS 846		O/C	0		
323006	PNEUMATIC BLOWDOWN/EMERGENCY BRAKE BOTTLE 9912505-2	ESGP		40005347-3 4384	MTH 19-Sep-2014 HRS 2628.1 LDG 2360		288		28-Feb-2029	144 m 26 d
Manufacture Date: 28-Feb-2005										
323007	LANDING GEAR CONTROL (VY047) VALVE 9912625-9	*CF		4219-1 0132	MTH 07-Jun-2006		O/C			
323008	DUMP VALVE 9912625-11	*CF		9615 0139	MTH 07-Jun-2006		O/C			
323009	LANDING GEAR CONTROL 9912550-1	ESGP		049801-001 H7930	MTH 31-Mar-2011 HRS 1314.3 LDG 1175		O/C			
323010	OLEO ASSEMBLY LEFT MAIN LANDING GEAR			6641615-6 373	MTH 02-Oct-2008 HRS 777 LDG 659		38000	630	38029	34917
323010	OLEO ASSEMBLY RIGHT MAIN LANDING GEAR	*CF		6641615-6 374	MTH 07-Jun-2006 LDG 0		38000	0	38000	34888
323010	VALVE-LOADING -- 9912625-4	*CF		4215-1 0144	MTH 07-Jun-2006		O/C			
323011	OLEO UPPER CAP LEFT MAIN LANDING GEAR	*CF		6641616-4 SN-UNKNOWN	MTH 07-Jun-2006 LDG 0		14900	0	14900	11788
323011	OLEO UPPER CAP RIGHT MAIN LANDING GEAR	*CF		6641616-4 SN-UNKNOWN	MTH 07-Jun-2006 LDG 0		14900	0	14900	11788
323014 323010A	LOADING VALVE 9912625-4	*CF		4215-1 N/A	MTH 07-Jun-2006		O/C			
324001	MAIN WHEEL ASSEMBLY LEFT	ESGP		3-1571-6 0533	MTH 01-Nov-2016 HRS 3329 LDG 3059 APUH 1763 APUS 3762		O/C			



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
324001 RIGHT	MAIN WHEEL ASSEMBLY 9912487-11	ESGP 3-1571-6 3476	MTH 17-Jul-2015 HRS 2962.1 LDG 2706		O/C			
324002 NOSE	WHEEL ASSEMBLY 9914069-2	ESGP 3-1418 4537	MTH 14-Mar-2016 HRS 3113.1 LDG 2859		O/C			
324003 LEFT	MAIN BRAKE ASSEMBLY 9912487-7	ESGP 2-1601-1 0622	MTH 03-Nov-2014 HRS 2697.6 LDG 2422		O/C			
324004 RIGHT	MAIN BRAKE ASSEMBLY 9912487-7	ESSB 2-1601-1 2085	MTH 20-Jul-2015 HRS 2964 LDG 2708		O/C	0	0	0
324005 LEFT	MAIN TIRE 9912488-3	ESGP M13702 5024S164	MTH 01-Nov-2016 HRS 3329 LDG 3059 APUH 1763 APUS 3762		O/C	0	0	
324005 RIGHT	MAIN TIRE 9912488-3	ESGP M13702 4247S199	MTH 17-Jul-2015 HRS 2962.1 LDG 2706		O/C	0	0	
324006	NOSE TIRE 9914070-1	ESGP 031-613-8 4337S00434	MTH 14-Mar-2016 HRS 3113.1 LDG 2859		O/C	0	0	
324009	POWER BRAKE VALVE 9912627-6	*CF 32-105-3 209	MTH 07-Jun-2006		O/C			
324010 LEFT	EXTEND/RETRACT VALVE	*CF 98120 3424	MTH 07-Jun-2006		O/C			
324010 NOSE	EXTEND/RETRACT VALVE	*CF 98120 3487	MTH 07-Jun-2006		O/C			
324010 RIGHT	EXTEND/RETRACT VALVE	*CF 98120 3428	MTH 07-Jun-2006		O/C			
324014	EMERGENCY AIR BRAKE CONTROL VALVE	*CF 65830-4 0895	MTH 07-Jun-2006		O/C			
324015 LEFT	BRAKE SHUTTLE VALVE	ESGP 211-114 1177	MTH 24-Feb-2011 HRS 1287.9 LDG 1149		O/C	0	0	
324015 RIGHT	BRAKE SHUTTLE VALVE	ESGP 211-114 1180	MTH 24-Feb-2011 HRS 1287.9 LDG 1149		O/C	0	0	
324019	BRAKE PRESS PUMP ASSEMBLY 9912166-3	*CF 640931 6405	MTH 07-Jun-2006		O/C			
324020	ANTISKID CONTROL (UY009) VALVE 9912489-4	*CF 39-837 731	MTH 07-Jun-2006		O/C			
324022	ANTISKID DIGITAL CONTROL 9912489-9	ESGP 42-985-2 385	MTH 15-Jul-2016 HRS 3240.4 LDG 2975 APUH 1687 APUS 3470		O/C			





## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
324023	POWER BRAKE ACCUMULATOR *CF	57C57652 0275T	MTH 07-Jun-2006		O/C			
324024 LEFT	WHEEL TRANSDUCER 9912305-2 *CF	40-955 SN-UNKNOWN	MTH 07-Jun-2006		O/C			
324024 RIGHT	WHEEL TRANSDUCER 9912305-2 *CF	40-955 SN-UNKNOWN	MTH 07-Jun-2006		O/C			
324025	PRESSURE (SN011) SWITCH *CF	GPP1250-52 0550763	MTH 07-Jun-2006		O/C			
324026	POWER PACK MOTOR *CF	MP50B1 3184	MTH 07-Jun-2006		O/C			
324027	ANTISKID FAULT DISPLAY 9912305-9 *CF	42-92750 1734A	MTH 07-Jun-2006		O/C			
324101	PARKING BRAKE VALVE 9912388-11 *CF	98433-2 0062	MTH 07-Jun-2006		O/C			
324153 3242153	PRESS ANTISKID BRK SWITCH *CF	GPP1250-73 0232254	MTH 07-Jun-2006		O/C			
324200 324201	ANTISKID PRESSURE GAUGE *CF	19940929-1 018923	MTH 07-Jun-2006		O/C			
324206	ANTISKID HYD RELIEF VALVE *CF	1785-2 738	MTH 07-Jun-2006		O/C			
326005 LEFT	MAIN GEAR UP & LOCKED (S3) SWITCH *CF	65-430087 SN-UNKNOWN	MTH 07-Jun-2006		O/C			
326005 RIGHT	MAIN GEAR UP & LOCKED (S3) SWITCH *CF	65-430087 SN-UNKNOWN	MTH 07-Jun-2006		O/C			
326005	NOSE GEAR UP & LOCKED (SN001) SWITCH *CF	65-430087 SN-UNKNOWN	MTH 07-Jun-2006		O/C			
326007 LEFT	MAIN GEAR DOWN & LOCK (SN011) SWITCH ESGP	1550030-1 00485	MTH 14-Mar-2016 HRS 3113.1 LDG 2859		O/C	0 0 0		
331001 CENTER	5 VDC UN004 DIMMER POWER SUPPLY *CF	273-1 205480308	MTH 07-Jun-2006		O/C			
331001 LEFT	5 VDC UN002 DIMMER POWER SUPPLY *CF	273-1 205350148	MTH 07-Jun-2006		O/C			
331001 RIGHT	5 VDC UN006 DIMMER POWER SUPPLY *CF	273-1 205500265	MTH 07-Jun-2006		O/C			
331011	EL PANEL INVERTER *CF	EM2044-1 5089A	MTH 07-Jun-2006		O/C			



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Components

Item Code	Description	City	Mod Lvl	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #			Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
332002	GLARESHIELD INVERTER	*CF		6900173 4063	MTH 07-Jun-2006		O/C			
334001	PULSE LITE CONTROL	*CF		2401C TR00695	MTH 07-Jun-2006		O/C			
334002	EMPENNAGE LIGHT ASSY	*CF		01-0790044-37 SN-UNKNOWN	MTH 07-Jun-2006		O/C			
334003	TAIL LIGHT ASSY	ESGP		01-0770966-00 01307A	MTH 18-May-2012 HRS 1716.7 LDG 1553		O/C	0	0	0
334006 LEFT	STROBE POWER SUPPLY	*CF		01-0790101-05 01365	MTH 07-Jun-2006		O/C			
334006 RIGHT	STROBE POWER SUPPLY	ENGM		01-0790101-05 02031	MTH 22-Sep-2016 HRS 3298.7 LDG 3028 APUH 1763 APUS 3762		O/C	0	0	
335001 AFT	EMERGENCY LIGHTING UC020 BATTERY PACK	ESGP		9913-1 2884	MTH 14-Mar-2016 HRS 3113.1 LDG 2859		O/C	0	0	
335001 FORWARD	EMERGENCY LIGHTING UC019 BATTERY PACK	ESGP		9913-1 2549	MTH 14-Mar-2016 HRS 3113.1 LDG 2859		O/C			
340037	MAGNETOMETER MAG-3000A	GSE		501-1826-03 1323	MTH 13-Jul-2007 HRS 392		O/C		0	
341009	SAFE FLIGHT AOA UF004 SENSOR	*CF		C-12717-1 1592	MTH 07-Jun-2006		O/C			
341011	SAFE FLIGHT AOA UC009 COMPUTER	*CF		C13006-3 1128	MTH 07-Jun-2006		O/C			
341014	SAFE FLIGHT AOA FI003 INDEXER	*CF		C12763-1 1066	MTH 07-Jun-2006		O/C			
341016 SECONDARY	ADU UF-031	*CF	1	501-1890-02 1565	MTH 07-Jun-2006		O/C			
341017	MEGGITT SECONDARY FLIGHT (EI016) DISPLAY GH-3000	*CF	15	501-1741-2103 1102	MTH 07-Jun-2006		O/C			
341101	DIFFERENTIAL PRESSURE SWITCH	*CF		D45C-24 828	MTH 07-Jun-2006		O/C			
341107 NO. 1	(PILOT) AIR DATA COMPUTER	*CF	D	7030700-71703 06010808	MTH 07-Jun-2006		O/C			
341107 NO. 2	(COPILOT) AIR DATA COMPUTER	*CF	D	7030700-71703 06010822	MTH 07-Jun-2006		O/C			
342023	RADAR CONTROLLER WC-880	*CF		7008471-407 06028688	MTH 07-Jun-2006		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Components

Item Code	Description	City	Mod Lvl	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #			Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
342050 LEFT	FLUX DETECTOR FX-220	*CF		2594484 05107341	MTH 07-Jun-2006		O/C			
342050 RIGHT	FLUX DETECTOR FX-220	*CF		2594484 05117348	MTH 07-Jun-2006		O/C			
342053	AERONETICS HSI-15 STANDBY HORIZONTAL SITUATION INDICATOR HSI-315B	*CF	4	520-3151-003 22894	MTH 07-Jun-2006		O/C			
342064 STANDBY 342064S	SECURAPLANE BATTERY	ESGP	2	100-2410-04 1038	MTH 25-Jul-2014 HRS 2545.3 LDG 2299		48	0	31-Jul-2018	17 m 29 d
342065 NO. 1	AHRS 1 BATTERY PACK PS-855	ESGP		501-1712-02 80902	MTH 20-Oct-2011 HRS 1557.4 LDG 1374		O/C			
342069	HONEYWELL PRIMUS 1000 EFIS MC800 MULTIFUNCTION DISPLAY CONTROLLER	*CF	C	7007062-987 05093161	MTH 07-Jun-2006		O/C			
342082 LEFT	LITEF LCR-93 AHRS TRAY	*CF		140691 3357	MTH 07-Jun-2006		O/C			
342082 RIGHT	LITEF LCR-93 AHRS TRAY	*CF		140691 3425	MTH 07-Jun-2006		O/C			
342083 LEFT	AHRS COMPUTER	*CF	8	142185-1100 2129	MTH 07-Jun-2006		O/C			
342083 RIGHT	AHRS COMPUTER			142185-1100 1726	MTH 12-Oct-2006 HRS 97		O/C		2172	
342104 LEFT	MSU CALIBRATION PROM UNIT	*CF		124282 5781	MTH 07-Jun-2006		O/C			
342104 RIGHT	MSU CALIBRATION PROM UNIT	*CF		124282 5783	MTH 07-Jun-2006		O/C			
342500	HONEYWELL PRIMUS 1000 EFIS RI553 REMOTE INSTRUMENT CONTROLLER RI-553	ESGP		7016954-971 04051831	MTH 10-Aug-2010 HRS 1108.4 LDG 954		O/C			
342504 COPILOT	HONEYWELL PRIMUS 1000 EFIS DC550 DISPLAY CONTROLLER	GSE		7016986-759 04074890	MTH 13-Mar-2007 HRS 231		O/C		0	
342504 PILOT	HONEYWELL PRIMUS 1000 EFIS DC550 DISPLAY CONTROLLER	ESGP	M	7016986-759 07127114	MTH 05-Oct-2015 HRS 3020.2 LDG 2760 APUH 1636.8 APUS 3428		O/C			
342505 NO.1	HONEYWELL PRIMUS 1000 EFIS IC600/IC615 INTEGRATED AVIONICS COMPUTER IC-615	ESGP		7017000-94814 04096453	MTH 05-Jan-2013 HRS 1987.1 LDG 1764		O/C			



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
342505 NO.2	HONEYWELL PRIMUS 1000 EFIS IC600/IC615 IC-615	ESGG	INTEGRATED AVIONICS COMPUTER 7017000-95814 08038414	MTH	13-Jan-2017			
			HRS 3372.5 LDG 3112 APUH 1763 APUS 3762		O/C			
342506 LEFT	AP/FD MODE SELECTOR MS-560	*CF	7018341-803 06042828	MTH	07-Jun-2006			
					O/C			
342506 RIGHT	AP/FD MODE SELECTOR MS-560	*CF	7018341-803 06022781	MTH	07-Jun-2006			
					O/C			
342507 LEFT	FMS DISPLAY CONTROLLER CD-820	*CF	2888-01-1 1616	MTH	07-Jun-2006			
					O/C			
342507 RIGHT	FMS DISPLAY CONTROLLER CD-820	*CF	2888-01-1 1085	MTH	07-Jun-2006			
					O/C			
342509 COPILOT <i>342501 : R</i>	HONEYWELL PRIMUS 1000 EFIS DU870 MULTIFUNCTION DISPLAY UNIT DU-1080/S3100-286	*CF J	7023460-05001 06012821	MTH	07-Jun-2006			
					O/C			
342509 PILOT <i>342501 : L</i>	HONEYWELL PRIMUS 1000 EFIS DU870 MULTIFUNCTION DISPLAY UNIT DU-1080/S3100-286	*CF J	7023460-05001 06012799	MTH	07-Jun-2006			
					O/C			
342510 CENTER <i>342501 : CNTR</i>	ELECTRONIC DISPLAY UNIT DU-1080/S3100-286	ESGP	7023460-05001 04121581	MTH	08-Nov-2010		0	
					HRS 1190.9 LDG 1053			
342613 <i>342501</i>	HONEYWELL PRIMUS 1000 EFIS RI552 REVERSION CONTROLLER RI-552	*CF	7016954-981 06022347	MTH	07-Jun-2006			
					O/C			
343001 NAVIGATION <i>343001A</i>	ANTENNA COUPLER	*CF	CI-120-5 5052522	MTH	07-Jun-2006			
					O/C			
343001	GLIDESLOPE ANTENNA COUPLER	*CF	CI503 115035	MTH	07-Jun-2006			
					O/C			
343002 <i>343001 : B</i>	MARKER BEACON ANTENNA COUPLER	*CF	CI509 108772	MTH	07-Jun-2006			
					O/C			
344005	RADAR TRANSCEIVER WU-880	*CF N	7021450-801 06016032	MTH	07-Jun-2006			
					O/C			
344022	RADIO ALTIMETER ALT-55B TRANSCEIVER RT-300	*CF	7001840-936 0601C528	MTH	07-Jun-2006			
					O/C			
344023 AFT	RADIO ALT RECEIVER ANTENNA	*CF	S67-2002 54333387	MTH	07-Jun-2006			
					O/C			
344023 FORWARD	RADIO ALT TRANSMITTER ANTENNA	*CF	S67-2002 54334246	MTH	07-Jun-2006			
					O/C			
344024	EGPWS COMPUTER S2800-702	*CF 9	965-0976-040-219-21 9 23381	MTH	07-Jun-2006			
					O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
345004 LEFT NO. 1	XPNDR BOTTOM ANTENNA *CF	DMNI50-2-2 104986	MTH 07-Jun-2006		O/C			
345004 RIGHT NO. 2	XPNDR BOTTOM ANTENNA *CF	DMNI50-2-2 107422	MTH 07-Jun-2006		O/C			
345005 LEFT NO. 1	TOP TRANSPONDER DIVERSITY ANTENNA 85226 *CF	DMNI50-2-2 104943	MTH 07-Jun-2006		O/C			
345005 RIGHT NO. 2	TOP TRANSPONDER DIVERSITY ANTENNA 85226 *CF	DMNI50-2-2 104992	MTH 07-Jun-2006		O/C			
345007 NO.1	DISTANCE MEASURING EQUIPMENT (DME) ANTENNA 85226 *CF	DMNI50-2-2 104950	MTH 07-Jun-2006		O/C			
345007 NO.2	DISTANCE MEASURING EQUIPMENT (DME) ANTENNA 85226 *CF	DMNI50-2-2 107428	MTH 07-Jun-2006		O/C			
345011 NO. 1	ADF RECEIVER MODULE DF-850 *CF	K 7510114-901 05077627	MTH 07-Jun-2006		O/C			
345011 NO. 2	ADF RECEIVER MODULE DF-850 *CF	K 7510114-901 0511A219	MTH 07-Jun-2006		O/C			
345014 NO. 1	ADF ANTENNA AT-860 ESGP	7510300-901 1108J634	MTH 30-Dec-2015 HRS 3090.8 LDG 2838 APUH 1636.8 APUS 3428		O/C			
345015 NO. 2 <i>345014 : 2</i>	ADF ANTENNA AT-860 ESGP	7510300-901 0907G166	MTH 11-Dec-2009 HRS 911.4 LDG 796		O/C	0 0		
345017	MARKER BEACON ANTENNA *CF	MB10-754 0278	MTH 07-Jun-2006		O/C			
345018	GLIDESLOPE ANTENNA *CF	RGS10-48 10786	MTH 07-Jun-2006		O/C			
345029 NO. 1	NAV CLUSTER MODULE XN-850 *CF	E 7510164-921 129320508	MTH 07-Jun-2006		O/C			
345029 NO. 2	NAV CLUSTER MODULE XN-850 *CF	E 7510164-921 129320687	MTH 07-Jun-2006		O/C			
345032 NO. 1	VHF NAV RECEIVER NV-850 *CF	P 7510134-731 05068739	MTH 07-Jun-2006		O/C			
345032 NO. 2	VHF NAV RECEIVER NV-850 *CF	T 7510134-731 0511A205	MTH 07-Jun-2006		O/C			
345034 NO. 1	ATC TRANSPONDER *CF	V 7517400-922 0601A483	MTH 07-Jun-2006		O/C			
345034 NO. 2	ATC TRANSPONDER *CF	V 7517400-922 0601A481	MTH 07-Jun-2006		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Components

Item Code	Description	City	Mod Lvl	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #			Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
345036 NO. 1	DME INTERROGATOR DM-850	*CF	M	7510184-902 05079203	MTH 07-Jun-2006		O/C			
345036 NO. 2	DME INTERROGATOR DM-850	*CF	M	7510184-902 0511A208	MTH 07-Jun-2006		O/C			
345038 NO. 1	INTEGRATED NAV UNIT RNZ-850	*CF	AR	7510100-731 05088231	MTH 07-Jun-2006		O/C			
345038 NO. 2	INTEGRATED NAV UNIT RNZ-850	*CF	AS	7510100-731 0512A226	MTH 07-Jun-2006		O/C			
345077	DATA TRANSFER UNIT DL-950	ESGP		G7226-01 2360	MTH 05-Jan-2013 HRS 1987.1 LDG 1764		O/C	0 0 0		
345088 NO. 1	RADIO MANAGEMENT UNIT	*CF	P	7013270-963 06015107	MTH 07-Jun-2006		O/C			
345088 NO. 2	RADIO MANAGEMENT UNIT	*CF	P	7013270-963 06025148	MTH 07-Jun-2006		O/C			
345093 NO.1	GPS ANTENNA	*CF		S67-1575-52 51217256	MTH 07-Jun-2006		O/C			
345093 NO.2	GPS ANTENNA	GSE		S67-1575-52 51221109	MTH 01-Oct-2009 HRS 846		O/C	0		
345201 LEFT	NAV ANTENNA DMN4-17/P	*CF		DMN4-17-1N 5062203	MTH 07-Jun-2006		O/C			
345201 RIGHT	NAV ANTENNA DMN4-17/P	*CF		DMN4-17-1N 5062204	MTH 07-Jun-2006		O/C			
346001	TCAS PROCESSOR RT-951 (S3100-196)	*CF	A	7517900-55003 20008079	MTH 07-Jun-2006		O/C			
346002 BOTTOM	TCAS ANTENNA AT-910	*CF		7514081-910 ANE23947	MTH 07-Jun-2006		O/C			
346002 TOP	TCAS ANTENNA AT-910	*CF		7514081-910 ANE23965	MTH 07-Jun-2006		O/C			
351001	OXYGEN PRESSURE (EI002) GAGE MD-97	*CF		C668512-0101 M05-11625	MTH 07-Jun-2006		O/C			
351004 COPILOT	OXYGEN MASK	ESGP		MC10-16-150 77021	MTH 07-Feb-2012 HRS 1633.6 LDG 1467		72	1 0 0	31-Jan-2018	11 m 29 d
351004 PILOT	OXYGEN MASK	ESGP		MC10-16-150 SE20092	MTH 07-Feb-2012 HRS 1633.6 LDG 1467		72	1 0 0	31-Jan-2018	11 m 29 d
351006	OXYGEN CYLINDER	ESGP		804882-14 ALT281-11393	MTH 20-Dec-2013 HRS 2331.6 LDG 2130		180		28-Feb-2021	48 m 26 d

Manufacture Date: 01-Feb-2006



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Components

Item Code	Description	City	Mod Lvl	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #			Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
351007	OXYGEN REGULATOR	*CF		804881-01 C06020262	MTH 07-Jun-2006		O/C	0		
351008	PASSENGER OXYGEN CONTROL VALVE 9914067-19	*CF		P21006 2373	MTH 07-Jun-2006		O/C			
352001	PASSENGER OXYGEN ALTITUDE PRESSURE SWITCH	*CF		P24032 0883	MTH 07-Jun-2006		O/C			
361010	DOOR SOLENOID VALVE	*CF		5035-00-1 0991	MTH 07-Jun-2006		O/C			
361011 LEFT	HEAT EXCHANGER ACTUATOR 9914519-4	*CF		1E50-2 1BB15	MTH 07-Jun-2006		O/C			
361011 RIGHT	HEAT EXCHANGER ACTUATOR 9914519-4	*CF		1E50-2 1BB12	MTH 07-Jun-2006		O/C			
361101 LEFT	BLEED AIR OVERTEMP (ST017) SWITCH 9914149-2	*CF		1173T181-2 4985	MTH 07-Jun-2006		O/C			
361101 RIGHT	BLEED AIR OVERTEMP (ST014) SWITCH 9914149-2	*CF		1173T181-2 4987	MTH 07-Jun-2006		O/C			
361102 LEFT	BLEED AIR MANIFOLD TEMPERATURE (TT001) SENSOR 9914519-2	*CF		1E51-1 8BA376	MTH 07-Jun-2006		O/C			
361102 RIGHT	BLEED AIR MANIFOLD TEMPERATURE (TT002) SENSOR 9914519-2	*CF		1E51-1 10BA474	MTH 07-Jun-2006		O/C			
361103 LEFT	HEAT B/A EXCHANGER 9912486-2	*CF		8230-2 S4883T1022	MTH 07-Jun-2006		O/C			
361103 RIGHT	HEAT B/A EXCHANGER 9912486-2	*CF		8230-2 S4883T1008	MTH 07-Jun-2006		O/C			
361104 LEFT	PRECOOLER VD003 VALVE 9914171-1	*CF		1406-7 0478	MTH 07-Jun-2006		O/C			
361104 RIGHT	PRECOOLER VD003 VALVE 9914171-1	*CF		1406-8 0291	MTH 07-Jun-2006		O/C			
361208 NO. 1	APU CHECK VALVE 9914171-1	*CF		8C210 5261	MTH 07-Jun-2006		O/C			
361208 NO. 2	APU CHECK VALVE 9914171-1	*CF		8C210 5301	MTH 07-Jun-2006		O/C			
361500 NO. 1	B/A CHECK VALVE 9914171-1	*CF		8C210 5220	MTH 07-Jun-2006		O/C			
361500 NO. 2	B/A CHECK VALVE 9914171-1	*CF		8C210 5113	MTH 07-Jun-2006		O/C			



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Components

Item Code	Description	City	Mod Lvl	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #			Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
361534	SERVICE AIR REGULATOR 9912510-1	*CF		1H75-18 9BA130	MTH 07-Jun-2006		O/C			
49APU1 490000	APU 9912484-1	*CF		3800722-1 P575	MTH 07-Jun-2006		E/C			
490001	APU ELECTRONIC CONTROL *CF			2119552-3 125K0015	07-Jun-2006		O/C			
490003	BLEED AIR SHUTOFF VALVE *CF			1413-7 0232	07-Jun-2006		O/C			
490004	DC AMMETER S3439-3	*CF		MD144-3 K0511473	07-Jun-2006		O/C			
490005	OVERHEAT DETECTOR 9912416-1	*CF		3001-212-1004/455-9 206131	07-Jun-2006		O/C			
490006	HOURMETER *CF			C664503-0104 SN-UNKNOWN	07-Jun-2006		O/C			
492003	COMPRESSOR ROTOR *CF			3822523-003 050350106060	07-Jun-2006 APUS 0		12000	0	12000	8238
492004	TURBINE ROTOR *CF			3842340-2 050134513096	07-Jun-2006 APUS 0		4000	0	4000	238
493000	FUEL CONTROL ASSEMBLY *CF			3883900-1 0500808	07-Jun-2006		O/C			
493001	TEE-FLOW DIVIDER VALVE *CF			3883921-2 SN-UNKNOWN	07-Jun-2006		O/C			
493002	FUEL SHUT-OFF VALVE			PN SN-UNKNOWN	07-Jun-2006		O/C	0		
494000	ELECTRICAL IGNITER LEAD *CF			3888302-20 SN-UNKNOWN	07-Jun-2006		O/C			
494001	IGNITER PLUG *CF			304634-2 SN-UNKNOWN	07-Jun-2006		O/C			
494002	IGNITION UNIT ESGP			3888000-7 060218071582	19-Sep-2014		O/C	63		
497006	RPM/MAX INDICATOR *CF			M453 24643	07-Jun-2006		O/C			
499000	LOW OIL PRESSURE SWITCH *CF			3876351-1 050922701004	07-Jun-2006		O/C			
499001	LUBE PUMP ASSEMBLY *CF			3881825-1 P888	07-Jun-2006		O/C			





## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Components

Item Code	Description	City	Mod Lvl	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #			Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
499002	OIL LEVEL SWITCH	*CF		3876318-3 SN-UNKNOWN	07-Jun-2006		O/C			
521003	ACOUSTIC LOWER FWD SEAL	*CF		9522-13 SN-UNKNOWN	MTH 07-Jun-2006		O/C			
521004	ACOUSTIC UPPER SEAL	*CF		9522-11 SN-UNKNOWN	MTH 07-Jun-2006		O/C			
521005	ACOUSTIC LOWER AFT SEAL	*CF		9522-15 SN-UNKNOWN	MTH 07-Jun-2006		O/C			
527000	EMERGENCY EXIT SWITCH	*CF		8-405-04 B60880	MTH 07-Jun-2006		O/C			
531001	TRUNNION SUPPORT ASSEMBLY	*CF		6613020-55 SN-UNKNOWN	MTH 07-Jun-2006					
LEFT NOSE LANDING GEAR					LDG 0		25500	0	25500	22388
531001	TRUNNION SUPPORT ASSEMBLY	*CF		6613020-56 SN-UNKNOWN	MTH 07-Jun-2006					
RIGHT NOSE LANDING GEAR					LDG 0		25500	0	25500	22388
531002	ACTUATOR ATTACH FITTING	*CF		6611591-9 SN-UNKNOWN	MTH 07-Jun-2006					
NOSE GEAR					LDG 0		25500	0	25500	22388
561001	MAIN WINDSHIELD	*CF		NP139721-11 06033H5965	MTH 07-Jun-2006		O/C			
LEFT	9914380-11									
561001	MAIN WINDSHIELD	ESMK		9914380-14 10287H4462	MTH 03-Feb-2012		O/C	0		
RIGHT					HRS 1633			0		
					LDG 1462			0		
561004	ELECTRICALLY HEATED COCKPIT FORWARD SIDE WINDOW	*CF		NP139722-7 05216H7908	MTH 07-Jun-2006		O/C			
LEFT	9914379-7									
561004	ELECTRICALLY HEATED COCKPIT FORWARD SIDE WINDOW	*CF		NP139722-8 04255H5874	MTH 07-Jun-2006		O/C			
RIGHT	9914379-8									
561005	OPENABLE COCKPIT AFT SIDE WINDOW	*CF		NP139703-3 1587	MTH 07-Jun-2006		O/C			
LEFT	9914116-33									
561005	OPENABLE COCKPIT AFT SIDE WINDOW	*CF		NP139703-4 1258	MTH 07-Jun-2006		O/C			
RIGHT	9914116-34									
562001	CABIN WINDOW	*CF		167400-03 SN-UNKNOWN	MTH 07-Jun-2006		O/C			
LEFT NO. 2	9914159-12									
562001	CABIN WINDOW	*CF		167400-03 SN-UNKNOWN	MTH 07-Jun-2006		O/C			
LEFT NO. 3	9914159-12									
562001	CABIN WINDOW	*CF		167400-03 SN-UNKNOWN	MTH 07-Jun-2006		O/C			
LEFT NO. 4	9914159-12									
562001	CABIN WINDOW	*CF		167400-03 SN-UNKNOWN	MTH 07-Jun-2006		O/C			
LEFT NO. 5	9914159-12									



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Components

Item Code	Description	City	Mod Lvl	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #			Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
562001 LEFT NO. 6	CABIN WINDOW 9914159-12	*CF		167400-03 SN-UNKNOWN	MTH 07-Jun-2006		O/C			
562001 RIGHT NO. 1	EMERGENCY DOOR WINDOW 9914159-12	*CF		167400-03 SN-UNKNOWN	MTH 07-Jun-2006		O/C			
562001 RIGHT NO. 2	CABIN WINDOW 9914159-12	*CF		167400-03 SN-UNKNOWN	MTH 07-Jun-2006		O/C			
562001 RIGHT NO. 3	CABIN WINDOW 9914159-12	*CF		167400-03 SN-UNKNOWN	MTH 07-Jun-2006		O/C			
562001 RIGHT NO. 4	CABIN WINDOW 9914159-12	*CF		167400-03 SN-UNKNOWN	MTH 07-Jun-2006		O/C			
562001 RIGHT NO. 5	CABIN WINDOW 9914159-12	*CF		167400-03 SN-UNKNOWN	MTH 07-Jun-2006		O/C			
562001 RIGHT NO. 6	CABIN WINDOW 9914159-12	*CF		167400-03 SN-UNKNOWN	MTH 07-Jun-2006		O/C			
562001 RIGHT NO. 7	CABIN WINDOW 9914159-12	*CF		167400-03 SN-UNKNOWN	MTH 07-Jun-2006		O/C			
571001 LEFT MAIN LANDING GEAR	FORWARD TRUNNION FITTING *CF			6622123-1 SN-UNKNOWN	MTH 07-Jun-2006 LDG 0		23800	0	23800	20688
571001 RIGHT MAIN LANDING GEAR	FORWARD TRUNNION FITTING *CF			6622123-2 SN-UNKNOWN	MTH 07-Jun-2006 LDG 0		23800	0	23800	20688
571002 LEFT MAIN LANDING GEAR	AFT TRUNNION FITTING *CF			6622124-1 SN-UNKNOWN	MTH 07-Jun-2006 LDG 0		23800	0	23800	20688
571002 RIGHT MAIN LANDING GEAR	AFT TRUNNION FITTING *CF			6622124-2 SN-UNKNOWN	MTH 07-Jun-2006 LDG 0		23800	0	23800	20688
571003 LEFT MAIN LANDING GEAR	ACTUATOR FITTING ASSEMBLY *CF			6621125-5 SN-UNKNOWN	MTH 07-Jun-2006 LDG 0		23800	0	23800	20688
571003 RIGHT MAIN LANDING GEAR	ACTUATOR FITTING ASSEMBLY *CF			6621125-6 SN-UNKNOWN	MTH 07-Jun-2006 LDG 0		23800	0	23800	20688
712001 LEFT	ENGINE AFT ISOLATOR 9912480-2	*CF		LM451-SA2 LK1054	MTH 07-Jun-2006 HRS 0		10000	0	10000	6627.5
712001 RIGHT	ENGINE AFT ISOLATOR 9912480-2	*CF		LM451-SA2 LK1009	MTH 07-Jun-2006 HRS 0		10000	0	10000	6627.5
712002 LEFT BOTTOM	FORWARD ENGINE ISOLATOR 9912480-1	*CF		LM451-SA4 LK2393	MTH 07-Jun-2006 HRS 0		10000	0	10000	6627.5
712002 LEFT UPPER	FORWARD ENGINE ISOLATOR ESGG			9912480-1 LK1978	MTH 16-Dec-2016 HRS 3363.6 LDG 3098 APUH 1763 APUS 3762		10000			?

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
712002 RIGHT BOTTOM	FORWARD ENGINE ISOLATOR 9912480-1	*CF		LM451-SA4 LK2405	MTH 07-Jun-2006 HRS 0		10000	0	10000	6627.5
712002 RIGHT UPPER	FORWARD ENGINE ISOLATOR 9912480-1	*CF		LM451-SA4 LK2340	MTH 07-Jun-2006 HRS 0		10000	0	10000	6627.5
712005	ENG VIBRATION MONITOR 9912519-2	*CF		2789 010642	MTH 07-Jun-2006		O/C			
71EN1 NO. 1 <i>710001 : E1**L</i>	ENGINE	ESGG		PW545B DD0261	MTH 16-Dec-2016 HRS 3363.6 LDG 3098		E/C	3298.7		
71EN2 NO. 2 <i>710001 : E2**R</i>	ENGINE			PW545B DD0258	MTH 07-Jun-2006		E/C			
721010 E1	ACCESS GEARBOX SHAFT	*CF		30J2201-01 RWA22A695	MTH 07-Jun-2006		O/C			
721010 E2	ACCESS GEARBOX SHAFT	*CF		30J2201-01 RWA23A935	MTH 07-Jun-2006		O/C			
722001 E1	OIL PUMP ASSEMBLY	*CF		30J2705-02 EC01A000A212	MTH 07-Jun-2006		O/C			
722001 E2	OIL PUMP ASSEMBLY	*CF		30J2705-02 EC01A000A198	MTH 07-Jun-2006		O/C			
723010 E1	LP COMPRESSOR FAN ROTOR	*CF		30J2681-01 A001XLHL	MTH 07-Jun-2006 LDG 70		15000	0	(15000)15070	11958
723010 E2	LP COMPRESSOR FAN ROTOR	*CF		30J2681-01 A001X5NM	MTH 07-Jun-2006 LDG 0		15000	0	(15000)15000	11888
723020 E1	LP COMPRESSOR BOOST ROTOR	*CF		30J2210-01 TXA1A8765	MTH 07-Jun-2006 LDG 70		13500	0	(13500)13570	10458
723020 E2	LP COMPRESSOR BOOST ROTOR	*CF		30J2210-01 TXA1A8656	MTH 07-Jun-2006 LDG 0		13500	0	(13500)13500	10388
723030 E1	1ST STAGE HP COMPRESSOR ROTOR	*CF		30J2821-01 A001X5P1	MTH 07-Jun-2006 LDG 70		13500	0	(13500)13570	10458
723030 E2	1ST STAGE HP COMPRESSOR ROTOR	*CF		30J2821-01 A001WWKY	MTH 07-Jun-2006 LDG 0		13500	0	(13500)13500	10388
723040 E1	2ND STAGE HP COMPRESSOR ROTOR	*CF		30J2429-01 A001XA66	MTH 07-Jun-2006 LDG 70		13500	0	(13500)13570	10458
723040 E2	2ND STAGE HP COMPRESSOR ROTOR	*CF		30J2429-01 A001WKBR	MTH 07-Jun-2006 LDG 0		13500	0	(13500)13500	10388
723060 E1	CENTRIFUGAL IMPELLER	*CF		30J1450-01 A001X548	MTH 07-Jun-2006 LDG 70		13500	0	(13500)13570	10458



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
723060 E2	CENTRIFUGAL IMPELLER *CF	30J1450-01 A001X549	MTH 07-Jun-2006 LDG 0		13500	0	(13500)13500	10388
724001 E1 INNER	COMBUSTION CHAMBER LINER *CF	30J2590-01 A001WWW1	MTH 07-Jun-2006		O/C			
724001 E2 INNER	COMBUSTION CHAMBER LINER *CF	30J2590-01 A001WRDN	MTH 07-Jun-2006		O/C			
725010 E1	1ST-STAGE TURBINE DISK *CF	30J1551-01 A001XAEP	MTH 07-Jun-2006 LDG 70		13500	0	(13500)13570	10458
725010 E2	1ST-STAGE TURBINE DISK *CF	30J1551-01 A001WRYM	MTH 07-Jun-2006 LDG 0		13500	0	(13500)13500	10388
725020 E1	2ND-STAGE TURBINE DISK *CF	30H3152 MAA31736	MTH 07-Jun-2006 LDG 70		13500	0	(13500)13570	10458
725020 E2	2ND-STAGE TURBINE DISK *CF	30H3152 MAA31741	MTH 07-Jun-2006 LDG 0		13500	0	(13500)13500	10388
725030 E1	3RD-STAGE TURBINE DISK *CF	30H3153 MAA32063	MTH 07-Jun-2006 LDG 70		13500	0	(13500)13570	10458
725030 E2	3RD-STAGE TURBINE DISK *CF	30H3153 MAA32027	MTH 07-Jun-2006 LDG 0		13500	0	(13500)13500	10388
725040 E1	4TH-STAGE TURBINE DISK *CF	30H3154 MAA32372	MTH 07-Jun-2006 LDG 70		13500	0	(13500)13570	10458
725040 E2	4TH-STAGE TURBINE DISK *CF	30H3154 MAA32317	MTH 07-Jun-2006 LDG 0		13500	0	(13500)13500	10388
733001 LEFT	FUEL FLOW TRANSMITTER 9914413-1 *CF	9-231-28 L9312	MTH 07-Jun-2006		O/C			
733001 RIGHT	FUEL FLOW TRANSMITTER 9914413-1 *CF	9-231-28 L9308	MTH 07-Jun-2006		O/C			
733004 LEFT	FUEL PRESSURE SWITCH 9914112-3 *CF	6057-3 2205	MTH 07-Jun-2006		O/C			
733004 RIGHT	FUEL PRESSURE SWITCH 9914112-3 *CF	6057-3 2207	MTH 07-Jun-2006		O/C			
731002 E1	FLOW DIVIDER VALVE 30J2887-01 *CF	1006479-1 F64006	MTH 07-Jun-2006		O/C			
731002 E2	FLOW DIVIDER VALVE 30J2887-01 *CF	1006479-1 F63964	MTH 07-Jun-2006		O/C			
731120 E1	EMERGENCY FUEL SHUTOFF VALVE	PN SN-UNKNOWN	MTH 07-Jun-2006		O/C	0		



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
731120 E2	EMERGENCY FUEL SHUTOFF VALVE	PN SN-UNKNOWN	MTH 07-Jun-2006		O/C	0		
732001 E1	HYDROMECHANICAL FUEL CONTROL	ESGP 1012636-17 F63887	MTH 05-Jan-2013 HRS 2052 LDG 1834		O/C	0		
732001 E2	HYDROMECHANICAL FUEL CONTROL	ESGP 1012636-18 F63969	MTH 05-Jan-2013 HRS 1987.1 LDG 1764		O/C	0		
741001 E1	IGNITION EXCITER	ESGP 31J2807-07 500335-1 NNA12390073	MTH 17-Mar-2015 HRS 2870.2 LDG 2619		O/C	0		
741001 E2	IGNITION EXCITER	ESGP 31J2807-07 500335-1 NNA05152891	MTH 16-Oct-2015 HRS 3032.8 LDG 2778		O/C			
742001 E1 INBOARD	IGNITOR	ESGP 30J2825-01 502600-1 NNA11300167	MTH 21-Feb-2014 HRS 2450.4 LDG 2225		O/C	0		
742001 E1 OUTBOARD	IGNITOR	ESGP 30J2825-01 502600-1 NNA15420291	MTH 14-Mar-2016 HRS 3178 LDG 2929		O/C	0		
742001 E2 INBOARD	IGNITOR	ESGP 30J2825-01 502600-1 NNA15420330	MTH 14-Mar-2016 HRS 3113.1 LDG 2859		O/C	0		
742001 E2 OUTBOARD	IGNITOR	ESGP 30J2825-01 502600-1 NNA15420334	MTH 14-Mar-2016 HRS 3113.1 LDG 2859		O/C	0		
742002 E1	SHORT IGNITOR LEAD	GSE 30J3125-01 508122-1 NSN	MTH 01-Oct-2009 HRS 910.9		O/C		0	
742002 E2	SHORT IGNITOR LEAD	GSE 30J3125-01 508122-1 NSN	MTH 01-Oct-2009 HRS 846		O/C		0	
742003 E1	LONG IGNITOR LEAD	GSE 30J3125-02 508122-2 NSN	MTH 01-Oct-2009 HRS 910.9		O/C		0	
742003 E2	LONG IGNITOR LEAD	GSE 30J3125-02 508122-2 NSN	MTH 01-Oct-2009 HRS 846		O/C		0	
751003 E1	COMPRESSOR BLEED VALVE ASSY	*CF 30J2596-01 AHX004832	MTH 07-Jun-2006		O/C			
751003 E2	COMPRESSOR BLEED VALVE ASSY	*CF 30J2596-01 AHX005036	MTH 07-Jun-2006		O/C			
751004 E1	INTERCOMPRESSOR BLEED VALVE SERVO VALVE	ESGP 30J3490-01 TR6111	MTH 05-Jan-2013 HRS 2052 LDG 1834		O/C	0		
751004 E2	INTERCOMPRESSOR BLEED VALVE SERVO VALVE	ESGP 30J3490-01 TR5249	MTH 22-Jun-2011 HRS 1419.3 LDG 1262		O/C	0		
751005 E1	LINEAR TRANSDUCER	*CF 31J2071-01 2171	MTH 07-Jun-2006		O/C			



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
751005 E2	LINEAR TRANSDUCER	*CF		31J2071-01 2173	MTH 07-Jun-2006		O/C			
761001 LEFT	THROTTLE DETENT VALVE	*CF		5303-2A 2781	MTH 07-Jun-2006		O/C			
761001 RIGHT	THROTTLE DETENT VALVE	*CF		5303-2A 2782	MTH 07-Jun-2006		O/C			
761001 E1	ELECTRONIC ENGINE CONTROL 30J2659-02	*CF		1004855-1-002 05087851	MTH 07-Jun-2006		O/C			
761001 E2	ELECTRONIC ENGINE CONTROL 30J2659-02	*CF		1004855-1-002 05087898	MTH 07-Jun-2006		O/C			
771006	ENGINE (AMLCD) INDICATOR 9912574-5	*CF		10644D02M05 06010576A	MTH 07-Jun-2006		O/C			
771004 E1	SPEED N1 SENSOR	*CF		31J2072-01 CH1387	MTH 07-Jun-2006		O/C			
771004 E2	SPEED N1 SENSOR	*CF		31J2072-01 CH1392	MTH 07-Jun-2006		O/C			
771005 E1	SPEED N2 SENSOR	*CF		31J2073-01 CH2262	MTH 07-Jun-2006		O/C			
771005 E2	SPEED N2 SENSOR	*CF		31J2073-01 CH2269	MTH 07-Jun-2006		O/C			
772001 E1	TEMPERATURE SENSOR	*CF		31J2113-03 RTK4149	MTH 07-Jun-2006		O/C			
772001 E2	TEMPERATURE SENSOR	*CF		31J2113-03 RTK4203	MTH 07-Jun-2006		O/C			
774001 E2	DATA COLLECTION UNIT 30J2673-02	ESGP		32205-03 DP06-4429	MTH 20-Jul-2012 HRS 1794.1 LDG 1617		O/C			
783001 LEFT ENGINE <i>783001X: E1**L</i>	THRUST REVERSER ASSEMBLY 9912609-13	*CF		64ND-78002-5 1001	MTH 07-Jun-2006		O/C			
783001 RIGHT ENGINE <i>783001X: E2**R</i>	THRUST REVERSER ASSEMBLY 9912609-14	*CF		64ND-78002-6 1002	MTH 07-Jun-2006		O/C			
783002 LEFT	THRUST REVERSER VALVE	*CF		4221 0277	MTH 07-Jun-2006		O/C			
783002 RIGHT	THRUST REVERSER VALVE	*CF		4221 0288	MTH 07-Jun-2006		O/C			
783010 LEFT INBOARD	THRUST REVERSER ACTUATOR	*CF		64ND-78204-7 SN-UNKNOWN	MTH 07-Jun-2006		O/C			



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
783010 LEFT OUTBOARD	THRUST REVERSER ACTUATOR *CF	64ND-78204-7 SN-UNKNOWN	MTH 07-Jun-2006		O/C			
783010 RIGHT INBOARD	THRUST REVERSER ACTUATOR *CF	64ND-78204-7 SN-UNKNOWN	MTH 07-Jun-2006		O/C			
783010 RIGHT OUTBOARD	THRUST REVERSER ACTUATOR *CF	64ND-78204-7 SN-UNKNOWN	MTH 07-Jun-2006		O/C			
783100 LEFT	THRUST REVERSER MANIFOLD ASSEMBLY *CF	8245 0276	MTH 07-Jun-2006		O/C			
783100 RIGHT	THRUST REVERSER MANIFOLD ASSEMBLY *CF	8245 0277	MTH 07-Jun-2006		O/C			
783101 LEFT	ARM PRESSURE SWITCH *CF	80637-1 0445	MTH 07-Jun-2006		O/C			
783101 RIGHT	ARM PRESSURE SWITCH *CF	80637-1 0442	MTH 07-Jun-2006		O/C			
783102 LEFT	THRUST REVERSER ISOLATION VALVE *CF	4222 0277M	MTH 07-Jun-2006		O/C			
783102 RIGHT	THRUST REVERSER ISOLATION VALVE *CF	4222 0278M	MTH 07-Jun-2006		O/C			
783103 LEFT INBOARD	STOW LIMIT SWITCH *CF	53ND78304-1 SN-UNKNOWN	MTH 07-Jun-2006		O/C			
783103 LEFT OUTBOARD	STOW LIMIT SWITCH *CF	53ND78304-1 SN-UNKNOWN	MTH 07-Jun-2006		O/C			
783103 RIGHT INBOARD	STOW LIMIT SWITCH *CF	53ND78304-1 SN-UNKNOWN	MTH 07-Jun-2006		O/C			
783103 RIGHT OUTBOARD	STOW LIMIT SWITCH *CF	53ND78304-1 SN-UNKNOWN	MTH 07-Jun-2006		O/C			
783104 LEFT	DEPLOY LIMIT SWITCH *CF	53ND78304-5 SN-UNKNOWN	MTH 07-Jun-2006		O/C			
783104 RIGHT	DEPLOY LIMIT SWITCH *CF	53ND78304-5 SN-UNKNOWN	MTH 07-Jun-2006		O/C			
793002 LEFT	OIL TEMP XMTR SENSOR *CF	102-00083 05295	MTH 07-Jun-2006		O/C			
793002 RIGHT	OIL TEMP XMTR SENSOR *CF	102-00083 05302	MTH 07-Jun-2006		O/C			
793102 LEFT	ENGINE OIL TRANSMITTER 9912464-1 *CF	APTE-237E-1000-25 0D 71684394	MTH 07-Jun-2006		O/C			



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Components

Item Code	Description	City	Mod Lvl	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #			Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
793102 RIGHT	ENGINE OIL TRANSMITTER 9912464-1	*CF		APTE-237E-1000-25 0D 7168789	MTH 07-Jun-2006		O/C			
793117 LEFT	OIL PRESSURE SWITCH 9912466-2	*CF		1153P0098-01 1599	MTH 07-Jun-2006		O/C			
793117 RIGHT	OIL PRESSURE SWITCH 9912466-2	*CF		1153P0098-01 1597	MTH 07-Jun-2006		O/C			
793003 E1	FUEL OIL HEAT EXCHANGER D2552-600B	*CF		31J2955-02 M161744	MTH 07-Jun-2006		O/C			
793003 E2	FUEL OIL HEAT EXCHANGER D2552-600B	*CF		31J2955-02 M161745	MTH 07-Jun-2006		O/C			
801000 LEFT ENGINE	STARTER/GENERATOR 9912499-6	ENGM	M-1	300SGL138Q-4 1759XL	MTH 22-Sep-2016 HRS 3298.7 LDG 3028 APUH 1763 APUS 3762		1000	0	4298.7	926.2
801000 RIGHT ENGINE	STARTER/GENERATOR 9912499-6	ESGP	M-1	300SGL138Q-4 5314XL	MTH 24-Aug-2015 HRS 2964.8 LDG 2709		1000	0	3964.8	592.3
801100 APU	STARTER/GENERATOR 9912499-31	ESGP	6	300SGL138Q-6 3203XL	MTH 09-Sep-2013 HRS 2237.1 LDG 2009 APUH 1323.8		1000	0	2323.8	560.8





# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-03-01	CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (STC)			INFORMATIONAL			-			
	<b>MOC :</b>									
SL CIL-99-04	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			INFORMATIONAL			-			
	<b>MOC :</b>									
SL 560XL-03-01 R1	SUPPLEMENTAL TYPE CERTIFICATE (THIS SL IS REPLACED BY CIL-03-01, DATED JUNE 3, 2013)			INFORMATIONAL			-			
	<b>MOC :</b>									
SL 560XL-99-01 R4	CESCOM PRICES			INFORMATIONAL			-			
	<b>MOC :</b>									
SL 560XL-99-03 R1	TRANSMITTAL OF CESSNA'S CERTIFICATION REQUIREMENTS FOR PORTABLE ELECTRONIC DEVICE USAGE			INFORMATIONAL			-			
	<b>MOC :</b>									
SL 560XL-99-04	CESSNA PART NUMBER SUFFIXES FOR REMANUFACTURED PARTS			INFORMATIONAL			A/R			
	<b>MOC :</b>									
SL 560XL-99-05	CESSNA SERVICE DOCUMENT CHANGE NOTIFICATION			INFORMATIONAL			A/R			
	<b>MOC :</b>									
SB 560XL-05-01 05SB-01 : XL	CONVERSION FROM CALENDAR SCHEDULE MAINTENANCE PROGRAM TO MSG-3 SCHEDULE MAINTENANCE PROGRAM			OPTIONAL	MTH		A/R			
	<b>MOC :</b>									
SL CIL-99-01 R1	USE OF CORROSION INHIBITING COMPOUNDS ESGP			INFORMATIONAL	MTH 25-Jul-2014 HRS 2545.3 LDG 2299		-			Complete
	<b>MOC :</b> COMPLIED WITH - COR-BAN TREATMENT OF LANDING GEAR WHEEL WELLS AND FLAP COVE AREA INCL. AFT SPAR									
SL CIL-99-01 R2	USE OF CORROSION INHIBITING COMPOUNDS			INFORMATIONAL			-			
	<b>MOC :</b>									
SL CIL-99-01	USE OF CORROSION INHIBITING COMPOUNDS			INFORMATIONAL			-			
	<b>MOC :</b>									
SL CIL-99-02	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			RECOMMENDED	MTH		-			
	<b>MOC :</b>									
SL CIL-20-01 R2	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			-			
	<b>MOC :</b>									



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-20-01	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			-			
	<b>MOC :</b>									
SL CIL-99-03 R1	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			RECOMMENDED			-			
	<b>MOC :</b>									
SL CIL-99-03	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			RECOMMENDED MTH			-			
	<b>MOC :</b>									
SL 560XL-20-01 R10	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			A/R			
	<b>MOC :</b>									
SB 560XL-21-22 R1	CABIN TEMPERATURE SENSOR RELOCATION			DISCRETIONARY			-			
	<b>MOC :</b>									
SB 560XL-21-22 21SB-22 : XL	CABIN TEMPERATURE SENSOR RELOCATION			DISCRETIONARY	MTH		A/R			
	<b>MOC :</b>									
SL CIL-21-03	AIR CONDITIONING - TRANSMITTAL OF HONEYWELL SB 2341316-21-2828, INSPECTION AND REPAIR OF THE INTERIOR SURFACES OF THE WATER SEPARATOR, PN 2341316-2 AND -3, FOR CORROSION			INFORMATIONAL			-			
	<b>MOC :</b>									
SL 560XL-21-11 21SL-11 : XL	AIR CYCLE MACHINE ASPIRATOR TUBING AND CLAMP INSPECTION			DISCRETIONARY	MTH		A/R			
	<b>MOC :</b>									
SB 560XL-24-02 R1 24SB-02 : XLR1	CONCORDE BATTERY INSTALLATION			OPTIONAL	MTH		-			
	<b>MOC :</b>									
SB 560XL-24-13 24SB-13 : XL	JC003/PC003 ELECTRICAL WIRE LOCATION CHANGE			RECOMMENDED	MTH 28-Mar-2008 HRS 621		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 560XL-24-14 R2 24SB-14 : XLR2	APU STARTER/GENERATOR WIRING IMPROVEMENT			RECOMMENDED	MTH 23-May-2011 HRS 1370 LDG 1222		300			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 560XL-24-15 24SB-15 : XL	TAILCONE/STINGER ELECTRICAL CONNECTOR IMPROVEMENT			DISCRETIONARY	MTH		A/R			
	<b>MOC :</b>									
SB 560XL-24-17	TAILCONE INVERTER RELOCATION			DISCRETIONARY			A/R			
	<b>MOC :</b>									
SL 560XL-24-04 24SL-04 : XL	STINGER WIRE BUNDLE INSPECTION			MANDATORY	MTH 13-Jul-2007 HRS 392		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 560XL-24-07	ELECTRICAL POWER - RIGHT AC GENERATOR WIRE ROUTING VERIFICATION			MANDATORY	DAYS HRS		180 25		12-Jul-2017 3397.5	New Req
<b>MOC :</b>										
SB 560XL-25-11 R1 25SB-11 : XLR1	ARTEX C406-2 THREE-FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT)	*CF		OPTIONAL	MTH		-			
<b>MOC :</b>										
SB 560XL-25-12 R1 25SB-12 : XLR1	GLARESHIELD LEATHER STRIP INSTALLATION	*CF		OPTIONAL	MTH		-			
<b>MOC :</b>										
SL 560XL-25-05 25SL-05 : XL	CABIN SYSTEMS AIRSHOW 400 DIGITAL INTERFACE UNIT (DIU) 920040 SERVICE BULLETIN 920040-44-01 SAVE MAIN CPU CMOS SETUP SETTINGS TO FLASH MEMORY			OPTIONAL	MTH		A/R			
<b>MOC :</b>										
SL 560XL-25-11 25SL-11 : XL	TRANSMITTAL OF ROCKWELL COLLINS SERVICE BULLETIN 9200XX-44-4 AIRSHOW 400 DIGITAL INTERFACE UNIT (DIU) AND AIRSHOW GENESYS DATA COMMUNICATION UNIT (DCU)			DISCRETIONARY	MTH		A/R			
<b>MOC :</b>										
SL 560XL-25-13	TRANSMITTAL OF ROCKWELL COLLINS AIRSHOW 4000 SERVICEBULLETIN 30, CORRECTION OF HARD DRIVE MOUNTING SCREWS - MOD U	GSE		RECOMMENDED	MTH 07-Jun-2011 HRS 1387 LDG 1237		-			N/A
<b>MOC : NOT APPLICABLE - N/A TO 560XL 5624 . EQUIPMENT NOT INSTALLED</b>										
SL 560XL-25-17	TRANSMITTAL OF GOODRICH SERVICE BULLETIN 1423-25-003 REVISION C LUMBAR ASSEMBLY CABLE WEAR	ESGP		RECOMMENDED	MTH 17-Mar-2015 HRS 2805.3 LDG 2549		-			Complete
<b>MOC : COMPLIED WITH - PERFORMED OK ON BOTH COCKPIT SEATS</b>										
ASL 560XL-26-01 R2 26ASL-01 : XLR2	TRANSMITTAL OF MEGGITT SAFETY SYSTEMS SERVICE BULLETIN 26-36 THERMISTORS DETECTORS	GSE		MANDATORY	MTH 13-Jul-2007 HRS 392		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SL CIL-26-01 R1	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING			MANDATORY	MTH HRS		36 1200		10-May-2019 4382.8	27 m 8 d 1010.3
<b>MOC :</b>										
SL CIL-26-01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING			MANDATORY	MTH		-			
<b>MOC :</b>										
SB 560XL-27-28 27SB-28 : XL	RUDDER PEDAL POSITION ADJUSTMENT MODIFICATION			DISCRETIONARY	MTH		A/R			
<b>MOC :</b>										
SB 560XL-27-31 27SB-31 : XL	FLAP HANDLE AND FLAP HANDLE GUARD IMPROVEMENT			OPTIONAL	MTH		A/R			
<b>MOC :</b>										



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB 560XL-27-32	FLIGHT CONTROLS - RUDDER PEDAL POSITION MODIFICATION							
		RECOMMENDED			A/R			N/A
	<b>MOC : NOT APPLICABLE - BY SERIAL NUMBER SUPERSEDED BY REVISION 1</b>							
SB 560XL-27-35 R1	STAINLESS STEEL HYDRAULIC TUBE REPLACEMENT							
		OPTIONAL			-			
	<b>MOC :</b>							
SB 560XL-27-35	STAINLESS STEEL HYDRAULIC TUBE REPLACEMENT							
		OPTIONAL			-			
	<b>MOC :</b>							
SL 560XL-27-14	HORIZONTAL AND VERTICAL STABILIZER EROSION BOOT INSTALLATION							
27SL-14 : XL		*CF OPTIONAL			-			
	<b>MOC :</b>							
SL 560XL-27-17	ELEVATOR TRIM WHEEL INSPECTION		MTH 01-Oct-2009		A/R			Complete
27SL-17 : XL		GSE RECOMMENDED	HRS 846					
	<b>MOC : COMPLIED WITH</b>							
SL 560XL-27-18	ELEVATOR TRIM CABLE REPLACEMENT INTERVALS							
		INFORMATIONAL			-			
	<b>MOC :</b>							
SL 560XL-27-20 R1	RUDDER TORQUE TUBE/SECTOR ASSEMBLY GAP INSPECTION		MTH					
		MANDATORY			-			
	<b>MOC :</b>							
SL 560XL-27-20 R2	RUDDER TORQUE TUBE/SECTOR ASSEMBLY GAP INSPECTION		MTH 21-Feb-2014					Complete
		ESGP MANDATORY	HRS 2385.5		-			
			LDG 2155					
	<b>MOC : COMPLIED WITH - PERFORMED OK. NO FINDINGS</b>							
SL 560XL-27-20	RUDDER TORQUE TUBE/SECTOR ASSEMBLY GAP INSPECTION		MTH					
		MANDATORY			-			
	<b>MOC :</b>							
SL 560XL-27-21	FLIGHT CONTROLS - RUDDER TORQUE TUBE/SECTOR ASSEMBLY INSPECTION		MTH 21-Feb-2014					N/A
		ESGP MANDATORY	HRS 2385.5		-			
			LDG 2155					
	<b>MOC : NOT APPLICABLE - DUE TO ALREADY IN COMPLIANCE WITH SL 560XL-27-20 R2</b>							
SL 560XL-27-33	ELEVATOR CABLE INSPECTION AT THE AFT CANTED BULKHEAD		MTH 14-Mar-2016					Complete
		ESGP MANDATORY	HRS 3113.1		-			
			LDG 2859					
	<b>MOC : COMPLIED WITH - PERFORMED OK</b>							
SL 560XL-27-34 R1	RIGHT OUTBOARD AILERON WING UP CABLE ASSEMBLY INSPECTION		MTH 14-Mar-2016					Complete
		ESGP MANDATORY	HRS 3113.1		-			
			LDG 2859					
	<b>MOC : COMPLIED WITH - PERFORMED OK</b>							
SL 560XL-27-34	RIGHT OUTBOARD AILERON WING UP CABLE ASSEMBLY INSPECTION		MTH					
		MANDATORY			-			
	<b>MOC :</b>							



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 560XL-27-35	FLIGHT CONTROLS - AFT AILERON SECTOR ASSEMBLY INSPECTION	ESGP		MANDATORY	MTH HRS 3113.1 LDG 2859		-			Complete
	<b>MOC : COMPLIED WITH - PERFORMED OK</b>									
SL 560XL-29-03 29SL-03 : XL	ENGINE HYDRAULIC HOSE INSPECTION	GSE		RECOMMENDED	MTH 01-Oct-2009 HRS 846		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SL 560XL-29-04	HYDRAULIC MANIFOLD CONTROL VALVE WIRE BUNDLE INSPECTION	ESGP		RECOMMENDED	MTH 17-Mar-2015 HRS 2805.3 LDG 2549		-			Complete
	<b>MOC : COMPLIED WITH - PERFORMED OK</b>									
SB 560XL-30-06 30SB-06 : XL	HORIZONTAL STABILIZER DEICE SYSTEM PRESSURE SWITCH INSTALLATION IMPROVEMENT			DISCRETIONARY	MTH		A/R			
	<b>MOC :</b>									
SL CIL-30-01 R1	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES			INFORMATIONAL			-			
	<b>MOC :</b>									
SL 560XL-31-04 R1 31SL-04 : XLR1	COCKPIT SWITCH INSPECTION	GSE		MANDATORY	MTH 18-Jul-2008 HRS 748		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SL 560XL-31-05	TRANSMITTAL OF L-3 COMMUNICATIONS ALERT BULLETIN NO. CESSNA SB 001	ESGP		MANDATORY	MTH 05-Oct-2012 HRS 1940.6 LDG 1715		A/R			N/A
	<b>MOC : NOT APPLICABLE - DUE TO INSTALLED COMPONENT S/N.</b>									
SB 560XL-32-32 32SB-32 : XL	BRAKE HYDRAULIC PACK FILTER BOWL REPLACEMENT	GSE		RECOMMENDED	MTH 01-Oct-2009 HRS 846		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 560XL-32-37 32SB-37 : XL	NOSE LANDING GEAR STEERING HARDWARE REPLACEMENT			DISCRETIONARY	MTH		A/R			
	<b>MOC :</b>									
SB 560XL-32-38 R1	LANDING GEAR - REMOVE THE QUICK DISCONNECT FROM THE NOSE LANDING GEAR TORQUE LINK			OPTIONAL			A/R			
	<b>MOC :</b>									
SB 560XL-32-38 32SB-38 : XL	REMOVE THE QUICK DISCONNECT FROM THE NOSE LANDING GEAR TORQUE LINK			OPTIONAL	MTH		A/R			
	<b>MOC :</b>									
SB 560XL-32-39 32SB-39 : XL	BRAKE METERING VALVE HARDWARE REPLACEMENT	GSE		RECOMMENDED	MTH 18-Jul-2008 HRS 748		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 560XL-32-40 32SB-40 : XL	LANDING GEAR ANNUNCIATION WIRING MODIFICATION			RECOMMENDED	MTH 15-Aug-2008 HRS 759		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 560XL-32-41 R1	LANDING GEAR - TRANSMITTAL OF GOODRICH SERVICE BULLETIN 3-1571-32-7	ESGP		MANDATORY	MTH 20-Feb-2012 HRS 1641.2 LDG 1472		A/R			Complete
	<b>MOC : COMPLIED WITH - BULLETIN PERFORMED OK</b>									
SB 560XL-32-42 R1	STAINLESS STEEL HYDRAULIC TUBE REPLACEMENT			OPTIONAL			-			
	<b>MOC :</b>									
SB 560XL-32-42 R2	STAINLESS STEEL HYDRAULIC TUBE REPLACEMENT			OPTIONAL			-			
	<b>MOC :</b>									
SB 560XL-32-42	STAINLESS STEEL HYDRAULIC TUBE REPLACEMENT			OPTIONAL			-			
	<b>MOC :</b>									
SL CIL-32-01	LANDING GEAR - IMPROVED NOSE WHEEL GREASE SEAL			INFORMATIONAL			-			
	<b>MOC :</b>									
SL CIL-32-04	WIRELESS TIRE PRESSURE MONITORING SYSTEM INSTALLATION			INFORMATIONAL			-			
	<b>MOC :</b>									
SL 560XL-32-15 32SL-15 : XL	TRANSMITTAL OF GOODRICH SERVICE BULLETIN 3-1571-32-1			OPTIONAL	MTH		A/R			
	<b>MOC :</b>									
SL 560XL-32-16 32SL-16 : XL	TRANSMITTAL OF GOODRICH SERVICE BULLETIN 2-1601-32-4, LANDING GEAR - BRAKE ASSEMBLY - P/N 2-1601-1, INTRODUCTION OF NEW O-RING			DISCRETIONARY	MTH		A/R			
	<b>MOC :</b>									
SL 560XL-32-18 32SL-18 : XL	TRANSMITTAL OF GOODRICH SERVICE BULLETINS 3-1571-32-2 AND 3-1571-32-3			RECOMMENDED	MTH 02-Oct-2008 HRS 777 LDG 659		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SL 560XL-32-19 R1 32SL-19 : XLR1	TRANSMITTAL OF GOODRICH SERVICE BULLETIN 3-1571-32-4 INTRODUCTION OF IMPROVED THERMAL RELIEF PLUG ASSEMBLY			DISCRETIONARY	MTH		A/R			
	<b>MOC :</b>									
SL 560XL-32-20 32SL-20 : XL	TRANSMITTAL OF GOODRICH SERVICE LETTER 2056			RECOMMENDED	MTH 02-Oct-2008 HRS 777 LDG 659		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SL 560XL-32-22 32SL-22 : XL	LANDING GEAR COMPONENT PLACARD INSTALLATION			OPTIONAL	MTH		A/R			
	<b>MOC :</b>									
SL 560XL-32-23 32SL-23 : XL	EMERGENCY GEAR RELEASE INSPECTION	ESGP		RECOMMENDED	MTH 07-May-2010 HRS 1008.7 LDG 891		150			Complete
	<b>MOC : COMPLIED WITH</b>									



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 560XL-32-24 R1	TRANSMITTAL OF CURTISS WRIGHT SB 049801-32-01, LANDING GEAR CONTROL ALTERNATE LED LIGHTING BULB									
	CANCELLED									
	<b>MOC :</b>									
SL 560XL-32-26	REPLACEMENT OF THE COTTER PIN FOR THE EMERGENCY GEAR-RELEASE	ESGP		MANDATORY	MTH 04-Aug-2011 HRS 1479 LDG 1299		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SL 560XL-32-27 R1	HYDRAULIC LOADING VALVE WIRE BUNDLE INSPECTION			MANDATORY	DAYS		-			
	<b>MOC :</b>									
SL 560XL-32-27	HYDRAULIC LOADING VALVE WIRE BUNDLE INSPECTION	ESGP		MANDATORY	DAYS 31-Oct-2014 HRS 2686.9 LDG 2416		-			Complete
	<b>MOC : COMPLIED WITH - PERFORMED OK</b>									
SB 560XL-33-13 R1 33SB-13 : XLR1	AFT EMERGENCY BATTERY INSTALLATION IMPROVEMENT	GSE		RECOMMENDED	MTH 21-May-2009 HRS 812		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 560XL-33-14 33SB-14 : XL	BAGGAGE COMPARTMENT LIGHT ASSEMBLY REPLACEMENT	GSE		MANDATORY	MTH 16-Dec-2008 HRS 802		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 560XL-33-15 33SB-15 : XL	WING TIP NAVIGATION AND ANTI-COLLISION LED LIGHT INSTALLATION			OPTIONAL	MTH		A/R			
	<b>MOC :</b>									
SB 560XL-33-16 33SB-16 : XL	GROUND RECOGNITION LIGHT LED UPGRADE			OPTIONAL	MTH		A/R			
	<b>MOC :</b>									
SB 560XL-34-32 R2	NAVIGATION - CATEGORY II OPERATIONS	GOT		OPTIONAL	MTH 04-Jan-2017 HRS 3363.6 LDG 3098 APUH 1763 APUS 3762		-			Complete
	<b>MOC : COMPLIED WITH - COMPLIED WITH DURING MANUFACTURE REF 560XLS-5624 DRAWING 8685624</b>									
SB 560XL-34-37 34SB-37 : XL	ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS) STEEP APPROACH SWITCH INSTALLATION	*CF		OPTIONAL	MTH		-			
	<b>MOC :</b>									
SB 560XL-34-40 R1 34SB-40 : XLR1	NAVIGATION - ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS) RUNWAY AWARENESS ADVISORY SYSTEM (RAAS) UPGRADE	*CF		OPTIONAL	MTH		A/R			
	<b>MOC :</b>									
SB 560XL-34-41 R2 34SB-41 : XLR2	HONEYWELL TRANSPONDER UPGRADE FOR ELEMENTARY SURVEILLANCE	*CF		OPTIONAL	MTH		A/R			
	<b>MOC :</b>									
SB 560XL-34-43 R1 34SB-43 : XLR1	UNIVERSAL AVIONICS PERFORMANCE DATABASE UPGRADE	*CF		OPTIONAL	MTH		A/R			
	<b>MOC :</b>									



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 560XL-34-44 R2 34SB-44 : XLR2	NAVIGATION - HONEYWELL MODE S TRANSPONDER UPGRADE FOR ENHANCED SURVEILLANCE	*CF		OPTIONAL	MTH		A/R			
<b>MOC :</b> - SERVICE BULLETIN ON HOLD.										
SB 560XL-34-44 R3	NAVIGATION - HONEYWELL MODE S TRANSPONDER UPGRADE FOR ENHANCED SURVEILLANCE			OPTIONAL			A/R			
<b>MOC :</b>										
SB 560XL-34-45 R1 34SB-45 : XLR1	ENHANCED VISION SYSTEMS (EVS) INSTALLATION	*CF		OPTIONAL	MTH		A/R			
<b>MOC :</b>										
SB 560XL-34-49 R1 34SB-49 : XLR1	RUNWAY AWARENESS ADVISORY SYSTEM (RAAS) AUDIO INHIBIT SWITCH INSTALLATION			OPTIONAL			A/R			
<b>MOC :</b>										
SB 560XL-34-55 R1 34SB-55 : XLR1	GH-3000 MAGNETOMETER CIRCUIT BREAKER INSTALLATION			OPTIONAL	MTH		A/R			
<b>MOC :</b>										
SB 560XL-34-56 R1 34SB-56 : XLR1	UNIVERSAL UNS1-ESP AND UNS1-CSP+ UPGRADE TO SOFTWARE CONTROL NUMBER (SCN) 803.0			OPTIONAL	MTH		A/R			
<b>MOC :</b>										
SB 560XL-34-59 R1 34SB-59 : XLR1	IC-615 FLIGHT DIRECTOR IMPROVEMENTS	GSE		DISCRETIONARY	MTH 01-Oct-2009 HRS 846		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SB 560XL-34-60	UNIVERSAL UNS-1ESPW FMS WIDE AREA AUGMENTATION SYSTEM (WAAS) UPGRADE			OPTIONAL			-			
<b>MOC :</b>										
SB 560XL-34-61 34SB-61 : XL	STANDBY COMPASS INSTALLATION			OPTIONAL	MTH		A/R			
<b>MOC :</b>										
SB 560XL-34-62 34SB-62 : XL	STANDBY GYRO BATTERY WIRING MODIFICATION	ESGP		RECOMMENDED	MTH 22-Nov-2010 HRS 1202.2		300			Complete
<b>MOC :</b> COMPLIED WITH - SERVICE BULLETIN PERFORMED OK										
SB 560XL-34-66 R1	INSTALLATION OF SCN 802.8 FOR UNS-1 FMS	ESGP		RECOMMENDED	MTH 05-Oct-2012 HRS 1940.6 LDG 1715		-			N/A
<b>MOC :</b> NOT APPLICABLE - DUE TO EQUIPMENT NOT INSTALLED										
SB 560XL-34-66	INSTALLATION OF SCN 802.8 FOR UNS-1 FMS			RECOMMENDED			-			
<b>MOC :</b>										
SB 560XL-34-70	UNIVERSAL SOLID STATE DATA TRANSFER UNIT (SSDTU) UPGRADE			OPTIONAL			A/R			
<b>MOC :</b>										





# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB 560XL-34-71 R1	TCAS 2000 INTERFERENCE LIMITING FUNCTIONALITY UPGRADE FOR SOFTWARE VERSION 7.0	MANDATORY	MTH 17-Mar-2015 HRS 2805.3 LDG 2549	-	-	-	-	Complete
	<b>MOC : COMPLIED WITH</b>							
SB 560XL-34-72 R1	TCAS 2000 UPDATE SOFTWARE TO VERSION 7.1	OPTIONAL	MTH 17-Mar-2015 HRS 2805.3 LDG 2549	-	-	-	-	Complete
	<b>MOC : COMPLIED WITH</b>							
SB 560XL-34-75 R1	NAVIGATION - HONEYWELL TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM II (TCAS II) VERSION 7.1 SOFTWARE UPDATE	OPTIONAL		-	-	-	-	
	<b>MOC :</b>							
SB 560XL-34-75	NAVIGATION - HONEYWELL TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM II (TCAS II) VERSION 7.1 SOFTWARE UPDATE	OPTIONAL		-	-	-	-	
	<b>MOC :</b>							
SB 560XL-34-77 R1	NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION	OPTIONAL		-	-	-	-	
	<b>MOC :</b>							
SB 560XL-34-77 R2	NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION	OPTIONAL		-	-	-	-	
	<b>MOC :</b>							
SB 560XL-34-77	NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION	OPTIONAL		-	-	-	-	
	<b>MOC :</b>							
SB 560XL-34-78	NAVIGATION - UNIVERSAL UNS-1ESPW FMS SOFTWARE UPGRADE 1000.8	OPTIONAL		-	-	-	-	
	<b>MOC :</b>							
ASL 560XL-34-08 34ASL08 : XL	TRANSMITTAL OF HONEYWELL TECHNICAL NEWSLETTER A23-3850-001	MANDATORY	MTH 07-Jun-2006 HRS 9	-	-	-	-	Complete
	<b>MOC : COMPLIED WITH</b>							
SL CIL-34-01	NAVIGATION - TRANSMIT UNIVERSAL AVIONICS ALERT SERVICE BULLETIN 3XXX.( )-34-3508	INFORMATIONAL		-	-	-	-	
	<b>MOC :</b>							
SL CIL-34-02	NAVIGATION - TRANSMITTAL OF HONEYWELL SIL D201301000032, PRIMUS II INTEGRATED RADIO SYSTEM	MANDATORY	MTH 25-Jul-2014 HRS 2545.3 LDG 2299	-	-	-	-	Complete
	<b>MOC : COMPLIED WITH - PERFORMED OK. NO ACTION NEEDED, UNITS MEETS REQUIRED MOD STATUS</b>							



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 (ENG) TSO 2 (ENG)	DUE 1 DUE 2	Remains Remains
SL CIL-34-06 R1	NAVIGATION - TRANSMITTAL OF HONEYWELL SIL D201206000008R002, PRIMUS EPIC AND PRIMUS II MODE S TRANSPONDER; (1) TCAS, CHANGE 7.1, REPORTS AN EARLIER TCAS II VERSION NUMBER TO ATC GROUND STATIONS, (2) IMPROPER SUPPORT OF EHS IN MODE S RADAR COVERAGE USING A SI CODE INFORMATIONAL									
<b>MOC :</b>										
SL CIL-34-06	NAVIGATION - TRANSMITTAL OF HONEYWELL SIL D201206000008R002, PRIMUS EPIC AND PRIMUS II MODE S TRANSPONDER; (1) TCAS, CHANGE 7.1, REPORTS AN EARLIER TCAS II VERSION NUMBER TO ATC GROUND STATIONS, (2) IMPROPER SUPPORT OF EHS IN MODE S RADAR COVERAGE USING A SI CODE INFORMATIONAL									
<b>MOC :</b>										
SL 560XL-34-24 R1	SERVICE INFORMATION FROM HONEYWELL INFORMATIONAL									
<b>MOC :</b>										
SL 560XL-34-24	NAVIGATION - SERVICE INFORMATION FROM HONEYWELL INFORMATIONAL						A/R			
<b>MOC :</b>										
SL CIL-35-05	OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001 ESGP MANDATORY				MTH HRS 3113.1 LDG 2859					N/A
<b>MOC : NOT APPLICABLE - NOT APPLICABLE DUE TO PART NUMBER NOT INSTALLED</b>										
SL 560XL-35-04 R1	TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240 MANDATORY									
<b>MOC :</b>										
SL 560XL-35-04 R2	TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240 ESGP MANDATORY				MTH 05-Jan-2013 HRS 1987.1 LDG 1764					N/A
<b>MOC : NOT APPLICABLE - TO SERIAL NUMBERS INSTALLED.</b>										
SL 560XL-35-04	TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240 MANDATORY									
<b>MOC :</b>										
SB 560XL-38-03	TOILET OVERRIDE RELAY INSTALLATION OPTIONAL									
<b>MOC :</b>										
SL 560XL-38-01	TRANSMITTAL OF MONOGRAM SYSTEMS SERVICE INFORMATION LETTER SIL15900-023 ESGP RECOMMENDED				MTH 20-Oct-2011 HRS 1557.4 LDG 1374		A/R			Complete
<b>MOC : COMPLIED WITH - SERVICE LETTER PERFORMED OK</b>										
SB 560XL-49-15 49SB-15 : XL	APU ADD OIL LIGHT REMOVAL DISCRETIONARY				MTH		A/R			
<b>MOC :</b>										
SB 560XL-49-17	AUXILIARY POWER - AUXILIARY POWER UNIT MOUNT BOLT CHANGE OPTIONAL									
<b>MOC :</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 560XL-49-11 49SL-11 : XL	TRANSMITTAL OF HONEYWELL SERVICE BULLETIN RE100-49-7896 OIL DIPSTICK REPLACEMENT			DISCRETIONARY	MTH		A/R			
<b>MOC :</b>										
SB 3615880-49-8149 R1	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE TURBINE ROTORS, PN3615880-1, PN 3615880-002, PN 3615880-3, AND PN 3615880-4, ON MULTIPLE APUS			RECOMMENDED			-			
<b>MOC :</b>										
SB 3615880-49-8149 R2	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE TURBINE ROTORS, PN 3615880-1, PN 3615880-002, PN 3615880-3, AND PN 3615880-4, ON MULTIPLE APUS			RECOMMENDED			-			
<b>MOC :</b>										
SB 3822101-49-8148 R1	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTORS, PN 3822101-1, ON MULTIPLE APUS			RECOMMENDED			-			
<b>MOC :</b>										
SB 3822101-49-8148 R2	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTORS, PN 3822101-1, ON MULTIPLE APUS			RECOMMENDED			-			
<b>MOC :</b>										
SB 3881800-49-7523 R4	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE LOW OIL PRESSURE SWITCH, PN 3876255-2 WITH PN 3876351-1 AND REIDENTIFY LUBE PUMP FROM PN 3881800-1 TO PN 3881825-1, ON RE100[XL] AND RE100[LJ] APUS			RECOMMENDED			-			
<b>MOC :</b>										
SB 49-7933 R4	OIL - GENERAL - APPROVED OILS						-			
<b>MOC :</b>										
SB 49-7933 R5	OIL - GENERAL - APPROVED OILS						-			
<b>MOC :</b>										
SB 49-7933 R6	AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS						-			
<b>MOC :</b>										
SB 49-7992 R1	REMOVE AND REPLACE ELECTRONIC CONTROL UNIT, PN 2119552-2 OR PN 2119552-3, WITH ELECTRONIC CONTROL UNIT, PN 2119552-4			OPTIONAL			-			
<b>MOC :</b>										
SB 49-7992	REMOVE AND REPLACE ELECTRONIC CONTROL UNIT, PN 2119552-2 OR PN 2119552-3, WITH ELECTRONIC CONTROL UNIT, PN 2119552-4			OPTIONAL			-			
<b>MOC :</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 49-7997 R2	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES									-
	<b>MOC :</b>									
SB 49-7997 R3	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES									-
	<b>MOC :</b>									
SB 49-7997 R4	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES									-
	<b>MOC :</b>									
SB 70721598-49-8168 R1	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTOR, PN 70721598-1, ON MULTIPLE APUS									-
	<b>MOC :</b>									
SB 70721598-49-8168 R2	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTOR, PN 70721598-1, ON MULTIPLE APUS									-
	<b>MOC :</b>									
SB 70721725-49-8152 R1	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE DUAL PILOT TURBINE ROTORS, PN 70721725-2 AND PN 70721725-5, ON MULTIPLE APUS									-
	<b>MOC :</b>									
SB 70721725-49-8152 R2	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE DUAL PILOT TURBINE ROTORS, PN 70721725-2 AND PN 70721725-5, ON MULTIPLE APUS									-
	<b>MOC :</b>									
SB RE100-49-7896 R1	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE OIL FILLER NECK AND (DIPSTICK) CAP, PN 361-530-9354, WITH OIL FILLER NECK CAP, PN 361-530-9355, ON THE RE100 APU OPTIONAL									-
	<b>MOC :</b>									
SB RE100-49-7933 R3	AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS									-
	<b>MOC :</b>									
SB RE100-49-8139	INCREASE THE INSTALLATION TORQUE AND ADD THE USE OF LOCKING COMPOUND DURING CARBON SEAL ASSEMBLY ON THE RE100 APU									-
	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 560XL-52-17 R1 52SB-17 : XLR1	CABIN ENTRY DOOR OPERATION IMPROVEMENT			RECOMMENDED	MTH 15-Aug-2008 HRS 759		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SL 560XL-52-07	DOORS - EXTERIOR DOOR SWITCH IMPROVEMENT			INFORMATIONAL			A/R			
<b>MOC :</b>										
SB 560XL-53-13 R1 52SB-17 : XLR1	FUSELAGE - NOSE DRIP CAP BOND INSPECTION			MANDATORY	MTH 29-May-2012 HRS 1721.1 LDG 1559		A/R			Complete
<b>MOC : COMPLIED WITH - PERFORMED OK. NDT INSPECTION REQUIRED AND PERFORMED WITHOUT ANY FINDINGS. BULLETIN COMPLETED</b>										
SB 560XL-53-13	FUSELAGE - NOSE DRIP CAP BOND INSPECTION			MANDATORY	MTH		A/R			
<b>MOC :</b>										
SB 560XL-53-14	FUSELAGE - CARBON FIBER STRAKE MODIFICATION			OPTIONAL			-			
<b>MOC :</b>										
SB 560XL-53-16	FUSELAGE - STINGER DRAIN INSTALLATION			MANDATORY	MTH 20-Feb-2012 HRS 1641.2 LDG 1472		A/R			Complete
<b>MOC : COMPLIED WITH - BULLETIN PERFORMED OK</b>										
ASL 560XL-53-08 R1 52SL-07 : XL	AFT CANTED BULKHEAD DRAIN INSTALLATION			MANDATORY	DAYS 22-Mar-2011 HRS 1310.1 LDG 1169		A/R			Complete
<b>MOC : COMPLIED WITH - ASL PERFORMED REFER EMS WORKCARD: 23491</b>										
ASL 560XL-53-08	AFT CANTED BULKHEAD DRAIN INSTALLATION			MANDATORY	DAYS		A/R			
<b>MOC : - SUPERSEDED BY REVISION 1</b>										
SL 560XL-53-07 53SL-07 : XL	LOWER SKIN ASSEMBLY FASTENER INSPECTION			MANDATORY	MTH 01-Oct-2009 HRS 846		-			Complete
<b>MOC : COMPLIED WITH</b>										
SL 560XL-53-17	FUSELAGE - DORSAL DUCT INSPECTION			RECOMMENDED	MTH 05-Jan-2013 HRS 1987.1 LDG 1764		-			Complete
<b>MOC : COMPLIED WITH - SL PERFORMED ACCORDING TO THE INSTRUCTION. REPLACEMENT NOT REQUIRED.</b>										
SL 560XL-55-01 R1	STABILIZERS - PIVOT FITTING INSPECTION (CANCELLED BY SL560XL-55-01 R3)			MANDATORY	MTH 07-Jun-2006		-			
<b>MOC :</b>										
SL 560XL-55-01 R2	PIVOT FITTING INSPECTION (CANCELLED BY SL560XL-55-01 R3)			MANDATORY			-			
<b>MOC :</b>										
SL 560XL-55-01 R3	STABILIZERS - PIVOT FITTING INSPECTION			CANCELLED			-			
<b>MOC :</b>										
SL 560XL-55-01	PIVOT FITTING INSPECTION (CANCELLED BY SL560XL-55-01 R3)			MANDATORY	MTH		-			
<b>MOC :</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SL 560XL-56-03	OPENABLE COCKPIT WINDOW HINGE AND LATCH INSPECTION	ESGP MANDATORY	MTH 27-Dec-2011 HRS 1612.3 LDG 1440		A/R			Complete
<b>MOC : COMPLIED WITH - PERFORMED OK.</b>								
SB 560XL-71-07 R1 71SB-07 : XLR1	MOTIVE FLOW FUEL LINE/OIL LINE CLEARANCE IMPROVEMENT	RECOMMENDED	MTH 09-Jul-2008 HRS 748		A/R			Complete
<b>MOC : COMPLIED WITH</b>								
SB 560XL-71-09 71SB-09 : XL	ENGINE OIL DOOR DOUBLER INSTALLATION	RECOMMENDED	MTH 09-Jul-2008 HRS 748		A/R			Complete
<b>MOC : COMPLIED WITH</b>								
SB 560XL-71-11 R1	ENGINE FUEL MANIFOLD DRAIN LINE INSTALLATION	OPTIONAL			-			
<b>MOC :</b>								
SB 560XL-71-11	POWER PLANT - ENGINE FUEL MANIFOLD DRAIN LINE INSTALLATION	OPTIONAL			A/R			
<b>MOC :</b>								
SB 560XL-71-12	POWER PLANT - ENGINE FUEL MANIFOLD DRAIN LINE REMOVAL	OPTIONAL			-			
<b>MOC :</b>								
SL CIL-71-01	TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN 30463	OPTIONAL			-			
<b>MOC :</b>								
ASL 560XL-72-19	TRANSMITTAL OF P&WC SERVICE DOCUMENTS - INTERCOMPRESSOR BLEED VALVE/SERVO - VALVE - INSPECTION/REPLACEMENT OF	GSE MANDATORY	MTH 01-Mar-2011 HRS 1291 LDG 1156		A/R			N/A
LEFT ENGINE								
<b>MOC : NOT APPLICABLE - N/A DUE MORE THAN 250 ENGINE HOURS IN SERVICE</b>								
ASL 560XL-72-19	TRANSMITTAL OF P&WC SERVICE DOCUMENTS - INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE-INSPECTION/REPLACEMENT OF	GSE MANDATORY	MTH 01-Mar-2011 HRS 1291 LDG 1156		A/R			N/A
RIGHT ENGINE								
<b>MOC : NOT APPLICABLE - COMMENTS: N/A DUE MORE THAN 250 ENGINE HOURS IN SERVICE</b>								
SL 560XL-72-12	TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW500-72-30331 MODIFICATION OF FUEL PRESSURE HOSE AND TUBE ROUTING	ESGP OPTIONAL	MTH 25-Jul-2014 HRS 2545.3 LDG 2299		A/R			Complete
72SL-12 : XL								
<b>MOC : COMPLIED WITH - PERFORMED BY MTU MAINTENANCE GMBH DE.145.0003 EASA FORM 1 J 026/14 WO:1084-14 K01150</b>								



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL 560XL-72-13 LEFT ENGINE 72SL-13 : XL	TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW500-72-30335 TURBOFAN ENGINE GAS-GENERATOR-CASE TO INTERMEDIATE-CASE RETAINING-BOLTS BORESCOPEINSPECTION OF	ESGP		RECOMMENDED	MTH 25-Jul-2014 HRS 2545.3 LDG 2299		300			Complete
THIS SERVICE LETTER IS DUE AT HOT SECTION BUT NOT TO EXCEED 4100 TOTAL ENGINE HOURS. <b>MOC : COMPLIED WITH - PERFORMED BY MTU MAINTENANCE GMBH DE.145.0003 EASA FORM 1 J 027/14</b> WO:1085-14 K01151										
SL 560XL-72-13 RIGHT ENGINE 72SL-13 : XL	TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW500-72-30335 TURBOFAN ENGINE GAS-GENERATOR-CASE TO INTERMEDIATE-CASE RETAINING-BOLTS BORESCOPEINSPECTION OF	ESGP		RECOMMENDED	MTH 25-Jul-2014 HRS 2545.3 LDG 2299		300			Complete
THIS SERVICE LETTER IS DUE AT HOT SECTION BUT NOT TO EXCEED 4100 TOTAL ENGINE HOURS. <b>MOC : COMPLIED WITH - PERFORMED BY MTU MAINTENANCE GMBH DE.145.0003 EASA FORM 1 J 026/14</b> WO:1084-14 K01150										
SL 560XL-72-14 LEFT ENGINE 72SL-14 : XL	TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN PW500-72-30306 TURBOFAN ENGINE NEW TRANSFER TUBES WITH HEAT SHIELD	ESGP		RECOMMENDED	MTH 25-Jul-2014 HRS 2545.3 LDG 2299		300			Complete
<b>MOC : COMPLIED WITH - PERFORMED BY MTU MAINTENANCE GMBH DE.145.0003 EASA FORM 1 J 027/14</b> WO:1085-14 K01151										
SL 560XL-72-14 RIGHT ENGINE 72SL-14 : XL	TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN PW500-72-30306 TURBOFAN ENGINE NEW TRANSFER TUBES WITH HEAT SHIELD	ESGP		RECOMMENDED	MTH 25-Jul-2014 HRS 2545.3 LDG 2299		300			Complete
<b>MOC : COMPLIED WITH - PERFORMED BY MTU MAINTENANCE GMBH DE.145.0003 EASA FORM 1 J 026/14</b> WO:1084-14 K01150										
SL 560XL-72-16 72SL-16 : XL	TRANSMITTAL OF PRATT AND WHITNEY CANADA TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW500-72-30368, TURBOFAN ENGINE INTERCOMPRESSOR BLEEDVALVE SERVO VALVE - INSPECTION	GSE		RECOMMENDED	MTH 16-Apr-2010 HRS 987 LDG 875		A/R			N/A
<b>MOC : NOT APPLICABLE - N/A DUE ENGINE SERIAL NUMBER</b>										
SL 560XL-72-17 LEFT ENGINE 72SL-17 : E1**L	TRANSMITTAL OF PRATT AND WHITNEY CANADA (P&WC) SERVICE BULLETIN PW500-72-30409, TURBOFAN ENGINE HYDROMECHANICAL FUEL CONTROL UNIT- REPLACEMENT,MODIFICATION OF	ESGP		MANDATORY	MTH 05-Jan-2013 HRS 1987.1 LDG 1764		A/R			Complete
<b>MOC : COMPLIED WITH - BY SENDING FCU FOR UPGRADE/OVERHAUL</b>										
SL 560XL-72-17 RIGHT ENGINE 72SL-17 : E2**R	TRANSMITTAL OF PRATT AND WHITNEY CANADA (P&WC) SERVICE BULLETIN PW500-72-30409, TURBOFAN ENGINE HYDROMECHANICAL FUEL CONTROL UNIT- REPLACEMENT,MODIFICATION OF	ESGP		MANDATORY	MTH 05-Jan-2013 HRS 1987.1 LDG 1764		A/R			Complete
<b>MOC : COMPLIED WITH - DURING UPGRADE/OVERHAUL OF FCU INSTALLED P/N: 1012636-18</b>										
SB PW300-72-30446 E1	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY			CATEGORY 7			A/R			
<b>MOC :</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB PW300-72-30446 E2	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY	CATEGORY 7			A/R			
<b>MOC :</b>								
SB PW500-72-30269 R1	REPLACEMENT OF GAS GENERATOR DIFFUSER SET AND NO. 4 BEARING	CATEGORY 7			-			
<b>MOC :</b>								
E1								
SB PW500-72-30269 R1	REPLACEMENT OF GAS GENERATOR DIFFUSER SET AND NO. 4 BEARING	CATEGORY 7			-			
<b>MOC :</b>								
E2								
SB PW500-72-30270 R1	REPLACEMENT OF TURBINE EXHAUST CASE ASSY	CATEGORY 7			-			
<b>MOC :</b>								
E1								
SB PW500-72-30270 E2	REPLACEMENT OF TURBINE EXHAUST CASE ASSY	CATEGORY 7			-			
<b>MOC :</b>								
SB PW500-72-30288 R2	MODIFICATION OF TURBINE CASE ASSEMBLY	CATEGORY 6			A/R			
<b>MOC :</b>								
E1								
SB PW500-72-30288 R2	MODIFICATION OF TURBINE CASE ASSEMBLY	CATEGORY 6			A/R			
<b>MOC :</b>								
E2								
SB PW500-72-30309 R4	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL	CATEGORY 6			-			
<b>MOC :</b>								
E1								
SB PW500-72-30309 R4	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL	CATEGORY 6			-			
<b>MOC :</b>								
E2								
SB PW500-72-30324 R2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL.	ESGP CATEGORY 6	MTH 05-Jan-2013		-			Complete
<b>MOC :</b>								
E1			HRS 2052					
			LDG 1834					
<b>MOC : COMPLIED WITH - DURING UPGRADE/OVERHAUL OF FCU INSTALLED P/N: 1012636-17</b>								





# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30324 R2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL.									
		ESGP		CATEGORY 6	MTH 05-Jan-2013 HRS 1987.1 LDG 1764		-			Complete
E2	<b>MOC : COMPLIED WITH - DURING UPGRADE/OVERHAUL OF FCU INSTALLED P/N: 1012636-18</b>									
SB PW500-72-30325 R2	REPLACEMENT OF OIL-PUMP PLAIN SEAL									
E1				CATEGORY 6			-			
	<b>MOC :</b>									
SB PW500-72-30325 R2	REPLACEMENT OF OIL-PUMP PLAIN SEAL									
E2				CATEGORY 6			-			
	<b>MOC :</b>									
SB PW500-72-30331 E1	MODIFICATION OF FUEL PRESSURE HOSE & TUBE ROUTING									
		ESGP		CATEGORY 5	MTH 25-Jul-2014 HRS 2610.2 LDG 2369		-			Complete
	<b>MOC : COMPLIED WITH - PERFORMED BY MTU MAINTENANCE GMBH DE.145.0003 EASA FORM 1 J 026/14 WO:1084-14 K01150</b>									
SB PW500-72-30331 E2	MODIFICATION OF FUEL PRESSURE HOSE & TUBE ROUTING									
		ESGP		CATEGORY 5	MTH 25-Jul-2014 HRS 2545.3 LDG 2299		-			Complete
	<b>MOC : COMPLIED WITH - PERFORMED BY MTU MAINTENANCE GMBH DE.145.0003 EASA FORM 1 J 026/14 WO:1084-14 K01150</b>									
SB PW500-72-30332 R2	REPLACEMENT OF ACCESSORY GEARBOX DRIVE SHAFT ANNULAR BALL BEARING									
				CATEGORY 6			A/R			
E1	<b>MOC :</b>									
SB PW500-72-30332 R2	REPLACEMENT OF ACCESSORY GEARBOX DRIVE SHAFT ANNULAR BALL BEARING									
				CATEGORY 6			A/R			
E2	<b>MOC :</b>									
SB PW500-72-30336 R1	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL									
				CATEGORY 7			-			
E1	<b>MOC :</b>									
SB PW500-72-30336 R1	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL									
				CATEGORY 7			-			
E2	<b>MOC :</b>									
SB PW500-72-30339 R2	REPLACEMENT/MODIFICATION OF FRONT FAN CASE ASSEMBLY									
				CATEGORY 6			A/R			
E1	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB PW500-72-30339 R2	REPLACEMENT/MODIFICATION OF FRONT FAN CASE ASSEMBLY							
		CATEGORY 6			A/R			
E2	<b>MOC :</b>							
SB PW500-72-30343 R6	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR-BLEED-VALVE							
		CATEGORY 7			-			
E1	<b>MOC :</b>							
SB PW500-72-30343 R6	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR-BLEED-VALVE							
		CATEGORY 7			-			
E2	<b>MOC :</b>							
SB PW500-72-30344 R1	REPLACEMENT OF VARIOUS CADMIUM PLATED PARTS							
		CATEGORY 7			-			
E1	<b>MOC :</b>							
SB PW500-72-30344 R1	REPLACEMENT OF VARIOUS CADMIUM PLATED PARTS							
		CATEGORY 7			-			
E2	<b>MOC :</b>							
SB PW500-72-30356 R2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL WITH ADDITIONAL PROTECTIVE SCREENS							
		ESGP CATEGORY 6	MTH 05-Jan-2013		-			Complete
			HRS 2052					
			LDG 1834					
E1	<b>MOC : COMPLIED WITH - DURING UPGRADE/OVERHAUL OF FCU INSTALLED P/N: 1012636-17</b>							
SB PW500-72-30356 R2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL WITH ADDITIONAL PROTECTIVE SCREENS							
		ESGP CATEGORY 6	MTH 05-Jan-2013		-			Complete
			HRS 1987.1					
			LDG 1764					
E2	<b>MOC : COMPLIED WITH - DURING UPGRADE/OVERHAUL OF FCU INSTALLED P/N: 1012636-18</b>							
SB PW500-72-30364 R1	REPLACEMENT ACCESSORY GEARBOX PLAIN SEALS							
		CATEGORY 7			A/R			
E1	<b>MOC :</b>							
SB PW500-72-30364 R1	REPLACEMENT ACCESSORY GEARBOX PLAIN SEALS							
		CATEGORY 7			A/R			
E2	<b>MOC :</b>							
SB PW500-72-30369 R1	REPLACEMENT/MODIFICATION OIL PUMP ASSEMBLY WITH A NEW REAR OIL PUMP HOUSING							
		CATEGORY 6			A/R			
E1	<b>MOC :</b>							



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB PW500-72-30369 R1	REPLACEMENT/MODIFICATION OIL PUMP ASSEMBLY WITH A NEW REAR OIL PUMP HOUSING							
		CATEGORY 6			A/R			
E2	<b>MOC :</b>							
SB PW500-72-30371 R1	TURBOFAN ENGINE - ACCESSORY GEARBOX FCU-STARTER GEARSHAFT OIL BAFFLE - INTRODUCTION							
		CATEGORY 6			-			
E1	<b>MOC :</b>							
SB PW500-72-30371 R1	TURBOFAN ENGINE - ACCESSORY GEARBOX FCU-STARTER GEARSHAFT OIL BAFFLE - INTRODUCTION							
		CATEGORY 6			-			
E2	<b>MOC :</b>							
SB PW500-72-30371 R2	INTRODUCTION ACCESSORY GEARBOX FCU-STARTER GEARSHAFT OIL BAFFLE							
		CATEGORY 10			-			
E1	<b>MOC :</b>							
SB PW500-72-30371 R2	INTRODUCTION ACCESSORY GEARBOX FCU-STARTER GEARSHAFT OIL BAFFLE							
		CATEGORY 10			-			
E2	<b>MOC :</b>							
SB PW500-72-30376 R1	REPLACEMENT/MODIFICATION OF OIL PUMP ASSEMBLY AND OIL-PUMP-DRIVE SPUR GEAR							
		CATEGORY 7			A/R			
E1	<b>MOC :</b>							
SB PW500-72-30376 R1	REPLACEMENT/MODIFICATION OF OIL PUMP ASSEMBLY AND OIL-PUMP-DRIVE SPUR GEAR							
		CATEGORY 7			A/R			
E2	<b>MOC :</b>							
SB PW500-72-30376 R2	REPLACEMENT/MODIFICATION OF OIL PUMP ASSEMBLY AND OIL-PUMP-DRIVE SPUR GEAR							
		CATEGORY 7			-			
E1	<b>MOC :</b>							
SB PW500-72-30376 R2	REPLACEMENT/MODIFICATION OF OIL PUMP ASSEMBLY AND OIL-PUMP-DRIVE SPUR GEAR							
		CATEGORY 7			-			
E2	<b>MOC :</b>							



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30381 R2	REPLACEMENT OF FUEL MANIFOLD AND FUEL SHUT-OFF CABLE GROMMETS AND COVER PLATE FAIRING									
		ESGP		CATEGORY 3	MTH 24-May-2011 HRS 1434.9 LDG 1292		-			Complete
E1	<b>MOC : COMPLIED WITH</b>									
SB PW500-72-30381 R2	REPLACEMENT OF FUEL MANIFOLD AND FUEL SHUT-OFF CABLE GROMMETS AND COVER PLATE FAIRING									
		ESGP		CATEGORY 3	MTH 24-May-2011 HRS 1370 LDG 1222		-			Complete
E2	<b>MOC : COMPLIED WITH</b>									
SB PW500-72-30384 R1 E1	REPLACEMENT OF AIR/OIL SEPARATOR			CATEGORY 6					A/R	
	<b>MOC :</b>									
SB PW500-72-30384 R1 E2	REPLACEMENT OF AIR/OIL SEPARATOR			CATEGORY 6					A/R	
	<b>MOC :</b>									
SB PW500-72-30387 R2	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY			CATEGORY 6					-	
E1	<b>MOC :</b>									
SB PW500-72-30387 R2	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY			CATEGORY 6					-	
E2	<b>MOC :</b>									
SB PW500-72-30387 R3	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY			CATEGORY 6					-	
E1	<b>MOC :</b>									
SB PW500-72-30387 R3	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY			CATEGORY 6					-	
E2	<b>MOC :</b>									
SB PW500-72-30387 R4	REPLACEMENT / MODIFICATION OF REAR BY-PASS DUCT ASSEMBLY			CATEGORY 6					-	
E1	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB PW500-72-30387 R4	REPLACEMENT / MODIFICATION OF REAR BY-PASS DUCT ASSEMBLY							
		CATEGORY 6						
E2	<b>MOC :</b>							
SB PW500-72-30387 R5	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY							
		CATEGORY 6						
E1	<b>MOC :</b>							
SB PW500-72-30387 R5	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY							
		CATEGORY 6						
E2	<b>MOC :</b>							
SB PW500-72-30390 R5	CAVITATION REPAIR HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY SB PW500-72-30409 R8, DATED JUNE 20, 2012)							
		CATEGORY 10						
E1	<b>MOC :</b>							
SB PW500-72-30390 R5	CAVITATION REPAIR HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY SB PW500-72-30409 R8, DATED JUNE 20, 2012)							
		CATEGORY 10						
E2	<b>MOC :</b>							
SB PW500-72-30399 E1	REPLACEMENT OF BOLTS							
		CATEGORY 7						
E1	<b>MOC :</b>							
SB PW500-72-30399 E2	REPLACEMENT OF BOLTS							
		CATEGORY 7						
E2	<b>MOC :</b>							
SB PW500-72-30400 R1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER							
		CATEGORY 6						A/R
E1	<b>MOC :</b>							
SB PW500-72-30400 R1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER							
		CATEGORY 6						A/R
E2	<b>MOC :</b>							
SB PW500-72-30400 R2	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER							
		CATEGORY 6						A/R
E1	<b>MOC :</b>							



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30400 R2	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER			CATEGORY 6			A/R			
E2	<b>MOC :</b>									
SB PW500-72-30400 R3	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER			CATEGORY 6			-			
E1	<b>MOC :</b>									
SB PW500-72-30400 R3	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER			CATEGORY 6			-			
E2	<b>MOC :</b>									
SB PW500-72-30400 R4	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER			CATEGORY 6			-			
E1	<b>MOC :</b>									
SB PW500-72-30400 R4	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER			CATEGORY 6			-			
E2	<b>MOC :</b>									
SB PW500-72-30400 E1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER			CATEGORY 6			A/R			
E1	<b>MOC :</b>									
SB PW500-72-30400 E2	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER			CATEGORY 6			A/R			
E2	<b>MOC :</b>									
SB PW500-72-30405 R1	REPLACEMENT OF FUEL NOZZLE MANIFOLD			CATEGORY 6			A/R			
E1	<b>MOC :</b>									
SB PW500-72-30405 R1	REPLACEMENT OF FUEL NOZZLE MANIFOLD			CATEGORY 6			A/R			
E2	<b>MOC :</b>									
SB PW500-72-30405 R2	REPLACEMENT OF FUEL NOZZLE MANIFOLD			CATEGORY 6			-			
E1	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30405 R2 E2	REPLACEMENT OF FUEL NOZZLE MANIFOLD			CATEGORY 6			-			
	<b>MOC :</b>									
SB PW500-72-30405 R3 E1	REPLACEMENT OF - FUEL NOZZLE MANIFOLD			CATEGORY 6			-			
	<b>MOC :</b>									
SB PW500-72-30405 R3 E2	REPLACEMENT OF - FUEL NOZZLE MANIFOLD			CATEGORY 6			-			
	<b>MOC :</b>									
SB PW500-72-30408 E1	REPLACEMENT OF ENGINE GASKET			CATEGORY 6			A/R			
	<b>MOC :</b>									
SB PW500-72-30408 E2	REPLACEMENT OF ENGINE GASKET			CATEGORY 6			A/R			
	<b>MOC :</b>									
SB PW500-72-30409 R10 E1	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 3	MTH		-			
	<b>MOC :</b>									
SB PW500-72-30409 R10 E2	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 3	MTH		-			
	<b>MOC :</b>									
SB PW500-72-30409 R8 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT	ESGP		CATEGORY 3	MTH 05-Jan-2013 HRS 2052 LDG 1834		-			Complete
	<b>MOC : COMPLIED WITH - BY SENDING FCU FOR UPGRADE/OVERHAUL</b>									
SB PW500-72-30409 R8 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT	ESGP		CATEGORY 3	MTH 05-Jan-2013 HRS 1987.1 LDG 1764		-			Complete
	<b>MOC : COMPLIED WITH - BY SENDING FCU FOR UPGRADE/OVERHAUL - NEW P/N: 1012636-18</b>									
SB PW500-72-30409 R9 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB PW500-72-30409 R9	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT							
		CATEGORY 7			-			
E2	<b>MOC :</b>							
SB PW500-72-30413 R1	INTRODUCTION OF DEEPER SUMP							
E1		CATEGORY 6			A/R			
	<b>MOC :</b>							
SB PW500-72-30413 R1	INTRODUCTION OF DEEPER SUMP							
E2		CATEGORY 6			A/R			
	<b>MOC :</b>							
SB PW500-72-30413 R2	INTRODUCTION OF DEEPER SUMP							
E1		CATEGORY 6			A/R			
	<b>MOC :</b>							
SB PW500-72-30413 R2	INTRODUCTION OF DEEPER SUMP							
E2		CATEGORY 6			A/R			
	<b>MOC :</b>							
SB PW500-72-30413 R3	INTRODUCTION OF DEEPER SUMP							
E1		CATEGORY 6			A/R			
	<b>MOC :</b>							
SB PW500-72-30413 R3	INTRODUCTION OF DEEPER SUMP							
E2		CATEGORY 6			A/R			
	<b>MOC :</b>							
SB PW500-72-30413 R4	INTRODUCTION OF DEEPER SUMP							
E1		CATEGORY 6			A/R			
	<b>MOC :</b>							
SB PW500-72-30413 R4	INTRODUCTION OF DEEPER SUMP							
E2		CATEGORY 6			A/R			
	<b>MOC :</b>							
SB PW500-72-30413 R5	INTRODUCTION OF DEEPER SUMP							
E1		CATEGORY 6			-			
	<b>MOC :</b>							
SB PW500-72-30413 R5	INTRODUCTION OF DEEPER SUMP							
E2		CATEGORY 6			-			
	<b>MOC :</b>							
SB PW500-72-30413 R6	INTRODUCTION OF DEEPER SUMP							
E1		CATEGORY 6			-			
	<b>MOC :</b>							





## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30413 R6 E2	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			-			
	<b>MOC :</b>									
SB PW500-72-30413 R7 E1	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			-			
	<b>MOC :</b>									
SB PW500-72-30413 R7 E2	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			-			
	<b>MOC :</b>									
SB PW500-72-30413 R8 E1	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			-			
	<b>MOC :</b>									
SB PW500-72-30413 R8 E2	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			-			
	<b>MOC :</b>									
SB PW500-72-30413 R9 E1	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			-			
	<b>MOC :</b>									
SB PW500-72-30413 R9 E2	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			-			
	<b>MOC :</b>									
SB PW500-72-30413 E1	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			A/R			
	<b>MOC :</b>									
SB PW500-72-30413 E2	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			A/R			
	<b>MOC :</b>									
SB PW500-72-30415 R1 E1	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 6			-			
	<b>MOC :</b>									
SB PW500-72-30415 R1 E2	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 6			-			
	<b>MOC :</b>									
SB PW500-72-30415 R2 E1	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 6			-			
	<b>MOC :</b>									
SB PW500-72-30415 R2 E2	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 6			-			
	<b>MOC :</b>									



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30415 R3 E1	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 6			-			
	<b>MOC :</b>									
SB PW500-72-30415 R3 E2	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 6			-			
	<b>MOC :</b>									
SB PW500-72-30415 E1	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 6			A/R			
	<b>MOC :</b>									
SB PW500-72-30415 E2	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 6			A/R			
	<b>MOC :</b>									
SB PW500-72-30416 R1 E1	REPLACEMENT OF NO.4 BEARING CARBON SEAL			CATEGORY 10			-			
	<b>MOC :</b>									
SB PW500-72-30416 R1 E2	REPLACEMENT OF NO.4 BEARING CARBON SEAL			CATEGORY 10			-			
	<b>MOC :</b>									
SB PW500-72-30416 E1	REPLACEMENT OF NO.4 BEARING CARBON SEAL			CATEGORY 7			-			
	<b>MOC :</b>									
SB PW500-72-30416 E2	REPLACEMENT OF NO.4 BEARING CARBON SEAL			CATEGORY 7			-			
	<b>MOC :</b>									
SB PW500-72-30417 R1 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING			CATEGORY 5			A/R			
	<b>MOC :</b>									
SB PW500-72-30417 R1 E2	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING			CATEGORY 5			A/R			
	<b>MOC :</b>									
SB PW500-72-30417 R2 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING			CATEGORY 5			A/R			
	<b>MOC :</b>									
SB PW500-72-30417 R2 E2	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING			CATEGORY 5			A/R			
	<b>MOC :</b>									
SB PW500-72-30417 R3 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING			CATEGORY 5			A/R			
	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30417 R3 E2	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING			CATEGORY 5			A/R			
<b>MOC :</b>										
SB PW500-72-30417 R4 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING			CATEGORY 5			A/R			
<b>MOC :</b>										
SB PW500-72-30417 R4 E2	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING			CATEGORY 5			A/R			
<b>MOC :</b>										
SB PW500-72-30417 R5 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING			CATEGORY 5			A/R			
<b>MOC :</b>										
SB PW500-72-30417 R5 E2	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING			CATEGORY 5			A/R			
<b>MOC :</b>										
SB PW500-72-30417 R6 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING			CATEGORY 5			A/R			
<b>MOC :</b>										
SB PW500-72-30417 R6 E2	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING			CATEGORY 5			A/R			
<b>MOC :</b>										
SB PW500-72-30417 R7 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING			CATEGORY 7			A/R			
<b>MOC :</b>										
SB PW500-72-30417 R7 E2	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING			CATEGORY 7			A/R			
<b>MOC :</b>										
SB PW500-72-30417 R8 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING			CATEGORY 10			-			
<b>MOC :</b>										
SB PW500-72-30417 R8 E2	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING			CATEGORY 10			-			
<b>MOC :</b>										
SB PW500-72-30417 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING			CATEGORY 5			A/R			
<b>MOC :</b>										
SB PW500-72-30417 E2	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING			CATEGORY 5			A/R			
<b>MOC :</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30419 R1 E1	REPLACEMENT OF COMBUSTION CHAMBER LINER			CATEGORY 7			-			
<b>MOC :</b>										
SB PW500-72-30419 R1 E2	REPLACEMENT OF COMBUSTION CHAMBER LINER			CATEGORY 7			-			
<b>MOC :</b>										
SB PW500-72-30419 E1	REPLACEMENT OF COMBUSTION CHAMBER LINER			CATEGORY 7			-			
<b>MOC :</b>										
SB PW500-72-30419 E2	REPLACEMENT OF COMBUSTION CHAMBER LINER			CATEGORY 7			-			
<b>MOC :</b>										
SB PW500-72-30420 R1  E1	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE			CATEGORY 3			-			
<b>MOC : - -SUPERSEDED BY REVISION 2</b>										
SB PW500-72-30420 R1  E2	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE			CATEGORY 3			-			
<b>MOC : - -SUPERSEDED BY REVISION 2</b>										
SB PW500-72-30420 R2  E1	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE	ESGP		CATEGORY 3	MTH 05-Jan-2013 HRS 2052 LDG 1834		-			Complete
<b>MOC : COMPLIED WITH - BY REPLACING BLEED VALVE SERVO VALVE</b>										
SB PW500-72-30420 R2  E2	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE	ESGP		CATEGORY 3	MTH 22-Jun-2011 HRS 1419.3 LDG 1262		-			Complete
<b>MOC : COMPLIED WITH</b>										
SB PW500-72-30420 R3  E1	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE			CATEGORY 3			-			
<b>MOC :</b>										
SB PW500-72-30420 R3  E2	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE			CATEGORY 3			-			
<b>MOC :</b>										



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30420 R4	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE			CATEGORY 6			-			
E1	<b>MOC :</b>									
SB PW500-72-30420 R4	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE			CATEGORY 6			-			
E2	<b>MOC :</b>									
SB PW500-72-30420 E1	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE			CATEGORY 3			-			N/A
E1	<b>MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1</b>									
SB PW500-72-30420 E2	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE			CATEGORY 3			-			N/A
E2	<b>MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1</b>									
SB PW500-72-30423 R1	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY			CATEGORY 6			-			
E1	<b>MOC :</b>									
SB PW500-72-30423 R1	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY			CATEGORY 6			-			
E2	<b>MOC :</b>									
SB PW500-72-30423 E1	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY			CATEGORY 6			A/R			
E1	<b>MOC :</b>									
SB PW500-72-30423 E2	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY			CATEGORY 6			A/R			
E2	<b>MOC :</b>									
SB PW500-72-30425 R1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			CATEGORY 3			A/R			
E1	<b>MOC :</b>									
SB PW500-72-30425 R1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			CATEGORY 3			A/R			
E2	<b>MOC :</b>									
SB PW500-72-30425 R2	REPLACEMENT OF NO. 4 BEARING CARBON SEAL						A/R			
E1	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30425 R2 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEAL						A/R			
	<b>MOC :</b>									
SB PW500-72-30425 R3 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			CATEGORY 10			-			
	<b>MOC :</b>									
SB PW500-72-30425 R3 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			CATEGORY 10			-			
	<b>MOC :</b>									
SB PW500-72-30425 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			CATEGORY 3			A/R			
	<b>MOC :</b>									
SB PW500-72-30425 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			CATEGORY 3			A/R			
	<b>MOC :</b>									
SB PW500-72-30427 R1 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7			-			
	<b>MOC :</b>									
SB PW500-72-30427 R1 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7			-			
	<b>MOC :</b>									
SB PW500-72-30427 R2 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7			-			
	<b>MOC :</b>									
SB PW500-72-30427 R2 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7			-			
	<b>MOC :</b>									
SB PW500-72-30427 R3 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7			-			
	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30427 R3	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7						-
E2	<b>MOC :</b>									
SB PW500-72-30428 R1 E1	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6						A/R
E1	<b>MOC :</b>									
SB PW500-72-30428 R1 E2	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6						A/R
E2	<b>MOC :</b>									
SB PW500-72-30428 R2 E1	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6						-
E1	<b>MOC :</b>									
SB PW500-72-30428 R2 E2	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6						-
E2	<b>MOC :</b>									
SB PW500-72-30428 R3 E1	REPLACEMENT OF - FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6						-
E1	<b>MOC :</b>									
SB PW500-72-30428 R3 E2	REPLACEMENT OF - FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6						-
E2	<b>MOC :</b>									
SB PW500-72-30428 R4 E1	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6						-
E1	<b>MOC :</b>									
SB PW500-72-30428 R4 E2	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6						-
E2	<b>MOC :</b>									
SB PW500-72-30429 R1	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY			CATEGORY 6						A/R
E1	<b>MOC :</b>									
SB PW500-72-30429 R1	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY			CATEGORY 6						A/R
E2	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB PW500-72-30429 R2	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY							
		CATEGORY 6			A/R			
E1	<b>MOC :</b>							
SB PW500-72-30429 R2	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY							
		CATEGORY 6			A/R			
E2	<b>MOC :</b>							
SB PW500-72-30429 R3	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY							
		CATEGORY 6			-			
E1	<b>MOC :</b>							
SB PW500-72-30429 R3	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY							
		CATEGORY 6			-			
E2	<b>MOC :</b>							
SB PW500-72-30429 R4	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY							
		CATEGORY 6			-			
E1	<b>MOC :</b>							
SB PW500-72-30429 R4	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY							
		CATEGORY 6			-			
E2	<b>MOC :</b>							
SB PW500-72-30429 R5	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY							
		CATEGORY 6			-			
E1	<b>MOC :</b>							
SB PW500-72-30429 R5	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY							
		CATEGORY 6			-			
E2	<b>MOC :</b>							
SB PW500-72-30429 E1	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY							
		CATEGORY 6			A/R			
E1	<b>MOC :</b>							





# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30429 E2	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY			CATEGORY 6			A/R			
<b>MOC :</b>										
SB PW500-72-30432 R1 E1	PLAIN SEAL ACCESSORY GEARBOX - REPLACEMENT OF			CATEGORY 7			A/R			
<b>MOC :</b>										
SB PW500-72-30432 R1 E2	PLAIN SEAL ACCESSORY GEARBOX - REPLACEMENT OF			CATEGORY 7			A/R			
<b>MOC :</b>										
SB PW500-72-30432 E1	PLAIN SEAL ACCESSORY GEARBOX - REPLACEMENT OF			CATEGORY 7			A/R			
<b>MOC :</b>										
SB PW500-72-30432 E2	PLAIN SEAL ACCESSORY GEARBOX - REPLACEMENT OF			CATEGORY 7			A/R			
<b>MOC :</b>										
SB PW500-72-30436 R1 E1	REPLACEMENT / MODIFICATION OF LPT 2ND STAGE VANE ASSEMBLY			CATEGORY 7			-			
<b>MOC :</b>										
SB PW500-72-30436 R1 E2	REPLACEMENT / MODIFICATION OF LPT 2ND STAGE VANE ASSEMBLY			CATEGORY 7			-			
<b>MOC :</b>										
SB PW500-72-30436 R2 E1	REPLACEMENT / MODIFICATION OF LPT 2ND STAGE VANE ASSEMBLY			CATEGORY 7			-			
<b>MOC :</b>										
SB PW500-72-30436 R2 E2	REPLACEMENT / MODIFICATION OF LPT 2ND STAGE VANE ASSEMBLY			CATEGORY 7			-			
<b>MOC :</b>										
SB PW500-72-30436 R3 E1	REPLACEMENT / MODIFICATION OF LPT 2ND STAGE VANE ASSEMBLY			CATEGORY 7			-			
<b>MOC :</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30436 R3	REPLACEMENT / MODIFICATION OF LPT 2ND STAGE VANE ASSEMBLY									
				CATEGORY 7						-
E2	<b>MOC :</b>									
SB PW500-72-30436 E1	LPT 2ND STAGE VANE ASSEMBLY - REPLACEMENT/MODIFICATION OF									A/R
	<b>MOC :</b>									
SB PW500-72-30436 E2	LPT 2ND STAGE VANE ASSEMBLY - REPLACEMENT/MODIFICATION OF									A/R
	<b>MOC :</b>									
SB PW500-72-30440 R1	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY									A/R
				CATEGORY 6						A/R
E1	<b>MOC :</b>									
SB PW500-72-30440 R1	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY									A/R
				CATEGORY 6						A/R
E2	<b>MOC :</b>									
SB PW500-72-30440 R2	REPLACEMENT OF TURBOFAN ENGINE NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY									A/R
				CATEGORY 6						A/R
E1	<b>MOC :</b>									
SB PW500-72-30440 R2	REPLACEMENT OF TURBOFAN ENGINE NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY									A/R
				CATEGORY 6						A/R
E2	<b>MOC :</b>									
SB PW500-72-30440 R3	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY									-
				CATEGORY 6						-
E1	<b>MOC :</b>									
SB PW500-72-30440 R3	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY									-
				CATEGORY 6						-
E2	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB PW500-72-30440 R4	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY							
		CATEGORY 6						-
E1	<b>MOC :</b>							
SB PW500-72-30440 R4	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY							
		CATEGORY 6						-
E2	<b>MOC :</b>							
SB PW500-72-30440 R5	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY							
		CATEGORY 6						-
E1	<b>MOC :</b>							
SB PW500-72-30440 R5	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY							
		CATEGORY 6						-
E2	<b>MOC :</b>							
SB PW500-72-30440 E1	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY							
		CATEGORY 6						A/R
E1	<b>MOC :</b>							
SB PW500-72-30440 E2	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY							
		CATEGORY 6						A/R
E2	<b>MOC :</b>							
SB PW500-72-30442 R1	REPLACEMENT/MODIFICATION OF TURBOFAN ENGINE HYDROMECHANICAL FUEL CONTROL UNIT							
		CATEGORY 6						A/R
E1	<b>MOC :</b>							
SB PW500-72-30442 R1	REPLACEMENT/MODIFICATION OF TURBOFAN ENGINE HYDROMECHANICAL FUEL CONTROL UNIT							
		CATEGORY 6						A/R
E2	<b>MOC :</b>							
SB PW500-72-30442 R2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT							
		ESGP CATEGORY 7	MTH 05-Jan-2013					Complete
			HRS 2052					
			LDG 1834					
E1	<b>MOC :</b>							
	<b>MOC : COMPLIED WITH - DURING UPGRADE/OVERHAUL OF FCU INSTALLED P/N: 1012636-17</b>							



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30442 R2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT									
		ESGP		CATEGORY 7	MTH 05-Jan-2013 HRS 1987.1 LDG 1764		-			Complete
E2	<b>MOC : COMPLIED WITH - DURING UPGRADE/OVERHAUL OF FCU INSTALLED P/N: 1012636-18</b>									
SB PW500-72-30442 R3	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT									
				CATEGORY 7			-			
E1	<b>MOC :</b>									
SB PW500-72-30442 R3	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT									
				CATEGORY 7			-			
E2	<b>MOC :</b>									
SB PW500-72-30442 E1	HYDROMECHANICAL FUEL CONTROL UNIT- REPLACEMENT/MODIFICATION OF									
				CATEGORY 6			A/R			
E1	<b>MOC :</b>									
SB PW500-72-30442 E2	HYDROMECHANICAL FUEL CONTROL UNIT- REPLACEMENT/MODIFICATION OF									
				CATEGORY 6			A/R			
E2	<b>MOC :</b>									
SB PW500-72-30446 R1	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY									
				CATEGORY 7			A/R			
E1	<b>MOC :</b>									
SB PW500-72-30446 R1	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY									
				CATEGORY 7			A/R			
E2	<b>MOC :</b>									
SB PW500-72-30446 R2	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY									
				CATEGORY 7			-			
E1	<b>MOC :</b>									
SB PW500-72-30446 R2	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY									
				CATEGORY 7			-			
E2	<b>MOC :</b>									
SB PW500-72-30447 R1	NEW COATING MODIFICATION OF GAS GENERATOR CASE									
				CATEGORY 6			-			
E1	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30447 R1 E2	NEW COATING MODIFICATION OF GAS GENERATOR CASE			CATEGORY 6			-			
<b>MOC :</b>										
SB PW500-72-30447 E1	NEW COATING MODIFICATION OF GAS GENERATOR CASE			CATEGORY 6			-			
<b>MOC :</b>										
SB PW500-72-30447 E2	NEW COATING MODIFICATION OF GAS GENERATOR CASE			CATEGORY 6			-			
<b>MOC :</b>										
SB PW500-72-30449 R1 E1	TURBOFAN ENGINE - HP TURBINE DISK ASSEMBLY - REPLACEMENT OF			CATEGORY 7			-			
<b>MOC :</b>										
SB PW500-72-30449 R1 E2	TURBOFAN ENGINE - HP TURBINE DISK ASSEMBLY - REPLACEMENT OF			CATEGORY 7			-			
<b>MOC :</b>										
SB PW500-72-30449 R2 E1	REPLACEMENT OF HP TURBINE DISK ASSEMBLY			CATEGORY 7			-			
<b>MOC :</b>										
SB PW500-72-30449 R2 E2	REPLACEMENT OF HP TURBINE DISK ASSEMBLY			CATEGORY 7			-			
<b>MOC :</b>										
SB PW500-72-30449 E1	REPLACEMENT OF HP TURBINE DISK ASSEMBLY			CATEGORY 7			A/R			
<b>MOC :</b>										
SB PW500-72-30449 E2	REPLACEMENT OF HP TURBINE DISK ASSEMBLY			CATEGORY 7			A/R			
<b>MOC :</b>										
SB PW500-72-30453 R1 E1	REPLACEMENT OF NO. 4 CARBON SEAL			CATEGORY 6			-			
<b>MOC :</b>										
SB PW500-72-30453 R1 E2	REPLACEMENT OF NO. 4 CARBON SEAL			CATEGORY 6			-			
<b>MOC :</b>										
SB PW500-72-30453 R2 E1	REPLACEMENT OF NO. 4 CARBON SEAL			CATEGORY 6			-			
<b>MOC :</b>										
SB PW500-72-30453 R2 E2	REPLACEMENT OF NO. 4 CARBON SEAL			CATEGORY 6			-			
<b>MOC :</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains	
Position	Drawing # / Task #	City Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB PW500-72-30453 E1	REPLACEMENT OF NO. 4 CARBON SEAL								
	<b>MOC :</b>		CATEGORY 6						
SB PW500-72-30453 E2	REPLACEMENT OF NO. 4 CARBON SEAL								
	<b>MOC :</b>		CATEGORY 6						
SB PW500-72-30455 R1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT								
	<b>MOC :</b>		CATEGORY 7						
E1									
SB PW500-72-30455 R1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT								
	<b>MOC :</b>		CATEGORY 7						
E2									
SB PW500-72-30455 R2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT								
	<b>MOC :</b>	ESGP	CATEGORY 7	MTH 05-Jan-2013 HRS 2052 LDG 1834				Complete	
E1									
SB PW500-72-30455 R2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT								
	<b>MOC :</b>	ESGP	CATEGORY 7	MTH 05-Jan-2013 HRS 1987.1 LDG 1764				Complete	
E2									
SB PW500-72-30455 R3	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT								
	<b>MOC :</b>		CATEGORY 7						
E1									
SB PW500-72-30455 R3	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT								
	<b>MOC :</b>		CATEGORY 7						
E2									
SB PW500-72-30455 R4	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT								
	<b>MOC :</b>		CATEGORY 7						
E1									
SB PW500-72-30455 R4	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT								
	<b>MOC :</b>		CATEGORY 7						
E2									



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB PW500-72-30455 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT	CATEGORY 6			-			
	<b>MOC :</b>							
SB PW500-72-30455 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT	CATEGORY 6			-			
	<b>MOC :</b>							
SB PW500-72-30462 R1 E1	CONVERSION OF PW545A BUILD SPECIFICATION 1156 TO 884 CONVERSION OF PW545B BUILD SPECIFICATION 1194 TO 1161	CATEGORY 8			-			
	<b>MOC :</b>							
SB PW500-72-30462 R1 E2	CONVERSION OF PW545A BUILD SPECIFICATION 1156 TO 884 CONVERSION OF PW545B BUILD SPECIFICATION 1194 TO 1161	CATEGORY 8			-			
	<b>MOC :</b>							
SB PW500-72-30462 E1	CONVERSION OF PW545A BUILD SPECIFICATION 1156 TO 884 CONVERSION OF PW545B BUILD SPECIFICATION 1194 TO 1161	CATEGORY 8			-			
	<b>MOC :</b>							
SB PW500-72-30462 E2	CONVERSION OF PW545A BUILD SPECIFICATION 1156 TO 884 CONVERSION OF PW545B BUILD SPECIFICATION 1194 TO 1161	CATEGORY 8			-			
	<b>MOC :</b>							
SB PW500-72-30463 R1 E1	REPLACEMENT OF ACCESSORY DRIVE LIP SEAL	CATEGORY 7			-			
	<b>MOC :</b>							
SB PW500-72-30463 R1 E2	REPLACEMENT OF ACCESSORY DRIVE LIP SEAL	CATEGORY 7			-			
	<b>MOC :</b>							
SB PW500-72-30463 R2 E1	REPLACEMENT OF ACCESSORY DRIVE LIP SEAL	CATEGORY 7			-			
	<b>MOC :</b>							
SB PW500-72-30463 R2 E2	REPLACEMENT OF ACCESSORY DRIVE LIP SEAL	CATEGORY 7			-			
	<b>MOC :</b>							
SB PW500-72-30463 E1	REPLACEMENT OF ACCESSORY DRIVE LIP SEAL	CATEGORY 7			-			
	<b>MOC :</b>							
SB PW500-72-30463 E2	REPLACEMENT OF ACCESSORY DRIVE LIP SEAL	CATEGORY 7			-			
	<b>MOC :</b>							



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB PW500-72-30464 E1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS	CATEGORY 7			-			
<b>MOC :</b>								
SB PW500-72-30464 E2	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS	CATEGORY 7			-			
<b>MOC :</b>								
SB PW500-72-30465 R1 E1	REPLACEMENT OF FUEL MANIFOLD TUBES	CATEGORY 7			-			
<b>MOC :</b>								
SB PW500-72-30465 R1 E2	REPLACEMENT OF FUEL MANIFOLD TUBES	CATEGORY 7			-			
<b>MOC :</b>								
SB PW500-72-30465 R2 E1	REPLACEMENT OF FUEL MANIFOLD TUBES	CATEGORY 7			-			
<b>MOC :</b>								
SB PW500-72-30465 R2 E2	REPLACEMENT OF FUEL MANIFOLD TUBES	CATEGORY 7			-			
<b>MOC :</b>								
SB PW500-72-30465 E1	REPLACEMENT OF FUEL MANIFOLD TUBES	CATEGORY 7			-			
<b>MOC :</b>								
SB PW500-72-30465 E2	REPLACEMENT OF FUEL MANIFOLD TUBES	CATEGORY 7			-			
<b>MOC :</b>								
SB PW500-72-30466 R1 E1	REPLACEMENT / MODIFICATION OF 2ND STAGE TURBINE VANE ASSY	CATEGORY 7			-			
<b>MOC :</b>								
SB PW500-72-30466 R1 E2	REPLACEMENT / MODIFICATION OF 2ND STAGE TURBINE VANE ASSY	CATEGORY 7			-			
<b>MOC :</b>								
SB PW500-72-30466 E1	REPLACEMENT OF 2ND STAGE TURBINE VANE ASSY	CATEGORY 7			-			
<b>MOC :</b>								
SB PW500-72-30466 E2	REPLACEMENT OF 2ND STAGE TURBINE VANE ASSY	CATEGORY 7			-			
<b>MOC :</b>								





# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30470 R1 E1	REPLACEMENT OF DATA COLLECTION UNIT			CATEGORY 7			-			
	<b>MOC :</b>									
SB PW500-72-30470 R1 E2	REPLACEMENT OF DATA COLLECTION UNIT			CATEGORY 7			-			
	<b>MOC :</b>									
SB PW500-72-30470 E1	REPLACEMENT OF DATA COLLECTION UNIT			CATEGORY 7			-			
	<b>MOC :</b>									
SB PW500-72-30470 E2	REPLACEMENT OF DATA COLLECTION UNIT			CATEGORY 7			-			
	<b>MOC :</b>									
SB PW500-72-30472 R1 E1	REPLACEMENT OF - N1 AND N2 SPEED SENSORS			CATEGORY 7			-			
	<b>MOC :</b>									
SB PW500-72-30472 R1 E2	REPLACEMENT OF - N1 AND N2 SPEED SENSORS			CATEGORY 7			-			
	<b>MOC :</b>									
SB PW500-72-30472 E1	REPLACEMENT OF N1 AND N2 SPEED SENSORS			CATEGORY 7			-			
	<b>MOC :</b>									
SB PW500-72-30472 E2	REPLACEMENT OF N1 AND N2 SPEED SENSORS			CATEGORY 7			-			
	<b>MOC :</b>									
SB PW500-72-30475 R2 PART A  E1	REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY //INSTALL THE FUEL CONTROL DRIVE GEARSHAFT			CATEGORY 7			-			
	<b>MOC :</b>									
SB PW500-72-30475 R2 PART A  E2	REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY //INSTALL THE FUEL CONTROL DRIVE GEARSHAFT			CATEGORY 7			-			
	<b>MOC :</b>									
SB PW500-72-30475 R2 PART B  E1	REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY //INSTALL THE ACCESSORY DRIVE GEARSHAFT			CATEGORY 7			-			
	<b>MOC :</b>									
SB PW500-72-30475 R2 PART B  E2	REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY //INSTALL THE ACCESSORY DRIVE GEARSHAFT			CATEGORY 7			-			
	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1 (ENG) DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2 (ENG) DUE 2	Remains
SB PW500-72-30475 R2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY						
		CATEGORY 7			-		
E1	<b>MOC :</b>						
SB PW500-72-30475 R2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY						
		CATEGORY 7			-		
E2	<b>MOC :</b>						
SB PW500-72-30475 R3 PART A	ACCOMPLISH REMOVE AND INSTALL FUEL CONTROL DRIVE GEARSHAFT						
		CATEGORY 7			-		
E1	<b>MOC :</b>						
SB PW500-72-30475 R3 PART A	ACCOMPLISH REMOVE AND INSTALL FUEL CONTROL DRIVE GEARSHAFT						
		CATEGORY 7			-		
E2	<b>MOC :</b>						
SB PW500-72-30475 R3 PART B	ACCOMPLISH REMOVE AND INSTALL THE ACCESSORY DRIVE GEARSHAFT						
		CATEGORY 7			-		
E1	<b>MOC :</b>						
SB PW500-72-30475 R3 PART B	ACCOMPLISH REMOVE AND INSTALL THE ACCESSORY DRIVE GEARSHAFT						
		CATEGORY 7			-		
E2	<b>MOC :</b>						
SB PW500-72-30475 R3	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY						
		CATEGORY 7			-		
E1	<b>MOC :</b>						
SB PW500-72-30475 R3	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY						
		CATEGORY 7			-		
E2	<b>MOC :</b>						
SB PW500-72-30479 R1	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE						
		CATEGORY 5			-		
E1	<b>MOC :</b>						



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30479 R1	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE									
				CATEGORY 5						-
E2	<b>MOC :</b>									
SB PW500-72-30479 R2	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE									
				CATEGORY 5						-
E1	<b>MOC :</b>									
SB PW500-72-30479 R2	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE									
				CATEGORY 5						-
E2	<b>MOC :</b>									
SB PW500-72-30479 R3	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE									
				CATEGORY 5						-
E1	<b>MOC :</b>									
SB PW500-72-30479 R3	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE									
				CATEGORY 5						-
E2	<b>MOC :</b>									
SB PW500-72-30479 R4	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE									
				CATEGORY 5						-
E1	<b>MOC :</b>									
SB PW500-72-30479 R4	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE									
				CATEGORY 5						-
E2	<b>MOC :</b>									
SB PW500-72-30479 R5	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE									
				CATEGORY 5						-
E1	<b>MOC :</b>									
SB PW500-72-30479 R5	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE									
				CATEGORY 5						-
E2	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30479 R6	REPLACEMENT OF NO. 4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE			CATEGORY 3	MTH HRS		DUE DUE		(5045.3)5110.2	1737.7
E1	<b>MOC :</b>									
SB PW500-72-30479 R6	REPLACEMENT OF NO. 4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE			CATEGORY 3	MTH HRS		DUE DUE		(5045.3)5045.3	1672.8
E2	<b>MOC :</b>									
SB PW500-72-30479 E1	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE			CATEGORY 6			-			
E1	<b>MOC :</b>									
SB PW500-72-30479 E2	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE			CATEGORY 6			-			
E2	<b>MOC :</b>									
SB PW500-72-30482 R1	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT	ESGP		CATEGORY 3	MTH 21-Feb-2014 HRS 2450.4 LDG 2225		-			N/A
E1	<b>MOC :</b> NOT APPLICABLE - BORESCOPE REVEALS NO NUTS TO INSPECT, SB IS ONLY APPLICABLE IF SB 30419 IS PERFORMED. UNABLE TO FIND ANY REFERENCES IN CESCOM OF SB 30419 HAVE BEEN PERFORMED									
SB PW500-72-30482 R1	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT	ESGP		CATEGORY 3	MTH 21-Feb-2014 HRS 2385.5 LDG 2155		-			N/A
E2	<b>MOC :</b> NOT APPLICABLE - BORESCOPE REVEALS NO NUTS TO INSPECT, SB IS ONLY APPLICABLE IF SB 30419 IS PERFORMED. UNABLE TO FIND ANY REFERENCES IN CESCOM OF SB 30419 HAVE BEEN PERFORMED									
SB PW500-72-30482 R2	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT			CATEGORY 3			-			
E1	<b>MOC :</b>									
SB PW500-72-30482 R2	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT			CATEGORY 3			-			
E2	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30482 R3	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT (SUPERSEDED BY SB PW500-72-30492 R2)			CATEGORY 10						-
E1	<b>MOC :</b>									
SB PW500-72-30482 R3	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT (SUPERSEDED BY SB PW500-72-30492 R2)			CATEGORY 10						-
E2	<b>MOC :</b>									
SB PW500-72-30482 E1	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT			CATEGORY 3						-
E1	<b>MOC :</b>									
SB PW500-72-30482 E2	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT			CATEGORY 3						-
E2	<b>MOC :</b>									
SB PW500-72-30483 R1	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY			CATEGORY 7						-
E1	<b>MOC :</b>									
SB PW500-72-30483 R1	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY			CATEGORY 7						-
E2	<b>MOC :</b>									
SB PW500-72-30483 R2	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY			CATEGORY 7						-
E1	<b>MOC :</b>									
SB PW500-72-30483 R2	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY			CATEGORY 7						-
E2	<b>MOC :</b>									
SB PW500-72-30483 R3	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY (SUPERSEDED BY SB PW500-72-30492 R2)			CATEGORY 10						-
E1	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30483 R3	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY (SUPERSEDED BY SB PW500-72-30492 R2)									
				CATEGORY 10			-			
E2	<b>MOC :</b>									
SB PW500-72-30483 E1	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY			CATEGORY 7			-			
	<b>MOC :</b>									
SB PW500-72-30483 E2	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY			CATEGORY 7			-			
	<b>MOC :</b>									
SB PW500-72-30485 R1 E1	REPLACEMENT OF REAR OUTER BY-PASS DUCT HARDWARE			CATEGORY 7			-			
	<b>MOC :</b>									
SB PW500-72-30485 R1 E2	REPLACEMENT OF REAR OUTER BY-PASS DUCT HARDWARE			CATEGORY 7			-			
	<b>MOC :</b>									
SB PW500-72-30486 R1 E1	REPLACEMENT OF BREATHER ADAPTER PREFORMED PACKING			CATEGORY 7			-			
	<b>MOC :</b>									
SB PW500-72-30486 R1 E2	REPLACEMENT OF BREATHER ADAPTER PREFORMED PACKING			CATEGORY 7			-			
	<b>MOC :</b>									
SB PW500-72-30486 R2	REPLACEMENT OF BREATHER ADAPTER PREFORMED PACKING.			CATEGORY 7			-			
E1	<b>MOC :</b>									
SB PW500-72-30486 R2	REPLACEMENT OF BREATHER ADAPTER PREFORMED PACKING.			CATEGORY 7			-			
E2	<b>MOC :</b>									
SB PW500-72-30486 E1	REPLACEMENT OF BREATHER ADAPTER PREFORMED PACKING			CATEGORY 7			-			
	<b>MOC :</b>									
SB PW500-72-30486 E2	REPLACEMENT OF BREATHER ADAPTER PREFORMED PACKING			CATEGORY 7			-			
	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30487 R3	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE LIP SEAL (SUPERSEDED BY SB PW500-72-30502)									
				CATEGORY 10						
E1	<b>MOC :</b>									
SB PW500-72-30487 R3	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE LIP SEAL (SUPERSEDED BY SB PW500-72-30502)									
				CATEGORY 10						
E2	<b>MOC :</b>									
SB PW500-72-30487 E1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE LIP SEAL									
E1	<b>MOC :</b>									
SB PW500-72-30487 E2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE LIP SEAL									
E2	<b>MOC :</b>									
SB PW500-72-30491 R1	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY									
				CATEGORY 7						
E1	<b>MOC :</b>									
SB PW500-72-30491 R1	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY									
				CATEGORY 7						
E2	<b>MOC :</b>									
SB PW500-72-30491 R2	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY									
				CATEGORY 7						
E1	<b>MOC :</b>									
SB PW500-72-30491 R2	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY									
				CATEGORY 7						
E2	<b>MOC :</b>									
SB PW500-72-30491 E1	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY									
				CATEGORY 7						
E1	<b>MOC :</b>									
SB PW500-72-30491 E2	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY									
				CATEGORY 7						
E2	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB PW500-72-30492 R1	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER							
		CATEGORY 7						-
E1	<b>MOC :</b>							
SB PW500-72-30492 R1	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER							
		CATEGORY 7						-
E2	<b>MOC :</b>							
SB PW500-72-30492 R2	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER							
		CATEGORY 7						-
E1	<b>MOC :</b>							
SB PW500-72-30492 R2	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER							
		CATEGORY 7						-
E2	<b>MOC :</b>							
SB PW500-72-30492 R3	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER							
		CATEGORY 6						-
E1	<b>MOC :</b>							
SB PW500-72-30492 R3	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER							
		CATEGORY 6						-
E2	<b>MOC :</b>							
SB PW500-72-30492 R4	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER							
		CATEGORY 6						-
E1	<b>MOC :</b>							
SB PW500-72-30492 R4	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER							
		CATEGORY 6						-
E2	<b>MOC :</b>							
SB PW500-72-30492 E1	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER							
		CATEGORY 7						-
E1	<b>MOC :</b>							





# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB PW500-72-30492 E2	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER	CATEGORY 7			-			
<b>MOC :</b>								
SB PW500-72-30495 R1	MODIFICATION OF ACCESSORY GEARBOX COVER BOLT TORQUING PROCEDURE	CATEGORY 10			-			
<b>MOC :</b>								
E1								
SB PW500-72-30495 R1	MODIFICATION OF ACCESSORY GEARBOX COVER BOLT TORQUING PROCEDURE	CATEGORY 10			-			
<b>MOC :</b>								
E2								
SB PW500-72-30495 E1	MODIFICATION OF ACCESSORY GEARBOX COVER BOLT TORQUING PROCEDURE (SUPERSEDED BY SB PW500-72-30498)	CATEGORY 10			-			
<b>MOC :</b>								
SB PW500-72-30495 E2	MODIFICATION OF ACCESSORY GEARBOX COVER BOLT TORQUING PROCEDURE (SUPERSEDED BY SB PW500-72-30498)	CATEGORY 10			-			
<b>MOC :</b>								
SB PW500-72-30496 E1	REPLACEMENT/MODIFICATION OF SECOND STAGE TURBINE VANE	CATEGORY 6			-			
<b>MOC :</b>								
SB PW500-72-30496 E2	REPLACEMENT/MODIFICATION OF SECOND STAGE TURBINE VANE	CATEGORY 6			-			
<b>MOC :</b>								
SB PW500-72-30498 R1	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY	CATEGORY 7			-			
<b>MOC :</b>								
E1								
SB PW500-72-30498 R1	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY	CATEGORY 7			-			
<b>MOC :</b>								
E2								
SB PW500-72-30498 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY	CATEGORY 7			-			
<b>MOC :</b>								
SB PW500-72-30498 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY	CATEGORY 7			-			
<b>MOC :</b>								



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB PW500-72-30502 R1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL							
		CATEGORY 7						-
E1	<b>MOC :</b>							
SB PW500-72-30502 R1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL							
		CATEGORY 7						-
E2	<b>MOC :</b>							
SB PW500-72-30502 R2 PART A E1	ACCOMPLISH FUEL CONTROL GEARSHAFT SEAL							
		CATEGORY 7						-
E1	<b>MOC :</b>							
SB PW500-72-30502 R2 PART A E2	ACCOMPLISH FUEL CONTROL GEARSHAFT SEAL							
		CATEGORY 7						-
E2	<b>MOC :</b>							
SB PW500-72-30502 R2 PART B E1	ACCOMPLISH ACCESSORY GEARSHAFT SEAL							
		CATEGORY 7						-
E1	<b>MOC :</b>							
SB PW500-72-30502 R2 PART B E2	ACCOMPLISH ACCESSORY GEARSHAFT SEAL							
		CATEGORY 7						-
E2	<b>MOC :</b>							
SB PW500-72-30502 R2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL							
		CATEGORY 7						-
E1	<b>MOC :</b>							
SB PW500-72-30502 R2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL							
		CATEGORY 7						-
E2	<b>MOC :</b>							
SB PW500-72-30502 R3 PART A E1	ACCOMPLISH REPLACE FUEL CONTROL GEARSHAFT SEAL							
		CATEGORY 7						-
E1	<b>MOC :</b>							
SB PW500-72-30502 R3 PART A E2	ACCOMPLISH REPLACE FUEL CONTROL GEARSHAFT SEAL							
		CATEGORY 7						-
E2	<b>MOC :</b>							
SB PW500-72-30502 R3 PART B E1	ACCOMPLISH REPLACE ACCESSORY GEARSHAFT SEAL							
		CATEGORY 7						-
E1	<b>MOC :</b>							



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30502 R3 PART B E2	ACCOMPLISH REPLACE ACCESSORY GEARSHAFT SEAL			CATEGORY 7			-			
<b>MOC :</b>										
SB PW500-72-30502 R3	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL			CATEGORY 7			-			
<b>MOC :</b>										
SB PW500-72-30502 R3	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL			CATEGORY 7			-			
<b>MOC :</b>										
SB PW500-72-30502 R4 PART A E1	ACCOMPLISH FUEL CONTROL GEARSHAFT SEAL			CATEGORY 7			-			
<b>MOC :</b>										
SB PW500-72-30502 R4 PART A E2	ACCOMPLISH FUEL CONTROL GEARSHAFT SEAL			CATEGORY 7			-			
<b>MOC :</b>										
SB PW500-72-30502 R4 PART B E1	ACCOMPLISH ACCESSORY GEARSHAFT SEAL			CATEGORY 7			-			
<b>MOC :</b>										
SB PW500-72-30502 R4 PART B E2	ACCOMPLISH ACCESSORY GEARSHAFT SEAL			CATEGORY 7			-			
<b>MOC :</b>										
SB PW500-72-30502 R4	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL			CATEGORY 7			-			
<b>MOC :</b>										
SB PW500-72-30502 R4	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL			CATEGORY 7			-			
<b>MOC :</b>										
SB PW500-72-30502 E1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL			CATEGORY 7			-			
<b>MOC :</b>										
SB PW500-72-30502 E2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL			CATEGORY 7			-			
<b>MOC :</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30504 R1 E1	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER			CATEGORY 7			-			
<b>MOC :</b>										
SB PW500-72-30504 R1 E2	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER			CATEGORY 7			-			
<b>MOC :</b>										
SB PW500-72-30504 R2 E1	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER			CATEGORY 7			-			
<b>MOC :</b>										
SB PW500-72-30504 R2 E2	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER			CATEGORY 7			-			
<b>MOC :</b>										
SB PW500-72-30504 E1	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER			CATEGORY 7			-			
<b>MOC :</b>										
SB PW500-72-30504 E2	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER			CATEGORY 7			-			
<b>MOC :</b>										
SB PW500-72-30505 R1 E1	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS			CATEGORY 3	MTH 17-Mar-2015 HRS 2870.2 LDG 2619		-			Complete
<b>MOC : COMPLIED WITH - PERFORMED OK</b>										
SB PW500-72-30505 R1 E2	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS			CATEGORY 3	MTH 17-Mar-2015 HRS 2805.3 LDG 2549		-			Complete
<b>MOC : COMPLIED WITH - PERFORMED OK</b>										
SB PW500-72-30505 R2 E1	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS			CATEGORY 3			-			
<b>MOC :</b>										
SB PW500-72-30505 R2 E2	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS			CATEGORY 3			-			
<b>MOC :</b>										
SB PW500-72-30505 E1	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS			CATEGORY 3			-			
<b>MOC :</b>										
SB PW500-72-30505 E2	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS			CATEGORY 3			-			
<b>MOC :</b>										
SB PW500-72-30506 R1 E1	REPLACEMENT OF FUEL MANIFOLD ADAPTERS			CATEGORY 7			-			
<b>MOC :</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30506 R1 E2	REPLACEMENT OF FUEL MANIFOLD ADAPTERS			CATEGORY 7			-			
	<b>MOC :</b>									
SB PW500-72-30506 R2 E1	REPLACEMENT OF FUEL MANIFOLD ADAPTERS			CATEGORY 7			-			
	<b>MOC :</b>									
SB PW500-72-30506 R2 E2	REPLACEMENT OF FUEL MANIFOLD ADAPTERS			CATEGORY 7			-			
	<b>MOC :</b>									
SB PW500-72-30506 E1	REPLACEMENT OF FUEL MANIFOLD ADAPTERS			CATEGORY 7			-			
	<b>MOC :</b>									
SB PW500-72-30506 E2	REPLACEMENT OF FUEL MANIFOLD ADAPTERS			CATEGORY 7			-			
	<b>MOC :</b>									
SB PW500-72-30507 E1	MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY			CATEGORY 8			-			
	<b>MOC :</b>									
SB PW500-72-30507 E2	MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY			CATEGORY 8			-			
	<b>MOC :</b>									
SB PW500-72-30508 R1 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS			CATEGORY 7			-			
	<b>MOC :</b>									
SB PW500-72-30508 R1 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS			CATEGORY 7			-			
	<b>MOC :</b>									
SB PW500-72-30508 R2 E1	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS			CATEGORY 7			-			
	<b>MOC :</b>									
SB PW500-72-30508 R2 E2	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS			CATEGORY 7			-			
	<b>MOC :</b>									
SB PW500-72-30508 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS			CATEGORY 7			-			
	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB PW500-72-30508 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS	CATEGORY 7			-			
<b>MOC :</b>								
SB PW500-72-30511 R1 E1	RE-TORQUEING OF AGB COVER BOLTS OR NUTS	CATEGORY 6			-			
<b>MOC :</b>								
SB PW500-72-30511 R1 E2	RE-TORQUEING OF AGB COVER BOLTS OR NUTS	CATEGORY 6			-			
<b>MOC :</b>								
SB PW500-72-30511 E1	RE-TORQUEING OF AGB COVER BOLTS OR NUTS	CATEGORY 6			-			
<b>MOC :</b>								
SB PW500-72-30511 E2	RE-TORQUEING OF AGB COVER BOLTS OR NUTS	CATEGORY 6			-			
<b>MOC :</b>								
SB PW500-72-30512 R1	INSPECTION/REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL	CATEGORY 3			-			
<b>MOC :</b>								
E1								
SB PW500-72-30512 R1	INSPECTION/REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL	CATEGORY 3			-			
<b>MOC :</b>								
E2								
SB PW500-72-30512 R2	INSPECTION/ REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL	CATEGORY 3	MTH HRS		12 600		11-Dec-2015 {34.28}3399.18	-13 m 22 d 26.68
<b>MOC :</b>								
E1								<b>Over Due</b>
SB PW500-72-30512 R2	INSPECTION/ REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL	CATEGORY 3	MTH HRS		12 600		11-Dec-2015 {34.28}3334.28	-13 m 22 d -38.22
<b>MOC :</b>								
E2								<b>Over Due</b>
SB PW500-72-30512 E1	INSPECTION/REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL	CATEGORY 3			-			
<b>MOC :</b>								
SB PW500-72-30512 E2	INSPECTION/REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL	CATEGORY 3			-			
<b>MOC :</b>								



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB PW500-72-30516 R1 E1	REPLACEMENT OF HP TURBINE SEAL RINGS	CATEGORY 7			-			
	<b>MOC :</b>							
SB PW500-72-30516 R1 E2	REPLACEMENT OF HP TURBINE SEAL RINGS	CATEGORY 7			-			
	<b>MOC :</b>							
SB PW500-72-30516 R2 E1	REPLACEMENT OF HP TURBINE SEAL RINGS	CATEGORY 7			-			
	<b>MOC :</b>							
SB PW500-72-30516 R2 E2	REPLACEMENT OF HP TURBINE SEAL RINGS	CATEGORY 7			-			
	<b>MOC :</b>							
SB PW500-72-30517 R1 E1	DELETION OF IGNITER FLANGE GASKETS	CATEGORY 6			-			
	<b>MOC :</b>							
SB PW500-72-30517 R1 E2	DELETION OF IGNITER FLANGE GASKETS	CATEGORY 6			-			
	<b>MOC :</b>							
SB PW500-72-30517 E1	DELETION OF IGNITER FLANGE GASKETS	CATEGORY 6			-			
	<b>MOC :</b>							
SB PW500-72-30517 E2	DELETION OF IGNITER FLANGE GASKETS	CATEGORY 6			-			
	<b>MOC :</b>							
SB PW500-72-30521 R1 E1	REPLACEMENT OF COMBUSTION CHAMBER LINER	CATEGORY 7			-			
	<b>MOC :</b>							
SB PW500-72-30521 R1 E2	REPLACEMENT OF COMBUSTION CHAMBER LINER	CATEGORY 7			-			
	<b>MOC :</b>							
SB PW500-72-30523 R1 E1	REPLACEMENT OF ACCESSORY GEARBOX COVER GASKET	CATEGORY 7			-			
	<b>MOC :</b>							
SB PW500-72-30523 R1 E2	REPLACEMENT OF ACCESSORY GEARBOX COVER GASKET	CATEGORY 7			-			
	<b>MOC :</b>							
SB PW500-72-30523 E1	REPLACEMENT OF ACCESSORY GEARBOX COVER GASKET	CATEGORY 7			-			
	<b>MOC :</b>							



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30523 E2	REPLACEMENT OF ACCESSORY GEARBOX COVER GASKET			CATEGORY 7			-			
	<b>MOC :</b>									
SB PW500-72-30526 E1	MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 6			-			
	<b>MOC :</b>									
SB PW500-72-30526 E2	MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 6			-			
	<b>MOC :</b>									
SB PW500-72-30527 E1	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 9			-			
	<b>MOC :</b>									
SB PW500-72-30527 E2	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 9			-			
	<b>MOC :</b>									
ASB PW500-72-A30421 R2	INSPECTION/REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE			CATEGORY 3			-			
E1	<b>MOC :</b>									
ASB PW500-72-A30421 R2	INSPECTION/REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE			CATEGORY 3			-			
E2	<b>MOC :</b>									
ASB PW500-72-A30452 R1	TURBOFAN ENGINE - OIL SYSTEM - SPECIAL INSPECTION OF MOP			CATEGORY 3	MTH		-			
E1	<b>MOC :</b>									
ASB PW500-72-A30452 R1	TURBOFAN ENGINE - OIL SYSTEM - SPECIAL INSPECTION OF MOP			CATEGORY 3	MTH		-			
E2	<b>MOC :</b>									
ASB PW500-72-A30452 R2	SPECIAL INSPECTION OF MOP OIL SYSTEM (CANCELLED)			CATEGORY 10			-			
	<b>MOC :</b>									
ASB PW500-72-A30452 R2	SPECIAL INSPECTION OF MOP OIL SYSTEM (CANCELLED)			CATEGORY 10			-			
	<b>MOC :</b>									





# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
ASB PW500-72-A30452	TURBOFAN ENGINE OIL SYSTEM - SPECIAL INSPECTION OF MOP			CATEGORY 3			-			
E1	<b>MOC :</b>									
ASB PW500-72-A30452	TURBOFAN ENGINE OIL SYSTEM - SPECIAL INSPECTION OF MOP			CATEGORY 3			-			
E2	<b>MOC :</b>									
SL 560XL-73-12 R1	TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW500-72-30381R2, FUEL MANIFOLD AND FUEL SHUT-OFF CABLE GROMMETS AND COVER PLATE/FAIRING/REPLACEMENT OF			RECOMMENDED			A/R			
	<b>MOC :</b>									
SL 560XL-73-12	TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW500-72-30381R2, FUEL MANIFOLD AND FUEL SHUT-OFF CABLE GROMMETS AND COVERPLATE/FAIRING/REPLACEMENT OF	ESGP		RECOMMENDED	MTH 23-May-2011 HRS 1370 LDG 1222		A/R			Complete
73SL-12 : XL	<b>MOC : COMPLIED WITH</b>									
SB PW500-72-30337 E2	TURBOFAN ENGINE- REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL	ESGP		CATEGORY 8	MTH 05-Jan-2013 HRS 1987.1 LDG 1764		-			Complete
	<b>MOC : COMPLIED WITH - PERFORMED DURING UPGRADE/OVERHAUL OF FCU INSTALLED P/N: 1012636-18E</b>									
SB PW500-72-30343 R5	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR-BLEED-VALVE			CATEGORY 7			A/R			
E1	<b>MOC :</b>									
SB PW500-72-30343 R5	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR-BLEED-VALVE			CATEGORY 7			A/R			
E2	<b>MOC :</b>									
SB PW500-72-30404 R3	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE			CATEGORY 7			A/R			
E1	<b>MOC :</b>									
SB PW500-72-30404 R3	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE			CATEGORY 7			A/R			
E2	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB PW500-72-30414 E1	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE			CATEGORY 10			A/R			
<b>MOC :</b>										
SB PW500-72-30414 E2	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE			CATEGORY 10			A/R			
<b>MOC :</b>										
ASB PW500-72-A30421 R1	INSPECTION/REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE			CATEGORY 3	MTH 03-Nov-2010 HRS 1251.9 LDG 1123		-			N/A
E1	<b>MOC : NOT APPLICABLE - NOT APPLICABLE DUE TO BOV ABOVE 250FH</b>									
ASB PW500-72-A30421 R1	INSPECTION/REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE			CATEGORY 3	MTH 03-Nov-2010 HRS 1187 LDG 1053		-			N/A
E2	<b>MOC : NOT APPLICABLE - NOT APPLICABLE DUE TO BOV ABOVE 250FH</b>									
ASB PW500-72-A30421	INSPECTION/REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE			CATEGORY 3			-			
E1	<b>MOC : - PLEASE NOTIFY YOUR ANALYST OF ANY REQUIREMENT OR DUE TIME CHANGES THAT ARE REQUIRED BASED ON SERVICE BULLETIN APPLICABILITY.</b>									
ASB PW500-72-A30421	INSPECTION/REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE			CATEGORY 3			-			
E2	<b>MOC : - PLEASE NOTIFY YOUR ANALYST OF ANY REQUIREMENT OR DUE TIME CHANGES THAT ARE REQUIRED BASED ON SERVICE BULLETIN APPLICABILITY.</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2013-09-11 (G)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM INSPECTION FOR PART NUMBER (P/N)			MANDATORY						
<b>MOC :</b>										
FAA 2013-09-11 (H)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM INSPECTION A/C COMPRESSOR HOUR METER AND MAINTENANCE RECORDS			MANDATORY						
<b>MOC :</b>										
FAA 2013-09-11 (I) & (J)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM REPLACEMENT OF A/C COMPRESSOR MOTOR BRUSHES AND RELATED MAINTENANCE MANUAL INFORMATION			MANDATORY						
<b>MOC :</b>										
FAA 2013-09-11 (K)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM DEACTIVATION OF A/C SYSTEM			MANDATORY			A/R			
<b>MOC :</b>										
FAA 2013-09-11 (L)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM REACTIVATION OF A/C SYSTEM			MANDATORY			A/R			
<b>MOC :</b>										
FAA 2013-09-11 (M)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM PARTS RETURN AND REPORTING REQUIREMENTS			MANDATORY						
<b>MOC :</b>										
FAA 2013-09-11	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM			MANDATORY						
<b>MOC :</b>										
EASA 2014-0088 (1)	REMOVE THE TEAM CVR P/N AP71232101 OR P/N AP71231101, AS APPLICABLE, FROM THE AIRCRAFT AND, DEPENDING ON OPERATIONAL REGULATIONS, INSTALL A SERVICEABLE CVR IN ACCORDANCE WITH APPROVED AIRCRAFT MODIFICATION INSTRUCTIONS	ESGP		MANDATORY	MTH 14-Mar-2016 HRS 3113.1 LDG 2859					N/A
<b>MOC : NOT APPLICABLE - N/A AS EQUIPMENT NOT INSTALLED</b>										
EASA 2014-0088 (2)	DO NOT INSTALL ON ANY AIRCRAFT A TEAM CVR P/N AP71232101 OR P/N AP71231101, AS REQUIRED BY PARAGRAPH (2.1) OR (2.2) OF THIS AD, AS APPLICABLE	ESGP		MANDATORY	MTH 14-Mar-2016 HRS 3113.1 LDG 2859					N/A
<b>MOC : NOT APPLICABLE - N/A AS EQUIPMENT NOT INSTALLED</b>										



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
EASA 2014-0088	APPLIANCE AD - COMMUNICATIONS - COCKPIT VOICE RECORDER - REPLACEMENT	ESGP		MANDATORY	MTH 14-Mar-2016 HRS 3113.1 LDG 2859		-			N/A
	<b>MOC : NOT APPLICABLE - N/A AS EQUIPMENT NOT INSTALLED</b>									
FAA 2006-19-04 34AD-14 : XL	APPLIANCE AD - HONEYWELL RCZ COMM & XPDRS	SGP		MANDATORY	MTH 13-Dec-2006 HRS 170		A/R			N/A
	<b>MOC : NOT APPLICABLE - NOT APPLICABLE</b>									
EASA 2013-0020 (1)	INSPECT EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT THE MARKINGS OF SAFETY BELTS AND/OR TORSO RESTRAINT SYSTEMS, TO DETERMINE IF THEY HAVE BEEN MAINTAINED OR REPAIRED BY ORGANISATIONS OTHER THAN THE DESIGN APPROVAL HOLDER			MANDATORY			-			
	<b>MOC :</b>									
EASA 2013-0020 (2)	VERIFY EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT IF THE ORGANISATION IS LISTED AMONG THE AUTHORIZED MAINTENANCE OR REPAIR ORGANISATION REFERENCE DOCUMENTS QUOTED IN THE REF. PUBLICATIONS SECTION OF THIS AD			MANDATORY	MTH		-			
	<b>MOC :</b>									
EASA 2013-0020 (3)	REMOVE EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT AND REPLACE BELTS NOT MEETING THE CERTIFICATION REQUIREMENTS OR MAKE RELEVANT SEAT INOPERATIVE			MANDATORY	MTH		-			
	<b>MOC :</b>									
EASA 2013-0020 R1 (1)	EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT INSPECT THE MARKINGS OF SAFETY BELTS AND/OR TORSO RESTRAINT SYSTEMS, TO DETERMINE IF THEY HAVE BEEN MAINTAINED OR REPAIRED BY ORGANISATIONS OTHER THAN THE DESIGN APPROVAL HOLDER	ESGP		MANDATORY	MTH 09-Jul-2013 HRS 2168.3 LDG 1941		-			Complete
	<b>MOC : COMPLIED WITH - ORIGINAL SEATBELTS INSTALLED - NO FURTHER ACTION REQUIRED</b>									
EASA 2013-0020 R1 (2)	EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT VERIFY IF THE ORGANISATION IS LISTED AMONG THE AUTHORIZED MAINTENANCE OR REPAIR ORGANISATION REFERENCE DOCUMENTS QUOTED IN THE REF. PUBLICATIONS SECTION OF THIS AD			MANDATORY			-			
	<b>MOC :</b>									
EASA 2013-0020 R1 (3)	EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT REMOVE AND REPLACE BELTS NOT MEETING THE CERTIFICATION REQUIREMENTS OR MAKE RELEVANT SEAT INOPERATIVE			MANDATORY			-			
	<b>MOC :</b>									
EASA 2013-0020 R1 (4)	EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT AFTER 14 FEBRUARY 2013 [THE EFFECTIVE DATE OF THE ORIGINAL ISSUE OF THIS AD], DO NOT INSTALL SAFETY BELTS OR TORSO RESTRAINT SYSTEMS ON ANY AIRCRAFT, UNLESS INSPECTED AND CORRECTED IN COMPLIANCE WITH THE REQUIREMENTS OF THIS AD.	ESGP		MANDATORY	MTH 09-Jul-2013 HRS 2168.3 LDG 1941		-			Complete
	<b>MOC : COMPLIED WITH - ORIGINAL SEATBELTS INSTALLED - NO FURTHER ACTION REQUIRED</b>									



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
EASA 2013-0020 R1	APPLIANCE AD - EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT	ESGP		MANDATORY	MTH 09-Jul-2013 HRS 2168.3 LDG 1941		-			Complete
<b>MOC : COMPLIED WITH - ORIGINAL SEATBELTS INSTALLED - NO FURTHER ACTION REQUIRED</b>										
EASA 2013-0020 R2 (1)	EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT INSPECT THE MARKINGS OF SAFETY BELTS AND/OR TORSO RESTRAINT SYSTEMS, TO DETERMINE IF THEY HAVE BEEN MAINTAINED OR REPAIRED BY ORGANISATIONS OTHER THAN THE DESIGN APPROVAL HOLDER			MANDATORY			-			
<b>MOC :</b>										
EASA 2013-0020 R2 (2)	EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT VERIFY IF THE ORGANISATION IS LISTED AMONG THE AUTHORIZED MAINTENANCE OR REPAIR ORGANISATION REFERENCE DOCUMENTS QUOTED IN THE REF. PUBLICATIONS SECTION OF THIS AD			MANDATORY			-			
<b>MOC :</b>										
EASA 2013-0020 R2 (3)	EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT REMOVE AND REPLACE BELTS NOT MEETING THE CERTIFICATION REQUIREMENTS OR MAKE RELEVANT SEAT INOPERATIVE			MANDATORY			-			
<b>MOC :</b>										
EASA 2013-0020 R2 (4)	EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT AFTER 14 FEBRUARY 2013 [THE EFFECTIVE DATE OF THE ORIGINAL ISSUE OF THIS AD], DO NOT INSTALL SAFETY BELTS OR TORSO RESTRAINT SYSTEMS ON ANY AIRCRAFT, UNLESS INSPECTED AND CORRECTED IN COMPLIANCE WITH THE REQUIREMENTS OF THIS AD			MANDATORY	MTH		-			
<b>MOC :</b>										
EASA 2013-0020 R2	APPLIANCE AD - EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT			MANDATORY	MTH		-			
<b>MOC :</b>										
EASA 2013-0020 R3 (1)	INSPECT THE MARKINGS OF SAFETY BELTS AND/OR TORSO RESTRAINT SYSTEMS, TO DETERMINE IF THEY HAVE BEEN MAINTAINED OR REPAIRED BY ORGANISATIONS OTHER THAN THE DESIGN APPROVAL HOLDER			MANDATORY	MTH		-			
<b>MOC :</b>										
EASA 2013-0020 R3 (2)	VERIFY IF THE ORGANISATION IS LISTED AMONG THE AUTHORIZED MAINTENANCE OR REPAIR ORGANISATION REFERENCE DOCUMENTS QUOTED IN THE REF. PUBLICATIONS SECTION OF THIS AD			MANDATORY	MTH		-			
<b>MOC :</b>										
EASA 2013-0020 R3 (3)	REMOVE AND REPLACE BELTS NOT MEETING THE CERTIFICATION REQUIREMENTS OR MAKE RELEVANT SEAT INOPERATIVE			MANDATORY	MTH		-			
<b>MOC :</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
EASA 2013-0020 R3 (4)	AFTER 14 FEBRUARY 2013 [THE EFFECTIVE DATE OF THE ORIGINAL ISSUE OF THIS AD], DO NOT INSTALL SAFETY BELTS OR TORSO RESTRAINT SYSTEMS ON ANY AIRCRAFT, UNLESS INSPECTED AND CORRECTED IN COMPLIANCE WITH THE REQUIREMENTS OF THIS AD			MANDATORY						
<b>MOC :</b>										
EASA 2013-0020 R3	APPLIANCE AD - EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT			MANDATORY						
<b>MOC :</b>										
EASA 2013-0020 R4 (1)	INSPECT THE MARKINGS OF SAFETY BELTS AND/OR TORSO RESTRAINT SYSTEMS, TO DETERMINE IF THEY HAVE BEEN MAINTAINED OR REPAIRED BY ORGANISATIONS OTHER THAN THE DESIGN APPROVAL HOLDER	ESGP		MANDATORY	MTH 19-Sep-2014 HRS 2628.1 LDG 2360					N/A
<b>MOC : NOT APPLICABLE - NOT APPLICABLE AS SEATBELTS HAS NOT BEEN REPAIRED</b>										
EASA 2013-0020 R4 (2)	VERIFY IF THE ORGANISATION IS LISTED AMONG THE AUTHORIZED MAINTENANCE OR REPAIR ORGANISATION REFERENCE DOCUMENTS QUOTED IN THE REF. PUBLICATIONS SECTION OF THIS AD	ESGP		MANDATORY	MTH 19-Sep-2014 HRS 2628.1 LDG 2360					N/A
<b>MOC : NOT APPLICABLE - NOT APPLICABLE AS SEATBELTS HAS NOT BEEN REPAIRED</b>										
EASA 2013-0020 R4 (3)	REMOVE AND REPLACE BELTS NOT MEETING THE CERTIFICATION REQUIREMENTS OR MAKE RELEVANT SEAT INOPERATIVE	ESGP		MANDATORY	MTH 19-Sep-2014 HRS 2628.1 LDG 2360					N/A
<b>MOC : NOT APPLICABLE - NOT APPLICABLE AS SEATBELTS HAS NOT BEEN REPAIRED</b>										
EASA 2013-0020 R4 (4)	AFTER 14 FEBRUARY 2013 [THE EFFECTIVE DATE OF THE ORIGINAL ISSUE OF THIS AD], DO NOT INSTALL SAFETY BELTS OR TORSO RESTRAINT SYSTEMS ON ANY AIRCRAFT, UNLESS INSPECTED AND CORRECTED IN COMPLIANCE WITH THE REQUIREMENTS OF THIS AD	ESGP		MANDATORY	MTH 19-Sep-2014 HRS 2628.1 LDG 2360					N/A
<b>MOC : NOT APPLICABLE - NOT APPLICABLE AS SEATBELTS HAS NOT BEEN REPAIRED</b>										
EASA 2013-0020 R4	APPLIANCE AD - EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT	ESGP		MANDATORY	MTH 19-Sep-2014 HRS 2628.1 LDG 2360					N/A
<b>MOC : NOT APPLICABLE - NOT APPLICABLE AS SEATBELTS HAS NOT BEEN REPAIRED</b>										
EASA 2013-0020	APPLIANCE AD - EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT			MANDATORY						
<b>MOC :</b>										
EASA 2014-0019 (1)	AMEND THE AFM OF THE AFFECTED AIRCRAFT			MANDATORY	DAYS					
<b>MOC :</b>										
EASA 2014-0019 (2)	REPLACE THE SYSTEM INTERFACE UNIT P/N 503-24-() OR 503-42-()			MANDATORY	MTH					
<b>MOC :</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
EASA 2014-0019 (3)	DO NOT INSTALL A HR SMITH (TECHNICAL DEVELOPMENTS) CPI SYSTEM SERIES 15-503-134 OR 15-503-134-1 EQUIPPED WITH CONTROL PANEL P/N 503-22-(), BEACON RELEASE UNIT P/N 503-21 AND SYSTEM INTERFACE UNIT P/N 503-24-() OR P/N 503-42-(), EXCLUDING SYSTEM INTERFACE UNIT P/N 503-24-A, OR 503-24-()-A, OR 503-24-G, OR 503-24-()-G, OR 503-42-A OR 503-42-()-A OR 503-42-G OR 503-42-()-G, ON AN AIRCRAFT, UNLESS IN COMPLIANCE WITH THE REQUIREMENTS OF THIS AD			MANDATORY						-
	<b>MOC :</b>									
EASA 2014-0019 (4)	REMOVE AFM AMENDMENT AND PLACARD AS REQUIRED BY PARAGRAPH (1) OF THIS AD			MANDATORY						-
	<b>MOC :</b>									
EASA 2014-0019	APPLIANCE AD - EQUIPMENT / FURNISHINGS - CRASH POSITION INDICATOR - MODIFICATION AIRCRAFT FLIGHT MANUAL - AMENDMENT (SUPERSEDED BY EASA 2014-0095)			MANDATORY						-
	<b>MOC :</b>									
EASA 2014-0095 (1)	INSTALL A PLACARD "DO NOT USE TRANSMIT OVER WATER" NEXT TO THE CPI CONTROL PANEL/AMEND THE AFM OF THE AIRCRAFT			MANDATORY	DAYS					-
	<b>MOC :</b>									
EASA 2014-0095 (2)	INCORPORATION OF APPENDIX A OF THIS AD INTO THE EMERGENCY PROCEDURESECTION OF THE AFM OF THE AIRCRAFT IS AN ACCEPTABLE METHOD TO COMPLY WITHTHE REQUIREMENT OF PARAGRAPH (1.2) OF THIS AD			MANDATORY						-
	<b>MOC :</b>									
EASA 2014-0095 (3)	REPLACE THE SYSTEM INTERFACE UNIT P/N 503-24-() (INCLUDING503-24) OR P/N 503-42-() (INCLUDING 503-42) WITH AN IMPROVED PART P/N503-24-A, OR P/N 503-24-()-A, OR P/N 503-24-G, OR P/N 503-24-()-G, OR P/N503-42-A OR P/N 503-42-()-A OR P/N 503-42-G OR P/N 503-42-()-G (THATINCORPORATES AUTOMATIC CPI DEPLOYMENT AFTER MANUAL ACTIVATION) INACCORDANCE WITH AN APPROVED AIRCRAFT MAINTENANCE INSTRUCTION			MANDATORY	MTH					-
	<b>MOC :</b>									
EASA 2014-0095 (4)	DO NOT INSTALL A HR SMITH (TECHNICAL DEVELOPMENTS) CPI SYSTEM SERIES 15-503-134OR 15-503-134-1 EQUIPPED WITH CONTROL PANEL P/N 503-22-(), BEACON RELEASE UNIT P/N 503-21 AND SYSTEM INTERFACE UNIT P/N 503-24-() (INCLUDING 503-24) OR P/N 503-42-() (INCLUDING 503-42) EXCLUDING SYSTEM INTERFACE UNIT P/N 503-24-A OR P/N 503-24-()-A OR P/N 503-24-G OR P/N 503-24-()-G OR P/N 503-42-A OR P/N 503-42-()-A OR P/N 503-42-G OR P/N 503-42-()-G ON AN AIRCRAFT UNLESS IN COMPLIANCE WITH THE REQUIREMENTS OF THIS AD			MANDATORY						-
	<b>MOC :</b>									
EASA 2014-0095 (5)	REMOVE THE AFM AMENDMENT AND PLACARD AS REQUIRED BY PARAGRAPH (1) OF THIS AD			MANDATORY						-
	<b>MOC :</b>									
EASA 2014-0095 R1 (1)	INSTALL A PLACARD "DO NOT USE TRANSMIT OVER WATER" NEXT TO THE CPI CONTROL PANEL/AMEND THE AFM OF THE AIRCRAFT			MANDATORY	MTH					-
	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
EASA 2014-0095 R1 (2)	INCORPORATION OF APPENDIX A OF THIS AD INTO THE EMERGENCY PROCEDURES SECTION OF THE AFM OF THE AIRCRAFT IS AN ACCEPTABLE METHOD TO COMPLY WITH THE REQUIREMENT OF PARAGRAPH (1.2) OF THIS AD			MANDATORY						-
<b>MOC :</b>										
EASA 2014-0095 R1 (3)	REPLACE THE SYSTEM INTERFACE UNIT P/N 503-24-() (INCLUDING 503-24) OR P/N 503-42-() (INCLUDING 503-42) WITH AN IMPROVED PART P/N 503-24-A, OR P/N 503-24-()-A, OR P/N 503-24-G, OR P/N 503-24-()-G, OR P/N 503-42-A OR P/N 503-42-()-A OR P/N 503-42-G OR P/N 503-42-()-G (THAT INCORPORATES AUTOMATIC CPI DEPLOYMENT AFTER MANUAL ACTIVATION) IN ACCORDANCE WITH AN APPROVED AIRCRAFT MAINTENANCE INSTRUCTION			MANDATORY	MTH		24			
<b>MOC :</b>										
EASA 2014-0095 R1 (4)	DO NOT INSTALL A HR SMITH (TECHNICAL DEVELOPMENTS) CPI SYSTEM SERIES 15-503-134 OR 15-503-134-1 EQUIPPED WITH CONTROL PANEL P/N 503-22-(), BEACON RELEASE UNIT P/N 503-21 AND SYSTEM INTERFACE UNIT P/N 503-24-() (INCLUDING 503-24) OR P/N 503-42-() (INCLUDING 503-42) EXCLUDING SYSTEM INTERFACE UNIT P/N 503-24-A OR P/N 503-24-()-A OR P/N 503-24-G OR P/N 503-24-()-G OR P/N 503-42-A OR P/N 503-42-()-A OR P/N 503-42-G OR P/N 503-42-()-G ON AN AIRCRAFT UNLESS IN COMPLIANCE WITH THE REQUIREMENTS OF THIS AD			MANDATORY						-
<b>MOC :</b>										
EASA 2014-0095 R1 (5)	REMOVE THE AFM AMENDMENT AND PLACARD AS REQUIRED BY PARAGRAPH (1) OF THIS AD			MANDATORY						-
<b>MOC :</b>										
EASA 2014-0095 R1	APPLIANCE AD - EQUIPMENT / FURNISHINGS - CRASH POSITION INDICATOR - MODIFICATION AIRCRAFT FLIGHT MANUAL - AMENDMENT			MANDATORY						-
<b>MOC :</b>										
EASA 2014-0095	APPLIANCE AD - EQUIPMENT / FURNISHINGS - CRASH POSITION INDICATOR - MODIFICATION AIRCRAFT FLIGHT MANUAL - AMENDMENT			MANDATORY						-
<b>MOC :</b>										
EASA 2014-0125 (1)	AMEND THE AFM OF AFFECTED AIRCRAFT TO INCORPORATE TEMPORARY CPI SIU OPERATING PROCEDURES BY INSERTING A COPY OF APPENDIX 1 OF THIS AD (OR ITS TEXT) INTO THE APPLICABLE NORMAL PROCEDURES SECTION OF THE AFM			MANDATORY						-
<b>MOC :</b>										
EASA 2014-0125 (2)	ACCOMPLISH THE COMPLETE START-UP PROCEDURE/APPLICABLE START-UP PROCEDURE/SHUTDOWN PROCEDURE			MANDATORY						-
<b>MOC :</b>										
EASA 2014-0125 (3)	COMPLIANCE WITH THE REQUIREMENTS OF PARAGRAPH (2) OF THIS AD			MANDATORY						-
<b>MOC :</b>										





# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
EASA 2014-0125 (4)	REPLACE THE CPI SIU HAVING P/N 503-24 OR P/N 503-24-2 OR P/N 503-24-6 WITH AN IMPROVED UNIT P/N 503-24G OR P/N 503-24-2G OR P/N 503-24-6G IN ACCORDANCE WITH THE APPLICABLE AIRCRAFT DESIGN APPROVAL HOLDER SERVICE INSTRUCTIONS AND, CONCURRENTLY, REMOVE THE TEMPORARY AFM PROCEDURE AS REQUIRED BY PARAGRAPH (2) OF THIS AD			MANDATORY			-			
<b>MOC :</b>										
EASA 2014-0125 (5)	MODIFICATION OF AN AIRCRAFT AS REQUIRED BY PARAGRAPH (4) OF THIS AD CONSTITUTES TERMINATING ACTION FOR ACCOMPLISHMENT OF THE PROCEDURES AS REQUIRED BY PARAGRAPH (2) OF THIS AD			MANDATORY			-			
<b>MOC :</b>										
EASA 2014-0125 (6)	FROM THE EFFECTIVE DATE OF THIS AD, INSTALLATION ON AN AIRCRAFT OF AN HR SMITH (TECHNICAL DEVELOPMENTS) CPI SYSTEM SERIES 15-503-134-1 EQUIPPED WITH BRU P/N 503-21-1 AND SIU P/N 503-24 OR P/N 503-24-2 OR P/N 503-24-6 IS ALLOWED, PROVIDED THE AIRCRAFT IS OPERATED IN COMPLIANCE WITH THE PROCEDURES AS REQUIRED BY THIS AD			MANDATORY			-			
<b>MOC :</b>										
EASA 2014-0125 (7)	AFTER REPLACEMENT OF THE CPI SIU ON AN AIRCRAFT AS REQUIRED BY PARAGRAPH (4) OF THIS AD, DO NOT INSTALL AN SIU P/N 503-24 OR P/N 503-24-2 OR P/N 503-24-6 ON THE CPI SYSTEM OF THAT AIRCRAFT			MANDATORY			-			
<b>MOC :</b>										
EASA 2014-0125	APPLIANCE AD - EQUIPMENT / FURNISHINGS - CRASH POSITION INDICATOR SYSTEM - REPLACEMENT; AIRCRAFT FLIGHT MANUAL - AMENDMENT			MANDATORY	MTH		-			
<b>MOC :</b>										
EASA 2014-0187	APPLIANCE AD - EQUIPMENT & FURNISHINGS ? SAFETY BELT ATTACHMENT BOLTS ? INSPECTION / REPLACEMENT			MANDATORY			-			
<b>MOC :</b>										
EASA 2014-0279 (1)	INSPECT THE LABEL OF THE ROTARY BUCKLE SUB-ASSEMBLY TO DETERMINE ITS PART NUMBER (P/N) AND SERIAL NUMBER (S/N)			MANDATORY	MTH 23-Jan-2015 HRS 2767 LDG 2503		-			N/A
<b>MOC : NOT APPLICABLE</b>										
EASA 2014-0279 (1.1)	REPLACE THE ROTARY BUCKLE SUB-ASSEMBLY WITH A SERVICEABLE PART			MANDATORY	MTH 23-Jan-2015 HRS 2767 LDG 2503		-			N/A
<b>MOC : NOT APPLICABLE</b>										
EASA 2014-0279 (1.2)	MARK THE SEAT AS ?INOPERATIVE? UNTIL REPLACEMENT OF THE ROTARY BUCKLE SUB-ASSEMBLY AS REQUIRED BY PARAGRAPH (2) OF THIS AD			MANDATORY	MTH 23-Jan-2015 HRS 2767 LDG 2503		-			N/A
<b>MOC : NOT APPLICABLE</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
EASA 2014-0279 (2)	REPLACE EACH ROTARY BUCKLE SUB-ASSEMBLY HAVING A P/N AND S/N AS SPECIFIED IN ROMTEX ANJOU AERONAUTIQUE SB 358SB-14-101 WITH A SERVICEABLE PART			MANDATORY	MTH 23-Jan-2015 HRS 2767 LDG 2503	-				N/A
<b>MOC : NOT APPLICABLE</b>										
EASA 2014-0279 (3)	DO NOT INSTALL:- ON ANY RESTRAINT SYSTEM A SPARE ROTARY BUCKLE SUB-ASSEMBLY, OR- ON ANY AIRCRAFT A RESTRAINT SYSTEM EQUIPPED WITH A ROTARY BUCKLESUB-ASSEMBLY HAVING A P/N AND A S/N LISTED IN ROMTEX ANJOU AERONAUTIQUE SB 358SB-14-101, UNLESS THE SUB-ASSEMBLY HAS BEEN REPAIRED,			MANDATORY	MTH 23-Jan-2015 HRS 2767 LDG 2503	-				N/A
<b>MOC : NOT APPLICABLE</b>										
EASA 2014-0279	APPLIANCE AD - EQUIPMENT / FURNISHING - RESTRAINT SYSTEM ROTARY BUCKLE SUBASSEMBLY - IDENTIFICATION / REPLACEMENT			MANDATORY	MTH 23-Jan-2015 HRS 2767 LDG 2503	-				N/A
<b>MOC : NOT APPLICABLE</b>										
FAA 1974-08-09 R2 053801	LAVATORY PAPER OR LINEN WASTE RECEPACLE FIRE PREVENTION ESGP			MANDATORY	MTH 07-May-2010 HRS 1008.7 LDG 891	-				Complete
<b>MOC : COMPLIED WITH</b>										
FAA 1974-08-09 R3	LAVATORY PAPER OR LINEN WASTE RECEPACLE FIRE PREVENTION ESGP			MANDATORY	MTH 24-Aug-2015 HRS 2964.8 LDG 2709	-				N/A
<b>MOC : NOT APPLICABLE - N/A EASA AIRCRAFT</b>										
FAA 1998-25-10 REV1 25AD-01 : XLR1	APPLIANCE AD - AIRCRAFT BELT INSPECTION ICT			MANDATORY	MTH 07-Jun-2006 HRS 9	-				N/A
<b>MOC : NOT APPLICABLE - NOT APPLICABLE</b>										
EASA 2009-0251-E	APPLIANCE/EMERGENCY AD - PORTABLE HALON 1211 FIRE EXTINGUISHERS ESGP			MANDATORY	DAYS 27-Nov-2009 HRS 884.8 LDG 777		A/R			N/A
<b>MOC : NOT APPLICABLE - AIRWORTHINESS DIRECTIVE NOT APPLICABLE DUE TO AFFECTED TYPE NOT INSTALLED</b>										
EASA 2016-0024 PARA (1)	INSPECT EACH SIEMENS SMOKE DETECTOR TO DETERMINE WHETHER IT IS AN AFFECTED PART GSE			MANDATORY	MTH 29-Mar-2016 HRS 3132.9 LDG 2877	-				N/A
<b>MOC : NOT APPLICABLE - EQUIPMENT NOT INSTALLED</b>										
EASA 2016-0024 PARA (2.1)	REPLACE CARGO COMPARTMENT SMOKE DETECTORS, IDENTIFIED IN PARAGRAPH (1), IN ACCORDANCE WITH TABLE 1 OR TABLE 2 GSE			MANDATORY	MTH 29-Mar-2016 HRS 3132.9 LDG 2877	-				N/A
<b>MOC : NOT APPLICABLE - EQUIPMENT NOT INSTALLED</b>										



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 (ENG) TSO 2 (ENG)	DUE 1 DUE 2	Remains Remains
EASA 2016-0024 PARA (2.2)	REPLACE PASSENGER, CABIN OR ANY OTHER ON BOARD LOCATION SMOKE DETECTORS, IDENTIFIED IN PARAGRAPH (1), IN ACCORDANCE WITH TABLE 3	GSE		MANDATORY	MTH 29-Mar-2016 HRS 3132.9 LDG 2877	-				N/A
<b>MOC : NOT APPLICABLE - EQUIPMENT NOT INSTALLED</b>										
EASA 2016-0024 PARA (2.3)	REPLACE REPAIRED SMOKE DETECTOR IDENTIFIED IN APPENDIX 1	GSE		MANDATORY	MTH 29-Mar-2016 HRS 3132.9 LDG 2877	-				N/A
<b>MOC : NOT APPLICABLE - EQUIPMENT NOT INSTALLED</b>										
EASA 2016-0024 PARA (3)	FROM THE EFFECTIVE DATE OF THIS AD, DO NOT INSTALL ON ANY AEROPLANE AN AFFECTED P/N SMOKE DETECTOR UNLESS THE UNIT (GMC ONLY) IS MARKED 'SIL PMC-26-002'	GSE		MANDATORY	MTH 29-Mar-2016 HRS 3132.9 LDG 2877	-				N/A
<b>MOC : NOT APPLICABLE - EQUIPMENT NOT INSTALLED</b>										
EASA 2016-0024	APPLIANCE AD - FIRE PROTECTION - OPTICAL AND AMBIENT SMOKE DETECTORS - IDENTIFICATION / REPLACEMENT	GSE		MANDATORY	MTH 29-Mar-2016 HRS 3132.9 LDG 2877	-				N/A
<b>MOC : NOT APPLICABLE - EQUIPMENT NOT INSTALLED</b>										
EASA 2016-0044 PARA (1)	INSPECT EACH FIRE EXTINGUISHER, EXCEPT THOSE HAVING P/N 57333 SERIES, INSTALLED ON BAE146 AND RJ AEROPLANES, AND THOSE HAVING P/N57183 SERIES, INSTALLED ON ATP AEROPLANES, AND DEPENDING ON FINDINGS, ACCOMPLISH CORRECTIVE ACTIONS IN ACCORDANCE WITH THE INSTRUCTIONS OF KG SB 26-080 REVISION 1	GSE		MANDATORY	MTH 29-Mar-2016 HRS 3132.9 LDG 2877	-				N/A
<b>MOC : NOT APPLICABLE - N/A DUE EQUIPMENT NOT INSTALLED</b>										
EASA 2016-0044 PARA (2)	ACCOMPLISHMENT OF AN OVERHAUL (SEE NOTE 2 OF THIS AD) OF A FIRE EXTINGUISHER BY KIDDE GRAVINER OR HUGEN, OR IN ACCORDANCE WITH THE INSTRUCTIONS OF KG SIL 01-10 OR IN ACCORDANCE WITH KG CMM 26-21-40 REVISION 14 OR LATER OR KG CMM 26-21-52 REVISION 13 OR LATER (AS APPLICABLE TO FIRE EXTINGUISHER P/N) IS ACCEPTABLE TO COMPLY WITH THE REQUIREMENT OF PARAGRAPH (1).	GSE		MANDATORY	MTH 29-Mar-2016 HRS 3132.9 LDG 2877	-				N/A
<b>MOC : NOT APPLICABLE - N/A DUE EQUIPMENT NOT INSTALLED</b>										
EASA 2016-0044 PARA (3)	FROM THE EFFECTIVE DATE OF THIS AD DO NOT INSTALL ON ANY AIRCRAFT AN AFFECTED FIRE EXTINGUISHER, UNLESS IT IS NEW, OR HAS PASSED AN INSPECTION IN ACCORDANCE WITH THE INSTRUCTIONS OF KG SB 26-080 REVISION 1, OR IT HAS BEEN OVERHAULED (SEE NOTE 2) BY KG, OR BY HUGEN OR IN ACCORDANCE WITH THE INSTRUCTIONS OF KG SIL 01-10 OR IN ACCORDANCE WITH THE INSTRUCTIONS OF KG CMM 26-21-40 REVISION 14, OR OF KG CMM 26-21-52 REVISION 13, AS APPLICABLE TO FIRE EXTINGUISHER P/N	GSE		MANDATORY	MTH 29-Mar-2016 HRS 3132.9 LDG 2877	-				N/A
<b>MOC : NOT APPLICABLE - N/A DUE EQUIPMENT NOT INSTALLED</b>										
EASA 2016-0044	APPLIANCE AD - ATA 26 - FIRE PROTECTION - ENGINE AND AUXILIARY POWER UNIT AUTOMATIC FIRE EXTINGUISHERS - INSPECTION/OVERHAUL	GSE		MANDATORY	MTH 29-Mar-2016 HRS 3132.9 LDG 2877	-				N/A
<b>MOC : NOT APPLICABLE - N/A DUE EQUIPMENT NOT INSTALLED</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 (ENG) TSO 2 (ENG)	DUE 1 DUE 2	Remains Remains
FAA 2006-04-10 26AD-03 : XL	INSTALLING IDENTIFICATION SLEEVES ON THE WIRES FOR THE POSITIVE AND NEGATIVE STUDS OF THE ENGINE AND/ OR (APU) FIRE EXTINGUISHING BOTTLES, AS APPLICABLE, AND RECONNECTING THE WIRES TO THE CORRECT TERMINAL STUDS.	ICT		MANDATORY	MTH 07-Jun-2006 HRS 9		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
FAA 2000-15-51 27AD-01 : XL	AILERON CABLE FAIRLEAD TUBE AND AILERON CABLE SECTOR	ICT		MANDATORY	MTH 07-Jun-2006 HRS 9		-			Complete
<b>MOC : COMPLIED WITH</b>										
FAA 2012-09-01	LANDING GEAR - TORQUE LUG - INSPECTION	ESGP		MANDATORY	MTH 09-Jul-2013 HRS 2168.3 LDG 1941		-			Complete
<b>MOC : COMPLIED WITH - ON BOTH MAIN WHEELS INSTALLED S/N: 1461 AND 3476</b>										
FAA 1995-22-01 33AD-01 : XL	APPLIANCE AD - AEROSPACE LIGHTING POWER UNIT	ICT		MANDATORY	MTH 07-Jun-2006 HRS 9		A/R			N/A
<b>MOC : NOT APPLICABLE - NOT APPLICABLE</b>										
EASA 2010-0003 R2 (1)	VERIFY AIRCRAFT TYPE MODE STRAPPING CODE S SET TO `0? (ZERO) OR `1?, AS DEFINED IN ROCKWELL-COLLINS SERVICE LETTER TDR-94( ) SIL 07-2.			MANDATORY			-			
<b>MOC :</b>										
EASA 2010-0003 R2 (2)	EXEMPTIONS: DASSAULT AEROPLANES			MANDATORY			-			
<b>MOC :</b>										
EASA 2010-0003 R2 (3)	EXEMPTIONS: ATR 42 AND ATR 72 AEROPLANES			MANDATORY			-			
<b>MOC :</b>										
EASA 2010-0003 R2 (4)	EXEMPTIONS: SAAB 2000 AEROPLANES			MANDATORY			-			
<b>MOC :</b>										
EASA 2010-0003 R2 (5)	EXEMPTIONS: BOMBARDIER AEROSPACE (CANADAIR) AEROPLANES: CL-600-2B16 (604 VARIANT) AND CL-600-2B19 (RJ100 AND RJ200)			MANDATORY			-			
<b>MOC :</b>										
EASA 2010-0003 R2 (6)	EXEMPTIONS: CESSNA AIRCRAFT COMPANY AEROPLANES: CESSNA MODEL 525, 525A, 525B; AND CESSNA MODEL 525, 525A, 525B, 560; 560XL			MANDATORY			-			
<b>MOC :</b>										
EASA 2010-0003 R2 (7)	EXEMPTIONS: PIAGGIO AERO INDUSTRIES AEROPLANES: P.180 (AVANTI) AND P.180 (AVANTI II)			MANDATORY			-			
<b>MOC :</b>										
EASA 2010-0003 R2	APPLIANCE AD - NAVIGATION - MODE S TRANSPONDER AIRCRAFT TYPE MODE STRAPPING - CHECK / MODIFICATION	ESGP		MANDATORY	MTH 31-Oct-2014 HRS 2686.9 LDG 2416		-			N/A
<b>MOC : NOT APPLICABLE - AD NOT APPLICABLE DUE TO EQUIPMENT NOT INSTALLED.</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
EASA 2015-0093 PARA (1)	AMEND THE AFM OF THE AIRCRAFT BY INSERTING A TEMPORARY REVISION (TR) TO THE AFM (SUPPLEMENT)									
		ESGP		MANDATORY	DAYS 24-Aug-2015 HRS 2964.8 LDG 2709		-			N/A
	<b>MOC : NOT APPLICABLE - N/A ITEM NOT INSTALLED</b>									
EASA 2015-0093 PARA (2)	MODIFY THE AIRCRAFT BY REPLACING EACH AHRS UNIT HAVING A P/N SPECIFIED AS 'OLD?' IN TABLE 2 OF THIS AD WITH A MODIFIED UNIT, HAVING A P/N SPECIFIED AS 'NEW?' IN TABLE 2 OF THIS AD									
		ESGP		MANDATORY	MTH 24-Aug-2015 HRS 2964.8 LDG 2709		-			N/A
	<b>MOC : NOT APPLICABLE - N/A ITEM NOT INSTALLED</b>									
EASA 2015-0093 PARA (3)	CONCURRENT WITH MODIFICATION OF AN AIRCRAFT AS REQUIRED BY PARAGRAPH (2) OF THIS AD, THE AFM CHANGE, IF REQUIRED BY PARAGRAPH (1) OF THIS AD (SEE NOTE 1 OF THIS AD), CAN BE REMOVED FROM THAT AIRCRAFT									
		ESGP		MANDATORY	MTH 24-Aug-2015 HRS 2964.8 LDG 2709		-			N/A
	<b>MOC : NOT APPLICABLE - N/A ITEM NOT INSTALLED</b>									
EASA 2015-0093 PARA (4)	DO NOT INSTALL ON ANY AIRCRAFT A LCR-100 AHRS UNIT, HAVING A P/N SPECIFIED AS 'OLD?' IN TABLE 1 OF THIS AD									
		ESGP		MANDATORY	MTH 24-Aug-2015 HRS 2964.8 LDG 2709		-			N/A
	<b>MOC : NOT APPLICABLE - N/A ITEM NOT INSTALLED</b>									
EASA 2015-0093	APPLIANCE AD - NAVIGATION ATTITUDE HEADING REFERENCE SYSTEM MODIFICATION / REPLACEMENT									
		ESGP		MANDATORY	MTH 24-Aug-2015 HRS 2964.8 LDG 2709		-			N/A
	<b>MOC : NOT APPLICABLE - N/A ITEM NOT INSTALLED</b>									
FAA 1997-05-03 R1 34AD-07 : XLR1	APPLIANCE AD - GNX-XLS AND GNS-XL GPS									
		ICT		MANDATORY	MTH 07-Jun-2006 HRS 9			A/R		N/A
	<b>MOC : NOT APPLICABLE - NOT APPLICABLE</b>									
FAA 2001-23-17 34AD-09 : XL	APPLIANCE AD - GARMIN INTERNATIONAL GNS 430									
		ICT		MANDATORY	MTH 07-Jun-2006 HRS 9			A/R		N/A
	<b>MOC : NOT APPLICABLE - NOT APPLICABLE</b>									
FAA 2003-04-06 34AD-03 : XL	APPLIANCE AD - HONEYWELL PRIMUS RNZ-850/851 NM									
		ICT		SUPERSEDED	MTH 07-Jun-2006 HRS 9			A/R		N/A
	<b>MOC : NOT APPLICABLE - NOT APPLICABLE</b>									
FAA 2006-16-18 34AD-13 : XL	APPLIANCE AD - SANDEL AVI MOD ST3400 TAWS/RM									
		SGP		MANDATORY	MTH 13-Dec-2006 HRS 170			A/R		N/A
	<b>MOC : NOT APPLICABLE - NOT APPLICABLE</b>									
FAA 2006-22-05 34AD-15 : XL	APPLIANCE AD - HONEYWELL PRIMUS RNZ-850/851 NM									
				MANDATORY	MTH 09-Jul-2008 HRS 748			A/R		Complete
	<b>MOC : COMPLIED WITH</b>									
FAA 2010-07-02	PERFORM A ONE-TIME GENERAL VISUAL INSPECTION OF THE MODIFICATION PLATE FOR THE HONEYWELL PRIMUS II NV-850 NAVIGATION RECEIVER MODULE (NRM)									
		ESGP		MANDATORY	MTH 25-Jul-2014 HRS 2545.3 LDG 2299			A/R		Complete
	<b>MOC : COMPLIED WITH - PERFORMED OK. NO ACTION NEEDED, UNITS MEETS REQUIRED MOD STATUS</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2012-02-08	APPLIANCE AD - AVIATION COMMUNICATION AND SURVEILLANCE SYSTEMS (ACSS) TRAFFICALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) UNITS	ESGP		MANDATORY	MTH 17-Mar-2015 HRS 2805.3 LDG 2549	-				Complete
<b>MOC : COMPLIED WITH</b>										
FAA 2012-26-15 (G) (1)	REMOVE IDENTIFY OUT OF SPEC AIR DATA COMPUTERS (ADC), AIRDATA MODULES (ADM), AIR DATA ATTITUDE HEADING REFERENCE SYSTEMS (ADAHRS) AND DIGITAL AIR DATA COMPUTERS (DADC) AFFECTED ADC, ADM, ADAHRS, OR DADC	ESGP		MANDATORY	DAYS 08-May-2013 HRS 2095.8 LDG 1878	-				Complete
<b>MOC : COMPLIED WITH - INSTALLED S/N NO AFFECTED ACCORDING TO HONEYWELL SERVICE BULLETIN ADM/ADC/ADAHRS?34?A01</b>										
FAA 2012-26-15 (G) (2)	PERFORM IDENTIFY OUT OF SPEC AIR DATA COMPUTERS (ADC), AIRDATA MODULES (ADM), AIR DATA ATTITUDE HEADING REFERENCE SYSTEMS (ADAHRS) AND DIGITAL AIR DATA COMPUTERS (DADC) PITOT-STATIC CERTIFICATION TEST	ESGP			DAYS 08-May-2013 HRS 2095.8 LDG 1878	-				Complete
<b>MOC : COMPLIED WITH - INSTALLED S/N NO AFFECTED ACCORDING TO HONEYWELL SERVICE BULLETIN ADM/ADC/ADAHRS?34?A01</b>										
FAA 2012-26-15 R1	APPLIANCE AD - AIR DATA PRESSURE TRANSDUCERS, AS INSTALLED IN AIR DATA COMPUTERS (ADC), AIR DATA MODULES (ADM), AIR DATA ATTITUDE HEADING REFERENCE SYSTEMS (ADAHRS), AND DIGITAL AIR DATA COMPUTERS (DADC)			MANDATORY	MTH	-				
<b>MOC :</b>										
FAA 2012-26-15	APPLIANCE AD - IDENTIFY OUT OF SPEC AIR DATA COMPUTERS (ADC), AIRDATA MODULES (ADM), AIR DATA ATTITUDE HEADING REFERENCE SYSTEMS (ADAHRS) AND DIGITAL AIR DATA COMPUTERS (DADC) (RESCINDED BY FAA 2012-26-15 R1)	ESGP		MANDATORY	MTH 08-May-2013 HRS 2095.8 LDG 1878	-				Complete
<b>MOC : COMPLIED WITH - INSTALLED S/N NO AFFECTED ACCORDING TO HONEYWELL SERVICE BULLETIN ADM/ADC/ADAHRS?34?A01</b>										
FAA 2014-05-27	APPLIANCE AD - ROCKWELL COLLINS, INC. TPR-720 AND TPR-900 MODE S TRANSPONDERS - TEST AND CALIBRATION	GSE		MANDATORY	MTH 29-Mar-2016 HRS 3132.9 LDG 2877	-				N/A
<b>MOC : NOT APPLICABLE - EQUIPMENT NOT INSTALLED</b>										
FAA 2014-18-01	NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION	ESGP		MANDATORY	MTH 19-Sep-2014 HRS 2628.1 LDG 2360	-				N/A
<b>MOC : NOT APPLICABLE - NOT APPLICABLE DUE TO EQUIPMENT NOT INSTALLED</b>										
FAA 2015-10-51-E	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.	ESGP		MANDATORY	MTH 24-Aug-2015 HRS 2964.8 LDG 2709	-				N/A
<b>MOC : NOT APPLICABLE - N/A ITEM NOT INSTALLED</b>										
FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS			MANDATORY		-				
<b>MOC :</b>										



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
EASA 2012-0254 (1)	INSPECT/CHECK OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR - IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT OXYGEN MASK REGULATOR TO IDENTIFY THE P/N AND S/N	ESGP		MANDATORY	DAYS 21-Aug-2014 HRS 2577.5 LDG 2311	-				N/A
<b>MOC : NOT APPLICABLE - NOT APPLICABLE DUE S/N INSTALLED 2013-01-13</b>										
EASA 2012-0254 (2.1)	REPLACE OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR - IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT AFFECTED OXYGEN MASK REGULATOR	ESGP		MANDATORY	MTH 21-Aug-2014 HRS 2577.5 LDG 2311	-				N/A
<b>MOC : NOT APPLICABLE - NOT APPLICABLE DUE S/N INSTALLED 2013-01-13</b>										
EASA 2012-0254 (2.2)	AMEND OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR - IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT AIRCRAFT FLIGHT MANUAL (AFM)	ESGP		MANDATORY	MTH 21-Aug-2014 HRS 2577.5 LDG 2311	-				N/A
<b>MOC : NOT APPLICABLE - NOT APPLICABLE DUE S/N INSTALLED 2013-01-13</b>										
EASA 2012-0254 (3)	REPLACE OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR - IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT EACH AFFECTED FLIGHT CREW OXYGEN MASK REGULATOR WITH A SERVICEABLE PART	ESGP		MANDATORY	MTH 21-Aug-2014 HRS 2577.5 LDG 2311	-				N/A
<b>MOC : NOT APPLICABLE - NOT APPLICABLE DUE S/N INSTALLED 2013-01-13</b>										
EASA 2012-0254 R1 (1)	INSPECT OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR - IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT EACH FLIGHT CREW OXYGEN MASK REGULATOR TO IDENTIFY THE P/N AND S/N	ESGP		MANDATORY	DAYS 21-Aug-2014 HRS 2577.5 LDG 2311	-				N/A
<b>MOC : NOT APPLICABLE - NOT APPLICABLE DUE S/N INSTALLED 2013-01-13</b>										
EASA 2012-0254 R1 (2.1)	REPLACE OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR - IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT EACH AFFECTED FLIGHT CREW OXYGEN MASK REGULATOR WITH A SERVICEABLE PART	ESGP		MANDATORY	DAYS 21-Aug-2014 HRS 2577.5 LDG 2311	-				N/A
<b>MOC : NOT APPLICABLE - NOT APPLICABLE DUE S/N INSTALLED 2013-01-13</b>										
EASA 2012-0254 R1 (2.2)	AMEND OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR - IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT THE AIRCRAFT FLIGHT MANUAL (AFM) AND INSTALL A PLACARD	ESGP		MANDATORY	DAYS 21-Aug-2014 HRS 2577.5 LDG 2311	-				N/A
<b>MOC : NOT APPLICABLE - NOT APPLICABLE DUE S/N INSTALLED 2013-01-13</b>										
EASA 2012-0254 R1 (3)	REPLACE OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR - IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT EACH AFFECTED FLIGHT CREW OXYGEN MASK REGULATOR	ESGP		MANDATORY	MTH 21-Aug-2014 HRS 2577.5 LDG 2311	-				N/A
<b>MOC : NOT APPLICABLE - NOT APPLICABLE DUE S/N INSTALLED 2013-01-13</b>										
EASA 2012-0254 R1	APPLIANCE AD - OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR - IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT	ESGP		MANDATORY	MTH 21-Aug-2014 HRS 2577.5 LDG 2311	-				N/A
<b>MOC : NOT APPLICABLE - NOT APPLICABLE DUE S/N INSTALLED 2013-01-13</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
EASA 2012-0254	APPLIANCE AD - OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT	ESGP		MANDATORY	MTH 21-Aug-2014 HRS 2577.5 LDG 2311	-				N/A
<b>MOC : NOT APPLICABLE - NOT APPLICABLE DUE S/N INSTALLED 2013-01-13</b>										
EASA 2014-0142 (1)	ACCOMPLISH ACCOMPLISH THE ACTIONS AS SPECIFIED IN PARAGRAPHS (1.1) AND (1.2) OF THIS AD - DETERMINE THE DATE OF MANUFACTURING / REPLACE THE HARNESS INFLATION HOSE P/N 445952 WITH A SERVICEABLE PART, OR REMOVE THE INFLATABLE HARNESS FROM THE MASK REGULATOR AND REPLACE IT WITH A SERVICEABLE HARNESS			MANDATORY	MTH	-				
<b>MOC :</b>										
EASA 2014-0142 (2)	ACCOMPLISH AN OXYGEN MASK REGULATOR EQUIPPED WITH A P/N MXH21-1 INFLATABLE HARNESS HAVING A DMF CODE OF NOVEMBER 2008 (0845-S OR 08/45-S) OR EARLIER, AND THOSE WITH A DMF OF JANUARY 2011 (1101-S OR 11/01-S) OR LATER, IS EXCLUDED FROM THE INSPECTION AND REPLACEMENT REQUIREMENTS OF PARAGRAPH (1) OF THIS AD			MANDATORY		-				
<b>MOC :</b>										
EASA 2014-0142 (3)	ACCOMPLISH IT IS ALLOWED TO INSTALL ON AN AEROPLANE A FLIGHT CREW OXYGEN MASK REGULATOR, HAVING A P/N AS IDENTIFIED IN SECTION 1.A.(1) OF ZODIAC AEROTECHNICS SB MC10-35-274, PROVIDED IT HAS BEEN DETERMINED THAT A P/N MXH21-31 INFLATABLE HARNESS IS INSTALLED, OR THAT THE P/N MXH21-1 INFLATABLE HARNESS INSTALLED ON THAT FLIGHT CREW OXYGEN MASK REGULATOR HAS BEEN CORRECTED, AS REQUIRED BY THIS AD.			MANDATORY		-				
<b>MOC :</b>										
EASA 2014-0142 R1 (1)	ACCOMPLISH ACCOMPLISH THE ACTIONS AS SPECIFIED IN PARAGRAPHS (1.1) AND (1.2) OF THIS AD - DETERMINE THE DATE OF MANUFACTURING / REPLACE THE HARNESS INFLATION HOSE P/N 445186 OR P/N 445952, AS APPLICABLE, WITH A SERVICEABLE PART, OR REMOVE THE INFLATABLE HARNESS FROM THE MASK REGULATOR AND REPLACE IT WITH A SERVICEABLE HARNESS	ESGP		MANDATORY	MTH 23-Jun-2016 HRS 3226.2 LDG 2961 APUH 1687 APUS 3470	-				N/A
<b>MOC : NOT APPLICABLE - INSPECTED AND FOUND NOT APPLICABLE</b>										
EASA 2014-0142 R1 (2)	ACCOMPLISH AN OXYGEN MASK REGULATOR EQUIPPED WITH A P/N MXH20-1 OR P/N MXH21-1 INFLATABLE HARNESS HAVING A DMF CODE OF NOVEMBER 2008 (0845-S OR 08/45-S) OR EARLIER, AND THOSE WITH A DMF OF JANUARY 2011 (1101-S OR 11/01-S) OR LATER, IS EXCLUDED FROM THE INSPECTION AND REPLACEMENT REQUIREMENTS OF PARAGRAPH (1) OF THIS AD	ESGP		MANDATORY	MTH 23-Jun-2016 HRS 3226.2 LDG 2961 APUH 1687 APUS 3470	-				N/A
<b>MOC : NOT APPLICABLE - INSPECTED AND FOUND NOT APPLICABLE</b>										
EASA 2014-0142 R1 (3)	ACCOMPLISH IT IS ALLOWED TO INSTALL ON AN AEROPLANE A FLIGHT CREW OXYGEN MASK REGULATOR, HAVING A P/N AS IDENTIFIED IN SECTION 1.A.(1) OF ZODIAC AEROTECHNICS SB MC10-35-274, PROVIDED IT HAS BEEN DETERMINED THAT A P/N MXH21-31 INFLATABLE HARNESS IS INSTALLED, OR THAT THE P/N MXH20-1 OR P/N MXH21-1 INFLATABLE HARNESS INSTALLED ON THAT FLIGHT CREW OXYGEN MASK REGULATOR HAS BEEN CORRECTED, AS REQUIRED BY THIS AD	ESGP		MANDATORY	MTH 23-Jun-2016 HRS 3226.2 LDG 2961 APUH 1687 APUS 3470	-				N/A
<b>MOC : NOT APPLICABLE - INSPECTED AND FOUND NOT APPLICABLE</b>										





# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
EASA 2014-0142 R1	APPLIANCE AD - OXYGEN OXYGEN MASK REGULATOR INFLATABLE HARNESS / INFLATION HOSE IDENTIFICATION / REPLACEMENT	ESGP		MANDATORY	MTH 23-Jun-2016 HRS 3226.2 LDG 2961 APUH 1687 APUS 3470	-				N/A
<b>MOC : NOT APPLICABLE - INSPECTED AND FOUND NOT APPLICABLE</b>										
EASA 2014-0142	APPLIANCE AD - OXYGEN - OXYGEN MASK REGULATOR INFLATABLE HARNESS / INFLATION HOSE - IDENTIFICATION / REPLACEMENT			MANDATORY		-				
<b>MOC :</b>										
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A..1	ESGP		MANDATORY	MTH 15-Jul-2016 HRS 3240.4 LDG 2975 APUH 1687 APUS 3470	-				N/A
<b>MOC : NOT APPLICABLE - AD FOUND NOT APPLICABLE DUE TO DRAGER AEROSPACE P/N:E28180-10 PBE INSTALLED.</b>										
FAA 2016-11-20 PARA (H)(1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL.	ESGP		MANDATORY	MTH 15-Jul-2016 HRS 3240.4 LDG 2975 APUH 1687 APUS 3470	-				N/A
<b>MOC : NOT APPLICABLE - AD FOUND NOT APPLICABLE DUE TO DRAGER AEROSPACE P/N:E28180-10 PBE INSTALLED.</b>										
FAA 2016-11-20 PARA (H)(2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT.	ESGP		MANDATORY	MTH 15-Jul-2016 HRS 3240.4 LDG 2975 APUH 1687 APUS 3470	-				N/A
<b>MOC : NOT APPLICABLE - AD FOUND NOT APPLICABLE DUE TO DRAGER AEROSPACE P/N:E28180-10 PBE INSTALLED.</b>										
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES.	ESGP		MANDATORY	MTH 15-Jul-2016 HRS 3240.4 LDG 2975 APUH 1687 APUS 3470	-				N/A
<b>MOC : NOT APPLICABLE - AD FOUND NOT APPLICABLE DUE TO DRAGER AEROSPACE P/N:E28180-10 PBE INSTALLED.</b>										
FAA 2012-06-01	MODIFY THE DRAIN INSTALLATION OF THE TAILCONE STINGER ON THE AFT CANTED BULKHEAD	ESGP		MANDATORY	MTH 05-Jan-2013 HRS 1987.1 LDG 1764	-				Complete
<b>MOC : COMPLIED WITH - SB560XL-53-16 FOUND PERFORMED 20-FEB-2012 AT ACTT:1641,2/1472</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2010-18-09 PARA (E)(2)	ACCOMPLISH INTERCOMPRESSOR BLEED VALVE/SERVO VALVE REMOVE									
		ESGP		MANDATORY	MTH 03-Nov-2010 HRS 1251.9 LDG 1123		-			N/A
E1	<b>MOC : NOT APPLICABLE - NOT APPLICABLE DUE TO BOV ABOVE 250FH</b>									
FAA 2010-18-09 PARA (E)(2)	ACCOMPLISH INTERCOMPRESSOR BLEED VALVE/SERVO VALVE REMOVE									
		ESGP		MANDATORY	MTH 03-Nov-2010 HRS 1187 LDG 1053		-			N/A
E2	<b>MOC : NOT APPLICABLE - NOT APPLICABLE DUE TO BOV ABOVE 250FH</b>									
FAA 2010-18-09 PARA (E)(3)	ACCOMPLISH INTERCOMPRESSOR BLEED VALVE/SERVO VALVE ENGINE TESTING									
		ESGP		MANDATORY	MTH 03-Nov-2010 HRS 1251.9 LDG 1123		-			N/A
E1	<b>MOC : NOT APPLICABLE - NOT APPLICABLE DUE TO BOV ABOVE 250FH</b>									
FAA 2010-18-09 PARA (E)(3)	ACCOMPLISH INTERCOMPRESSOR BLEED VALVE/SERVO VALVE ENGINE TESTING									
		ESGP		MANDATORY	MTH 03-Nov-2010 HRS 1187 LDG 1053		-			N/A
E2	<b>MOC : NOT APPLICABLE - NOT APPLICABLE DUE TO BOV ABOVE 250FH</b>									
FAA 2010-18-09 E1	INTERCOMPRESSOR BLEED VALVE/SERVO VALVE									
		ESGP		MANDATORY	MTH 03-Nov-2010 HRS 1251.9 LDG 1123		-			N/A
	<b>MOC : NOT APPLICABLE - NOT APPLICABLE DUE TO BOV ABOVE 250FH</b>									
FAA 2010-18-09 E2	INTERCOMPRESSOR BLEED VALVE/SERVO VALVE									
		ESGP		MANDATORY	MTH 03-Nov-2010 HRS 1187 LDG 1053		-			N/A
	<b>MOC : NOT APPLICABLE - NOT APPLICABLE DUE TO BOV ABOVE 250FH</b>									



## CESCOM 10 - Aircraft Status Report

Owner: **EFS EUROPEAN FLIGHT SERVICE AB**  
 Aircraft Model: **560XLS - CITATION XLS (MSG)**  
 Aircraft Serial: **560XL-5624** Unit: **5624** Reg No: **SE-RCM**  
 Airworthiness: **07-Jun-2006**  
 Print Date: **02-Feb-2017 10:07AM**  
 MSG-3 Program Applied Date: **14-Mar-2016**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>ENG 1</b>	<b>3307.6</b>	<b>3042</b>	<b>13-Jan-2017</b>	<b>.02</b>
<b>ENG 2</b>	<b>3372.5</b>	<b>3112</b>	<b>13-Jan-2017</b>	<b>.58</b>
<b>APU</b>	<b>1763</b>	<b>3762</b>	<b>13-Jan-2017</b>	<b>.1</b>

### Factory Installed

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
23FO-01XL <i>23FO-01 : XL</i>	ST-3100 TELEPHONE SYS AIRCELL FACTORY OPTION	*CF		807D FO	MTH 07-Jun-2006	-				
23FO-05XL/C <i>23FO-05 : XL/C</i>	RECORDER: FLIGHT DATA JAA ALLIEDSIGNAL FACTORY OPTION	*CF		634C FO	MTH 07-Jun-2006	-				
23FO-07XL <i>23FO-07 : XL</i>	SELCAL: CSD-714 FACTORY OPTION	*CF		631Y FO	MTH 07-Jun-2006	-				
25FO-08XL <i>25FO-08 : XL</i>	WEIS COLORED CKPT & CBN DR TRM FACTORY OPTION	*CF		729 FO	MTH 07-Jun-2006	-				
33FO-01XL <i>33FO-01 : XL</i>	PULSELITE SYS INTERFC TO TCAS FACTORY OPTION	*CF		817 FO	MTH 07-Jun-2006	-				
34FO-01XL <i>34FO-01 : XL</i>	COCKPIT SPEAKER MUTE SWITCH FACTORY OPTION	*CF		674B FO	MTH 07-Jun-2006	-				
34FO-02XL <i>34FO-02 : XL</i>	PBS-250 PASSENGER BRIEFING SYS FACTORY OPTION	*CF		810 FO	MTH 07-Jun-2006	-				
34FO-06XL/E <i>34FO-06 : XL/E</i>	2ND ADF: HONEYWELL FACTORY OPTION	*CF		659E FO	MTH 07-Jun-2006	-				
34FO-08XL/L <i>34FO-08 : XL/L</i>	TCAS: 2000 FACTORY OPTION	*CF		635L FO	MTH 07-Jun-2006	-				
34FO-21XL <i>34FO-21 : XL</i>	HF-1050 HONEYWELL FACTORY OPTION	*CF		632J FO	MTH 07-Jun-2006	-				
34FO-26XL <i>34FO-26 : XL</i>	DUAL MODE S DIV XPDR W EN SURV FACTORY OPTION	*CF		624F FO	MTH 07-Jun-2006	-				
34FO-28XL <i>34FO-28 : XL</i>	DUAL PRIMUS 1000 FMS HNYWELL FACTORY OPTION	*CF		805E FO	MTH 07-Jun-2006	-				