

OWNER: HUMMINGBIRD AVIATION SERVICES
ADDRESS: TEGELUDDSVAGEN 76
 STOCKHOLM 115 28
PHONE:
FAX:

OPERATOR: HUMMINGBIRD AVIATION SERVICES
ADDRESS: TEGELUDDSVAGEN 76
 STOCKHOLM 115 28
PHONE:
FAX:

ANALYST: VINCENT FERRY +33 (0) 1.55.93.45.80 (OFFICE)
EMAIL: VINCENT.FERRY@CAMPSYSTEMS.EU +33 (0) 1.53.01.66.18 (EFAX-CARDS)
 WWW.CAMPSYSTEMS.COM

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

Filter Criteria: Special Requirement: INCLUDE SPECIAL REQUIREMENTS; With: WARRANTY;

AIRCRAFT SERIAL/REGNO: 45-372/SE-RMO **MODEL:** LEARJET 45 **MANUFACTURER:** BOMBARDIER INCORPORATED

DATES	LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE: 11-AUG-2008	2792.6 A/C HRS	as of 25-FEB-2019	_____ A/C HRS	as of ____/____/____
	2223 AFL	as of 25-FEB-2019	_____ AFL	as of ____/____/____
	1074.52 APH	as of 13-FEB-2019	_____ APH	as of ____/____/____

APU SERIAL/PART: P-410/3800726-1 **MODEL:** RE100 (CIMMS) **MANUFACTURER:** HONEYWELL

INSTALLED ON 11-AUG-2008	LAST ACTUALS		CURRENT ACTUAL	
0 APU HRS	1074.52 APU HRS	as of 13-FEB-2019	_____ APU HRS	as of ____/____/____
0 APUS	2554 APUS	as of 13-FEB-2019	_____ APUS	as of ____/____/____

ENGINE NO. 1 SERIAL/PART: P-116969C/3060084-1 **MODEL:** TFE731-20BR-1 B **MANUFACTURER:** HONEYWELL

INSTALLED ON 19-MAY-2008	LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	0 A/C HRS	2792.6 ENG. HRS	as of 25-FEB-2019	_____ ENG. HRS
0 ENC		2178 ENC	as of 25-FEB-2019	_____ ENC

ENGINE NO. 2 SERIAL/PART: P-116968C/3060084-1 **MODEL:** TFE731-20BR-1B **MANUFACTURER:** HONEYWELL

INSTALLED ON 19-MAY-2008	LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	0 A/C HRS	2792.6 ENG. HRS	as of 25-FEB-2019	_____ ENG. HRS
0 ENC		2178 ENC	as of 25-FEB-2019	_____ ENC



Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 05	TIME LIMITS/MAINTENANCE CHECKS							
+ 051101	PHASE A1-300 HOUR CHECKS							
05.110	PKG 1	MOS	12			29-AUG-2018	29-AUG-2019	12-SEP-2019
		HRS/MSC	300	+14d/-14d		2621.3	2913.6	2938.6
	REF: See Workcard	AFL		+25/-25	-7.7	2079		
+ 051102	PHASE A2-300 HOUR CHECKS							
	PKG 2	MOS	12			29-AUG-2018	29-AUG-2019	12-SEP-2019
		HRS/MSC	300	+14d/-14d		2621.3	2913.6	2938.6
	REF: See Workcard	AFL		+25/-25	-7.7	2079		
+ 051103	PHASE A3-300 HOUR CHECKS							
	PKG 3	MOS	12			29-AUG-2018	29-AUG-2019	12-SEP-2019
		HRS/MSC	300	+14d/-14d		2621.3	2913.6	2938.6
	REF: See Workcard	AFL		+25/-25	-7.7	2079		
+ 051104	PHASE A4-300 HOUR CHECKS							
	PKG 4	MOS	12			29-AUG-2018	29-AUG-2019	12-SEP-2019
		HRS/MSC	300	+14d/-14d		2621.3	2913.6	2938.6
	REF: See Workcard	AFL		+25/-25	-7.7	2079		
+ 051105	PHASE A5-300 HOUR CHECKS							
	PKG 5	MOS	12			29-AUG-2018	29-AUG-2019	12-SEP-2019
		HRS/MSC	300	+14d/-14d		2621.3	2913.6	2938.6
	REF: See Workcard	AFL		+25/-25	-7.7	2079		
+ 051106	PHASE A6-300 HOUR CHECKS							
	PKG 6	MOS	12			29-AUG-2018	29-AUG-2019	12-SEP-2019
		HRS/MSC	300	+14d/-14d		2621.3	2913.6	2938.6
	REF: See Workcard	AFL		+25/-25	-7.7	2079		
+ 051201	PHASE B1 600 HOUR CHECKS							
	PKG 7	MOS	24		5	30-NOV-2017	05-DEC-2019	19-DEC-2019
		HRS/MSC	600	+14d/-14d		2313.6	2913.6	2938.6
	REF: See Workcard	AFL		+25/-25		1848		
+ 051202	PHASE B2 600 HOUR CHECKS							
	PKG 8	MOS	24		5	30-NOV-2017	05-DEC-2019	19-DEC-2019
		HRS/MSC	600	+14d/-14d		2313.6	2913.6	2938.6
	REF: See Workcard	AFL		+25/-25		1848		
+ 051203	PHASE B3 600 HOUR CHECKS							
	PKG 9	MOS	24		5	30-NOV-2017	05-DEC-2019	19-DEC-2019
		HRS/MSC	600	+14d/-14d		2313.6	2913.6	2938.6
	REF: See Workcard	AFL		+25/-25		1848		
+ 051204	PHASE B4 600 HOUR CHECKS							
	PKG 10	MOS	24		5	30-NOV-2017	05-DEC-2019	19-DEC-2019
		HRS/MSC	600	+14d/-14d		2313.6	2913.6	2938.6
	REF: See Workcard	AFL		+25/-25		1848		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W (#)-RTS Pending (!)-RTS Overdue
(ENG/APU) = Engine/APU Units



Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 051205	PHASE B5 600 HOUR CHECKS PKG 11 REF: See Workcard	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25	5	30-NOV-2017 2313.6 1848	05-DEC-2019 2913.6	19-DEC-2019 2938.6
+ 051206	PHASE B6 600 HOUR CHECKS PKG 12 REF: See Workcard	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25	5	30-NOV-2017 2313.6 1848	05-DEC-2019 2913.6	19-DEC-2019 2938.6
+ 051301	PHASE C1 1200 HOUR CHECKS PKG 13 REF: See Workcard	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25	-4	20-MAY-2016 1821.7 1492	16-MAY-2020 3021.7	30-MAY-2020 3046.7
+ 051302	PHASE C2 1200 HOUR CHECKS PKG 14 REF: See Workcard	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25	-4	20-MAY-2016 1821.7 1492	16-MAY-2020 3021.7	30-MAY-2020 3046.7
+ 051303	PHASE C3 1200 HOUR CHECKS PKG 15 REF: See Workcard	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25	-4	20-MAY-2016 1821.7 1492	16-MAY-2020 3021.7	30-MAY-2020 3046.7
+ 051304	PHASE C4 1200 HOUR CHECKS PKG 16 REF: See Workcard	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25	-4	20-MAY-2016 1821.7 1492	16-MAY-2020 3021.7	30-MAY-2020 3046.7
+ 051305	PHASE C5 1200 HOUR CHECKS PKG 17 REF: See Workcard	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25	-4	20-MAY-2016 1821.7 1492	16-MAY-2020 3021.7	30-MAY-2020 3046.7
+ 051306	PHASE C6 1200 HOUR CHECKS PKG 18 REF: See Workcard	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25	-4	20-MAY-2016 1821.7 1492	16-MAY-2020 3021.7	30-MAY-2020 3046.7
+ 051401	PHASE D1 2400 HOUR CHECKS PKG 19 REF: See Workcard	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25		20-MAY-2016 1821.7 1492	20-MAY-2024 4221.7	03-JUN-2024 4246.7
+ 051402	PHASE D2 2400 HOUR CHECKS PKG 20 REF: See Workcard	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25		20-MAY-2016 1821.7 1492	20-MAY-2024 4221.7	03-JUN-2024 4246.7



Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 051403	PHASE D3 2400 HOUR CHECKS PKG 21 REF: See Workcard	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			20-MAY-2016 1821.7 1492	20-MAY-2024 4221.7	03-JUN-2024 4246.7
+ 051404	PHASE D4 2400 HOUR CHECKS PKG 22 REF: See Workcard	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			20-MAY-2016 1821.7 1492	20-MAY-2024 4221.7	03-JUN-2024 4246.7
+ 051405	PHASE D5 2400 HOUR CHECKS PKG 23 REF: See Workcard	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			20-MAY-2016 1821.7 1492	20-MAY-2024 4221.7	03-JUN-2024 4246.7
+ 051406	PHASE D6 2400 HOUR CHECKS PKG 24 REF: See Workcard	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			20-MAY-2016 1821.7 1492	20-MAY-2024 4221.7	03-JUN-2024 4246.7
+ 051500	4800 HOUR CHECKS PKG 25 REF: See Workcard	MOS HRS/MSC AFL	4800	+25/-25			11-AUG-2008 0 0	4800	4825
+ 051600	9600 HOUR CHECKS PKG 26 REF: See Workcard	MOS HRS/MSC AFL	9600	+25/-25			11-AUG-2008 0 0	9600	9625
+ 051700	MAJOR LANDING GEAR INSPECTION PKG 27 REF: See Workcard	MOS HRS/MSC AFL	10000	+25/-25			11-AUG-2008 0 0	10000	10025
ENGINE NO. 1 Model : TFE731-20/-40/-60 (CIMMS) Serial # P-116969C Part # 3060084-1									
057110	NO. 1 ENGINE - 150 TO 250 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS PKG 0 REF: LMM 72-00-00	MOS HRS/MSC ENC	150	+100	-1.4		29-AUG-2018 2621.3 2034	(2769.9) 2769.9	2869.9
057120	NO. 1 ENGINE - 300 TO 440 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS PKG 0 REF: LMM 72-00-00	MOS HRS/MSC ENC	N/A				29-JUN-2015 1602.9 1293		
057130	NO. 1 ENGINE - 500 TO 650 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS PKG 0 REF: LMM 72-00-00	MOS HRS/MSC ENC	600	+50/-100	57.2		30-NOV-2017 2313.6 1803	(2970.8) 2970.8	3020.8



Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
057140	NO. 1 ENGINE - 500 TO 850 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS PKG 0 REF: LMM 72-00-00	MOS HRS/MSC ENC	800	+50/-300	20	16-FEB-2018 2383.6 1854	(3203.6) 3203.6	3253.6
057150	NO. 1 ENGINE - 1000 TO 1300 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS PKG 0 REF: LMM 72-00-00	MOS HRS/MSC ENC	1200	+100/-200	57.2	30-NOV-2017 2313.6 1803	(3570.8) 3570.8	3670.8
057160	NO. 1 ENGINE - 1500 TO 1650 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS PKG 0 REF: LMM 72-00-00	MOS HRS/MSC ENC	1600	+50/-100	-2.9	29-JUN-2015 1602.9 1293	(3200) 3200	3250
ENGINE NO. 2 Model : TFE731-20/-40/-60 (CIMMS) Serial # P-116968C Part # 3060084-1								
057110	NO. 2 ENGINE - 150 TO 250 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS PKG 0 REF: LMM 72-00-00	MOS HRS/MSC ENC	150	+100	-1.4	29-AUG-2018 2621.3 2034	(2769.9) 2769.9	2869.9
057120	NO. 2 ENGINE - 300 TO 440 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS PKG 0 REF: LMM 72-00-00	MOS HRS/MSC ENC	N/A			29-JUN-2015 1602.9 1293		
057130	NO. 2 ENGINE - 500 TO 650 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS PKG 0 REF: LMM 72-00-00	MOS HRS/MSC ENC	600	+50/-100	57.2	30-NOV-2017 2313.6 1803	(2970.8) 2970.8	3020.8
057140	NO. 2 ENGINE - 500 TO 850 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS PKG 0 REF: LMM 72-00-00	MOS HRS/MSC ENC	800	+50/-300	20	16-FEB-2018 2383.6 1854	(3203.6) 3203.6	3253.6
057150	NO. 2 ENGINE - 1000 TO 1300 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS PKG 0 REF: LMM 72-00-00	MOS HRS/MSC ENC	1200	+100/-200	57.2	30-NOV-2017 2313.6 1803	(3570.8) 3570.8	3670.8
057160	NO. 2 ENGINE - 1500 TO 1650 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS PKG 0 REF: LMM 72-00-00	MOS HRS/MSC ENC	1600	+50/-100	-2.9	29-JUN-2015 1602.9 1293	(3200) 3200	3250

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 00	INFORMATION								
CI45-111007	REVIEW LEARJET 45 MM, TEMPORARY REVISION: 5-84, OCTOBER 31, 2011 - CAMP CHANGE FORM								
REQUIREMENT CHANGE FORMS	REF: RCF CI45	MOS HRS/MSC - AFL						14-MAR-2013	
CI45-111205	REVIEW TEMPORARY REVISION 5-85 CAMP CHANGE FORM								
REQUIREMENT CHANGE FORMS	REF: RCF CI45	MOS HRS/MSC - AFL						03-JAN-2012	
CI45-120709	REVIEW LEARJET 45 MAINTENANCE MANUEL REV 57, DATED JUN 11, 2012 - CAMP CHANGE FORM								
REQUIREMENT CHANGE FORMS	REF: RCF CI45	MOS HRS/MSC - AFL						30-JUL-2012	
CI45-130226	REVIEW LEARJET 45 MAINTENANCE MANUAL REV 58 DTD JAN. 21, 2013 - CAMP CHANGE FORM								
REQUIREMENT CHANGE FORMS	REF: RCF CI45	MOS HRS/MSC - AFL						07-MAR-2013	
CI45-130715	REVIEW LEARJET 45 MAINTENANCE MANUAL, REVISION NO. 59								
REQUIREMENT CHANGE FORMS	REF: RCF CI45	MOS HRS/MSC - AFL						18-JUL-2013	
CI45-131003	REVIEW LEARJET 45 MAINTENANCE MANUAL MM-105, REVISION NO. 60, DATED SEP 23, 2013 - CAMP CHANGE FORM								
REQUIREMENT CHANGE FORMS	REF: RCF CI45	MOS HRS/MSC - AFL						09-OCT-2013	

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CI45-140111	REVIEW LEARJET 45 AMM REVISION NO. 61, DATED DEC 23, 2013 - CAMP CHANGE FORM						(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF CI45	MOS HRS/MSC - AFL							
CI45-140214	REVIEW LEARJET 45, MM TEMPORARY REVISION NO.5-90 DATED 27 JAN 2014 - CAMP CHANGE FORM						(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF CI45	MOS HRS/MSC - AFL							
CI45-140214-1	REVIEW LEARJET 45, MM TEMPORARY REVISION NO.5-91 DATED 27 JAN 2014 - CAMP CHANGE FORM						(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF CI45	MOS HRS/MSC - AFL							
CI45-140508	REVIEW LEARJET 45, MM TR NO. 4-37, 5-92, 5-93, 5-94, 5-95, 5-96, 5-97, 5-98, 5-99, 5-100 - CAMP CHANGE FORM						(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF CI45	MOS HRS/MSC - AFL							
CI45-140714	REVIEW LEARJET 45, REVISION NO. 62, DATED JUN 2, 2014 - CAMP CHANGE FORM						26-AUG-2014 1426 1166		
REQUIREMENT CHANGE FORMS	REF: RCF CI45	MOS HRS/MSC - AFL							
CI45-150106	REVIEW LEARJET 45, MM TR 5-101 TO 5-105, DATED 30-JUN-2014 - CAMP CHANGE FORM						27-JAN-2015		
REQUIREMENT CHANGE FORMS	REF: RCF CI45	MOS HRS/MSC - AFL							

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CI45-150213	REVIEW LEARJET 45, MM REVISION 63 DATED JAN 12, 2015 - CAMP CHANGE FORM								
REQUIREMENT CHANGE FORMS	REF: RCF CI45	MOS HRS/MSC - AFL					04-MAR-2015 1524.6 1260		
CI45-150331	REVIEW LEARJET 45, MM TR 4-39, 5-107, 5-108, JAA 4-38, JAA 5-83 DATED 23 MARCH 2015 - CAMP CHANGE FORM								
REQUIREMENT CHANGE FORMS	REF: RCF CI45	MOS HRS/MSC - AFL					(EBT)		
CI45-150629	REVIEW LEARJET 45, MM REVISION 64 DATED 05-26-2015 - CAMP CHANGE FORM								
REQUIREMENT CHANGE FORMS	REF: RCF CI45	MOS HRS/MSC - AFL					25-AUG-2015		
CI45-150629-1	REVIEW LEARJET 45, MM REVISION 12 (JAA SUPPLEMENT) DATED 05-26-2015 - CAMP CHANGE FORM								
REQUIREMENT CHANGE FORMS	REF: RCF CI45	MOS HRS/MSC - AFL					25-AUG-2015		
CI45-150721	REVIEW CONCORDE EMERGENCY BATTERY CMM 5-0167 REV E								
REQUIREMENT CHANGE FORMS	REF: RCF CI45	MOS HRS/MSC - AFL					(EBT)		
CI45-151223	REVIEW LEARJET 45 AMM REVISION 65 - DATED 7-DEC-2015 - CAMP CHANGE FORM								
REQUIREMENT CHANGE FORMS	REF: RCF CI45	MOS HRS/MSC - AFL					(EBT)		



Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CI45-160212	REVIEW LEARJET 45, MM-104 JAA SUPPLEMENT REVISION 13, DATED 12-07-2015								
REQUIREMENT CHANGE FORMS	REF: RCF CI45	MOS HRS/MSC - AFL					11-MAR-2016		
CI45-160215	REVIEW LEARJET 45, MM-104 TR 5-109, DATED 12-14-2015 - CAMP CHANGE FORM								
REQUIREMENT CHANGE FORMS	REF: RCF CI45	MOS HRS/MSC - AFL					11-MAR-2016		
CI45-160527	REVIEW LEARJET AMM REVISION 66								
REQUIREMENT CHANGE FORMS	REF: RCF CI45	MOS HRS/MSC - AFL					(EBT)		
CI45-160603	REVIEW LEARJET 45 AMM TR 4-40								
REQUIREMENT CHANGE FORMS	REF: RCF CI45	MOS HRS/MSC - AFL					(EBT)		
CI45-160613	REVIEW LEARJET 45 AMM TR 5-110								
REQUIREMENT CHANGE FORMS	REF: RCF CI45	MOS HRS/MSC - AFL					(EBT)		
CI45-161207B	REVIEW LEARJET 45 AMM REVISION 67								
REQUIREMENT CHANGE FORMS	REF: RCF CI45	MOS HRS/MSC - AFL					04-JAN-2017		



Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CI45-170421	REVIEW LEARJET 45 AMM REVISION 68	MOS						03-MAY-2017	
REQUIREMENT CHANGE FORMS	REF: RCF CI45	HRS/MSC - AFL							
CI45-170731	REVIEW LEARJET 45 AMM TR 4-41	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF CI45	HRS/MSC - AFL							
+ CI45-171103A	REVIEW LEARJET 45 AMM REVISION 69	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF CI45	HRS/MSC - AFL							
CI45-171116A	REVIEW LEARJET 45/45XR AMM TR 05-115	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF CI45	HRS/MSC - AFL							
CI45-171116B	REVIEW LEARJET 45/45XR AMM TR 05-116	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF CI45	HRS/MSC - AFL							
CI45-171116C	REVIEW LEARJET 45/45XR AMM TR 05-117	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF CI45	HRS/MSC - AFL							

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CI45-171116D	REVIEW LEARJET 45/45XR AMM TR 05-118	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF CI45	HRS/MSC - AFL							
CI45-171116E	REVIEW LEARJET 45/45XR AMM TR 05-119	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF CI45	HRS/MSC - AFL							
CI45-180125A	REVIEW LEARJET 45 AMM TEMPORARY REVISION 04-44	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF CI45	HRS/MSC - AFL							
CI45-180125B	REVIEW LEARJET 45 AMM TEMPORARY REVISION 04-45	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF CI45	HRS/MSC - AFL							
CI45-180125C	REVIEW LEARJET 45 AMM TEMPORARY REVISION 04-46	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF CI45	HRS/MSC - AFL							
CI45-180420A	REVIEW LEARJET 45 AMM REVISION 70	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF CI45	HRS/MSC - AFL							



Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CI45-180430A	REVIEW LEARJET 45/45XR AMM TR 05-113	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF CI45	HRS/MSC - AFL							
CI45-180430B	REVIEW LEARJET 45/45XR AMM TR 05-120	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF CI45	HRS/MSC - AFL							
CI45-180621B	REVIEW LEARJET 45 AUDIT SUMMARY CHANGE FORM	MOS					(EBT)		
AUDIT SUMMARY CHANGE FORM	REF: RCF CI45	HRS/MSC - AFL							
CI45-180829A	REVIEW LEARJET 45 AUDIT SUMMARY CHANGE FORM	MOS					(EBT)		
AUDIT SUMMARY CHANGE FORM	REF: RCF CI45	HRS/MSC - AFL							
CI45-181109B	REVIEW LEARJET 45/45XR AMM REVISION 71	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF CI45	HRS/MSC - AFL							
CI45-190225	REVIEW LEARJET 45/45XR AMM TR 05-121	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF CI45	HRS/MSC - AFL							
	NEW REQUIREMENT ADDED ON 27-FEB-2019 (EFFECTIVE: 25-FEB-2019). REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.								

APU Model : RE100 (CIMMS) Serial # P-410 Part # 3800726-1



Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
AC16-180112	APU - REVIEW HONEYWELL GTCP RE100 (CIMMS) APU-49 SIL REV 10						(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF APU-SIL-49	MOS HRS/MSC - APUS							
ENGINE NO. 1 Model : TFE731-20BR-1 B Serial # P-116969C Part # 3060084-1									
EC04-130830	NO. 1 ENGINE - REVIEW LIGHT MAINTENANCE MANUAL TFE731-20/-40/-50/-60 TEMPORARY REVISION NO. 72-215 DATED FROM 26 JUNE 2013 - CAMP CHANGE FORM							09-OCT-2013	
REQUIREMENT CHANGE FORMS	REF: RCF EC04	MOS HRS/MSC - ENC							
EC04-140327	NO. 1 ENGINE - REVIEW LMM TFE731-20/-40/-60 TR NO.72-219 DATED 15 MARCH 2014 - CAMP REQUIREMENT CHANGE FORM							28-APR-2014	
REQUIREMENT CHANGE FORMS	REF: RCF EC04	MOS HRS/MSC - ENC					1346.5 1066		
EC04-170913	NO. 1 ENGINE - REVIEW TFE731-20/-40/-60 (CIMMS) LMM (72-03-06) TR 72-235						(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF EC04	MOS HRS/MSC - ENC							
EC04-180118	NO. 1 ENGINE - REVIEW TFE731-20/-40/-60 (CIMMS) LMM REV 13						(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF EC04	MOS HRS/MSC - ENC							
EC04-180226	NO. 1 ENGINE - REVIEW TFE731-20/-40/-60 (CIMMS) LMM TR 72-241						(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF EC04	MOS HRS/MSC - ENC							



Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
EC04-180226-1	NO. 1 ENGINE - REVIEW	TFE731-20/-40/-60 (CIMMS)	LMM TR 73-22				(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF EC04	MOS HRS/MSC - ENC							
EC04-180226-2	NO. 1 ENGINE - REVIEW	TFE731-20/-40/-60 (CIMMS)	LMM TR 72-242				(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF EC04	MOS HRS/MSC - ENC							
EC04-180710	NO. 1 ENGINE - REVIEW	TFE731-20/-40/-60	CHANGE FORM				(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF EC04	MOS HRS/MSC - ENC							
EC04-180802	NO. 1 ENGINE - REVIEW	TFE731-20/-40/-60 (CIMMS)	LMM TR 5-17				(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF EC04-180802	MOS HRS/MSC - ENC							
ENGINE NO. 2 Model : TFE731-20BR-1B Serial # P-116968C Part # 3060084-1									
EC04-130830	NO. 2 ENGINE - REVIEW	LIGHT MAINTENANCE MANUAL	TFE731-20/-40/-50/-60	TEMPORARY REVISION NO. 72-215				09-OCT-2013	
REQUIREMENT CHANGE FORMS	REF: RCF EC04	MOS HRS/MSC - ENC	DATED FROM 26 JUNE 2013 - CAMP CHANGE FORM						
EC04-140327	NO. 2 ENGINE - REVIEW	LMM TFE731-20/-40/-60	TR NO.72-219	DATED 15 MARCH 2014 - CAMP REQUIREMENT				28-APR-2014	
REQUIREMENT CHANGE FORMS	REF: RCF EC04	MOS HRS/MSC - ENC	CHANGE FORM				1346.5 1066		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
EC04-170913	NO. 2 ENGINE - REVIEW	TFE731-20/-40/-60 (CIMMS) LMM (72-03-06) TR 72-235					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF EC04	MOS HRS/MSC - ENC							
EC04-180118	NO. 2 ENGINE - REVIEW	TFE731-20/-40/-60 (CIMMS) LMM REV 13					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF EC04	MOS HRS/MSC - ENC							
EC04-180226	NO. 2 ENGINE - REVIEW	TFE731-20/-40/-60 (CIMMS) LMM TR 72-241					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF EC04	MOS HRS/MSC - ENC							
EC04-180226-1	NO. 2 ENGINE - REVIEW	TFE731-20/-40/-60 (CIMMS) LMM TR 73-22					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF EC04	MOS HRS/MSC - ENC							
EC04-180226-2	NO. 2 ENGINE - REVIEW	TFE731-20/-40/-60 (CIMMS) LMM TR 72-242					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF EC04	MOS HRS/MSC - ENC							
EC04-180710	NO. 2 ENGINE - REVIEW	TFE731-20/-40/-60 CHANGE FORM					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF EC04	MOS HRS/MSC - ENC							



Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
EC04-180802	NO. 2 ENGINE - REVIEW	TFE731-20/-40/-60 (CIMMS)	LMM TR 5-17				(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF EC04-180802	MOS HRS/MSC - ENC							
CHAPTER 04 LIMITATIONS									
04-01	PERFORM YEARLY RENEWAL OF ARC							04-MAY-2018	04-MAY-2019 M
AIRWORTHINESS	REF:	MOS HRS/MSC AFL	12 DUE						
04-02	PERFORM RENEWAL OF FULL ARC EVERY THREE YEARS							04-MAY-2017	04-MAY-2020 M
AIRWORTHINESS	REF:	MOS HRS/MSC AFL	36 DUE						
04-03	CERTIFICATE OF AIRWORTHINESS							20-DEC-2013	
AIRWORTHINESS	REF:	MOS HRS/MSC AFL	DUE						
04-04	CERTIFICATE NOISE							20-DEC-2013	
AIRWORTHINESS DIRECTIVE	REF:	MOS HRS/MSC AFL	DUE						
04-05	RENEWAL OF CERTIFICATE OF INSURANCE							20-APR-2018	19-APR-2019 M
AIRWORTHINESS	REF:	MOS HRS/MSC AFL	12 O/C						
04-10	RENEWAL OF THE SWEDISH POST AND TELECOM AUTHORITY							15-DEC-2014	31-DEC-2019 M
AIRWORTHINESS	REF:	MOS HRS/MSC AFL	108						

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
04-15	CERTIFICATE OF NATO AND REGISTRATION								
AIRWORTHINESS	REF:	MOS HRS/MSC AFL	DUE				11-DEC-2013		
CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS									
05-19-02	PERFORM RVSM CHEK IAW LJ45 MM 05-19-02								
RVSM	REF:	MOS HRS/MSC AFL	24				14-MAY-2018 2469.9 1969	14-MAY-2020	
050001	PERFORM INSPECTION, AIRWORTHINESS REVIEW I.A.W. EASA PART M, M.A. 710								
CUSTOMER CODE	REF:	MOS HRS/MSC AFL	12				04-MAY-2018	04-MAY-2019 M	
05HB28	DRAIN FUEL SAMPLE FROM THE TANKS AND INSPECT FOR CONTAMINATION								
REF:		DAYS HRS/MSC AFL	30 DUE				14-FEB-2019 2789.1 2218	16-MAR-2019	
05HB30	CHECK BRAKE WEAR PINS, TIRES PRESSURE AND INSPECT TIRES CONDITION								
REF:		DAYS HRS/MSC AFL	30 DUE				14-FEB-2019 2789.1 2218	16-MAR-2019	
+ 5-50-00-BS	INSPECTION BIRD STRIKE								
INSPECT	REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R						
5-50-00-EV	PERFORM ENGINE VIBRATION TEST AND INSPECTION								
REF: AMM 05-50-00		MOS HRS/MSC AFL	A/R						

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 5-50-00-HL	INSPECTION HARD LANDING								
INSPECT	REF: AMM 05-50-00	MOS HRS/MSC AFL	A/R						
+ 5-50-00-LS	INSPECTION LIGHTNING STRIKE							11-AUG-2008	
INSPECT	REF: AMM 05-50-00	MOS HRS/MSC AFL	A/R				0 0		
+ 5-50-00-OW	INSPECTION OVERWEIGHT LANDING (WEIGHT IN EXCESS OF MAXIMUM LANDING WEIGHT)								
INSPECT	REF: AMM 05-50-00	MOS HRS/MSC AFL	A/R						

CHAPTER	05-00	TIME LIMITS/MAINTENANCE CHECKS							
05EA30		PERFORM H-BIRD MONTHLY INSPECTION							
OPERATOR REQUEST	REF:	DAYS HRS/MSC AFL	30	+14/-14			14-FEB-2019 2789.1 2218	16-MAR-2019	30-MAR-2019

CHAPTER	08	LEVELING AND WEIGHING							
082000		REWEIGH AIRCRAFT							
	REF: See Workcard	MOS HRS/MSC AFL	48		-4		20-MAY-2016 1821.7 1492	16-MAY-2020	

CHAPTER	11	PLACARDS AND MARKINGS							
G1130000 (s)		CHECK CHECK BRIGHTNESS LEVEL OF ALL SELF-LUMINOUS PLACARDS					PKG		
	REF: AMM 11-30-00	MOS HRS/MSC AFL	48	+14d/-14d +25/-25			20-MAY-2016 1821.7 1492		

CHAPTER	12	SERVICING							
---------	----	-----------	--	--	--	--	--	--	--

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-00-Q1221064	FLAP ACTUATOR JOINT (P/N 145673-1) - APPLY CORROSION PREVENTIVE COMPOUND (CPC). (REFER TO 12-21-03.)	MOS					18-JUN-2013		
NOT INSTALLED	REF: AMM 12-21-03	HRS/MSC AFL	N/A				1323.2 1060		
5-19-00-U1210004	LUBRICATE FLAP FLEXIBLE TRANSMISSION SHAFTS - BY HAND. (ZONE/ACCESS 540/640 IRN # U1210004)	MOS					11-AUG-2008		
	REF: GENERIC NO REF	HRS/MSC AFL	4800	+25/-25			0 0	4800	4825
A1210007 (s)	NOSE AND MAIN TIRES - CHECK FOR PROPER INFLATION.						PKG		
	PKG 5	MOS	12	+14d/-14d			29-AUG-2018		
	REF: AMM 12-10-04	HRS/MSC AFL	300	+25/-25			2621.3 2079		
D1210020 (s)	EMERGENCY EXIT DOOR PINS - LUBRICATE.						PKG		
	PKG 6	MOS	12	+14d/-14d			29-AUG-2018		
	REF: AMM 12-21-02	HRS/MSC AFL	300	+25/-25			2621.3 2079		
H1210018 (s)	PASSENGER/CREW DOOR TENSION BOLTS - LUBRICATE.						PKG		
	PKG 6	MOS	12	+14d/-14d			29-AUG-2018		
	REF: AMM 12-21-02	HRS/MSC AFL	300	+25/-25			2621.3 2079		
L1221042 (s)	HORIZONTAL STABILIZER UPPER AND LOWER TORQUE LINKS - LUBRICATE						PKG		
	PKG 9	MOS	24	+14d/-14d			30-NOV-2017		
	REF: AMM 12-21-03	HRS/MSC AFL	600	+25/-25			2313.6 1848		
O1210002 (s)	FLAP ACTUATORS - CHECK OIL LEVEL.						PKG		
	PKG 10	MOS	24	+14d/-14d			30-NOV-2017		
	REF: AMM 12-21-03	HRS/MSC AFL	600	+25/-25			2313.6 1848		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
01210005 (s)	NOSE LANDING GEAR TRUNNION PIN - LUBRICATE. PKG 5 REF: AMM 12-21-01	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 29-AUG-2018 2621.3 2079		
01210006 (s)	NOSE LANDING GEAR ACTUATOR ATTACH FITTING - LUBRICATE. PKG 5 REF: AMM 12-21-01	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 29-AUG-2018 2621.3 2079		
01210009 (s)	NOSE GEAR DOOR HINGE - LUBRICATE. PKG 1 REF: AMM 12-21-02	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 29-AUG-2018 2621.3 2079		
01210011 (s)	MAIN LANDING GEAR ACTUATOR JOINTS - LUBRICATE. PKG 5 REF: AMM 12-21-01	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 29-AUG-2018 2621.3 2079		
01210012 (s)	MAIN LANDING GEAR AXLE BEAM/PISTON JOINTS - LUBRICATE. PKG 5 REF: AMM 12-21-01	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 29-AUG-2018 2621.3 2079		
01210013 (s)	MAIN LANDING GEAR TORQUE LINKS - LUBRICATE. PKG 5 REF: AMM 12-21-01	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 29-AUG-2018 2621.3 2079		
01210014 (s)	MAIN GEAR DOOR HINGE - LUBRICATE PKG 5 REF: AMM 12-21-02	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 29-AUG-2018 2621.3 2079		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
01210016 (s)	PASSENGER/CREW DOOR HINGE - LUBRICATE PKG 6 REF: AMM 12-21-02	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 29-AUG-2018 2621.3 2079		
01210017 (s)	PASSENGER/CREW DOOR PINS - LUBRICATE PKG 6 REF: AMM 12-21-02	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 29-AUG-2018 2621.3 2079		
01210019 (s)	EMERGENCY EXIT DOOR LATCHING MECHANISM - LUBRICATE. PKG 6 REF: AMM 12-21-02	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 29-AUG-2018 2621.3 2079		
01210021 (s)	BAGGAGE COMPARTMENT DOOR LATCH PINS - LUBRICATE. PKG 6 REF: AMM 12-21-02	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 29-AUG-2018 2621.3 2079		
01210022 (s)	BAGGAGE COMPARTMENT DOOR HINGE - LUBRICATE PKG 6 REF: AMM 12-21-02	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 29-AUG-2018 2621.3 2079		
01210023 (s)	OXYGEN SYSTEM SERVICING DOOR HINGE - LUBRICATE PKG 1 REF: AMM 12-21-02	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 29-AUG-2018 2621.3 2079		
01210024 (s)	TOILET SERVICING DOOR HINGE - LUBRICATE. PKG 4 REF: AMM 12-21-02	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 29-AUG-2018 2621.3 2079		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
01210025 (s)	PRESSURE REFUELING DOOR HINGE - LUBRICATE. PKG 2	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 29-AUG-2018 2621.3 2079		
	REF: AMM 12-21-02								
01210026 (s)	FUSELAGE FUEL FILLER DOOR HINGE - LUBRICATE PKG 2	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 29-AUG-2018 2621.3 2079		
	REF: AMM 12-21-02								
01210027 (s)	TAILCONE ACCESS DOOR PINS - LUBRICATE PKG 6	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 29-AUG-2018 2621.3 2079		
	REF: AMM 12-21-02								
01210028 (s)	TAILCONE ACCESS DOOR HINGE - LUBRICATE. PKG 6	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 29-AUG-2018 2621.3 2079		
	REF: AMM 12-21-02								
01210029 (s)	MAIN LANDING GEAR TRUNNION PIN - LUBRICATE PKG 5	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 29-AUG-2018 2621.3 2079		
	REF: AMM 12-21-01								
Q1227000 (s)	EMERGENCY PARK BRAKE HANDLE SHAFT - LUBRICATE PKG 1	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 29-AUG-2018 2621.3 2079		
	REF: AMM 12-27-00								
R1210003 (s)	FLAP ACTUATOR BALLNUT - LUBRICATE. PKG 4	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 29-AUG-2018 2621.3 2079		
	REF: AMM 12-21-03								

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
T1221037 (s)	FLAPS - LUBRICATE ROLLING SURFACES OF MAIN AND NOSE ROLLER TRACKS PKG 4	MOS	12	+14d/-14d			PKG 29-AUG-2018 2621.3 2079		
	REF: AMM 12-21-03	HRS/MSC AFL	300	+25/-25					
U1210000 (s)	NOSE LANDING GEAR SHOCK STRUT - CHECK FOR PROPER FLUID LEVEL AND INFLATION PRESSURE. PKG 5	MOS	12	+14d/-14d			PKG 29-AUG-2018 2621.3 2079		
	REF: AMM 12-10-02	HRS/MSC AFL	300	+25/-25					
U1210001 (s)	MAIN LANDING GEAR SHOCK STRUTS - CHECK FOR PROPER FLUID LEVEL AND INFLATION PRESSURE. PKG 5	MOS	12	+14d/-14d			PKG 29-AUG-2018 2621.3 2079		
	REF: AMM 12-10-03	HRS/MSC AFL	300	+25/-25					
CHAPTER 21 AIR CONDITIONING									
211001	SERVO AIR PRESSURE REGULATING VALVE PN	MOS					11-AUG-2008		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0		0		
	REF: AMM 36-15-01	AFL			TSN:0		0		
211011	LEFT PLENUM CHECK VALVE PN	MOS					11-AUG-2008		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0		0		
	REF: AMM 21-20-09	AFL			TSN:0		0		
211012	RIGHT PLENUM CHECK VALVE PN	MOS					11-AUG-2008		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0		0		
	REF: AMM 21-20-09	AFL			TSN:0		0		
211017	LEFT EMERGENCY PRESSURIZATION ISOLATION CHECK VALVE 3202744-1	MOS					11-AUG-2008		
	2967	HRS/MSC	O/C		TSN:0		0		
	REF: AMM 21-20-03	AFL			TSN:0		0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
211018	RIGHT EMERGENCY PRESSURIZATION ISOLATION CHECK VALVE 3202744-1 2968 REF: AMM 21-20-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
212001	COCKPIT AIR CHECK VALVE PN SN-UNKNOWN REF: AMM 21-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
212007	AFT BLOWER MOTOR PN SN-UNKNOWN REF: AMM 21-51-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
212008	FWD BLOWER MOTOR PN SN-UNKNOWN REF: GENERIC CUSTOM	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
212011	LINEAR ELECTRO-MECHANICAL ACTUATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
212041	LEFT ENGINE OZONE CONVERTER 53A405-4-800 1230-2547 REF: AMM 21-20-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
+ 212041A	TEST LEFT ENGINE OZONE CONVERTER EFFICIENCY. (W2140001) 53A405-4-800 1230-2547 REF: AMM 21-20-12	MOS HRS/MSC AFL	3600	+25/-25			11-AUG-2008 0 0	3600	3625

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
212042	RIGHT ENGINE OZONE CONVERTER 53A405-4-800 1234-2551 REF: AMM 21-20-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
+ 212042A	TEST RIGHT ENGINE OZONE CONVERTER EFFICIENCY (W2140001) 53A405-4-800 1234-2551 REF: AMM 21-20-12	MOS HRS/MSC AFL	3600	+25/-25			11-AUG-2008 0 0	3600	3625
212101	NO. 1 THERMAL CONTROL ACTUATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
212102	NO. 2 THERMAL CONTROL ACTUATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
212105	LEFT ECS TRANSITION DUCT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
212106	RIGHT ECS TRANSITION DUCT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
212201	LEFT GASPER AIR CHECK VALVE PN SN-UNKNOWN REF: AMM 21-20-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
212202	RIGHT GASPER AIR CHECK VALVE PN SN-UNKNOWN REF: AMM 21-20-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
212213	LEFT CABIN AIR CHECK VALVE PN SN-UNKNOWN REF: AMM 21-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
212214	RIGHT CABIN AIR CHECK VALVE PN SN-UNKNOWN REF: AMM 21-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
212801	AVIONICS COOLING B13 FAN 4521208521-009 A00806552-01(B) REF: AMM 21-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
213000	CABIN PRESSURE CONTROLLER 2119858-10 58-K0059 REF: AMM 21-30-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
213001	LEFT EMERGENCY PRESSURE SHUTOFF VALVE 3291224-1 1096 REF: AMM 21-31-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
213002	RIGHT EMERGENCY PRESSURE SHUTOFF VALVE 3291224-1 1094 REF: AMM 21-31-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
213021	JET PUMP EJECTOR PN SN-UNKNOWN REF: AMM 21-30-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
213031	PRIMARY OUTFLOW VALVE 103858-1 117A-A0516 REF: AMM 21-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
213032	OUTFLOW, SECONDARY VALVE 103858-2 127-C0303 REF: AMM 21-30-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
213055	EMERGENCY PRESSURE ANEROID SWITCH E45C-47 5768 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
213056	ABSOLUTE PRESSURE SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
213101	TAILCONE CHECK VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
213110	CABIN PRESSURIZATION CHECK VALVE 130158-3-1 127-A1048 REF: AMM 21-30-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
214301	FOOT WARMER (S167) THERMOSTAT PN SN-UNKNOWN REF: AMM 21-41-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
214925	LEFT CHECK, ECS (3.0 DIAMETER) VALVE PN SN-UNKNOWN REF: AMM 36-10-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
214926	RIGHT CHECK, ECS (3.0 DIAMETER) VALVE PN SN-UNKNOWN REF: AMM 36-10-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
215001	WATER SEPARATOR ASSEMBLY 2341168-1 601 REF: AMM 21-50-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
215002	WATER SEPERATOR BYPASS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
215010	ACM PRECOOLER ASSEMBLY PN SN-UNKNOWN REF: AMM 21-50-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
215013	BI-LEVEL PRESSURE REGULATING & SHUTOFF (L19) VALVE 3215612-1 454 REF: AMM 21-50-02	MOS HRS/MSC AFL	O/C				03-DEC-2014 1476.8 1219		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
215015	ACM BYPASS CHECK VALVE PN SN-UNKNOWN REF: AMM 21-50-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
215019	CABIN REFRIGERATION CONDENSER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
215030	ENVIRONMENTAL CONTROL UNIT 2215150-3 600 REF: AMM 21-50-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
215033	AIR CYCLE MACHINE PN SN-UNKNOWN REF: AMM 21-50-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
215036	HEAT, PRIMARY, SECONDARY EXCHANGER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
215039	AIR CYCLE MACHINE TURBINE PN SN-UNKNOWN REF: AMM 21-50-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
215043	AFT EVAPORATOR PN SN-UNKNOWN REF: AMM 21-51-09	MOS HRS/MSC AFL	N/A	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
215044	FORWARD EVAPORATOR PN SN-UNKNOWN REF: AMM 21-51-07	MOS HRS/MSC AFL	N/A	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
215100	AIR CONDITIONING COMPRESSOR PN SN-UNKNOWN REF: AMM 21-51-01	MOS HRS/MSC AFL	N/A	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
215101	AIR CONDITIONING COMPRESSOR DRIVE MOTOR PN SN-UNKNOWN REF: AMM 21-51-02	MOS HRS/MSC AFL	N/A	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
215101A	PERFORM AIR CONDITIONING COMPRESSOR DRIVE MOTOR BRUSH WEAR INSPECTION - IRN L2150054 PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				11-AUG-2008 0 0		
215101B	OVERHAUL AIR CONDITIONING COMPRESSOR DRIVE MOTOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				11-AUG-2008 0 0		
216001	INTEGRATED ECS TEMPERATURE CONTROLLER 1151830-3 1151830-00873 REF: AMM 21-60-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
216013	COCKPIT TEMPERATURE CONTROL VALVE 3291222-1 1110 REF: AMM 21-60-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216014	CABIN TEMPERATURE CONTROL VALVE 3291222-1 1113 REF: AMM 21-60-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
216025	COCKPIT TEMPERATURE CONTROL SELECTOR PN SN-UNKNOWN REF: AMM 21-60-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
216026	CABIN TEMPERATURE CONTROL SELECTOR PN SN-UNKNOWN REF: AMM 21-60-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
216036	OVERHEAT, COCKPIT DUCT THERMOSTAT PN SN-UNKNOWN REF: AMM 21-60-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
216037	OVERHEAT, CABIN DUCT THERMOSTAT PN SN-UNKNOWN REF: AMM 21-60-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
216040	CABIN TEMP 28VDC SENSOR/FAN ASSEMBLY PN SN-UNKNOWN REF: AMM 21-60-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
216047	TEMP CONTROL, COCKPIT VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		



Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216049	CABIN DUCT OVERTEMP LIMITER 627962-2 / N531-9056 627962-21685 REF: AMM 21-60-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
216071	LOW LIMIT TEMPERATURE CONTROL VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
216074	REGULATING, SERVO AIR PRESSURE VALVE 60810-1 1318 REF: AMM 36-15-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
216081	TEMPERATURE, COCKPIT DUCT SENSOR 627962-2 / N531-9056 21795 REF: AMM 21-60-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
216083	COCKPIT TEMPERATURE SENSOR PN SN-UNKNOWN REF: AMM 21-60-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
216084	CABIN TEMPERATURE, LOW LIMIT SENSOR PN SN-UNKNOWN REF: AMM 21-50-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
+ 5-19-00-E2130065	CABIN PRESSURIZATION SYSTEM. (IRN # E2130065). REF: AMM 21-30-00	MOS HRS/MSC AFL	1200	+25/-25			30-NOV-2017 2313.6 1848	3513.6	3538.6

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-00-L2150054	WEAR INSPECTION - AIR CONDITIONING COMPRESSOR DRIVE MOTOR BRUSHES - PERFORM WEAR INSPECTION. (RETURN DRIVE MOTOR TO AUTHORIZED SERVICE FACILITY FOR OVERHAUL). (EFFECTIVE ON AIRCRAFT 45-250 AND SUBSEQUENT EQUIPPED WITH KEITH PRODUCTS VAPOR CYCLE AIR CONDITIONING SYSTEM USING REFRIGERANT R-134).								
NOT INSTALLED	REF: GENERIC NO REF	MOS HRS/MSC - AFL					11-AUG-2008 0 0		
5-19-00-L2150055	OVERHAUL - AIR CONDITIONING COMPRESSOR MOTOR - PERFORM OVERHAUL. (RETURN DRIVE MOTOR TO AUTHORIZED SERVICE FACILITY FOR OVERHAUL). (EFFECTIVE ON AIRCRAFT 45-250 AND SUBSEQUENT EQUIPPED WITH KEITH PRODUCTS VAPOR CYCLE AIR CONDITIONING SYSTEM USING REFRIGERANT R-134).								
NOT INSTALLED	REF: GENERIC NO REF	MOS HRS/MSC - AFL					11-AUG-2008 0 0		
+ 5-19-01-O2141002	WATER SEPERATOR COALESCER BAG. (ZONE/ACCESS 310HL, 310RR IRN # O2141002)								
	REF: GENERIC NO REF	MOS HRS/MSC O/C AFL					12-AUG-2008 11.9 10		
C2141001 (s)	WATER SEPARATOR COALESCER BAG - PERFORM VISUAL INSPECTION. CLEAN IF NECESSARY. (NOTE: THE SERVICING ACTIVITY MAY REQUIRE A MORE FREQUENT INTERVAL, DEPENDING ON ENVIRONMENTAL AND OPERATIONAL REQUIREMENTS, AND SHOULD BE ADJUSTED BY INDIVIDUAL OPERATORS)						PKG		
	REF: AMM 05-10-00	PKG 2 MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			29-AUG-2018 2621.3 2079		
E2130003 (s)	PRESSURIZATION CONTROL SYSTEM - PERFORM OPERATIONAL CHECK						PKG		
	REF: AMM 21-30-00	PKG 7 MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			30-NOV-2017 2313.6 1848		
J2160007 (s)	TEMPERATURE CONTROL SYSTEM - INSPECT AND CLEAN CABIN AND COCKPIT TEMPERATURE CONTROL VALVE SERVO AIR FILTERS. (EFFECTIVE ON AIRCRAFT 45-005 THRU 45-232 POST SB 45-21-16, AND AIRCRAFT 45-233 THRU 45-2000.)						PKG		
	REF: AMM 21-60-11	PKG 8 MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			30-NOV-2017 2313.6 1848		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
02130000 (s)	PERFORM PRIMARY AND SECONDARY OUTFLOW VALVES - INSPECTION. PKG 13	MOS	48	+14d/-14d			PKG 20-MAY-2016		
	REF: See Workcard	HRS/MSC AFL	1200	+25/-25			1821.7 1492		
02130001 (s)	REPLACE OUTFLOW VALVE AIR FILTER - REMOVE AND REPLACE. PKG 19	MOS	96	+14d/-14d			PKG 20-MAY-2016		
	REF: AMM 21-30-04	HRS/MSC AFL	2400	+25/-25			1821.7 1492		
02130002 (s)	PERFORM ** PRESSURIZATION CONTROL SYSTEM - FUNCTIONAL TEST. PKG 13	MOS	48	+14d/-14d			PKG 20-MAY-2016		
AIRWORTHINESS	REF: AMM 21-30-00	HRS/MSC AFL	1200	+25/-25			1821.7 1492		
CHAPTER 22 AUTO FLIGHT									
2210-RVSM	FLIGHT CHECK AUTOMATIC ALTITUDE HOLD FUNCTIONAL. RVSM COMPLIANT AIRCRAFT.	MOS					11-AUG-2008		
	REF: GENERIC CUSTOM	HRS/MSC AFL	N/R				0 0		
221001	FLIGHT GUIDANCE, AUTOPILOT CONTROLLER 7021170-901	MOS		TSN:0			11-AUG-2008		
	08041877	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 22-10-01	AFL		TSN:0			0		
221041	AUTOPILOT, ROLL SERVO 4006719-949	MOS		TSN:0			11-AUG-2008		
	0709J003	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 22-10-04	AFL		TSN:0			0		
221045	SERVO, ROLL BRACKET 4005842	MOS		TSN:0			11-AUG-2008		
	0801J191	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 22-10-05	AFL		TSN:0			0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
221051	AUTOPILOT, PITCH SERVO 4006719-923 04068601 REF: AMM 22-10-02	MOS HRS/MSC AFL	O/C				30-NOV-2017 2313.6 1848		
221055	SERVO, PITCH BRACKET 4005842 0704H720 REF: AMM 22-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
221061	AUTOPILOT, YAW SERVO 7012919-904 0708H105 REF: AMM 22-10-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
221065	SERVO, YAW BRACKET 7012098-902 0706/065 REF: AMM 22-10-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
225001	YAW INTERFACE UNIT 4522108501-011 100808941 REF: AMM 22-50-01	MOS HRS/MSC AFL	O/C				17-NOV-2008 171.72 135		
225031	PILOT YAW FORCE, RUDDER BOOST SYSTEM SENSOR PN SN-UNKNOWN REF: AMM 22-50-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
225032	COPILOT YAW FORCE, RUDDER BOOST SYSTEM. SENSOR PN SN-UNKNOWN REF: AMM 22-50-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A2210033 (s)	** AUTOPILOT SYSTEM - PERFORM AUTOPILOT DISCONNECT TONE TEST						PKG		
	PKG 7	MOS	24	+14d/-14d			30-NOV-2017		
AIRWORTHINESS	REF: AMM 22-10-00	HRS/MSC AFL	600	+25/-25			2313.6 1848		
G2210030 (s)	PERFORM PITCH SERVO CABLES - CABLE TENSION CHECK						PKG		
	PKG 14	MOS	48	+14d/-14d			20-MAY-2016		
	REF: AMM 22-10-03	HRS/MSC AFL	1200	+25/-25			1821.7 1492		
G2210031 (s)	PERFORM ROLL SERVO CABLES - CABLE TENSION CHECK						PKG		
	PKG 13	MOS	48	+14d/-14d			20-MAY-2016		
	REF: AMM 22-10-05	HRS/MSC AFL	1200	+25/-25			1821.7 1492		
CHAPTER 23 COMMUNICATIONS									
230001	UNILINK PROCESSER								
	1066-10-000	MOS					TSN:0	11-AUG-2008	
	428	HRS/MSC	O/C				TSN:0	0	
	REF: GENERIC NO REF	AFL					TSN:0	0	
230002	CONFIGURATION MODULE								
	10651	MOS					TSN:0	11-AUG-2008	
	2298	HRS/MSC	O/C				TSN:0	0	
	REF: GENERIC NO REF	AFL					TSN:0	0	
231011	NO. 1 POWER AMPLIFIER/HF ANTENNA COUPLER								
	064-01074-0101	MOS					TSN:0	11-AUG-2008	
	2537	HRS/MSC	O/C				TSN:0	0	
	REF: GENERIC NO REF	AFL					TSN:0	0	
231012	NO. 2 POWER AMPLIFIER/HF ANTENNA COUPLER								
	064-01074-0101	MOS					TSN:0	11-AUG-2008	
	2535	HRS/MSC	O/C				TSN:0	0	
	REF: GENERIC NO REF	AFL					TSN:0	0	

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231021	NO. 1 VHF COMMUNICATIONS TRANSCEIVER UNIT 7510700-667 0809C196 REF: AMM 23-11-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			05-DEC-2015 1743.3 1436		
231021A	TEST/INSPECT NO. 1 VHF COMMUNICATIONS TRANSCEIVER UNIT ATC TRANSPONDER (FAR 91.413) 7510700-667 0809C196 REF: See Workcard	MOS HRS/MSC AFL	24	+14d/-14d			15-NOV-2017	15-NOV-2019	29-NOV-2019
231022	NO. 2 VHF COMMUNICATIONS TRANSCEIVER UNIT 7510700-667 00125769 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			05-DEC-2015 1743.3 1436		
231022A	TEST/INSPECT NO. 2 VHF COMMUNICATIONS TRANSCEIVER UNIT ATC TRANSPONDER (FAR 91.413) 7510700-667 00125769 REF: See Workcard	MOS HRS/MSC AFL	24	+14d/-14d			15-NOV-2017	15-NOV-2019	29-NOV-2019
231030	NO. 1 HF SELCAL RECEIVER/EXCITER 064-01073-0102 3023 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				12-APR-2013 1283.02 1022		
231031	NO. 2 HF SELCAL RECEIVER/EXCITER 064-01073-0102 3093 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
231032	HF SELCAL ANTENNA PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231033	UPPER VHF ANTENNA DM C60-17-1 15316 REF: AMM 23-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
231034	LOWER VHF ANTENNA DM C60-17-1 15318 REF: AMM 23-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
231045	NO. 1 HF (KCU-951) CONTROL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
231046	NO. 2 HF (KCU-951) CONTROL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
231051	NO. 1 BRIDGING, HF AMPLIFIER 064-01072-0101 3063 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
231052	NO. 2 BRIDGING, HF AMPLIFIER 064-01072-0101 3067 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
231090	PILOT HEADSET PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231091	COPILOT HEADSET PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
231300	PHONE MAGNASTAR TRANSCEIVER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
231305	MAGNASTAR ANTENNA PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
231307	COCKPIT ASSEMBLY PHONE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
231308	CABIN ASSEMBLY PHONE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
231310	ARTU TRAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
231313	NO. 1 CABIN DISTRIBUTION BUS REPEATER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231314	NO. 2 CABIN DISTRIBUTION BUS REPEATER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
231315	CALL ALERTER (CAS) SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
231320	CABIN IRIDIUM SATCOM HANDSET PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
231321	CABIN IRIDIUM SATCOM PHONE CRADLE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
231322	CABIN IRIDIUM SATCOM HANDSET PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
231323	AFT LAVATORY IRIDIUM SATCOM TRANSCEIVER 500617-2 5762 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
231325	IRIDIUM SATCOM SONALERT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231327	COCKPIT IRIDIUM SATCOM PHONE CRADLE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
231328	COCKPIT IRIDIUM SATCOM HANDSET 9L8810A-B 3001999 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
231330	FWD IRIDIUM SATCOM ANTENNA CI490-1 / 500644-1 212548 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
231335	COCKPIT IRIDIUM SATCOM BASE UNIT ECHS2507-016-001 S3001954 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
231351	SATELLITE DATA (SDU) UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
233001	FORWARD CABIN VIDEO MONITOR- LCD-9121-101-2 050800038 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				06-MAY-2010 619.22 493		
233002	AFT CABIN VIDEO MONITOR- LCD-9121-101-1 050800039 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
233003	AUDIO DISTRIBUTION MODULE AV-4589-01-1 050800075 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
233005	PA SYSTEM AMPLIFER PA-7501-01-1 030801046 REF: AMM 23-30-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
233010	INFRARED REMOTE MODULE RECEIVER IFR-485-05-1 050800814 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
233015	AUDIO/VIDEO CONTROLLER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
233053	DVD PLAYER DVD-301-01-1 120700564 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
233054-1	CD PLAYER CHANGER MCD-102-RU-3 040800294 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
233054-2	CD PLAYER CONTROL UNIT MCD-102-CH-1 050800495 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
233055	CASSETTE TAPE PLAYER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
233101	LEFT FORWARD CABIN SPEAKER EN-MT-45A 050800403 REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
233102	RIGHT FORWARD CABIN SPEAKER EN-MT-45A 050800404 REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
233103	LEFT AFT CABIN SPEAKER EN-MT-45A 040800763 REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
233104	RIGHT AFT CABIN SPEAKER EN-MT-45A 050800303 REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
233105	SUBWOOFER SPEAKER EN-646-W 100700557 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
233201	PASSENGER INTERFACE UNIT PIU-45-04-1 050800812 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
234000	INTERPHONE JACK BOX ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
235001	#1 AUDIO CONTROL UNIT 4523558501-003 0803C793 REF: AMM 23-50-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
235002	#2 AUDIO CONTROL UNIT 7511001-937 98032879 REF: AMM 23-50-01	MOS HRS/MSC AFL	O/C	TSR:4 TSR:0 TSR:0			13-FEB-2017 2031.6 1662		
235013	LEFT COCKPIT SPEAKER PN SN-UNKNOWN REF: AMM 23-50-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
235014	RIGHT COCKPIT SPEAKER PN SN-UNKNOWN REF: AMM 23-50-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
236001	STATIC INVERTER 2D1200-1A-1011 GB001100 REF:	MOS HRS/MSC AFL	O/C	TSR:13 TSR:0 TSR:0			30-NOV-2017 2313.6 1848		
236005	WEATHER XM RADIO RECEIVER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
236010	WEATHER XM DATA PORT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
236015	XM RADIO ANTENNA PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
236096	NO. 1 NAVIGATION STRAP BOARD PN SN-UNKNOWN REF: AMM 34-51-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
236097	NO. 2 NAVIGATION STRAP BOARD PN SN-UNKNOWN REF: AMM 34-51-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
236098	NO. 1 COMMUNICATION STRAP BOARD PN SN-UNKNOWN REF: AMM 23-11-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
236099	NO. 2 COMMUNICATION STRAP BOARD PN SN-UNKNOWN REF: AMM 23-11-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
237001	COCKPIT VOICE (CVR) RECORDER 980-6022-011 CVR120-09753 REF: AMM 23-70-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			20-MAY-2016 1821.7 1492		



Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
237001A	INTELLIGIBILITY CHECK COCKPIT VOICE (CVR) RECORDER CVR 980-6022-011 CVR120-09753 REF: GENERIC CUSTOM	MOS HRS/MSC AFL	12		-3		15-APR-2018 2434.6 1948	12-APR-2019	
CUSTOMER CODE									
237005	CVR UNDERWATER LOCATOR (ULB) BEACON DK120/90 AT115110 REF: See Workcard	MOS HRS/MSC AFL	O/C				29-JUN-2018 2539.7 2020		
+ 237005A	FUNCTIONAL TEST CVR UNDERWATER LOCATOR (ULB) BEACON / CLEAN BEACON SWITCH AND PERFORM TEST OF ULB BATTERY (IRN # L2560000) DK120/90 AT115110 REF: See Workcard	MOS HRS/MSC AFL	24	+14d/-14d			11-JUN-2018	11-JUN-2020	25-JUN-2020
+ 237005B	REPLACE CVR UNDERWATER LOCATOR (ULB) BEACON BATTERY ON OR BEFORE ULB BATTERY REPLACEMENT DATE. (ZONE/ACCESS 300 IRN # D2566001) DK120/90 AT115110 REF: See Workcard	MOS HRS/MSC AFL	DUE				01-MAY-2018	01-JUN-2025 M	
237018	CVR INERTIA SWITCH 3LO-453/8 82678 REF: See Workcard	MOS HRS/MSC AFL	O/C				11-AUG-2008 0 0		
237019	COCKPIT AREA MICROPHONE 980-6113-001 CAMDSHMT-05304 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				11-AUG-2008 0 0		
237030	PANEL SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
237031	COCKPIT VOICE RECORDER PRE-AMPLIFIER 980-6118-001 CAMPRAMP-00750 REF: AMM 23-70-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
238001	NO. 1 RADIO MANAGEMENT (RMU) UNIT 7013270-967 07075892 REF: AMM 23-80-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
238002	NO. 2 RADIO MANAGEMENT (RMU) UNIT 7013270-967 07035701 REF: AMM 23-80-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
238025	CLEARANCE DELIVERY UNIT 7513000-835 08023669 REF: AMM 23-82-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
239004	MASTER CONTROL SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
239011	LAVATORY MASTER CONTROL SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
A2300000 (s)	** COMMUNICATIONS SYSTEMS - PERFORM OPERATIONAL CHECK PKG 7	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 30-NOV-2017 2313.6 1848		
AIRWORTHINESS	REF: AMM 23-00-00								

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
V2312003 (s)	HF ANTENNA- PERFORM VISUAL INSPECTION. CHECK FOR PROPER TENSION ON HF ANTENNA WIRE	MOS					20-MAY-2016		
	REF: AMM 23-12-04	HRS/MSC AFL	1200				1821.7 1492		
CHAPTER 24 ELECTRICAL POWER									
240109	AFT CIRCUIT BREAKER PANEL ASSY	PN					11-AUG-2008		
	REF: AMM 24-60-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			0 0 0		
242001	NO. 1 AC 5KVA ALTERNATOR	90278-2					30-NOV-2017		
	REF: AMM 24-20-01	MOS HRS/MSC AFL	O/C	TSO:5 TSO:0 TSO:0			2313.6 1848		
+ 242001A	REPLACE NO. 1 AC 5KVA ALTERNATOR BEARING. (**IRN # F2420000)	90278-2					30-NOV-2017		
AIRWORTHINESS	REF: GENERIC NO REF	MOS HRS/MSC AFL	1200	+25/-25			2313.6 1848	3513.6	3538.6
242002	NO. 2 AC 5KVA ALTERNATOR	90278-2					30-NOV-2017		
	REF: AMM 24-20-01	MOS HRS/MSC AFL	O/C	TSO:3 TSO:0 TSO:0			2313.6 1848		
+ 242002A	REPLACE NO. 2 AC 5KVA ALTERNATOR BEARING. (**IRN # F2420000)	90278-2					30-NOV-2017		
AIRWORTHINESS	REF: GENERIC NO REF	MOS HRS/MSC AFL	1200	+25/-25			2313.6 1848	3513.6	3538.6
242008	AC/DC VOLT INDICATOR	PN					11-AUG-2008		
	REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			0 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
242050	REMOTE CONTROL CIRCUIT BREAKER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
242052	REMOTE CONTROL CIRCUIT BREAKER SM600BA75N1 / N936-9076 94579 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
242054	REMOTE CONTROL CIRCUIT BREAKER M83383/01-07 97817 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				16-MAY-2012 1018.22 813		
242081	AC 1200 AMP INVERTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
242082	TAILCONE AC INVERTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
242083	AC INVERTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
243001	NO. 1 STARTER/GENERATOR 6608258-012 P1217/CA REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:4 TSO:0 TSO:0			30-NOV-2017 2313.6 1848		



Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 243001A	OVERHAUL NO. 1 STARTER/GENERATOR IRN P2430003. (ZONE/ACCESS 410) 6608258-012 P1217/CA REF: AMM 24-30-01	MOS HRS/MSC AFL	1200	+25/-25			30-NOV-2017 2313.6 1848	3513.6	3538.6
243001B	REPLACE NO. 1 STARTER/GENERATOR BEARING (EFFECTIVE ON AIRCRAFT 45-005 THRU 45-366 NOT MODIFIED PER SB 45-24-12 AND 45-71-6). IRN P2430007 6608258-012 P1217/CA REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A						
243002	NO. 2 STARTER/GENERATOR 6608458-012 P198/CA REF: AMM 24-30-01	MOS HRS/MSC AFL	O/C	TSO:5 TSO:0 TSO:0			30-NOV-2017 2313.6 1848		
+ 243002A	OVERHAUL NO. 2 STARTER/GENERATOR IRN P2430003. (ZONE/ACCESS 410) 6608458-012 P198/CA REF: AMM 24-30-01	MOS HRS/MSC AFL	1200	+25/-25			30-NOV-2017 2313.6 1848	3513.6	3538.6
243002B	REPLACE NO. 2 STARTER/GENERATOR BEARING (EFFECTIVE ON AIRCRAFT 45-005 THRU 45-366 NOT MODIFIED PER SB 45-24-12 AND 45-71-6). IRN P2430007 6608458-012 P198/CA REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A						
243003	APU STARTER/GENERATOR 23080-023B P-1038 REF: AMM 49-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
+ 243003A	OVERHAUL APU STARTER/GENERATOR AND BRUSH REPLACEMENT. (IRN # V4900021, V4900003) 23080-023B P-1038 REF: AMM 49-40-01	MOS HRS/MSC AFL APH	1200	+25/-25			11-AUG-2008 0 0 0	1200	1225

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 243003B	VISUALLY INSPECT APU STARTER/GENERATOR GEAR BOX DRIVE SPLINE. (IRN # 04900006) 23080-023B P-1038 REF: AMM 05-10-00	MOS HRS/MSC AFL APH	1200	+25/-25			11-AUG-2008 0 0 0	1200	1225
243005	LEFT (GCU) GENERATOR CONTROL UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
243006	RIGHT (GCU) GENERATOR CONTROL UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
243019	NO. 1 MAIN SHIP BATTERY RG380E/40L 40608621 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			28-APR-2017 2080.2 1694		
+ 243019A	CHECK/SERVICE NO. 1 MAIN SHIP BATTERY (IRN O1222000 NI-CAD) - CAPACITY CHECK (IRN T1222004 38 AMP HOUR LEAD- ACID) - CAPACITY CHECK (IRN T1222007 28 AMP HOUR LEAD ACID) RG380E/40L 40608621 REF: See Workcard	MOS HRS/MSC AFL	12	+1m/-1m			14-JAN-2019 2767.3 2201	14-JAN-2020	14-FEB-2020
VENDOR RECOMMENDED									
243020	NO. 2 MAIN SHIP BATTERY RG-380E/40L 40812355 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:6 TSN:0 TSN:0			16-DEC-2016 2003.7 1639		
+ 243020A	CHECK/SERVICE NO. 2 MAIN SHIP BATTERY (IRN O1222000 NI-CAD) - CAPACITY CHECK (IRN T1222004 38 AMP HOUR LEAD- ACID) - CAPACITY CHECK (IRN T1222007 28 AMP HOUR LEAD ACID) RG-380E/40L 40812355 REF: See Workcard	MOS HRS/MSC AFL	12	+1m/-1m	-16		14-MAY-2018 2469.9 1969	28-APR-2019	28-MAY-2019
VENDOR RECOMMENDED									

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243037	EMERGENCY (IRN N2431063 FOR RG-443) BATTERY RG-443 40966794 REF: See Workcard	MOS HRS/MSC AFL	60 5000	+14d/-14d +25/-25	TSN:2 TSN:0 TSN:0		14-JAN-2019 2767.3 2201	14-NOV-2023 7767.3	28-NOV-2023 7792.3
+ 243037A	PERFORM EMERGENCY (IRN N2431063 FOR RG-443) BATTERY CAPACITY CHECK (P/N 7624308001, IRN O2431002), (P/N RG-443, IRN N2431062) RG-443 40966794 REF: CMM 24-30-67	MOS HRS/MSC AFL	12 1000	+14d/-14d +25/-25			14-JAN-2019 2767.3 2201	14-JAN-2020 3767.3	28-JAN-2020 3792.3
246001	LEFT FORWARD POWER DISTRIBUTION PANEL 650GC02Y03 542 REF: AMM 24-60-02	MOS HRS/MSC AFL			TSN:118 TSN:2505.33 TSN:2002		14-JUN-2018 2505.33 2002		
246002	RIGHT FORWARD POWER DISTRIBUTION PANEL 655GC02Y03 546 REF: AMM 24-60-02	MOS HRS/MSC AFL			TSN:0 TSN:0 TSN:0		11-AUG-2008 0 0		
246003	LEFT AFT POWER DISTRIBUTION PANEL 660GC02Y07 619 REF: AMM 24-60-03	MOS HRS/MSC AFL			TSN:0 TSN:0 TSN:0		11-AUG-2008 0 0		
246004	RIGHT AFT POWER DISTRIBUTION PANEL 665GC02Y07 685 REF: AMM 24-60-03	MOS HRS/MSC AFL			TSR:2 TSR:0 TSR:0		18-FEB-2013 1267.22 1008		
246101	LEFT GENERATOR CONTROL UNIT PRINTED CIRCUIT BOARD PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL			TSN:0 TSN:0 TSN:0		11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
246102	LEFT LOGIC PRINTED CIRCUIT BOARD PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
246104	RIGHT GENERATOR CONTROL UNIT PRINTED CIRCUIT BOARD PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
246105	RIGHT LOGIC PRINTED CIRCUIT BOARD PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
246106	APU GENERATOR CONTROL UNIT PRINTED CIRCUIT BOARD PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
+ 5-19-00-U2431005	CABLES AND RECEPTACLES - PERFORM BATTERY CONNECTOR TOLERANCE CHECK. (REFER TO 24-31-00.). IRN U2431005 REF: AMM 24-31-00	MOS HRS/MSC AFL	300	+25/-25	-7.7		29-AUG-2018 2621.3 2079	2913.6	2938.6
B2450002 (s)	PERFORM ** ELECTRICAL SYSTEM CONTROL - OPERATIONAL CHECK PKG 13 REF: GENERIC NO REF	MOS HRS/MSC AFL	48	+14d/-14d +25/-25			PKG 20-MAY-2016 1821.7 1492		
G2431001 (s)	EMERGENCY BATTERY CABLES - PERFORM VISUAL INSPECTION PKG 7 REF: AMM 05-10-00	MOS HRS/MSC AFL	24	+14d/-14d +25/-25			PKG 30-NOV-2017 2313.6 1848		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
H2450001 (s)	** AUXILIARY POWER SUPPLIES - PERFORM FUNCTIONAL TEST						PKG		
	PKG 7	MOS	24	+14d/-14d			30-NOV-2017		
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC AFL	600	+25/-25			2313.6 1848		
H2450023 (s)	** EMER BATT LOW AND GEN AMPS HIGH INDICATION - PERFORM OPERATIONAL CHECK.						PKG		
	PKG 7	MOS	24	+14d/-14d			30-NOV-2017		
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC AFL	600	+25/-25			2313.6 1848		
L2400002 (s)	ELECTRICAL WIRING - PERFORM VISUAL INSPECTION FOR ROUTING, SECURITY, CLEARANCES, CHAFING, AND ELECTRICAL COMPONENTS FOR SECURITY AND GENERAL CONDITION						PKG		
	PKG 7	MOS	24	+14d/-14d			30-NOV-2017		
	REF: AMM 05-10-00	HRS/MSC AFL	600	+25/-25			2313.6 1848		
L2400025 (s)	ELECTRICAL WIRING - PERFORM VISUAL INSPECTION FOR ROUTING, SECURITY, CLEARANCES, CHAFING, AND ELECTRICAL COMPONENTS FOR SECURITY AND GENERAL CONDITION						PKG		
	PKG 8	MOS	24	+14d/-14d			30-NOV-2017		
	REF: AMM 05-10-00	HRS/MSC AFL	600	+25/-25			2313.6 1848		
L2430005 (s)	STARTER/GENERATOR - PERFORM GROUNDING LUG BONDING CHECK						PKG		
	PKG 9	MOS	24	+14d/-14d			30-NOV-2017		
	REF: AMM 24-30-01	HRS/MSC AFL	600	+25/-25			2313.6 1848		
L2430006 (s)	STARTER/GENERATOR - PERFORM VISUAL INSPECTION OF GROUNDING LUGS						PKG		
	PKG 9	MOS	24	+14d/-14d			30-NOV-2017		
	REF: AMM 05-10-00	HRS/MSC AFL	600	+25/-25			2313.6 1848		
Q2460001 (s)	PERFORM ** POWER DISTRIBUTION SYSTEM - SQUAT SWITCH CHECK.						PKG		
	PKG 17	MOS	48	+14d/-14d			20-MAY-2016		
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC AFL	1200	+25/-25			1821.7 1492		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 25	EQUIPMENT/FURNISHINGS								
250010	RELAY MODULE								
	MSM9646-01-1	MOS		TSN:0			11-AUG-2008		
	050800429	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
252000-1	#1 PASSENGER SEAT								
	M6613100-(001)-(D)	MOS		TSN:0			11-AUG-2008		
	080421-04	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 25-20-45	AFL		TSN:0			0		
252000-2	#2 PASSENGER SEAT								
	M6613100-(002)-(D)	MOS		TSN:0			11-AUG-2008		
	080421-06	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 25-20-45	AFL		TSN:0			0		
252000-3	#3 PASSENGER SEAT								
	M6613100-(001)-(D)	MOS		TSN:0			11-AUG-2008		
	080421-03	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 25-20-45	AFL		TSN:0			0		
252000-4	#4 PASSENGER SEAT								
	M6613100-(002)-(D)	MOS		TSN:0			11-AUG-2008		
	080421-07	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 25-20-45	AFL		TSN:0			0		
252000-5	#5 PASSENGER SEAT								
	M6613100-(001)-(D)	MOS		TSN:0			11-AUG-2008		
	080421-02	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 25-20-45	AFL		TSN:0			0		
252000-6	#6 PASSENGER SEAT								
	M6613100-(002)-(D)	MOS		TSN:0			11-AUG-2008		
	080421-05	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 25-20-45	AFL		TSN:0			0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
252000-7	#7 PASSENGER SEAT M6613100-(001)-(D) 080421-01 REF: AMM 25-20-45	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
252000-8	#8 PASSENGER SEAT M6613100-(002)-(D) 080421-08 REF: AMM 25-20-45	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
252000-9	JUMP SEAT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
252001-1	#1 PASSENGER SEAT PCU SP-45-54 020800050 REF: AMM 25-20-45	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
252001-2	#2 PASSENGER SEAT PCU SP-45-54 050800241 REF: AMM 25-20-45	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
252001-3	#3 PASSENGER SEAT PCU SP-45-54 050800244 REF: AMM 25-20-45	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
252001-4	#4 PASSENGER SEAT PCU SP-45-54 050800243 REF: AMM 25-20-45	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
252001-5	#5 PASSENGER SEAT PCU SP-45-54 050800239 REF: AMM 25-20-45	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
252001-6	#6 PASSENGER SEAT PCU SP-45-54 010800058 REF: AMM 25-20-45	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
252001-7	#7 PASSENGER SEAT PCU SP-45-54 050800240 REF: AMM 25-20-45	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
252001-8	#8 PASSENGER SEAT PCU SP-45-54 040800746 REF: AMM 25-20-45	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
252001-9	LAVATORY PASSENGER CONTROL UNIT PCU SP-45-55 031600471 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R	TSN:22 TSN:0 TSN:0			29-JUN-2018 2539.7 2020		
252005	AIRSHOW FLIGHT DECK CONTROLLER 922000-2 H01004247 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
252010	AIRSHOW DISPLAY UNIT 925000-100 D01003967 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
252020	CLOSET SWITCH PANEL ASSEMBLY SP-45-21 050800485 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
252090	POWER PORT 110 VOLT OUTLET SP-45-26 050800176 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
252091	POWER PORT 110 VOLT OUTLET PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
252092	POWER PORT 110 VOLT OUTLET PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
252095	POWER PORT 110 VOLT OUTLET PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
252097	NO. 1 AC OUTLET PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
252098	NO. 2 AC OUTLET PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
252099	NO. 3 AC OUTLET PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
253001	WARMING OVEN 255A-LH-28/115 231569503 REF:	MOS HRS/MSC AFL	-	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
253075	NO. 1 HEATED WATER CONTAINER AR9061-3 0235 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
253076	NO. 2 HEATED WATER CONTAINER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
253077	HEATED WATER SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
253080	GALLEY DRAIN VALVE SOLENOID PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
256001	PILOT CREW SEAT TALJ2-14PM01-02 / 4525103038-007 922 REF: AMM 25-10-50	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256002	COPILOT CREW SEAT TALJ2-14CM01-02 / 4525103038-008 930 REF: AMM 25-10-50	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
256030	PILOT PROTECTIVE BREATHING (PBE), (IRN A3510008) EQUIPMENT UNIT 119003-21 004-14135M REF: AMM 25-60-00	MOS HRS/MSC AFL	120	+14d/-14d TSN:3 TSN:0 TSN:0			05-OCT-2016 1952.1 1591	05-JUL-2026	19-JUL-2026
256032	COPILOT PROTECTIVE BREATHING (PBE), (IRN A3510008) EQUIPMENT UNIT PN SN-UNKNOWN REF: AMM 25-60-00	MOS HRS/MSC AFL	-	TSN:0			30-JUN-2008		
256061	PILOT LIFE VEST 63600-101 L2293694 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			02-DEC-2013 1323.8 1061		
+ 256061A	INSPECT PILOT LIFE VEST (IRN # E2561002) 63600-101 L2293694 REF: See Workcard	MOS HRS/MSC AFL	60				14-NOV-2018	14-NOV-2023	
256062	COPILOT LIFE VEST 63600-101 L2293697 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			02-DEC-2013 1323.8 1061		
+ 256062A	INSPECT COPILOT LIFE VEST (IRN # E2561002) 63600-101 L2293697 REF: See Workcard	MOS HRS/MSC AFL	60				14-NOV-2018	14-NOV-2023	



Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256063	NO. 1 LIFE VEST 63600-101 L2294024 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			02-DEC-2013 1323.8 1061		
+ 256063A	INSPECT NO. 1 LIFE VEST (IRN # E2561002) 63600-101 L2294024 REF: See Workcard	MOS HRS/MSC AFL	60				14-NOV-2018	14-NOV-2023	
256064	NO. 2 LIFE VEST 63600-101 L2294020 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			02-DEC-2013 1323.8 1061		
+ 256064A	INSPECT NO. 2 LIFE VEST (IRN # E2561002) 63600-101 L2294020 REF: See Workcard	MOS HRS/MSC AFL	60				14-NOV-2018	14-NOV-2023	
256065	NO. 3 LIFE VEST 63600-101 L2294025 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			02-DEC-2013 1323.8 1061		
+ 256065A	INSPECT NO. 3 LIFE VEST (IRN # E2561002) 63600-101 L2294025 REF: See Workcard	MOS HRS/MSC AFL	60				14-NOV-2018	14-NOV-2023	
256066	NO. 4 LIFE VEST 63600-101 L2294021 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			02-DEC-2013 1323.8 1061		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 256066A	INSPECT NO. 4 LIFE VEST (IRN # E2561002) 63600-101 L2294021 REF: See Workcard	MOS HRS/MSC AFL	60				14-NOV-2018	14-NOV-2023	
256067	NO. 5 LIFE VEST 63600-101 L2294026 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			02-DEC-2013 1323.8 1061		
+ 256067A	INSPECT NO. 5 LIFE VEST (IRN # E2561002) 63600-101 L2294026 REF: See Workcard	MOS HRS/MSC AFL	60				14-NOV-2018	14-NOV-2023	
256068	NO. 6 LIFE VEST 63600-101 L2294022 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			02-DEC-2013 1323.8 1061		
+ 256068A	INSPECT NO. 6 LIFE VEST (IRN # E2561002) 63600-101 L2294022 REF: See Workcard	MOS HRS/MSC AFL	60				14-NOV-2018	14-NOV-2023	
256069	NO. 7 LIFE VEST 63600-101 L2294028 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			02-DEC-2013 1323.8 1061		
+ 256069A	INSPECT NO. 7 LIFE VEST (IRN # E2561002) 63600-101 L2294028 REF: See Workcard	MOS HRS/MSC AFL	60				14-NOV-2018	14-NOV-2023	

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256070	NO. 8 LIFE VEST 63600-101 L2294023 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			02-DEC-2013 1323.8 1061		
+ 256070A	INSPECT NO. 8 LIFE VEST (IRN # E2561002) 63600-101 L2294023 REF: See Workcard	MOS HRS/MSC AFL	60				14-NOV-2018	14-NOV-2023	
256071	LAVATORY LIFE VEST 63600-101 L2294029 REF: CMM 25-60-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			02-DEC-2013 1323.8 1061		
+ 256071A	INSPECT LAVATORY LIFE VEST (IRN # E2561002) 63600-101 L2294029 REF: See Workcard	MOS HRS/MSC AFL	60				14-NOV-2018	14-NOV-2023	
256076	FIRST AID KIT 2-7129 661/7129 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2014 1480.5 1223		
256076A	VISUALLY INSPECT FIRST AID KIT PER MANUFACTURER INSTRUCTIONS 2-7129 661/7129 REF: GENERIC CUSTOM	MOS HRS/MSC AFL	12				15-APR-2018 2434.6 1948	15-APR-2019	
256080	INSPECT LIFE VESTS 05-19-00-E2561002 REF: CMM 25-60-05	MOS HRS/MSC AFL	60	+14d/-14d			14-NOV-2018 2721.83 2167	14-NOV-2023	28-NOV-2023

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256109	(ELT) EMERGENCY LOCATOR TRANSMITTER 453-5000-(262) 170-03439 REF: AMM 25-62-01	MOS HRS/MSC AFL	O/C	TSN:68			28-APR-2014 1346.5 1096		
+ 256109A	FUNCTIONAL TEST (ELT) EMERGENCY LOCATOR TRANSMITTER ELT SYSTEM (IF INSTALLED). (REFER TO 25-62-00.) PERFORM FUNCTIONAL TEST IN ACCORDANCE WITH FAR 91.207. (IRN # P2561001 12-MONTH)	MOS HRS/MSC AFL	12	+14d/-14d	-16		14-MAY-2018 2469.9 1969	28-APR-2019	12-MAY-2019
+ 256109B	INSPECT (ELT) EMERGENCY LOCATOR TRANSMITTER ELT BATTERIES (IF INSTALLED). (IRN # P2561001) NOTE: PERFORM FUNCTIONAL TEST IN ACCORDANCE WITH FAR 91.207.	MOS HRS/MSC AFL	12	+14d/-14d	-16		14-MAY-2018 2469.9 1969	28-APR-2019	12-MAY-2019
256109C	REPLACE (ELT) EMERGENCY LOCATOR TRANSMITTER ELT BATTERY 453-5000-(262) 170-03439 REF: See Workcard	MOS HRS/MSC AFL	72	+14d/-14d			28-APR-2017 2080.2 1694	28-APR-2023	12-MAY-2023
256109D (s)	REPLACE (ELT) EMERGENCY LOCATOR TRANSMITTER REMOTE SWITCH BATTERY ARTEX 110 SYSTEMS WITHOUT 406 MHZ CAPABILITIES. 453-5000-(262) 170-03439 REF: See Workcard	MOS HRS/MSC AFL	N/A						
N/A EQUIPMENT NOT INSTALLED									
256109E	REPLACE (ELT) EMERGENCY LOCATOR TRANSMITTER REMOTE SWITCH BATTERY (DORNE AND MARGOLIN ELT REMOTE CONTROL BATTERY (P/N U264-1). (ZONE/ACCESS 200 IRN # N2561004)	MOS HRS/MSC AFL	N/A						
NOT INSTALLED	REF: AMM 25-62-04								

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256110	ELT NAV INTERFACE UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
256115	ELT ANTENNA 110-337 210865 REF: AMM 25-62-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
256116	ELT REMOTE SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
258001	CABIN AIRSHOW DISPLAY COMPUTER UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
5-19-01-N2561004	REPLACE REMOTE SWITCH BATTERY (DORNE AND MARGOLIN ELT REMOTE CONTROL BATTERY (P/N U264-1). (ZONE/ACCESS 200 IRN # N2561004)	MOS HRS/MSC AFL	N/A						
NOT INSTALLED	REF:								
L2520000 (s)	CABIN - PERFORM VISUAL INSPECTION OF THE FOLLOWING: A. CABIN SEATS AND SEAT BELTS. ENSURE THAT THE SEATS FUNCTION CORRECTLY AND LOCK IN PLACE. B. STOWAGE CABINETS. C. HEADLINER. D. SIDE PANELS. E. RUG.	PKG 1					29-AUG-2018 2621.3 2079		
	REF: AMM 05-10-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25					

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
02510000 (s)	GLARESHIELD, HEADLINER, AND TRIM STRIPS - PERFORM VISUAL INSPECTION PKG 1 REF: AMM 05-10-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 29-AUG-2018 2621.3 2079		
02510001 (s)	CREW SEATS AND SEAT BELTS - PERFORM VISUAL INSPECTION PKG 1 REF: AMM 05-10-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 29-AUG-2018 2621.3 2079		
U2540000 (s)	ALL LAVATORY PAPER AND LINEN WASTE RECEPTACLE ACCESS DOORS AND DISPOSAL DOORS FOR PROPER OPERATION, FIT, SEALING, LATCHING, AND LEGIBILITY OF PLACARD. PKG 7 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 30-NOV-2017 2313.6 1848		

CHAPTER 26 FIRE PROTECTION

261012	NO. 1 ENGINE FIREWALL FIRE DETECT ELEMENT PN SN-UNKNOWN REF: AMM 26-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
261013	NO. 2 ENGINE FIREWALL FIRE DETECT ELEMENT PN SN-UNKNOWN REF: AMM 26-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
261014	NO. 1 ENGINE ACCESSORY GEARBOX FIRE DETECT ELEMENT PN SN-UNKNOWN REF: AMM 26-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
261015	NO. 2 ENGINE ACCESSORY GEARBOX FIRE DETECT ELEMENT PN SN-UNKNOWN REF: AMM 26-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
261016	NO. 1 ENGINE HOT SECTION FIRE DETECT ELEMENT PN SN-UNKNOWN REF: AMM 26-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
261017	NO. 2 ENGINE HOT SECTION FIRE DETECT ELEMENT PN SN-UNKNOWN REF: AMM 26-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
261057	NO. 1 FIRE DETECT CONTROL UNIT 877-01032 0747-418 REF: AMM 26-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
261058	NO. 2 FIRE DETECT CONTROL UNIT 877-01032 0747-420 REF: AMM 26-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
261069	NO. 1 BLEED AIR LEAK(A76) DETECTION UNIT 35009-39 2056 REF: AMM 26-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
261070	NO. 2 BLEED AIR LEAK(A78) DETECTION UNIT 35009-39 2058 REF: AMM 26-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
261071	ANTI-ICE BLEED AIR LEAK(A77) DETECTION UNIT 35009-39 2065 REF: AMM 26-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
261075	APU FIRE/OVERHEAT DETECTOR 10-1093 00-0126 REF: AMM 26-13-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-DEC-2013 1323.8 1061		
262001	FIRE EXTINGUISHER 33100021-1 55017B1 REF: AMM 26-21-01	MOS HRS/MSC AFL	O/C	TSO:1 TSO:0 TSO:0			30-NOV-2017 2313.6 1848		
+ 262001A	FIRE EXTINGUISHER 33100021-1 55017B1 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+14d/-14d			17-OCT-2017	17-OCT-2022	31-OCT-2022
SCHEDULED MAINTENANCE TASKS AND INTERVALS									
262002	FIRE EXTINGUISHER 33100021-1 43795B1 REF: AMM 26-21-01	MOS HRS/MSC AFL	O/C	TSO:3 TSO:0 TSO:0			30-NOV-2017 2313.6 1848		
+ 262002A	FIRE EXTINGUISHER 33100021-1 43795B1 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+14d/-14d			15-AUG-2017	15-AUG-2022	29-AUG-2022
262013	LEFT NO. 1 ENGINE FIRE EXTINGUISHER SQUIB 30903856 2437VF REF: Manufacture Date: 17-OCT-2017	MOS HRS/MSC AFL	180	TSN:0 TSN:0			30-NOV-2017 2313.6 1848	17-OCT-2032	
+ 262013A	REPLACE LEFT NO. 1 ENGINE FIRE EXTINGUISHER SQUIB (SERVICE LIFE IRN # D2620007 AND D2620008). 30903856 2437VF REF:	MOS HRS/MSC AFL	120				17-OCT-2017	17-OCT-2027	
LIFE LIMIT									

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262014	RIGHT NO. 1 ENGINE FIRE EXTINGUISHER SQUIB 30903859 2414VH REF: Manufacture Date: 17-OCT-2017	MOS HRS/MSC AFL	180	TSN:0 TSN:0			30-NOV-2017 2313.6 1848	17-OCT-2032	
+ 262014A	REPLACE RIGHT NO. 1 ENGINE FIRE EXTINGUISHER SQUIB (SERVICE LIFE IRN # D2620007 AND D2620008). 30903859 2414VH REF:	MOS HRS/MSC AFL	120				17-OCT-2017	17-OCT-2027	
262015	LEFT NO. 2 ENGINE FIRE EXTINGUISHER SQUIB 30903856 0317VF REF: Manufacture Date: 15-AUG-2017	MOS HRS/MSC AFL	180	TSN:0 TSN:0			30-NOV-2017 2313.6 1848	15-AUG-2032	
+ 262015A	REPLACE LEFT NO. 2 ENGINE FIRE EXTINGUISHER SQUIB (SERVICE LIFE IRN # D2620007 AND D2620008). 30903856 0317VF REF:	MOS HRS/MSC AFL	120				15-AUG-2017	15-AUG-2027	
262016	RIGHT NO. 2 ENGINE FIRE EXTINGUISHER SQUIB 30903859 1446VD REF: Manufacture Date: 15-AUG-2017	MOS HRS/MSC AFL	180	TSN:0 TSN:0			30-NOV-2017 2313.6 1848	15-AUG-2032	
+ 262016A	REPLACE RIGHT NO. 2 ENGINE FIRE EXTINGUISHER SQUIB (SERVICE LIFE IRN # D2620007 AND D2620008). 30903859 1446VD REF:	MOS HRS/MSC AFL	120				15-AUG-2017	15-AUG-2027	
262040	APU FIRE WARNING HORN 430-M1 23388 REF: AMM 26-13-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		



Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262041	PILOT PORTABLE FIRE EXTINGUISHER A344 C-90489165 REF: GENERIC CUSTOM	MOS HRS/MSC AFL	O/C				28-AUG-2018 2621.3 2079		
262041A	PILOTS PORTABLE FIRE EXTINGUISHER IRN (W2620009) REF: AMM 26-23-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25		-7.7	28-AUG-2018 2621.3 2079	28-AUG-2019 2913.6	11-SEP-2019 2938.6
+ 262041B	HYDROSTATIC TEST PILOT PORTABLE FIRE EXTINGUISHER (IRN # Q2510003). A344 C-90489165 REF: AMM 26-23-00 SCHEDULED MAINTENANCE TASKS AND INTERVALS	MOS HRS/MSC AFL	144	+14d/-14d			31-JAN-2017	31-JAN-2029	14-FEB-2029
262042	COPILOT PORTABLE FIRE EXTINGUISHER A344 C-90489166 REF: GENERIC CUSTOM	MOS HRS/MSC AFL	O/C				28-AUG-2018 2621.3 2079		
262042A	CO-PILOT'S PORTABLE FIRE EXTINGUISHER (IRN W2620009) REF: AMM 26-23-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25		-7.7	28-AUG-2018 2621.3 2079	28-AUG-2019 2913.6	11-SEP-2019 2938.6
+ 262042B	HYDROSTATIC TEST COPILOT PORTABLE FIRE EXTINGUISHER (IRN # Q2510003). A344 C-90489166 REF: AMM 26-23-00 SCHEDULED MAINTENANCE TASKS AND INTERVALS	MOS HRS/MSC AFL	144	+14d/-14d			31-JAN-2017	31-JAN-2029	14-FEB-2029
262051	CABIN PORTABLE FIRE EXTINGUISHER C352TS B-10811218 REF: GENERIC CUSTOM	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-APR-2017 2080.2 1694		
262051A	VISUAL INSPECTION AND WEIGHT CHECK CABIN PORTABLE FIRE EXTINGUISHER (IRN Y2620009) C352TS B-10811218 REF: AMM 26-23-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25		-7.7	28-AUG-2018 2621.3 2079	28-AUG-2019 2913.6	11-SEP-2019 2938.6



Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 262051B	HYDROSTATIC TEST CABIN PORTABLE FIRE EXTINGUISHER (IRN # Q2510003). C352TS B-10811218 REF: AMM 26-23-00	MOS HRS/MSC AFL	144	+14d/-14d			28-FEB-2017	28-FEB-2029	14-MAR-2029
SCHEDULED MAINTENANCE TASKS AND INTERVALS									
262075	APU FIRE EXTINGUISHER 51600-2 0398 REF: AMM 26-22-01	MOS HRS/MSC AFL				O/C	TSO:0 TSO:0 TSO:0	30-NOV-2017 2313.6 1848	
+ 262075A	PERFORM APU FIRE EXTINGUISHER CONTAINER - ICC HYDROSTATIC TEST. (ZONE/ACCESS 310JL, 310QR) (IRN # Q4900014) 51600-2 0398 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+14d/-14d			14-NOV-2017	14-NOV-2022	28-NOV-2022
262076	REPLACE APU ENGINE FIRE EXTINGUISHER CONTAINER CARTRIDGE 30600-22 LOT108 REF: AMM 26-21-02 Manufacture Date: 31-OCT-2016	MOS HRS/MSC AFL	144				TSN:0 TSN:0	28-APR-2017 2080.2 1694	31-OCT-2028
+ 262076A	REPLACE REPLACE APU ENGINE FIRE EXTINGUISHER CONTAINER CARTRIDGE SERVICE LIFE (IRN # L4900015) 30600-22 LOT108 REF:	MOS HRS/MSC AFL	144				27-FEB-2017	27-FEB-2029	
+ 5-19-00-O2610001-LEFT	VISUALLY INSPECT NO. 1 ENGINE HOT SECTION FIRE DETECTOR ELEMENT. (ZONE/ACCESS 410 IRN O2610001) DURING MAJOR ENGINE INSPECTION/UNSCHEDULED ENGINE CHANGE REF: AMM 05-10-00	MOS HRS/MSC AFL	3000	+100/-100			11-AUG-2008 0 0	3000	3100
+ 5-19-00-O2610001-RIGHT	VISUALLY INSPECT NO. 2 ENGINE HOT SECTION FIRE DETECTOR ELEMENT. (ZONE/ACCESS 410 IRN O2610001) DURING MAJOR ENGINE INSPECTION/UNSCHEDULED ENGINE CHANGE REF: AMM 05-10-00	MOS HRS/MSC AFL	3000	+100/-100			11-AUG-2008 0 0	3000	3100

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
G2610000 (s)	FIREWALL AND ACCESSORY COMPARTMENT FIRE DETECTOR ELEMENTS - PERFORM VISUAL INSPECTION PKG 9 REF: AMM 05-10-00	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 30-NOV-2017 2313.6 1848		
G2620009 (s)	INSPECT PORTABLE HAND HELD FIRE EXTINGUISHERS FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE. PKG 1 REF:	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 29-AUG-2018 2621.3 2079		
O2620002 (s)	ENGINE FIRE EXTINGUISHER CONTAINERS - PERFORM VISUAL INSPECTION. CHECK CONTAINERS FOR CONDITION, CARTRIDGES AND CARTRIDGE WIRING FOR SECURITY AND CONDITION, CONTAINER PRESSURE GAUGE FOR PROPER PRESSURES, AND PLUMBING FOR SECURITY AND CONDITION PKG 2 REF: AMM 05-10-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 29-AUG-2018 2621.3 2079		
T2620001 (s)	PERFORM ** FIREWALL SHUTOFF VALVES - OPERATIONAL CHECK. PKG 13 REF: AMM 26-21-00	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 20-MAY-2016 1821.7 1492		
Z2620021	NO. 1 ENGINE FIRE EXTINGUISHER CONTAINER PLUMBING - PERFORM DETAILED INSPECTION PKG 2 REF: AMM 26-21-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25		-7.7	29-AUG-2018 2621.3 2079	29-AUG-2019 2913.6	12-SEP-2019 2938.6
Z2620021	NO. 2 ENGINE FIRE EXTINGUISHER CONTAINER PLUMBING - PERFORM DETAILED INSPECTION PKG 2 REF: AMM 26-21-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25		-7.7	29-AUG-2018 2621.3 2079	29-AUG-2019 2913.6	12-SEP-2019 2938.6
CHAPTER 27	FLIGHT CONTROLS								
270301	TRIM SWITCH PANEL ASSY PN SN-UNKNOWN REF: AMM 27-00-01	MOS HRS/MSC AFL	O/C				11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
271001	LEFT AILERON CONTROL SYSTEM CROSSOVER CABLE PN SN-UNKNOWN REF: AMM 27-10-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
271002	RIGHT AILERON CONTROL SYSTEM CROSSOVER CABLE PN SN-UNKNOWN REF: AMM 27-10-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
271003	LEFT AILERON CONTROL SYSTEM CABLE 7627102004-005 SN-UNKNOWN REF: AMM 27-10-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-DEC-2013 1323.8 1061		
271004	RIGHT AILERON CONTROL SYSTEM CABLE 7627102005-009 SN-UNKNOWN REF: AMM 27-10-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-DEC-2013 1323.8 1061		
271005	AILERON CONTROL SYSTEM AFT CABLE ASSEMBLY 7627102001-005 SN-UNKNOWN REF: AMM 27-10-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-DEC-2013 1323.8 1061		
271045	ASSEMBLY, AILERON CONTROL INBOARD LEFT CABLE 4527103077-011 1078362-9 REF: AMM 27-10-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
271046	ASSEMBLY, AILERON CONTROL INBOARD RIGHT CABLE 4527103076-015 1079890-8 REF: AMM 27-10-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
271051	LEFT AILERON FORWARD OUTBOARD CONTROL CABLE 4527103078-009 1078373-27 REF: AMM 27-10-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
271052	RIGHT AILERON FORWARD OUTBOARD CONTROL CABLE 4527103078-009 1078373-11 REF: AMM 27-10-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
271053	LEFT AILERON OUTBOARD AFT CONTROL CABLE 4527103079-009 1079894-4 REF: AMM 27-10-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
271054	RIGHT AILERON AFT OUTBOARD CONTROL CABLE 4527103079-009 1079894-8 REF: AMM 27-10-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
271083	AILERON TRIM TAB ACTUATOR 4323338A 0542 REF: AMM 27-10-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
271095	PILOT ANGLE OF ATTACK (AOA) INDICATOR C-38805-1 83373 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
271096	COPILOT ANGLE OF ATTACK (AOA) INDICATOR C-38805-1 83407 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
272001	FORWARD UPPER RUDDER CONTROL SYSTEM CABLE 7627202001-009 SN-UNKNOWN REF: AMM 27-20-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-DEC-2013 1323.8 1061		
272002	FORWARD LOWER RUDDER CONTROL SYSTEM CABLE PN SN-UNKNOWN REF: AMM 27-20-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
272003	LEFT AFT UPPER RUDDER CONTROL SYSTEM CABLE 7627202003-005 SN-UNKNOWN REF: AMM 27-20-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-DEC-2013 1323.8 1061		
272004	RIGHT AFT UPPER RUDDER CONTROL SYSTEM CABLE 7627202004-005 SN-UNKNOWN REF: AMM 27-20-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-DEC-2013 1323.8 1061		
272005	LEFT AFT LOWER RUDDER CONTROL SYSTEM CABLE 7627202005-005 SN-UNKNOWN REF: AMM 27-20-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-DEC-2013 1323.8 1061		
272006	RIGHT AFT LOWER RUDDER CONTROL SYSTEM CABLE 7627202006-005 SN-UNKNOWN REF: AMM 27-20-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-DEC-2013 1323.8 1061		
272021	RUDDER TRIM TAB ACTUATOR 4323322 0536 REF: AMM 27-20-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
272031	PILOT RUDDER PEDAL ADJUST ACTUATOR 4389596 1160 REF: AMM 27-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
272032	COPILOT RUDDER PEDAL ADJUST ACTUATOR 4389596 1163 REF: AMM 27-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
273001	FORWARD PILOT ELEVATOR CONTROL SYSTEM CABLE 7627302021-009 SN-UNKNOWN REF: AMM 27-30-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-DEC-2013 1323.8 1061		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
273002	FORWARD COPILOT ELEVATOR CONTROL SYSTEM CABLE 7627302022-009 SN-UNKNOWN REF: AMM 27-30-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-DEC-2013 1323.8 1061		
273003	LEFT AFT UPPER ELEVATOR CONTROL SYSTEM CABLE 7627302024-005 SN-UNKNOWN REF: AMM 27-30-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-DEC-2013 1323.8 1061		
273004	RIGHT AFT UPPER ELEVATOR CONTROL SYSTEM CABLE 7627302023-005 SN-UNKNOWN REF: AMM 27-30-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-DEC-2013 1323.8 1061		
273005	LEFT AFT LOWER ELEVATOR CONTROL SYSTEM CABLE PN SN-UNKNOWN REF: AMM 27-30-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
273006	RIGHT AFT LOWER ELEVATOR CONTROL SYSTEM CABLE 7627302025-005 SN-UNKNOWN REF: AMM 27-30-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-DEC-2013 1323.8 1061		
273015	LEFT ANGLE OF ATTACK (AOA) VANE 6627308500-803 SN-UNKNOWN REF: AMM 27-31-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-DEC-2013 1323.8 1061		
273016	RIGHT ANGLE OF ATTACK (AOA) VANE 1714-115 3576 REF: AMM 27-31-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
273051	ELEVATOR DISCONNECT ACTUATOR PN SN-UNKNOWN REF: AMM 27-30-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
273063	PILOT STICK SHAKER 72672-1 1788 REF: AMM 27-31-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
273064	COPILOT STICK SHAKER 72672-1 1786 REF: AMM 27-31-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
273075	LEFT ANGLE OF ATTACK (AOA) TRANSMITTER C-38817-1 1257 REF: AMM 27-31-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
273076	RIGHT ANGLE OF ATTACK (AOA) TRANSMITTER C-38817-1 1220 REF: AMM 27-31-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
273087	STALL WARNING DISPLAY UNIT C-38806-2 637 REF: AMM 27-31-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
273201	ELEVATOR DISCONNECT (A83) CURRENT LIMITER PN SN-UNKNOWN REF: AMM 27-30-13	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
273420	ELEVATOR OVERRIDE (L45) ACTUATOR PN SN-UNKNOWN REF: AMM 27-30-14	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
274011	HORIZONTAL STABILIZER ACTUATOR 6627401000-009 B0173 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			20-MAY-2016 1821.7 1492		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 274011A	INSPECT HORIZONTAL STABILIZER ACTUATOR * (6627401000-009 - IRN P2740032). (6627401000-007 - IRN T2740002) 6627401000-009 B0173 REF: AMM 27-40-00	MOS HRS/MSC AFL	1200				20-MAY-2016 1821.1 1492	3021.1	
+ 274011B	DETAILED INSPECTION HORIZONTAL STABILIZER ACTUATOR * (6627401000-009 - IRN P2740033). (6627401000-007 - IRN N2740025) 6627401000-009 B0173 REF: GENERIC NO REF	MOS HRS/MSC AFL	2400				20-MAY-2016 1821.1 1492	4221.1	
+ 274011C	REPLACE HORIZONTAL STABILIZER ACTUATOR * ACME SCREW (P/N 2A94568008). EFFECTIVE ON AIRCRAFT EQUIPPED WITH (6627401000-007 - IRN N2740023) 6627401000-009 B0173 REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A						
+ 274011D	REPLACE HORIZONTAL STABILIZER ACTUATOR * ACME NUT (P/N 2A94567005). (EFFECTIVE ON AIRCRAFT EQUIPPED WITH (6627401000-007 - IRN N2740024) 6627401000-009 B0173 REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A						
274031	TRIM-IN-MOTION DETECTOR 1625-1-1 208020068 REF: AMM 27-41-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
274041	FORWARD INTERFACE UNIT PN SN-UNKNOWN REF: AMM 27-40-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
274051	CONTROL BOX ASSEM, HORIZONTAL STAB ACTUATOR REPLACE E6D201C D0323 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275020	LEFT FLAP, OUTBOARD ACTUATOR 6627503000-033 1094 REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C				18-JUN-2013 1323.2 1060		
275021	LEFT FLAP, INBOARD ACTUATOR 6627503000-031 1787 REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	TSR:4 TSR:0 TSR:0			18-JUN-2013 1323.2 1060		
275022	RIGHT FLAP, INBOARD ACTUATOR 6627503000-031 1647 REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	TSR:4 TSR:0 TSR:0			18-JUN-2013 1323.2 1060		
275023	RIGHT FLAP, OUTBOARD ACTUATOR 6627503000-033 1653 REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C				18-JUN-2013 1323.2 1060		
275057	FLAP DRIVE POWER UNIT 6627503000-029 1149 REF: AMM 27-50-08	MOS HRS/MSC AFL	O/C				14-APR-2011 803.6 653		
275058	FLAP CONTROL UNIT C144486-3-003 1491 REF: AMM 27-50-05	MOS HRS/MSC AFL	O/C				14-NOV-2018 2721.83 2167		
275069	FLAP POSITION INDICATOR C145159-1 1606 REF: AMM 27-50-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
275080	FLAP CONTROL MODULE 69013-17 526 REF: AMM 27-50-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275081	LEFT FLAP DRIVE RVDT C144489-2 A1008 REF: AMM 27-50-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
275082	RIGHT FLAP DRIVE RVDT C144489-2 A1018 REF: AMM 27-50-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
276001	LEFT SPOILER ACTUATOR P455A0001-04 AAA172P455 REF: AMM 27-60-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
276002	RIGHT SPOILER ACTUATOR P455A0001-04 AAA166P455 REF: AMM 27-60-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
276005	SPOILER CONTROL MODULE 69014-9 537 REF: AMM 27-60-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
276010	SPOILERON CONTROLLER RESISTOR BOX ASSEMBLY PN SN-UNKNOWN REF: AMM 27-60-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
276013	SPOILER SHUTOFF VALVE 100291000-003 0209TK REF: AMM 27-60-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
276020	SPOILER LOW PRESSURE ASSEMBLY (L41) SWITCH PN SN-UNKNOWN REF: AMM 27-60-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		



Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
276031	LEFT SPOILER RVDT 3A2-249A A1017 REF: AMM 27-60-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
276032	RIGHT SPOILER RVDT 3A2-249A A1016 REF: AMM 27-60-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
276073	SPOILERON DISPLAY UNIT 402800-06-02 00783 REF: AMM 27-60-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
276076	CONTROL WHEEL RVDT 3G4-211A 0530/0749 REF: AMM 27-60-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
+ 5-19-00-D2740003	HORIZONTAL STABILIZER ACTUATOR SECONDARY TRIM . (ZONE/ACCESS 220 IRN # D2740003) REF: AMM 27-40-02	MOS HRS/MSC AFL	600	+25/-25			30-NOV-2017 2313.6 1848	2913.6	2938.6
+ 5-19-00-D2740004	HORIZONTAL STABILIZER ACTUATOR PRIMARY TRIM. (ZONE/ACCESS 220 IRN # D2740004) REF: AMM 27-40-02	MOS HRS/MSC AFL	600	+25/-25			30-NOV-2017 2313.6 1848	2913.6	2938.6
5-19-00-K2700007	AILERON CONTROL SYSTEM PRIMARY CABLES (ZONE/ACCESS 230AC, 230BC, 230CC, 230DC, 230EC *IRN # K2700007) REF: AMM 27-00-00	MOS HRS/MSC AFL	4800				11-AUG-2008 0 0	4800	
AIRWORTHINESS									
+ 5-19-00-K2700008	ELEVATOR CONTROL SYSTEM PRIMARY CABLES (ZONE/ACCESS 230AC, 230BC, 230CC, 230DC, 230EC *IRN # K2700008) REF: AMM 27-00-00	MOS HRS/MSC AFL	4800				11-AUG-2008 0 0	4800	
AIRWORTHINESS									



Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 5-19-00-K2700009	RUDDER CONTROL SYSTEM PRIMARY CABLES (ZONE/ACCESS 230AC, 230BC, 230CC, 230DC, 230EC *IRN # K2700009)	MOS					11-AUG-2008		
AIRWORTHINESS	REF: AMM 27-00-00	HRS/MSC AFL	4800				0 0		4800
+ 5-19-00-K2700010	ELEVATOR CONTROL SYSTEM PRIMARY CABLES (ZONE/ACCESS 310CC, 310DC, 310HL, 310JL, 310QR, 310RR, 840AR *IRN # K2700010)	MOS					11-AUG-2008		
AIRWORTHINESS	REF: AMM 27-00-00	HRS/MSC AFL	4800				0 0		4800
+ 5-19-00-K2700012	RUDDER CONTROL SYSTEM PRIMARY CABLES (ZONE/ACCESS 310CC, 310DC, 310HL, 310JL, 310QR, 310RR, 840AR *IRN # K2700012)	MOS					11-AUG-2008		
AIRWORTHINESS	REF: AMM 27-00-00	HRS/MSC AFL	4800				0 0		4800
+ 5-19-00-K2700014	DETAILED VISUAL INSPECTION AILERON CONTROL SYSTEM PRIMARY CABLES (ZONE/ACCESS 540/640 *IRN # K2700014)	MOS					11-AUG-2008		
AIRWORTHINESS	REF: AMM 27-00-00	HRS/MSC AFL	4800				0 0		4800
+ 5-19-00-M5540022	RUDDER TORQUE TUBE, (REFER TO 27-20-01.) EFFECTIVE ON AIRCRAFT WITH LIGHT SURFACE CORROSION DISCOVERED DURING COMPLIANCE OF SB45-27-24, PART C AND NOT MODIFIED PER SB45-27-25.	MOS					16-MAY-2012		
	REF: AMM 55-40-00	HRS/MSC AFL	N/A				1018.22 813		
5-19-00-N2720030	DETAILED VISUAL INSPECTION RUDDER TORQUE TUBE AND SPINDLE - PERFORM DETAILED VISUAL INSPECTION. (REFER TO 27-20-01.) EFFECTIVE 6 YEARS FROM C OF A OR COMPLIANCE WITH SB 45-27-24 THEN EVERY 6 YEARS THEREAFTER). ZONE 320BL	MOS	72	+14d/-14d	-3		05-DEC-2015	02-DEC-2021	16-DEC-2021
AIRWORTHINESS	REF: AMM 27-20-01	HRS/MSC AFL					1743.3 1436		
5-19-00-R2750056	FLAP ACTUATOR JOINT (P/N 145673-1) - PERFORM DETAILED VISUAL INSPECTION. (REFER TO 27-50-06.) APPLY CORROSION PREVENTIVE COMPOUND (CPC) TO JOINT. (REFER TO 12-21-03.). IRN R2750056	MOS					12-APR-2013		
NOT APPLICABLE	REF: See Workcard	HRS/MSC AFL	N/A				1283.02 1022		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-00-S2750057	PERFORM FLAP ACTUATOR BALLNUT ORIGINAL SLEEVE - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL (NDI-104). PART 8, 27-50-01 OR 27-50-02).	MOS					12-APR-2013		
NOT APPLICABLE	REF: See Workcard	HRS/MSC AFL	N/A				1283.02 1022		
5-19-01-Q2750055	FLAP ACTUATOR JOINT (P/N 145673-1) (IRN Q2750055)	MOS		TSN:0			18-JUN-2013		
NOT APPLICABLE	159174-1 SN-UNKNOWN REF: AMM 27-50-06	HRS/MSC AFL	N/A	TSN:0 TSN:0			1323.2 1060		
5-19-01-R2710041	AILERON SPINDLE (P/N 4527102103-001). (IRN R2710041)	MOS					11-AUG-2008		
N/A BY A/C SERIAL NUMBER	REF: AMM 27-10-07	HRS/MSC AFL	N/A				0 0		
A2711001 (s)	** AILERON TRIM TAB CONTROL SYSTEM - PERFORM OPERATIONAL CHECK	MOS	24	+14d/-14d			PKG 30-NOV-2017		
AIRWORTHINESS	PKG 7 REF: AMM 27-10-04	HRS/MSC AFL	600	+25/-25			2313.6 1848		
A2712000 (s)	** ROLL DISCONNECT - PERFORM OPERATIONAL CHECK. (REFER TO 27-60-09.)	MOS	24	+25d/-25d			PKG 30-NOV-2017		
AIRWORTHINESS	PKG 7 REF: AMM 27-60-09	HRS/MSC AFL	600	+14/-14			2313.6 1848		
A2721001 (s)	** RUDDER TRIM SYSTEM - PERFORM OPERATIONAL CHECK	MOS	24	+14d/-14d			PKG 30-NOV-2017		
AIRWORTHINESS	PKG 7 REF: AMM 27-20-00	HRS/MSC AFL	600	+25/-25			2313.6 1848		
A2731002 (s)	** ELEVATOR DISCONNECT SYSTEM - PERFORM OPERATIONAL CHECK	MOS	24	+14d/-14d			PKG 30-NOV-2017		
AIRWORTHINESS	PKG 8 REF: AMM 27-30-00	HRS/MSC AFL	600	+25/-25			2313.6 1848		
A2760001 (s)	** SPOILER ACTUATOR CHECK VALVE - PERFORM OPERATIONAL CHECK	MOS	24	+14d/-14d			PKG 30-NOV-2017		
AIRWORTHINESS	PKG 10 REF: AMM 27-60-04	HRS/MSC AFL	600	+25/-25			2313.6 1848		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A2760002 (s)	** SPOILER SYSTEM - PERFORM SPOILER AUTHORITY WITH FLAPS CHECK						PKG		
	PKG 10	MOS	24	+14d/-14d			30-NOV-2017		
AIRWORTHINESS	REF: AMM 27-60-00	HRS/MSC AFL	600	+25/-25			2313.6 1848		
C2700000 (s)	AILERON CONTROL CABLE SYSTEM - WITH CENTER CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF ACCESSIBLE CABLES						PKG		
	PKG 7	MOS	24	+14d/-14d			30-NOV-2017		
	REF: AMM 27-00-00	HRS/MSC AFL	600	+25/-25			2313.6 1848		
C2700001 (s)	RUDDER CONTROL CABLE SYSTEM - WITH CENTER CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF ACCESSIBLE CABLES						PKG		
	PKG 7	MOS	24	+14d/-14d			30-NOV-2017		
	REF: AMM 27-00-00	HRS/MSC AFL	600	+25/-25			2313.6 1848		
C2700002 (s)	ELEVATOR CONTROL CABLE SYSTEM - WITH CENTER CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF ACCESSIBLE CABLES						PKG		
	PKG 7	MOS	24	+14d/-14d			30-NOV-2017		
	REF: AMM 27-00-00	HRS/MSC AFL	600	+25/-25			2313.6 1848		
C2700003 (s)	AILERON CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF CABLES WITHIN WING						PKG		
	PKG 10	MOS	24	+14d/-14d			30-NOV-2017		
	REF: AMM 27-00-00	HRS/MSC AFL	600	+25/-25			2313.6 1848		
C2700004 (s)	RUDDER CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF ACCESSIBLE UPPER AND LOWER CABLES						PKG		
	PKG 8	MOS	24	+14d/-14d			30-NOV-2017		
	REF: AMM 27-00-00	HRS/MSC AFL	600	+25/-25			2313.6 1848		
C2700005 (s)	ELEVATOR CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF ACCESSIBLE UPPER AND LOWER CABLES						PKG		
	PKG 8	MOS	24	+14d/-14d			30-NOV-2017		
	REF: AMM 27-00-00	HRS/MSC AFL	600	+25/-25			2313.6 1848		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
C2700006 (s)	RUDDER AND ELEVATOR CONTROL CABLES AND ASSOCIATED PULLEYS, LOCATED IN AFT PRESSURE BULKHEAD SUPPORT CHANNEL - PERFORM VISUAL INSPECTION						PKG		
	PKG 9	MOS	24	+14d/-14d			30-NOV-2017	2313.6	1848
	REF: AMM 27-00-00	HRS/MSC AFL	600	+25/-25					
G2710003 (s)	PERFORM AILERON CONTROL SYSTEM CABLES (LOCATED IN WING AREA) - CABLE TENSION CHECK.						PKG		
	PKG 16	MOS	48	+14d/-14d			20-MAY-2016	1821.7	1492
	REF: AMM 27-10-00	HRS/MSC AFL	1200	+25/-25					
G2710004 (s)	PERFORM AILERON CONTROL SYSTEM CABLES (LOCATED IN FUSELAGE AREA) - CABLE TENSION CHECK.						PKG		
	PKG 13	MOS	48	+14d/-14d			20-MAY-2016	1821.7	1492
	REF: AMM 27-10-00	HRS/MSC AFL	1200	+25/-25					
G2720003 (s)	PERFORM RUDDER CONTROL CABLES - TENSION CHECK.						PKG		
	PKG 14	MOS	48	+14d/-14d			20-MAY-2016	1821.7	1492
	REF: AMM 27-20-00	HRS/MSC AFL	1200	+25/-25					
G2720004 (s)	PERFORM RUDDER PEDALS, PEDAL PUSHRODS, ADJUSTMENT ACTUATOR, AND SECTORS - VISUAL INSPECTION. CHECK DURING FULL TRAVEL OF RUDDER.						PKG		
	PKG 13	MOS	48	+14d/-14d			20-MAY-2016	1821.7	1492
	REF: AMM 05-10-00	HRS/MSC AFL	1200	+25/-25					
G2730003 (s)	PERFORM ELEVATOR CONTROL CABLES - TENSION CHECK.						PKG		
	PKG 14	MOS	48	+14d/-14d			20-MAY-2016	1821.7	1492
	REF: AMM 27-30-00	HRS/MSC AFL	1200	+25/-25					
G2750000 (s)	FLAP DRIVE INSTALLATION - PERFORM VISUAL INSPECTION WITH FLAPS LOWERED						PKG		
	PKG 10	MOS	24	+14d/-14d			30-NOV-2017	2313.6	1848
	REF: AMM 05-10-00	HRS/MSC AFL	600	+25/-25					

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
G2760000 (s)	SPOILER AND SPOILER ACTUATOR - PERFORM VISUAL INSPECTION WITH FLAPS LOWERED AND ACCESS PANELS OPENED						PKG		
	PKG 10	MOS	24	+14d/-14d			30-NOV-2017		
		HRS/MSC	600	+25/-25			2313.6		
	REF: AMM 05-10-00	AFL					1848		
J2750053 (s)	FLAP DRIVE ACTUATORS - PERFORM A VISUAL INSPECTION OF THE ACTUATOR ATTACHMENT, PAYING PARTICULAR ATTENTION TO THE GIMBAL PIN RETAINING RINGS						PKG		
	PKG 10	MOS	24	+14d/-14d			30-NOV-2017		
		HRS/MSC	600	+25/-25			2313.6		
	REF: AMM 05-10-00	AFL					1848		
O2720000 (s)	RUDDER - PERFORM VISUAL INSPECTION						PKG		
	PKG 2	MOS	12	+14d/-14d			29-AUG-2018		
		HRS/MSC	300	+25/-25			2621.3		
	REF: AMM 05-10-00	AFL					2079		
O2730001 (s)	ELEVATORS - PERFORM VISUAL INSPECTION						PKG		
	PKG 2	MOS	12	+14d/-14d			29-AUG-2018		
		HRS/MSC	300	+25/-25			2621.3		
	REF: AMM 05-10-00	AFL					2079		
O2750001 (s)	FLAPS - PERFORM VISUAL INSPECTION						PKG		
	PKG 4	MOS	12	+14d/-14d			29-AUG-2018		
		HRS/MSC	300	+25/-25			2621.3		
	REF: AMM 05-10-00	AFL					2079		
T2710000 (s)	AILERONS, AILERON TRIM TAB AND VISIBLE PORTION OF RODS - PERFORM VISUAL INSPECTION						PKG		
	PKG 10	MOS	24	+14d/-14d			30-NOV-2017		
		HRS/MSC	600	+25/-25			2313.6		
	REF: AMM 05-10-00	AFL					1848		
U2721000 (s)	RUDDER TRIM TAB AND VISIBLE RODS - PERFORM VISUAL INSPECTION. NOTE: ON AIRCRAFT 45-005 THRU 45-364 NOT MODIFIED BY SB 45-27-34 AND AIRCRAFT 45-005 THRU 45-428 NOT MODIFIED PER SB 45-27-37, REPLACE THE RUDDER TRIM TAB HINGE LOWER COTTER PIN DURING THIS INSPECTION.						PKG		
	PKG 2	MOS	12	+14d/-14d			29-AUG-2018		
		HRS/MSC	300	+25/-25			2621.3		
	REF: AMM 05-10-00	AFL					2079		

CHAPTER 28 FUEL



Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281001	LEFT NO. 1 FUEL, EJECTOR SCAVENGE PUMP HTE230008 8081775 REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
281002	RIGHT NO. 1 FUEL, EJECTOR SCAVENGE PUMP HTE230008 8081759 REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
281003	LEFT NO. 2 FUEL, EJECTOR SCAVENGE PUMP HTE230008 8081755 REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
281004	RIGHT NO. 2 FUEL, EJECTOR SCAVENGE PUMP HTE230008 8081784 REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
281005	LEFT NO. 3 FUEL, EJECTOR SCAVENGE PUMP HTE230008 8081786 REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
281006	RIGHT NO. 3 FUEL, EJECTOR SCAVENGE PUMP HTE230008 8081780 REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
281007	LEFT NO. 4 FUEL, EJECTOR SCAVENGE PUMP HTE230008 8081781 REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
281008	RIGHT NO. 4 FUEL, EJECTOR SCAVENGE PUMP HTE230008 8081751 REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281009	LEFT NO. 5 FUEL, EJECTOR SCAVENGE PUMP HTE230008 8081785 REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
281010	RIGHT NO. 5 FUEL, EJECTOR SCAVENGE PUMP HTE230008 8081779 REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
281031	FUEL, FUSELAGE CELL 506878 108873 REF: AMM 28-10-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
281051	FUEL CROSSFLOW SHUTOFF VALVE PN SN-UNKNOWN REF: AMM 28-12-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
281401	SURGE TANK FLOAT VALVE PN SN-UNKNOWN REF: AMM 28-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
281501	LEFT FLEX FUEL HOSE ASSY PN SN-UNKNOWN REF: GENERIC CUSTOM	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
281502	RIGHT FLEX FUEL HOSE ASSY PN SN-UNKNOWN REF: GENERIC CUSTOM	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
281521	LEFT FUEL TRANSFER CHECK VALVE HTE460072 5080949 REF: AMM 28-12-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281522	RIGHT FUEL TRANSFER CHECK VALVE HTE460072 5080944 REF: AMM 28-12-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
282001	LEFT FUEL SHUTOFF VALVE EM91-102-2 0596 REF: AMM 28-20-06	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			10-FEB-2011 803.6 653		
282003	RIGHT FUEL SHUTOFF VALVE EM91-102-2 1850 REF: AMM 28-20-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
282011	SHUTOFF - REFUEL VALVE 980056-2 5081143 REF: AMM 28-20-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
282031	LEFT NO. 1 FUEL SUPPLY CHECK VALVE HTE460071 7080525 REF: AMM 28-20-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
282032	LEFT NO. 2 FUEL SUPPLY CHECK VALVE HTE460071 7080523 REF: AMM 28-20-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
282033	RIGHT NO. 1 FUEL SUPPLY CHECK VALVE HTE460071 7080508 REF: AMM 28-20-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
282034	RIGHT NO. 2 FUEL SUPPLY CHECK VALVE HTE460071 7080535 REF: AMM 28-20-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282037	RIGHT FUEL SUPPLY SHUT-OFF (L10) VALVE ASSEMBLY EM91-102-2 1854 REF: AMM 28-20-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
282038	LEFT FUEL SUPPLY SHUT-OFF (L11) VALVE ASSEMBLY EM91-102-2 1856 REF: AMM 28-20-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
282041	CONTROL - REFUELING PANEL 4528408000V5-001 08031019BA REF: AMM 28-20-14	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
282051	LEFT CHECK, MOTIVE FLOW VALVE 6628200106-003 46070778 REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
282052	RIGHT CHECK, MOTIVE FLOW VALVE 6628200106-003 46070786 REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
282063	PRE-CHECK, SPPR VALVE HTE940032-1 54071364 REF: AMM 28-20-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
282064	PILOT, SPPR VALVE 61087-2 512 REF: AMM 28-20-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
282075	LEFT ASSEMBLY, FUEL MAIN EJECTOR PUMP HTE230009 8080693 REF: AMM 28-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282076	RIGHT ASSEMBLY, FUEL MAIN EJECTOR PUMP HTE230009 8080689 REF: AMM 28-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
282087	LEFT FUEL, STANDBY PUMP 1C12-39 2BD8 REF: AMM 28-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
282088	RIGHT FUEL, STANDBY PUMP 1C12-39 2BD7 REF: AMM 28-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
282601	DEFUEL (B24) SHUTOFF VALVE EM91-102-2 1817 REF: AMM 28-20-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
282602	REFUEL CHECK VALVE PN SN-UNKNOWN REF: AMM 28-20-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
282603	SINGLE POINT PRESSURE REFUELING (SPPR) ADAPTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
282640	SINGLE POINT PRESSURE REFUELING ADAPTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
282815	APU FUEL SHUTOFF VALVE 7086048-1 072203001003C REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284001	ASSEMBLY, FUEL C1 PROBE 10665T01Y00 MN14022 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
284002	FUEL C2 PROBE 10665T03Y00 MN15053 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
284003	ASSEMBLY, FUEL C3 PROBE 10552T03Y00 MN14370 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
284004	ASSEMBLY, FUEL C4 PROBE 10552T04Y00 MN15250 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
284005	ASSEMBLY, FUEL C5 PROBE 10552T05Y00 MN13130 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
284006	ASSEMBLY, FUEL C6 PROBE 10552T06Y00 MN07268 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
284008	FUEL C8 PROBE 10665T01Y00 MN14915 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
284009	ASSEMBLY, FUEL C9 PROBE 10665T03Y00 MN15058 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284010	ASSEMBLY, FUEL C10 PROBE 10552T03Y00 MN14377 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
284011	ASSEMBLY, FUEL C11 PROBE 10552T04Y00 MN15258 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
284012	ASSEMBLY, FUEL C12 PROBE 10552T05Y00 MN14898 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
284013	ASSEMBLY, FUEL C13 PROBE 10552T06Y00 MN07291 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
284014	ASSEMBLY, FUEL C14 PROBE 10552T01Y00 MN15106 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
284015	FUEL C15 PROBE 10552T01Y00 MN15108 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
284016	ASSEMBLY, FUEL C16 PROBE 10552T06Y00 MN07972 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
284017	FUEL C17 PROBE 10552T06Y00 MN07977 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284033	FUSELAGE FUEL PROBE 10554T02Y00 DT76995 REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
284035	NO. 1 FUEL, LOW PRESSURE (S21) SWITCH PN SN-UNKNOWN REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
284036	NO. 2 FUEL, LOW PRESSURE (S21) SWITCH PN SN-UNKNOWN REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
284041	LEFT FLOAT, FUEL (S19 & S20) SWITCH PN SN-UNKNOWN REF: AMM 28-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
284042	RIGHT FLOAT, FUEL (S19 & S20) SWITCH PN SN-UNKNOWN REF: AMM 28-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
284045	FUEL QUANTITY SIGNAL CONDITIONER 10551B08Y09 1121 REF: AMM 28-40-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
284047	LEFT FUEL, LOW LEVEL SENSOR PN SN-UNKNOWN REF: AMM 28-40-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
284048	RIGHT FUEL, LOW LEVEL SENSOR PN SN-UNKNOWN REF: AMM 28-40-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-00-D2820013	PERFORM INITIAL CLEANING AND LEAK CHECK OF LOW PRESSURE FUEL FILTERS. (NEW AIRCRAFT 50-FLIGHT HOUR CHECK) (ZONE/ACCESS 510AL IRN # D2820013)	MOS					03-SEP-2008		
	REF: AMM 28-20-15	HRS/MSC AFL	A/R				50.2 32		
+ 5-19-00-H2840001	DUAL FUEL FLOW CONVERTER (DFFC) (10540B06F07) - PERFORM ACCEPTANCE TEST AND LOW TEMPERATURE SCREENING. (ZONE/ACCESS 320 *IRN # H2840001)	MOS					11-AUG-2008		
NOT INSTALLED	REF: GENERIC NO REF	HRS/MSC AFL	N/A				0 0		
F2840003 (s)	PERFORM ** FUEL QUANTITY SIGNAL CONDITIONER - FUNCTIONAL TEST TO VERIFY WEIGHT-ON-WHEELS (WOW) INPUTS. (EFFECTIVE ON AIRCRAFT 45-005 THRU 45-194 POST SB 45-28-5 AND 45-195 AND SUBSEQUENT.)	MOS	48	+14d/-14d			20-MAY-2016		
	PKG 14	HRS/MSC AFL	1200	+25/-25			1821.7 1492		
AIRWORTHINESS	REF: AMM 28-40-00								
O2820000 (s)	LOW PRESSURE FUEL FILTER - REMOVE AND INSPECT FOR CONTAMINATION. CLEAN IF NECESSARY	MOS	24	+14d/-14d			30-NOV-2017		
	PKG 10	HRS/MSC AFL	600	+25/-25			2313.6 1848		
REF: AMM 28-20-15									
Q2810001 (s)	WING TANKS - REMOVE FUEL TANK ACCESS PANELS AND PERFORM VISUAL INSPECTION	MOS	24	+14d/-14d			30-NOV-2017		
	PKG 10	HRS/MSC AFL	600	+25/-25			2313.6 1848		
REF: AMM 05-10-00									
CHAPTER 29 HYDRAULIC POWER									
29-CUS-001	LOW PRESSURE SWITCH SPOILER	MOS					29-NOV-2017		
	662910004-003	HRS/MSC AFL	O/C				2313.6 1848		
	0688								
REF:									
291001	HYDRAULIC RESERVOIR	MOS					11-AUG-2008		
	PN	HRS/MSC AFL	O/C				0 0		
	SN-UNKNOWN								
REF: AMM 29-10-02									

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291012	L8 HYDRAULIC SHUTOFF VALVE PN SN-UNKNOWN REF: AMM 29-10-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
291013	L9 HYDRAULIC SHUTOFF VALVE PN SN-UNKNOWN REF: AMM 29-10-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
291033	RESERVOIR PRESSURIZATION CONTROL MODULE ZVM11-2 07-1217310 REF: AMM 29-10-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
291034	RESERVOIR FLUID LEVEL SENSOR 3L14F-17 727 REF: AMM 29-30-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
291045	NO. 1 HYDRAULIC, ENGINE DRIVEN PUMP 848888 MX720303A REF: AMM 29-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
291046	NO. 2 HYDRAULIC, ENGINE DRIVEN PUMP 848888 MX716952A REF: AMM 29-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
291051	NO. 1 PRESSURE, MAIN HYDRAULIC SYSTEM SWITCH PN SN-UNKNOWN REF: AMM 29-30-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
291052	NO. 2 PRESSURE, MAIN HYDRAULIC SYSTEM SWITCH PN SN-UNKNOWN REF: AMM 29-30-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291057	MAIN HYDRAULIC SYSTEM ACCUMULATOR 88746-1 509 REF: AMM 29-10-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
291059	MAIN HYDRAULIC FILTER MANIFOLD PN SN-UNKNOWN REF: AMM 29-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
291069	THERMAL SHUTOFF VALVE 98050 0798 REF: AMM 29-10-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
292001	AUXILIARY FILTER MANIFOLD ASSEMBLY PN SN-UNKNOWN REF: AMM 29-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
292011	AUXILIARY HYDRAULIC PUMP ASSEMBLY 66157-02 K0566 REF: AMM 29-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
292012	AUXILIARY HYDRAULIC PUMP 6629201000-015 K0116 REF: AMM 29-20-01	MOS HRS/MSC AFL	O/C	TSR:14 TSR:0 TSR:0			30-NOV-2017 2313.6 1848		
292013	AUXILIARY HYDRAULIC PUMP ELECTRIC MOTOR 6629201000-011 101A REF: AMM 29-20-04	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			04-JAN-2013 1255.7 997		
292025	AUXILIARY PRESSURE, HYDRAULIC SYSTEM (S29) SWITCH PN SN-UNKNOWN REF: AMM 29-30-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
292401	AUXILIARY HUDRAULIC PRESSURE CHECK VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
293001	GROUND SERVICE CONTROL BOX 4529308000-013 AS0237 REF: AMM 29-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
293011	HYDRAULIC PRESSURE TRANSDUCER 7629301001-001 7418-3-105 REF: AMM 29-30-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
+ 5-19-01-D2910017/18	REPLACE MAIN HYDRAULIC FILTER MANIFOLD ELEMENTS . (REFER TO 29-10-03.) (IRN # D2910017 AND D2910018) REF: AMM 29-10-03	MOS HRS/MSC AFL	300	+25/-25	-7.7		29-AUG-2018 2621.3 2079	2913.6	2938.6
5-19-01-Q2910005	REPLACE AUXILIARY HYDRAULIC FILTER MANIFOLD ELEMENTS. (REFER TO 29-20-02.) (IRN # Q2910005) REF: AMM 29-20-02	MOS HRS/MSC AFL	2400	+25/-25	16.4		16-FEB-2018 2383.6 1899	4800	4825
T2910026 (s)	PERFORM RELIEF FUNCTION OF THE HYDRAULIC RESERVOIR PRESSURIZATION CONTROL MODULE - FUNCTIONAL TEST. PKG 14 REF: AMM 29-10-06	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			PKG 20-MAY-2016 1821.7 1492		
CHAPTER 30	ICE AND RAIN PROTECTION								
301006	RELAY (P40) - ANTI-ICE VERTICAL STABILIZER. PANEL ASSY PN SN-UNKNOWN REF: AMM 30-10-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
301010	LEFT HORIZONTAL STABILIZER CONTROL (MT47) SENSOR PN SN-UNKNOWN REF: AMM 30-10-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
301011	RIGHT HORIZONTAL STABILIZER CONTROL (MT46) SENSOR PN SN-UNKNOWN REF: AMM 30-10-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
301051	LEFT CHECK, ANTI-ICE (2.0 DIAMETER) VALVE PN SN-UNKNOWN REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
301052	RIGHT CHECK, ANTI-ICE (2.0 DIAMETER) VALVE PN SN-UNKNOWN REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
301063	LEFT ANTI-ICE PRESSURE REGULATING SHUTOFF (PRSOV L12) VALVE 3215616-2 476 REF: AMM 30-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
301064	RIGHT ANTI-ICE PRESSURE REGULATING SHUTOFF (PRSOV L13) VALVE 3215616-2 1097 REF: AMM 30-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
301065	LEFT SHUTTLE, ANTI-ICE VALVE PN SN-UNKNOWN REF: AMM 30-10-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
301066	RIGHT SHUTTLE, ANTI-ICE VALVE PN SN-UNKNOWN REF: AMM 30-10-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
301240	ANTI-ICE MANIFOLD ASSEMBLY 453010278-017 01248621 REF: AMM 30-10-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-NOV-2017 2313.6 1848		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
302001	NO. 1 NACELLE INLET ANTI-ICE SHUTOFF VALVE PN SN-UNKNOWN REF: AMM 30-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
302002	NO. 2 NACELLE INLET ANTI-ICE SHUTOFF VALVE PN SN-UNKNOWN REF: AMM 30-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
302013	NO. 1 NACELLE ANTI-ICE PRESSURE SWITCH PN SN-UNKNOWN REF: AMM 30-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
302014	NO. 2 NACELLE ANTI-ICE PRESSURE SWITCH PN SN-UNKNOWN REF: AMM 30-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
303501	LEFT NOSE RELAY (P15) BOX PN SN-UNKNOWN REF: AMM 30-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
303510	RIGHT NOSE RELAY (P16) BOX PN SN-UNKNOWN REF: AMM 30-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
304021	WINDSHIELD ANTI-ICE CONTROLLER 90825-7 554 REF: AMM 30-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
304060	NO. 1 WING SURFACE TEMPERATURE (MT42) SENSOR 6621000000-057 112C-3869 REF: AMM 30-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-DEC-2013 1323.8 1061		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
304061	NO. 2 WING SURFACE TEMPERATURE (MT43) SENSOR PN SN-UNKNOWN REF: AMM 30-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
304062	NO. 3 WING SURFACE TEMPERATURE (MT44) SENSOR PN SN-UNKNOWN REF: AMM 30-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
304063	NO. 4 WING SURFACE TEMPERATURE (MT45) SENSOR PN SN-UNKNOWN REF: AMM 30-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
308005	ICE DETECTION PROBE 0871HN2 0520 REF: AMM 30-80-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
+ 5-19-00-Q3010006	BORESCOPE INSPECTION ANTI-ICE MANIFOLD ASSEMBLY. (ZONE/ACCESS 300 **IRN # Q3010006). REFER TO 30-10-07. REF: AMM 30-10-07	MOS HRS/MSC AFL	1200				30-NOV-2017 2313.6 1848	3513.6	
+ 5-19-00-Y3020005-LEFT	LEFT * ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS. REF: AMM 30-20-00	MOS HRS/MSC AFL	250				26-OCT-2018 2712.5 2159	2962.5	
AIRWORTHINESS									
+ 5-19-00-Y3020005-RIGHT	RIGHT * ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS. REF: AMM 30-20-00	MOS HRS/MSC AFL	250				26-OCT-2018 2712.5 2159	2962.5	
AIRWORTHINESS									

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A3020000 (s)	PERFORM ** NACELLE ANTI-ICE SYSTEM - FUNCTIONAL TEST						PKG		
	PKG 15	MOS	48	+14d/-14d			20-MAY-2016		
AIRWORTHINESS	REF: AMM 30-20-00	HRS/MSC AFL	1200	+25/-25			1821.7 1492		
A3030000 (s)	PERFORM ** PITOT/STATIC HEAT SYSTEM - OPERATIONAL CHECK						PKG		
	PKG 19	MOS	96	+14d/-14d			20-MAY-2016		
AIRWORTHINESS	REF: AMM 30-30-00	HRS/MSC AFL	2400	+25/-25			1821.7 1492		
H3010000 (s)	** WING/STAB ANTI-ICE SWITCH - PERFORM OPERATIONAL CHECK						PKG		
	PKG 7	MOS	24	+14d/-14d			30-NOV-2017		
AIRWORTHINESS	REF: AMM 30-10-00	HRS/MSC AFL	600	+25/-25			2313.6 1848		
L3010007 (s)	WING ANTI-ICE PICCOLO TUBE - PERFORM DETAILED VISUAL INSPECTION FOR CRACKS AT W.S. 43 AND W.S. 176.						PKG		
	PKG 10	MOS	24	+14d/-14d			30-NOV-2017		
	REF: GENERIC NO REF	HRS/MSC AFL	600	+25/-25			2313.6 1848		
T3040000 (s)	** WINDSHIELD ANTI-ICE - PERFORM FUNCTIONAL TEST OF THE WINDSHIELD ANTI-ICE SYSTEM.						PKG		
	PKG 7	MOS	24	+14d/-14d			30-NOV-2017		
AIRWORTHINESS	REF: AMM 30-40-00	HRS/MSC AFL	600	+25/-25			2313.6 1848		
CHAPTER 31 INDICATING/RECORDING SYSTEMS									
311001	PILOT CIRCUIT BREAKER PANEL ASSY								
	PN	MOS					TSN:0	11-AUG-2008	
	SN-UNKNOWN	HRS/MSC	O/C				TSN:0	0	
	REF: AMM 24-60-01	AFL					TSN:0	0	
311005	COPILOT CIRCUIT BREAKER PANEL ASSY								
	PN	MOS					TSN:0	11-AUG-2008	
	SN-UNKNOWN	HRS/MSC	O/C				TSN:0	0	
	REF: AMM 24-60-01	AFL					TSN:0	0	
311601	GEAR UP/DOWN S47 SWITCH								
	PN	MOS					TSN:0	11-APR-2014	
	SN-UNKNOWN	HRS/MSC	O/C				TSN:0	1345.4	
	REF: AMM 32-30-02	AFL					TSN:0	1094	

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
311805	ENGINE FUEL CONTROL (P7) PANEL ASSY PN SN-UNKNOWN REF: AMM 31-11-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
311806	ENGINE/FUEL CONTROL PANEL OVERLAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
311906	FORWARD QUADRANT SWITCH PANEL (P6) OVERLAY PN SN-UNKNOWN REF: AMM 31-11-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
311906-1	RUDDER BOOST (DS48) SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
312001	PILOT CLOCK M850-5V-LA A4576 REF: AMM 31-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
312001A	REPLACE PILOTS DAVTRON M850 DIGITAL CLOCK (REFER TO 31-21-02) IRN# P3121000 BATTERY PN SN-UNKNOWN REF: AMM 31-21-02	MOS HRS/MSC AFL	12	+14d/-14d TSN:0 TSN:0 TSN:0			16-FEB-2018 2383.6 1899	01-JUL-2020 M 15-JUL-2020	
312002	COPILOT CLOCK M850-5V-LA A4492 REF: AMM 31-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
312002A	REPLACE COPILOTS DAVTRON M850 DIGITAL CLOCK (REFER TO 31-21-02) IRN P3121000 BATTERY PN SN-UNKNOWN REF: AMM 31-21-02	MOS HRS/MSC AFL	12	+14d/-14d TSN:0 TSN:0 TSN:0			16-FEB-2018 2383.6 1899	01-JUL-2020 M 15-JUL-2020	

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
312101	LEFT INCLINOMETER ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
312104	RIGHT INCLINOMETER ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
313001	FLIGHT DATA RECORDER 2100-2042-00 000352201 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			10-FEB-2011 803.6 653		
313001A	DOWNLOAD FLIGHT DATA RECORDER 2100-2042-00 000352201 REF: GENERIC CUSTOM	MOS HRS/MSC AFL	24				28-APR-2017 2080.2 1694	28-APR-2019	
	EUROPEAN OPS REQ								
313003	FDR ACCELEROMETER 3001-01-111 0308-12532 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
313005	FDR UNDERWATER LOCATOR BEACON 068E5542-00 ULB001945 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-MAY-2016 1821.7 1492		
+ 313005A	PERFORM FDR UNDERWATER LOCATOR BEACON FUNCTIONAL TEST OF BEACON, CLEAN BEACON SWITCH AND PERFORM TEST OF ULB BATTERY. (IRN # L2560000) 068E5542-00 ULB001945 REF: See Workcard	MOS HRS/MSC AFL	24	+14d/-14d	8		15-APR-2018 2434.6 1948	23-APR-2020	07-MAY-2020
+ 313005B	REPLACE FDR UNDERWATER LOCATOR BEACON BATTERY ON OR BEFORE ULB BATTERY REPLACEMENT DATE. (ZONE/ACCESS 300 IRN # D2566001) 068E5542-00 ULB001945 REF: See Workcard	MOS HRS/MSC AFL	DUE				20-MAY-2016 1821.7 1492	01-NOV-2021 M	

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
313010	HOBBS METER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
313018	INERTIA, FDR SWITCH 3LO-871/8 88712 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
314001	SELCAL DECODER 1200006-102 1953 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
314011	NO. 1 DATA ACQUISITION (DAU) UNIT 7013348-938 08036715 REF: AMM 31-42-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
314012	NO. 2 DATA ACQUISITION (DAU) UNIT 7013348-938 08036718 REF: AMM 31-42-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
314023	NO. 1 INTEGRATED AVIONICS (IC-600) DISPLAY UNIT 7017000-82223 08038445 REF: AMM 31-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
314024	NO. 2 INTEGRATED AVIONICS (IC-600) DISPLAY UNIT 7017000-82223 08048447 REF: AMM 31-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
314051	NO. 1 CENTRAL COMPUTING IM-600 MEMORY MODULE 7025973-04216 07055114 REF: AMM 31-41-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
314052	NO. 2 CENTRAL COMPUTING IM-600 MEMORY MODULE 7025973-04216 07125369 REF: AMM 31-41-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
315001	CREW WARNING PANEL ASSEMBLY 90-42801-8 562 REF: AMM 31-51-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
316001	NO. 1 DU870 COMPUTER 7014300-901 0803H060 REF: AMM 31-60-01	MOS HRS/MSC AFL	O/C	TSN:114 TSN:2383.6 TSN:1899			16-FEB-2018 2383.6 1899		
316001-1	PILOT (#1) MFD CONTROLLER BEZEL PN SN-UNKNOWN REF: AMM 31-60-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
316002	NO. 2 DU870 COMPUTER 7014300-901 0803H058 REF: AMM 31-60-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
316002-1	PILOT (#2) MFD CONTROLLER BEZEL PN SN-UNKNOWN REF: AMM 31-60-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
316003	NO. 3 DU870 COMPUTER 7014300-901 0803H059 REF: AMM 31-60-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
316003-1	COPILOT (#3) MFD CONTROLLER BEZEL PN SN-UNKNOWN REF: AMM 31-60-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		



Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
316004	NO. 4 DU870 COMPUTER 7014300-901 0205B554 REF: AMM 31-60-01	MOS HRS/MSC AFL	O/C	TSR:8 TSR:70 TSR:51			16-FEB-2018 2383.6 1899		
316004-1	COPILOT (#4) MFD CONTROLLER BEZEL PN SN-UNKNOWN REF: AMM 31-60-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
316005	PILOT EFIS DISPLAY CONTROLLER 7016986-733 07046837 REF: AMM 31-60-02	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			16-FEB-2018 2383.6 1899		
316006	COPILOT EFIS DISPLAY CONTROLLER 7016986-733 08037206 REF: AMM 31-60-02	MOS HRS/MSC AFL	O/C				14-MAR-2017 2045.2 1670		
316091	DATA TRANSFER, AFIS UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
B3100000 (s)	** INDICATING/RECORDING SYSTEM - PERFORM OPERATIONAL CHECK PKG 7 REF: AMM 31-00-00	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 30-NOV-2017 2313.6 1848		
CHAPTER 32	LANDING GEAR								
320041	REPLACE LEFT MAIN LANDING GEAR UPPER LINK PIN (P/N 200-0214) IRN N3220101 200-0214-101 H2304 REF: AMM 32-10-01	MOS HRS/MSC AFL		TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		5800
320042	REPLACE RIGHT MAIN LANDING GEAR UPPER LINK PIN (P/N 200-0214) (IRN N3220101) 200-0214-101 H2313 REF: AMM 32-10-01	MOS HRS/MSC AFL		TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		5800

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320051	REPLACE PISTON PIN (P/N 200-0215). (IRN N3220102)								
	200-0215-101	MOS		TSN:0			11-AUG-2008		
	H1109	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF: See Workcard	AFL	10000	TSN:0			0		10000
320052	REPLACE RIGHT MAIN LANDING GEAR PISTON PIN (P/N 200-0215) (IRN N3220102) ASSEMBLY								
	200-0215-101	MOS		TSN:0			11-AUG-2008		
	H1113	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF: See Workcard	AFL	10000	TSN:0			0		10000
320061	REPLACE LEFT MAIN LANDING GEAR ACTUATOR PISTON (P/N 200-0301) (IRN N3220103) (JAA IRN Q3220065) ASSEMBLY								
	200-0301-103	MOS		TSN:0			11-AUG-2008		
	H1237	HRS/MSC		TSN:0			0		
JAA	REF: See Workcard	AFL	13700	TSN:0			0		13700
320062	REPLACE RIGHT MAIN LANDING GEAR ACTUATOR PISTON (IRN N3220103) (JAA IRN Q3220065) ASSEMBLY								
	200-0301-103	MOS		TSN:0			11-AUG-2008		
	H1235	HRS/MSC		TSN:0			0		
JAA	REF: See Workcard	AFL	13700	TSN:0			0		13700
320071	REPLACE LEFT MAIN LANDING GEAR ACTUATOR CYLINDER (IRN N3220104) (JAA IRN Q3220066) ASSEMBLY								
	200-0302-101	MOS		TSN:0			11-AUG-2008		
	H1101	HRS/MSC		TSN:0			0		
JAA	REF: See Workcard	AFL	13700	TSN:0			0		13700
320072	REPLACE RIGHT MAIN LANDING GEAR ACTUATOR CYLINDER (IRN N3220104) (JAA IRN Q3220066) ASSEMBLY								
	200-0302-101	MOS		TSN:0			11-AUG-2008		
	H1111	HRS/MSC		TSN:0			0		
JAA	REF: See Workcard	AFL	13700	TSN:0			0		13700
320081	REPLACE LEFT MAIN LANDING GEAR END CAP (P/N 200-0303) (IRN T3220105) (JAA IRN T3220067) ASSEMBLY								
	200-0303-001	MOS		TSN:0			29-JUN-2018		
	H2753	HRS/MSC		TSN:0			2539.7		
JAA	REF: See Workcard	AFL	1988	TSN:0			2020		4008
320082	REPLACE RIGHT MAIN LANDING GEAR END CAP (P/N 200-0303) (IRN T3220105) (JAA IRN T3220067) ASSEMBLY								
	200-0303-001	MOS		TSN:0			29-JUN-2018		
	H2733	HRS/MSC		TSN:0			2539.7		
JAA	REF: See Workcard	AFL	1988	TSN:0			2020		4008

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320091	REPLACE LEFT MAIN LANDING GEAR ACTUATOR HOUSING (P/N 200-0304) (IRN N3220106) (JAA IRN Q3220068) ASSEMBLY								
	200-0304-001	MOS		TSN:0			11-AUG-2008		
	H1549	HRS/MSC		TSN:0			0		
JAA	REF: See Workcard	AFL	13700	TSN:0			0		13700
320092	REPLACE RIGHT MAIN LANDING GEAR ACTUATOR HOUSING (P/N 200-0304) (IRN N3220106) (JAA IRN Q3220068) ASSEMBLY								
	200-0304-001	MOS		TSN:0			11-AUG-2008		
	H1552	HRS/MSC		TSN:0			0		
JAA	REF: See Workcard	AFL	13700	TSN:0			0		13700
321001	LEFT MAIN LANDING GEAR STRUT (P/N 6632101000, 200-0200) (IRN N3220012) ASSEMBLY								
	200-0200-013	MOS		TSN:0			11-AUG-2008		
	H0501	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF: AMM 32-10-01	AFL	10000	TSN:0			0		10000
321001A	PERFORM SPECIAL DETAILED INSPECTION ON LEFT MAIN LANDING GEAR SHOCK STRUTS (IRN# T3220018)								
		MOS	96	+14d/-14d			20-MAY-2016	20-MAY-2024	03-JUN-2024
		HRS/MSC					1821.7		
	REF: See Workcard	AFL	6600	+25/-25			1492	8092	8117
321002	RIGHT MAIN LANDING GEAR STRUT (P/N 6632101000, 200-0200) (IRN N3220012) ASSEMBLY								
	200-0200-014	MOS		TSN:0			11-AUG-2008		
	H1507	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF: AMM 32-10-01	AFL	10000	TSN:0			0		10000
		APH							
321002A	PERFORM SPECIAL DETAILED INSPECTION ON RIGHT MAIN LANDING GEAR SHOCK STRUTS (IRN T3220018)								
		MOS	96	+14d/-14d			20-MAY-2016	20-MAY-2024	03-JUN-2024
		HRS/MSC					1821.7		
	REF: See Workcard	AFL	6600	+25/-25			1492	8092	8117
321011	LEFT MAIN LANDING GEAR SHOCK STRUT CYLINDER (IRN#S N3220116, Q3220137, Q3220128) ASSEMBLY								
	200-0201-005	MOS		TSN:0			11-AUG-2008		
	H0639	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF: AMM 32-10-01	AFL	10000	TSN:0			0		10000

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 321011A	ULTRASONIC INSPECTION LEFT MAIN LANDING GEAR SHOCK STRUT CYLINDER (IRN#S N3220116, Q3220137, Q3220128) ASSEMBLY MLG SHOCK STRUT CYLINDER. PERFORM ULTRASONIC INSPECTION OF THE LOWER SERVICE PORT AND FORGING PARTING LINE. IRN L3220118, M3220136, P3220146, (JAA IRN L3220122)								
	200-0201-005 H0639 REF: See Workcard	MOS HRS/MSC AFL	4800				11-AUG-2008 0 0	4800	
321012	RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER (IRN#S N3220116, Q3220137, Q3220128) ASSEMBLY								
	200-0201-006 H0639 REF: AMM 32-10-01	MOS HRS/MSC AFL	10000	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0	10000	
LIFE LIMIT									
+ 321012A	ULTRASONIC INSPECTION RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER (IRN#S N3220116, Q3220137, Q3220128) ASSEMBLY MLG SHOCK STRUT CYLINDER LOWER SERVICE PORT AND FORGING LINE. IRN# M3220136, L3220118, P3220146. (JAA IRN L3220122)								
	200-0201-006 H0639 REF: See Workcard	MOS HRS/MSC AFL	4800				11-AUG-2008 0 0	4800	
+ 321025	REPLACE LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR UPPER PIN (P/N 200-0325) (REFER TO 32-31-01) (IRN # T3220014)								
	200-0325-101 H2862 REF: See Workcard	MOS HRS/MSC AFL APH	96	TSN:0 TSN:0 TSN:0			05-AUG-2015 1656.2 1364	05-AUG-2023	
LIFE LIMIT									
321025A	REPLACE MAIN LANDING GEAR SIDE-STAY ACTUATOR UPPER PIN (P/N 200-0325) (REFER TO 32-31-01) (IRN # T3220014)								
	200-0325-101 H2862 REF: See Workcard	MOS HRS/MSC AFL	48				05-AUG-2015 1656.2 1364	05-AUG-2019	
AIRWORTHINESS									
321025B	REPLACE MAIN LANDING GEAR SIDE-STAY ACTUATOR UPPER PIN (P/N 200-0325) (REFER TO 32-31-01) (IRN # T3220014)								
	200-0325-101 H2862 REF: AMM 05-10-00	MOS HRS/MSC AFL	48				05-AUG-2015 1656.2 1364	05-AUG-2019	
AIRWORTHINESS									

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 321026	REPLACE MAIN LANDING GEAR SIDE STAY ACTUATOR UPPER PIN (P/N 200-0325) (REFER TO 32-31-01) (IRN # T3220014)								
	200-0325-101	MOS	96	TSN:0			05-AUG-2015		05-AUG-2023
	H3002	HRS/MSC		TSN:0			1656.2		
LIFE LIMIT	REF: See Workcard	AFL		TSN:0			1364		
	APH								
321026A	REPLACE MAIN LANDING GEAR SIDE STAY ACTUATOR UPPER PIN (P/N 200-0325) (REFER TO 32-31-01) (IRN # T3220014)								
	200-0325-101	MOS	48				05-AUG-2015		05-AUG-2019
	H3002	HRS/MSC					1656.2		
AIRWORTHINESS	REF: See Workcard	AFL					1364		
321026B	REPLACE MAIN LANDING GEAR SIDE STAY ACTUATOR UPPER PIN (P/N 200-0325) (REFER TO 32-31-01) (IRN # T3220014)								
	200-0325-101	MOS	48				05-AUG-2015		05-AUG-2019
	H3002	HRS/MSC					1656.2		
AIRWORTHINESS	REF: AMM 05-10-00	AFL					1364		
+ 321037	LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR LOWER PIN (P/N 200-0217) (REFER TO 32.31-01) (IRN T3220038) ASSEMBLY								
	200-0217-101	MOS	96	TSN:0			20-MAY-2016		20-MAY-2024
	H3275	HRS/MSC		TSN:0			1821.7		
LIFE LIMIT	REF: GENERIC NO REF	AFL		TSN:0			1492		
	APH								
321037A	MAGNETIC PARTICLE INSPECT LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR LOWER PIN (P/N 200-0217) (REFER TO 32.31-01) (IRN T3220038) ASSEMBLY (IRN T3220024)								
	200-0217-101	MOS	48				20-MAY-2016		20-MAY-2020
	H3275	HRS/MSC					1821.1		
AIRWORTHINESS	REF: See Workcard	AFL					1492		
321037B	DETAILED VISUAL INSPECTION LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR LOWER PIN (P/N 200-0217) (REFER TO 32.31-01) (IRN T3220038) ASSEMBLY (IRN T3220135)								
	200-0217-101	MOS	48				20-MAY-2016		20-MAY-2020
	H3275	HRS/MSC					1821.1		
AIRWORTHINESS	REF: AMM 05-10-00	AFL					1492		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 321038	RIGHT MAIN LANDING GEAR SIDE-STAY ACTUATOR LOWER PIN (P/N 200-0217) (REFER TO 32-31-01) (T3220038) ASSEMBLY								
	200-0217-101	MOS	96	TSN:0			20-MAY-2016		20-MAY-2024
	H3282	HRS/MSC		TSN:0			1821.7		
LIFE LIMIT	REF: GENERIC NO REF	AFL		TSN:0			1492		
	APH								
321038A	MAGNETIC PARTICLE INSPECT RIGHT MAIN LANDING GEAR SIDE-STAY ACTUATOR LOWER PIN (P/N 200-0217) (REFER TO 32-31-01) (T3220038) ASSEMBLY (IRN T3220024)								
	200-0217-101	MOS	48				20-MAY-2016		20-MAY-2020
	H3282	HRS/MSC					1821.1		
AIRWORTHINESS	REF: See Workcard	AFL					1492		
321038B	DETAILED VISUAL INSPECTION RIGHT MAIN LANDING GEAR SIDE-STAY ACTUATOR LOWER PIN (P/N 200-0217) (REFER TO 32-31-01) (T3220038) ASSEMBLY (IRN T3220135)								
	200-0217-101	MOS	48				20-MAY-2016		20-MAY-2020
	H3282	HRS/MSC					1821.1		
AIRWORTHINESS	REF: AMM 05-10-00	AFL					1492		
321049	LEFT MAIN LANDING GEAR AXLE BEAM (P/N 200-0203) (ZONE/ACCESS 720/730 * IRN N3220036) ASSEMBLY								
	200-0203-001	MOS		TSN:0			29-AUG-2018		
	H1742	HRS/MSC		TSN:0			2621.3		
LIFE LIMIT	REF: AMM 32-10-01	AFL	10000	TSN:0			2079		12079
	APH			TSN:0					
321049A	INSPECTION LEFT MAIN LANDING GEAR AXLES - PERFORM MAIN LANDING GEAR AXLE BEAM ASSEMBLY BORESCOPE INSPECTION (IRN T3220007)								
		MOS	48				15-APR-2018		15-APR-2022
		HRS/MSC					2434.6		
	REF: AMM 32-10-01	AFL					1948		
321050	RIGHT MAIN LANDING GEAR AXLE BEAM (P/N 200-0203) (ZONE/ACCESS 720/730 * IRN N3220036) ASSEMBLY								
	200-0203-001	MOS		TSN:0			11-AUG-2008		
	H1109	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF: AMM 32-10-01	AFL	10000	TSN:0			0		10000
	APH								

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321050A	INSPECTION RIGHT MAIN LANDING GEAR AXLES - PERFORM MAIN LANDING GEAR AXLE BEAM ASSEMBLY BORESCOPE INSPECTION (IRN T3220007)	MOS	48				15-APR-2018 2434.6 1948	15-APR-2022	
	REF: AMM 32-10-01	HRS/MSC AFL							
321061	LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR PIN	PN		TSN:0			11-AUG-2008 0 0		
	SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0					
321062	RIGHT MAIN LANDING GEAR SIDE-STAY ACTUATOR PIN	PN		TSN:0			11-AUG-2008 0 0		
	SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0					
321073	LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR DISPLACEMENT TUBE	200-0305-003		TSN:0			11-AUG-2008 0 0		
	H0137 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0					
321074	RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR DISPLACEMENT TUBE	200-0305-003		TSN:0			11-AUG-2008 0 0		
	H0127 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0					
321085	LEFT FORWARD TRUNNION ASSEMBLY	4532103011-011		TSN:0			11-AUG-2008 0 0		
	CMI-194 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0					
321086	RIGHT FORWARD TRUNNION ASSEMBLY	4532103011-012		TSN:0			11-AUG-2008 0 0		
	CMI-134 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0					
321087	LEFT AFT TRUNNION ASSEMBLY	4532130009-813					11-APR-2011 803.6 653		
	CMI-176 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321088	RIGHT AFT TRUNNION ASSEMBLY 4532130009-817 CMI-169 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				11-APR-2011 803.6 653		
321101	REPLACE LEFT MAIN LANDING GEAR TRUNNION FORWARD PIN (P/N 200-0212, 200-0213). (IRN N3220023) ASSEMBLY 200-0212-103 H1215 REF: See Workcard	MOS HRS/MSC AFL	10000	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0	10000	
321101A	MAGNETIC PARTICLE INSPECT LEFT MAIN LANDING GEAR TRUNNION FORWARD PIN - (IRN V3220022) REF: See Workcard	MOS HRS/MSC AFL	96	+14d/-14d			20-MAY-2016 1821.7 1492	20-MAY-2024	03-JUN-2024
321102	REPLACE RIGHT MAIN LANDING GEAR TRUNNION FORWARD PIN (P/N 200-0212, 200-0213) (IRN N3220023) ASSEMBLY 200-0212-103 H1067 REF: See Workcard	MOS HRS/MSC AFL	10000	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0	10000	
321102A	MAGNETIC PARTICLE INSPECT RIGHT MAIN LANDING GEAR TRUNNION FORWARD PIN (IRN V3220022) REF: See Workcard	MOS HRS/MSC AFL	96	+14d/-14d			20-MAY-2016 1821.7 1492	20-MAY-2024	03-JUN-2024
321103	REPLACE LEFT MAIN LANDING GEAR TRUNNION AFT PIN (P/N 200-0212, 200-0213) (IRN N3220023) ASSEMBLY 200-0213-103 H1048 REF: See Workcard	MOS HRS/MSC AFL	10000	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0	10000	
321103A	MAGNETIC PARTICLE INSPECT LEFT MAIN LANDING GEAR TRUNNION AFT PIN (IRN V3220022) REF: See Workcard	MOS HRS/MSC AFL	96	+14d/-14d			20-MAY-2016 1821.7 1492	20-MAY-2024	03-JUN-2024
321104	REPLACE RIGHT MAIN LANDING GEAR AFT TRUNNION PIN (P/N 200-0212, 200-0213) (IRN N3220023) ASSEMBLY 200-0213-103 H1045 REF: See Workcard	MOS HRS/MSC AFL	10000	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0	10000	



Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321104A	MAGNETIC PARTICLE INSPECT	RIGHT MAIN LANDING GEAR AFT TRUNNION PIN (IRN V3220022)							
		MOS	96	+14d/-14d			20-MAY-2016	20-MAY-2024	03-JUN-2024
	REF: See Workcard	HRS/MSC					1821.7		
		AFL					1492		
321111	LEFT MAIN GEAR FORWARD LOWER P/N 4532103015 AND 4532103132. (IRN # N3220041). AND P/N 4532103201 (IRN# N3220139). TRUNNION SHEAR PIN								
	4532103201-001	MOS		TSN:0			11-AUG-2008		
	CMI-2227	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF: AMM 57-10-05	AFL	5000	TSN:0			0	5000	
321111A	INSPECT LEFT MAIN LANDING GEAR FORWARD LOWER TRUNNION SHEAR PINS - PERFORM VISUAL INSPECTION FOR PIN MIGRATION. (REFER TO 57-10-05.) (EFFECTIVE ON AIRCRAFT 45-005 THRU 45-425 NOT MODIFIED PER SB 45-57-11.) IRN T3220147								
		MOS							
NOT APPLICABLE	REF: AMM 57-10-05	HRS/MSC	N/A						
		AFL							
321112	RIGHT MAIN GEAR FORWARD LOWER P/N 4532103015 AND 4532103132. (IRN # N3220041). AND P/N 4532103201 (IRN# N3220139). TRUNNION SHEAR PIN								
	4532103201-001	MOS		TSN:0			11-AUG-2008		
	CMI-1675	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF: AMM 57-10-05	AFL	5000	TSN:0			0	5000	
321112A	INSPECT RIGHT MAIN LANDING GEAR FORWARD LOWER TRUNNION SHEAR PINS - PERFORM VISUAL INSPECTION FOR PIN MIGRATION. (REFER TO 57-10-05.) (EFFECTIVE ON AIRCRAFT 45-005 THRU 45-425 NOT MODIFIED PER SB 45-57-11.) IRN T3220147								
		MOS							
NOT APPLICABLE	REF: AMM 57-10-05	HRS/MSC	N/A						
		AFL							
321113	LEFT MAIN GEAR FORWARD UPPER P/N 4532103015 AND 4532103132. (IRN # N3220041). AND P/N 4532103201 (IRN# N3220139). TRUNNION SHEAR PIN								
	4532103201-001	MOS		TSN:0			11-AUG-2008		
	CMI-2314	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF: AMM 57-10-05	AFL	5000	TSN:0			0	5000	
321113A	INSPECT LEFT MAIN LANDING GEAR FORWARD UPPER TRUNNION SHEAR PINS - PERFORM VISUAL INSPECTION FOR PIN MIGRATION. (REFER TO 57-10-05.) (EFFECTIVE ON AIRCRAFT 45-005 THRU 45-425 NOT MODIFIED PER SB 45-57-11.) IRN T3220147								
		MOS							
NOT APPLICABLE	REF: AMM 57-10-05	HRS/MSC	N/A						
		AFL							

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321114	RIGHT MAIN GEAR FORWARD UPPER P/N 4532103015 AND 4532103132. (IRN # N3220041). AND P/N 4532103201 (IRN# N3220139). TRUNNION SHEAR PIN								
	4532103201-001	MOS		TSN:0			11-AUG-2008		
	CMI-1693	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF: AMM 57-10-05	AFL	5000	TSN:0			0		5000
321114A	INSPECT RIGHT MAIN LANDING GEAR FORWARD UPPER TRUNNION SHEAR PINS - PERFORM VISUAL INSPECTION FOR PIN MIGRATION. (REFER TO 57-10-05.) (EFFECTIVE ON AIRCRAFT 45-005 THRU 45-425 NOT MODIFIED PER SB 45-57-11.) IRN T3220147								
		MOS							
		HRS/MSC	N/A						
NOT APPLICABLE	REF: AMM 57-10-05	AFL							
321117	LEFT MAIN GEAR AFT UPPER P/N 4532103025 AND 4532103133. (IRN # N3220042) P/N 4532103202 (IRN # N3220140) TRUNNION SHEAR PIN								
	4532103202-001	MOS		TSN:0			11-AUG-2008		
	CMI-759	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF: AMM 57-10-05	AFL	5000	TSN:0			0		5000
321117A	INSPECT LEFT MAIN LANDING GEAR AFT UPPER TRUNNION SHEAR PINS - PERFORM VISUAL INSPECTION FOR PIN MIGRATION. (EFFECTIVE 57-10-05) (EFFECTIVE ON AIRCRAFT 45-005 THRU 45-425 NOT MODIFIED PER SB 45-57-11.) IRN T3220147								
		MOS							
		HRS/MSC	N/A						
NOT APPLICABLE	REF: AMM 57-10-05	AFL							
321118	RIGHT MAIN GEAR AFT UPPER P/N 4532103025 AND 4532103133. (IRN # N3220042) P/N 4532103202 (IRN # N3220140) TRUNNION SHEAR PIN								
	4532103202-001	MOS		TSN:0			11-AUG-2008		
	CMI-819	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF: AMM 57-10-05	AFL	5000	TSN:0			0		5000
321118A	INSPECT RIGHT MAIN LANDING GEAR AFT UPPER TRUNNION SHEAR PINS - PERFORM VISUAL INSPECTION FOR PIN MIGRATION. (REFER TO 57-10-05.) (EFFECTIVE ON AIRCRAFT 45-005 THRU 45-425 NOT MODIFIED PER SB 45-57-11.) IRN T3220147								
		MOS							
		HRS/MSC	N/A						
NOT APPLICABLE	REF: AMM 57-10-05	AFL							



Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321119	LEFT MAIN GEAR AFT LOWER P/N 4532103026 AND 4532103134. (IRN # N3220043) P/N 4532103203 (IRN # N3220141) TRUNNION SHEAR PIN								
	4532103203-001	MOS		TSN:0			11-AUG-2008		
	CMI-915	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF: AMM 57-10-05	AFL	5000	TSN:0			0		5000
321119A	INSPECT LEFT MAIN LANDING GEAR AFT LOWER TRUNNION SHEAR PINS - PERFORM VISUAL INSPECTION FOR PIN MIGRATION. (REFER TO 57-10-05.) (EFFECTIVE ON AIRCRAFT 45-005 THRU 45-425 NOT MODIFIED PER SB 45-57-11.) IRN T3220147								
		MOS							
		HRS/MSC	N/A						
NOT APPLICABLE	REF: AMM 57-10-05	AFL							
321120	RIGHT MAIN GEAR AFT LOWER P/N 4532103026 AND 4532103134. (IRN # N3220043) P/N 4532103203 (IRN # N3220141) TRUNNION SHEAR PIN								
	4532103203-001	MOS		TSN:0			11-AUG-2008		
	CMI-914	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF: AMM 57-10-05	AFL	5000	TSN:0			0		5000
321120A	INSPECT RIGHT MAIN LANDING GEAR AFT LOWER TRUNNION SHEAR PINS - PERFORM VISUAL INSPECTION FOR PIN MIGRATION. (REFER TO 57-10-05.) (EFFECTIVE ON AIRCRAFT 45-005 THRU 45-425 NOT MODIFIED PER SB 45-57-11.) IRN T3220147								
		MOS							
		HRS/MSC	N/A						
NOT APPLICABLE	REF: AMM 57-10-05	AFL							
321201	LEFT MAIN LANDING GEAR OLEO ASSEMBLY								
	PN	MOS		TSN:0			11-AUG-2008		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
321202	RIGHT MAIN LANDING GEAR OLEO ASSEMBLY								
	PN	MOS		TSN:0			11-AUG-2008		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
321215	REPLACE LEFT MAIN LANDING GEAR SHOCK STRUT PISTON (P/N 200-0202) (IRN N3220035) ASSEMBLY								
	200-0202-003	MOS		TSN:0			11-AUG-2008		
	H1104	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF: See Workcard	AFL	10000	TSN:0			0		10000
		APH							

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321216	REPLACE RIGHT MAIN LANDING GEAR SHOCK STRUT PISTON (P/N 200-0202) (IRN N3220035) ASSEMBLY								
	200-0202-003	MOS		TSN:0			11-AUG-2008		
	H1088	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF: See Workcard	AFL	10000	TSN:0			0		10000
	APH								
321227	REPLACE LEFT MAIN LANDING GEAR SHOCK STRUT LINK (P/N 200-0204) (IRN N3220037) ASSEMBLY								
	200-0204-001	MOS		TSN:0			11-AUG-2008		
	H1384	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF: AMM 32-10-01	AFL	10000	TSN:0			0		10000
	APH								
321228	REPLACE RIGHT MAIN LANDING GEARSHOCK STRUT LINK (P/N 200-0204) (IRN N3220037) ASSEMBLY								
	200-0204-001	MOS		TSN:0			11-AUG-2008		
	H1389	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF: AMM 32-10-01	AFL	10000	TSN:0			0		10000
	APH								
321301	LEFT MAIN LANDING GEAR OUTBOARD DOOR								
	4552803003-003	MOS		TSN:0			11-AUG-2008		
	890909500479	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 52-80-01	AFL		TSN:0			0		
321302	LEFT MAIN LANDING GEAR INBOARD DOOR								
	4552803004-003	MOS		TSN:0			11-AUG-2008		
	381144600480	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 52-80-01	AFL		TSN:0			0		
321303	RIGHT MAIN LANDING GEAR INBOARD DOOR								
	4552803004-004	MOS		TSN:0			11-AUG-2008		
	574395600450	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 52-80-01	AFL		TSN:0			0		
321304	RIGHT MAIN LANDING GEAR OUTBOARD DOOR								
	4552803003-004	MOS		TSN:0			11-AUG-2008		
	011779500479	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 52-80-01	AFL		TSN:0			0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
322001	REPLACE NOSE LANDING GEAR STRUT (P/N 2342100) (ZONE/ACCESS 710 *IRN # 03220009) (JAA E3220069) ASSEMBLY								
	4532201000V16-005	MOS		TSN:0			11-AUG-2008		
	463	HRS/MSC		TSN:0			0		
ALI / JAA	REF: AMM 32-20-01	AFL	16000	TSN:0			0		16000
322002	NOSE LANDING GEAR CYLINDER								
	2342102	MOS		TSN:0			11-AUG-2008		
	T683	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
322003	NOSE LANDING GEAR PISTON								
	2342104	MOS		TSN:0			11-AUG-2008		
	F436	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF: GENERIC NO REF	AFL	20000	TSN:0			0		20000
322004	NOSE LANDING GEAR ACTUATOR BRACKET								
	2342111	MOS		TSN:0			11-AUG-2008		
	R502	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
322005	NOSE LANDING GEAR FORK								
	2342116	MOS		TSN:0			11-AUG-2008		
	R672	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
322011	REPLACE NOSE LANDING GEAR ACTUATOR (P/N 6632201000) (ZONE/ACCESS 710 *IRN # 03220010) (JAA IRN E3220073) ASSEMBLY								
	6632201000-005	MOS					10-FEB-2011		
	EFS580	HRS/MSC		TSN:284			803.6		
ALI / JAA	REF: AMM 32-32-01	AFL	16000	TSN:305			653		16348
322041	NOSE LANDING GEAR (P/N 2342110) IRN 03220029 AXLE								
	2342117-002	MOS		TSN:0			20-MAY-2016		
	R1535	HRS/MSC	O/C	TSN:0			1821.7		
	REF:	AFL		TSN:0			1492		
322061	REPLACE NOSE LANDING GEAR TRUNNION AXLE (P/N 2342110) (IRN 03220029 JAA IRN E3220072)								
	2342110-003	MOS		TSN:0			11-AUG-2008		
	R761	HRS/MSC		TSN:0			0		
ALI / JAA	REF: AMM 32-20-01	AFL	16000	TSN:0			0		16000

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
322071	REPLACE LEFT NOSE GEAR TRUNNION PIN (P/N 2342108) (IRN O3220028 JAA IRN E3220071)								
	2342108-003	MOS		TSN:0			11-AUG-2008		
	E419	HRS/MSC		TSN:0			0		
ALI / JAA	REF: AMM 32-20-01	AFL	16000	TSN:0			0		16000
322072	REPLACE RIGHT NOSE GEAR TRUNNION PIN (P/N 2342108) (IRN O3220028 JAA IRN E3220071)								
	2342108-003	MOS		TSN:0			11-AUG-2008		
	E453	HRS/MSC		TSN:0			0		
ALI / JAA	REF: AMM 32-20-01	AFL	16000	TSN:0			0		16000
322095	LEFT NOSE LANDING GEAR DOOR								
	4552800001-007	MOS		TSN:0			11-AUG-2008		
	501	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 52-81-01	AFL		TSN:0			0		
322096	RIGHT NOSE LANDING GEAR DOOR								
	4552800002-007	MOS		TSN:0			11-AUG-2008		
	497	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 52-81-01	AFL		TSN:0			0		
322111	NOSE LANDING GEAR CHASSIS ASSEMBLY								
	PN	MOS		TSN:0			11-AUG-2008		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
322121	NOSE LANDING GEAR UPLOCK MECHANISM								
	2269H000-003	MOS		TSN:0			11-AUG-2008		
	1545	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-32-02	AFL		TSN:0			0		
323001	LEFT * MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY REPLACE								
	200-0300-003	MOS		TSR:1			29-JUN-2018		
	H0536	HRS/MSC		TSN:2469.9 TSR:0			2539.7		
JAA	REF: AMM 32-31-01	AFL	13700	TSN:1969 TSR:0			2020		13751
323001A	INSPECT LH MAIN LANDING GEAR SIDE-STAY ACTUATOR - DISASSEMBLE ACTUATOR AND PERFORM DETAILED VISUAL INSPECTION. (IRN S3220111)								
		MOS	96	+14d/-14d			20-MAY-2016	20-MAY-2024	03-JUN-2024
		HRS/MSC					1821.7		
	REF: GENERIC NO REF	AFL	10000	+25/-25			1492	11492	11517

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323002	RIGHT * MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY REPLACE 200-0300-004 H1537	MOS HRS/MSC AFL		TSR:1 TSN:2469.9 TSR:0 TSN:1969 TSR:0			29-JUN-2018 2539.7 2020		13751
JAA	REF: AMM 32-31-01	AFL	13700						
323002A	INSPECT RH MAIN LANDING GEAR SIDE-STAY ACTUATOR - DISASSEMBLE ACTUATOR AND PERFORM DETAILED VISUAL INSPECTION. (IRN S3220111)	MOS HRS/MSC AFL	96 10000	+14d/-14d +25/-25			20-MAY-2016 1821.7 1492	20-MAY-2024 11492	03-JUN-2024 11517
REF: GENERIC NO REF									
323037	MAIN LANDING GEAR UPLOCK INBD DOOR, LEFT MECHANISM 3000H000-005 2080	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
REF: AMM 32-31-04									
323038	MAIN LANDING GEAR UPLOCK INBD DOOR, RIGHT MECHANISM 3000H000-006 2082	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
REF: AMM 32-31-04									
323110	NOSE LANDING GEAR DOWN-LOCK (S139) SWITCH PN SN-UNKNOWN	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-APR-2014 1345.4 1094		
REF: AMM 32-60-05									
323220	DOWN AND LOCKED (S96) SWITCH 604HE162 1472	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
REF: AMM 32-60-02									
323221	DOWN AND LOCKED (S100) SWITCH 604HE162 1459	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
REF: AMM 32-60-02									

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323301	REPLACE LEFT MAIN LANDING GEAR INBOARD DOOR ACTUATOR (P/N 7469-1) CAP SCREWS (IRN L3231024) EFFECTIVE ON 45-005 THRU 45-276 MODIFIED PER SB 45-32-19 AND 45-277 AND SUBSEQUENT								
	7469-1	MOS					16-FEB-2018		
LIFE LIMIT	SN-UNKNOWN	HRS/MSC	2400	TSN:0			2383.6		4783.6
	REF: AMM 32-31-02	AFL		TSN:0			1899		
		APH							
323302	REPLACE RIGHT MAIN LANDING GEAR INBOARD DOOR ACTUATOR (P/N 7469-1) CAP SCREWS (IRN L3231024) EFFECTIVE ON 45-005 THRU 45-276 MODIFIED PER SB 45-32-19 AND 45-277 AND SUBSEQUENT								
	6632303003-003	MOS		TSO:0			05-DEC-2015		
	1199	HRS/MSC	2400	TSO:0			1743.3		4143.3
	REF: AMM 32-31-02	AFL		TSO:0			1436		
323305	LEFT MLG ACTUATOR GIMBAL ASSEMBLY								
	PN	MOS		TSN:0			11-AUG-2008		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-31-06	AFL		TSN:0			0		
323306	RIGHT MLG ACTUATOR GIMBAL ASSEMBLY								
	PN	MOS		TSN:0			11-AUG-2008		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-31-06	AFL		TSN:0			0		
323307	LEFT MLG SHAFT GIMBAL ASSEMBLY								
	PN	MOS		TSN:0			11-AUG-2008		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-31-06	AFL		TSN:0			0		
323308	RIGHT MLG SHAFT GIMBAL ASSEMBLY								
	PN	MOS		TSN:0			11-AUG-2008		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-31-06	AFL		TSN:0			0		
323309	LEFT MLG INBOARD DOOR GIMBAL BRACKET ASSEMBLY								
	PN	MOS		TSN:0			11-AUG-2008		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-31-06	AFL		TSN:0			0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323310	RIGHT MLG INBOARD DOOR GIMBAL BRACKET ASSEMBLY PN SN-UNKNOWN REF: AMM 32-31-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
323735	CONTROL VALVE 6632302001-003 0025 REF: AMM 32-30-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			14-APR-2011 803.6 653		
324001	NO. 1 MAIN LANDING GEAR WHEEL 3-1545-1 2795 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			30-NOV-2017 2313.6 1848		
324001A	NON DESTRUCTIVE TEST NO. 1 MAIN LANDING GEAR WHEEL 3-1545-1 2795 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				30-NOV-2017 2313.6 1848		
324002	NO. 2 MAIN LANDING GEAR WHEEL 3-1545-1 2652 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			29-JUN-2018 2539.7 2020		
324002A	NON DESTRUCTIVE TEST NO. 2 MAIN LANDING GEAR WHEEL 3-1545-1 2652 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						
324003	NO. 3 MAIN LANDING GEAR WHEEL 3-1545-1 2959 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			30-NOV-2017 2313.6 1848		
324003A	NON DESTRUCTIVE TEST NO. 3 MAIN LANDING GEAR WHEEL 3-1545-1 2959 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				30-NOV-2017 2313.6 1848		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324004	NO. 4 MAIN LANDING GEAR WHEEL 3-1545-1 2654 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			29-JUN-2018 2539.7 2020		
324004A	NON DESTRUCTIVE TEST NO. 4 MAIN LANDING GEAR WHEEL 3-1545-1 2654 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						
324005	NOSE GEAR WHEEL ASSEMBLY 9544207-4 APR15-11470 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C				06-SEP-2017 2287.7 1785		
324021	NO. 1 MAIN LANDING GEAR TIRE 226K08-4 61362924 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	TSN:14 TSN:0 TSN:0			30-NOV-2017 2313.6 1848		
324022	NO. 2 MAIN LANDING GEAR TIRE 226K08-4 80252532 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JUN-2018 2539.7 2020		
324023	NO. 3 MAIN LANDING GEAR TIRE 226K08-4 61332669 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	TSN:14 TSN:0 TSN:0			30-NOV-2017 2313.6 1848		
324024	NO. 4 MAIN LANDING GEAR TIRE 226K08-4 70882472 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JUN-2018 2539.7 2020		
324025	NOSE LANDING GEAR TIRE 031-613-8 7041S00465 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	TSN:7 TSN:0 TSN:0			06-SEP-2017 2287.7 1785		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324061	LEFT ANTI-SKID CONTROL VALVE 39-787 1146 REF: AMM 32-41-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
324062	RIGHT ANTI-SKID CONTROL VALVE 39-787 1153 REF: AMM 32-41-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
324066	LEFT ANTI-SKID SHUTOFF VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
324067	RIGHT ANTI-SKID SHUTOFF VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
324097	BRAKE CONTROL UNIT 42-933-3 654 REF: AMM 32-41-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
324108	EMERGENCY PARKING BRAKE CHECK VALVE 6632401002-011 339 REF: AMM 32-42-09	MOS HRS/MSC AFL	O/C	TSR:20 TSR:0 TSR:0		04/22/2016	22-APR-2014 1345.4 1094		
324109	EMERGENCY/PARK BRAKE VALVE 6632401002-011 0655 REF: AMM 32-42-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			29-APR-2011 803.6 653		
324110	PRESSURE, EMERGENCY/PARK BRAKE TRANSDUCER 7629301001-001 7467-8-302 REF: AMM 32-42-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324111	NO. 1 ASSEMBLY, MAIN LANDING GEAR BRAKE 2-1579-2 2298 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
324112	NO. 2 ASSEMBLY, MAIN LANDING GEAR BRAKE 2-1579-2 2277 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
324113	NO. 3 ASSEMBLY, MAIN LANDING GEAR BRAKE 2-1579-2 1318 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C				20-MAY-2016 1821.7 1492		
324114	NO. 4 ASSEMBLY, MAIN LANDING GEAR BRAKE 2-1579-2 2283 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
324201	NO. 1 BRAKE SHUTTLE VALVE 5116-1 2045 REF: AMM 32-42-04	MOS HRS/MSC AFL	O/C	TSN:32 TSN:803.6 TSN:653			29-APR-2011 803.6 653		
324202	NO. 2 BRAKE SHUTTLE VALVE 5116-1 2040 REF: AMM 32-42-04	MOS HRS/MSC AFL	O/C	TSN:32 TSN:803.6 TSN:653			29-APR-2011 803.6 653		
324203	NO. 3 BRAKE SHUTTLE VALVE 5116-1 2046 REF: AMM 32-42-04	MOS HRS/MSC AFL	O/C	TSN:32 TSN:803.6 TSN:653			29-APR-2011 803.6 653		
324204	NO. 4 BRAKE SHUTTLE VALVE 5116-1 2047 REF: AMM 32-42-04	MOS HRS/MSC AFL	O/C	TSN:32 TSN:803.6 TSN:653			29-APR-2011 803.6 653		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324205	BRAKE SHUTTLE MODULE PN SN-UNKNOWN REF: AMM 32-41-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
324305	LEFT PILOT BRAKE TRANSDUCER PN SN-UNKNOWN REF: AMM 32-41-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
324306	RIGHT PILOT BRAKE TRANSDUCER PN SN-UNKNOWN REF: AMM 32-41-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
324610-1	LEFT INBOARD BRAKE SWIVEL PN SN-UNKNOWN REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
324610-2	LEFT OUTBOARD BRAKE SWIVEL PN SN-UNKNOWN REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
324611-1	RIGHT INBOARD BRAKE SWIVEL 144890-04 1623 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-APR-2017 2080.2 1694		
324611-2	RIGHT OUTBOARD BRAKE SWIVEL 144890-06 1769 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	TSN:3 TSN:0 TSN:0			30-NOV-2017 2313.6 1848		
324701	NO. 1 HYDRAULIC, BRAKE FUSE PN SN-UNKNOWN REF: AMM 32-41-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324702	NO. 2 HYDRAULIC, BRAKE FUSE PN SN-UNKNOWN REF: AMM 32-41-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
324703	NO. 3 HYDRAULIC, BRAKE FUSE PN SN-UNKNOWN REF: AMM 32-41-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
324704	NO. 4 HYDRAULIC, BRAKE FUSE PN SN-UNKNOWN REF: AMM 32-41-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
324711	NO. 1 WHEEL SPEED - ANTI-SKID TRANSDUCER PN SN-UNKNOWN REF: AMM 32-41-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
324712	NO. 2 WHEEL SPEED - ANTI-SKID TRANSDUCER PN SN-UNKNOWN REF: AMM 32-41-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
324713	NO. 3 WHEEL SPEED - ANTI-SKID TRANSDUCER PN SN-UNKNOWN REF: AMM 32-41-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
324714	NO. 4 WHEEL SPEED - ANTI-SKID TRANSDUCER PN SN-UNKNOWN REF: AMM 32-41-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
324721	(MT56) PRESSURE BRAKE TRANSDUCER ASSEMBLY PN SN-UNKNOWN REF: AMM 32-41-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324722	(MT57) PRESSURE BRAKE TRANSDUCER ASSEMBLY PN SN-UNKNOWN REF: AMM 32-41-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
324723	(MT58) PRESSURE BRAKE TRANSDUCER ASSEMBLY PN SN-UNKNOWN REF: AMM 32-41-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
324724	(MT59) PRESSURE BRAKE TRANSDUCER ASSEMBLY PN SN-UNKNOWN REF: AMM 32-41-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
324801	EMERGENCY/PARK BRAKE FUSE PN SN-UNKNOWN REF: AMM 32-42-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
324805	EMER/PARK BRAKE ACCUMULATOR 88744-1 531 REF: AMM 32-42-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
325007	FILTER, NOSE WHEEL STEERING (P41) BOX PN SN-UNKNOWN REF: AMM 32-50-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
325011	NOSE WHEEL STEERING SERVO ACTUATOR JR5208C A0542 REF: AMM 32-50-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
325021	NOSE WHEEL STEERING GEARBOX 2W3201D C0543 REF: AMM 32-50-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
325031	NOSE WHEEL STEERING DISPLAY UNIT 498000-03-02 00642 REF: AMM 32-50-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
325035	NOSE WHEEL STEERING POWER SUPPLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
325041	LEFT NOSE WHEEL STEERING TRANSDUCER 19710 / 3A1-279A A1060 REF: AMM 32-50-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
325042	RIGHT NOSE WHEEL STEERING TRANSDUCER 19710 / 3A1-279A A1066 REF: AMM 32-50-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
325051	NOSE LANDING GEAR ACTUATOR UPPER. (P/N 4532302043). (IRN O3220011) OR (JAA - IRN E3220070 @ 16,000 LDGS). 4532302043-007 720 REF: AMM 32-32-01	MOS HRS/MSC AFL	16000	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		16000
ALI / JAA									
326000	NOSE LANDING GEAR WIRE HARNESS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
326104	NOSE LANDING GEAR SQUAT/WOW (S178) SWITCH PN SN-UNKNOWN REF: AMM 32-50-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
326105	NO. 1 MAIN GEAR SQUAT SWITCH PN SN-UNKNOWN REF: AMM 32-60-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
326106	NO. 2 MAIN GEAR SQUAT SWITCH PN SN-UNKNOWN REF: AMM 32-60-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
326107	NO. 3 MAIN GEAR SQUAT SWITCH PN SN-UNKNOWN REF: AMM 32-60-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
326108	NO. 4 MAIN GEAR SQUAT SWITCH PN SN-UNKNOWN REF: AMM 32-60-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
326115	SQUAT SWITCH P21 RELAY BOX PN SN-UNKNOWN REF: AMM 32-60-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
5-19-00-D3260006	NOSE LANDING GEAR SQUAT SWITCH ROTATING DISK ASSEMBLY. EFFECTIVE ON AIRCRAFT 45-001 THRU 45-071 MODIFIED PER SB 45-32-3 AND AIRCRAFT 45-072 THRU 45-114 NO MODIFIED PER SB 45-32-8. (ZONE/ACCESS 700 IRN # D326006) REF: AMM 12-21-01	MOS HRS/MSC AFL	N/A				11-AUG-2008 0 0		
5-19-00-J3220120	VISUAL INSPECT MLG TRUNNION SHEAR PIN BUSHING- FOR BUSHING MIGRATION. EFFECTIVE ON AIRCRAFT 45-005 THRU 45-208, 45-210 THRU 45-222, 45-224, 45-225, 45-229 AND 45-230 NOT MODIFIED PER SB 45-57-7, REF: AMM 57-10-05	MOS HRS/MSC AFL	O/C				11-AUG-2008 0 0		
5-19-00-JAA-L3220122	INSPECTION MAIN LANDING GEAR SHOCK STRUT CYLINDER P/N 200-0201-101, -102, -103, -104, -105, -106, -107, -108. (ZONE/ACCESS 720/730 IRN # L3220122) REF:	MOS HRS/MSC AFL					11-AUG-2008 0 0		
ALI / JAA			2400						2400



Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 5-19-00-L3220020	MAIN LANDING GEAR (MLG) TRUNNION FITTINGS ON MID AND REAR SPAR - PERFORM EDDY CURRENT INSPECTION. (REFER TO NDI MANUAL [NDI-104], PART 6, 32-11-00. IRN # L3220020	MOS					11-AUG-2008		
AIRWORTHINESS	REF: NDT PART 6/32-11-00	HRS/MSC AFL	10000				0 0		10000
5-19-00-P3231020	EDDY CURRENT INSPECTION MAIN LANDING GEAR DOOR ACTUATOR GIMBAL ASSEMBLY - PERFORM EDDY CURRENT INSPECTION. (REFER TO NDI MANUAL (NDI-104), PART 6, 32-13-00.) EFFECTIVE ON AIRCRAFT 45-005 THRU 45-354 NOT MODIFIED PER SB 45-32-25,	MOS					11-AUG-2008		
32.101 N/A BY SERIAL NUMBER	REF: NDT PART 6/32-13-00	HRS/MSC - AFL					0 0		
5-19-00-P3231021	FLUORESCENT PENETRANT INSPECT MAIN LANDING GEAR DOOR ACTUATOR GIMBAL SHAFT - PERFORM FLUORESCENT PENETRANT INSPECTION. (REFER TO NDI MANUAL (NDI-104), PART 8, 32-13-02.) EFFECTIVE ON AIRCRAFT 45-005 THRU 45-354 NOT MODIFIED PER SB 45-32-25,	MOS					11-AUG-2008		
32.102 N/A BY SERIAL NUMBER	REF: NDT PART 8/32-13-02	HRS/MSC - AFL					0 0		
5-19-00-P3231022	MAIN LANDING GEAR INBOARD DOOR GIMBAL BRACKET - PERFORM EDDY CURRENT INSPECTION. (REFER TO NDI MANUAL (NDI-104), PART 6, 32-13-01.) (EFFECTIVE ON AIRCRAFT 45-005 THRU 45-354 NOT MODIFIED PER SB 45-32-25, "LANDING GEAR - REPLACEMENT OF MLG INBOARD DOOR ACTUATOR GIMBAL")	MOS					11-AUG-2008		
32.103 N/A BY SERIAL NUMBER	REF: NDT PART 6/32-13-01	HRS/MSC - AFL					0 0		
5-19-01-F3220045	REPLACE NOSE LANDING GEAR ACTUATOR ATTACHMENT FITTING (ZINK COATED). (AIRCRAFT 45-002 THRU 45-039.)	MOS					11-AUG-2008		
NOT INSTALLED	REF: AMM 32-32-01	HRS/MSC N/A AFL					0 0		
5-20-00-JAA-Q3220065	REPLACE MAIN LANDING GEAR ACTUATOR PISTON P/N 200-0301. (ZONE/ACCESS 720/730 IRN # Q3220065)	MOS					11-AUG-2008		
JAA	REF:	HRS/MSC AFL	13700				0 0		13700
5-20-00-JAA-Q3220066	REPLACE MAIN LANDING ACTUATOR CYLINDER P/N 200-0302. (ZONE/ACCESS 720/730 IRN # Q3220066)	MOS					11-AUG-2008		
JAA	REF:	HRS/MSC AFL	13700				0 0		13700



Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-20-00-JAA-Q3220068	REPLACE MAIN LANDING GEAR ACTUATOR HOUSING P/N 200-0304. (ZONE/ACCESS 720/730 IRN # Q3220068)								
JAA	REF:	MOS HRS/MSC AFL					11-AUG-2008 0 0		13700
571010	REPLACE LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR (P/N 4532103041) (IRN N3220126) (JAA IRN Q3220132, P/N 4532103031) FITTING								
57.010	4532103041-009PP 18692/1-04	MOS HRS/MSC AFL		TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		17000
JAA	REF: See Workcard		17000						
571011	REPLACE RIGHT MAIN LANDING GEAR SIDE-STAY ACTUATOR (P/N 4532103041) (IRN N3220126) (JAA IRN Q3220132, P/N 4532103031) FITTING								
57.011	4532103041-010PP 18694/1-08	MOS HRS/MSC AFL		TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		17000
JAA	REF: See Workcard		17000						
A3230001 (s)	** LANDING GEAR - PERFORM EMERGENCY GEAR EXTENSION FUNCTIONAL TEST						PKG		
	PKG 11	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			30-NOV-2017 2313.6 1848		
AIRWORTHINESS	REF: AMM 32-33-00								
A3230002 (s)	MAIN LANDING GEAR FREE FALL ROLLER - PERFORM VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO BINDING OF ROLLERS						PKG		
	PKG 5	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			29-AUG-2018 2621.3 2079		
AIRWORTHINESS	REF: AMM 05-10-00								
A3240005 (s)	PERFORM ** BRAKE HYDRAULIC FUSES - FUNCTIONAL TEST						PKG		
	PKG 17	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			20-MAY-2016 1821.7 1492		
AIRWORTHINESS	REF: AMM 32-41-09								
A3240006 (s)	PERFORM ** BRAKE SHUTTLE MODULE - FUNCTIONAL TEST						PKG		
	PKG 17	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			20-MAY-2016 1821.7 1492		
AIRWORTHINESS	REF: AMM 32-41-04								

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
A3240007 (s)	PERFORM **BRAKE SHUTTLE VALVES - FUNCTIONAL TEST PKG 23	MOS	96	+14d/-14d			PKG 20-MAY-2016		
AIRWORTHINESS	REF: AMM 32-42-04	HRS/MSC AFL	2400	+25/-25			1821.7 1492		
D3260005 (s)	NOSE LANDING GEAR SQUAT SWITCH ROTATING DISK ASSEMBLY - LUBRICATE. (EFFECTIVE ON AIRCRAFT 45-001 THRU 45-114 POST SB 45-32-8 AND AIRCRAFT 45-115 AND SUBSEQUENT) PKG 5	MOS	12	+14d/-14d			PKG 29-AUG-2018		
	REF: AMM 12-21-01	HRS/MSC AFL	300	+25/-25			2621.3 2079		
G3220000 (s)	NOSE LANDING GEAR ASSEMBLY - PERFORM VISUAL INSPECTION PKG 11	MOS	24	+14d/-14d			PKG 30-NOV-2017		
	REF: AMM 05-10-00	HRS/MSC AFL	600	+25/-25			2313.6 1848		
G3220001 (s)	MAIN LANDING GEAR ASSEMBLY - PERFORM VISUAL INSPECTION. INSPECTION TO INCLUDE ACTUATOR, FASTENERS, SUPPORT STRUCTURE, AND SQUAT SWITCHES PKG 11	MOS	24	+14d/-14d			PKG 30-NOV-2017		
	REF: AMM 05-10-00	HRS/MSC AFL	600	+25/-25			2313.6 1848		
G3220002 (s)	NOSE LANDING GEAR ACTUATOR PRESSURE AND RETURN LINES - PERFORM VISUAL INSPECTION. LOWER ACTUATOR DUST BOOT TO INSPECT LINES PKG 11	MOS	24	+14d/-14d			PKG 30-NOV-2017		
	REF: AMM 05-10-00	HRS/MSC AFL	600	+25/-25			2313.6 1848		
G3220004 (s)	MAIN LANDING GEAR ACTUATOR AND GEAR INBOARD DOOR ACTUATOR ATTACH POINTS - PERFORM VISUAL INSPECTION PKG 11	MOS	24	+14d/-14d			PKG 30-NOV-2017		
	REF: AMM 05-10-00	HRS/MSC AFL	600	+25/-25			2313.6 1848		
G3220006 (s)	LANDING GEAR ELECTRICAL WIRING - PERFORM VISUAL INSPECTION (THAT PORTION VISIBLE INSIDE WHEEL WELL) PKG 11	MOS	24	+14d/-14d			PKG 30-NOV-2017		
	REF: AMM 05-10-00	HRS/MSC AFL	600	+25/-25			2313.6 1848		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
G3240001 (s)	BRAKE LINES - PERFORM VISUAL INSPECTION. INSPECT ALL BRAKE LINES VISIBLE IN WHEEL WELLS AND ON STRUTS						PKG		
	PKG 11	MOS	24	+14d/-14d			30-NOV-2017		
		HRS/MSC	600	+25/-25			2313.6		
	REF: AMM 05-10-00	AFL					1848		
L3220124 (s)	NOSE LANDING GEAR - PERFORM DETAILED VISUAL INSPECTION OF THE NOSE LANDING GEAR UPLOCK ROLLER BRACKET						PKG		
	PKG 11	MOS	24	+14d/-14d			30-NOV-2017		
		HRS/MSC	600	+25/-25			2313.6		
	REF: AMM 05-10-00	AFL					1848		
O3240000 (s)	NOSE AND MAIN TIRES - PERFORM VISUAL INSPECTION						PKG		
	PKG 5	MOS	12	+14d/-14d			29-AUG-2018		
		HRS/MSC	300	+25/-25			2621.3		
	REF: AMM 12-10-04	AFL					2079		
O3240002 (s)	BRAKE ASSEMBLIES - PERFORM VISUAL INSPECTION WITH PARKING BRAKE SET. WORN BRAKES ARE VISUALLY INDICATED WHEN THE WEAR INDICATOR PINS BECOME EVEN WITH THE OUTER SURFACE OF THE WEAR INDICATOR SLEEVE						PKG		
	PKG 5	MOS	12	+14d/-14d			29-AUG-2018		
		HRS/MSC	300	+25/-25			2621.3		
	REF: AMM 32-41-01	AFL					2079		
X3220003 (s)	NOSE GEAR SHOCK STRUT - REMOVE AND REPLACE RETAINER RING LOCKSCREW						PKG		
	PKG 11	MOS	24	+14d/-14d			30-NOV-2017		
		HRS/MSC	600	+25/-25			2313.6		
	REF: GENERIC NO REF	AFL					1848		

CHAPTER 33

LIGHTS

330000	MODIFIED PULSE CONTROLLER								
	2401S	MOS					11-AUG-2008		
	01290	HRS/MSC	O/C		TSN:0		0		
	REF: GENERIC NO REF	AFL			TSN:0		0		
331001	NO. 1 LIGHTING CONTROL UNIT								
	RDC4-1	MOS					11-AUG-2008		
	1015	HRS/MSC	O/C		TSN:0		0		
	REF: AMM 33-10-06	AFL			TSN:0		0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
331002	NO. 2 LIGHTING CONTROL UNIT RDC4-1 1018 REF: AMM 33-10-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
331010	PILOT FORWARD SWITCH PANEL OVERLAY PN SN-UNKNOWN REF: AMM 33-10-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
331011	PILOT SWITCH PANEL ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
331012	COPILOT FORWARD SWITCH PANEL OVERLAY PN SN-UNKNOWN REF: AMM 33-10-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
331013	COPILOT FORWARD SWITCH PANEL ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
331015	CENTER SWITCH (P5) PANEL ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
331016	CENTER SWITCH PANEL (P5) OVERLAY PN SN-UNKNOWN REF: AMM 33-10-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
331017	THROTTLE QUADRANT OVERLAY PANEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
331018	PILOT AFT CIRCUIT BREAKER PANEL OVERLAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
331019	COPILOT AFT CIRCUIT BREAKER PANEL OVERLAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
331020	DIMMER CONTROL BOX LT-48(G) 2230 REF: AMM 33-10-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
331023	GLARESHIELD FLOOR FLOODLIGHTS INVERTER 6900135-001 678 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
331025	COCKPIT MISC RELAY BOX PN SN-UNKNOWN REF: AMM 33-10-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
331030	CENTER SWITCH PANEL DIODE (P12) BOX PN SN-UNKNOWN REF: AMM 33-10-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
331033	GLARESHIELD FLOODLIGHT POWER SUPPLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
331040	PILOT REVERSION PANEL (DS55) OVERLAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
331101	P35 FUSE PANEL ASSY PN SN-UNKNOWN REF: AMM 33-10-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
331401-1	NO. 1 LEFT INVERTER (PS5009) SUPPLY PWR PN SN-UNKNOWN REF: AMM 33-20-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
331401-10	INVERTER SUPPLY PWR PN SN-UNKNOWN REF: AMM 33-20-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
331401-11	INVERTER SUPPLY PWR PN SN-UNKNOWN REF: AMM 33-20-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
331401-2	NO. 1 RIGHT INVERTER (PS5003) SUPPLY PWR PN SN-UNKNOWN REF: AMM 33-20-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
331401-3	NO. 2 LEFT INVERTER (PS5008) SUPPLY PWR PN SN-UNKNOWN REF: AMM 33-20-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
331401-4	NO. 2 RIGHT INVERTER (PS5004) SUPPLY PWR PN SN-UNKNOWN REF: AMM 33-20-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
331401-5	NO. 3 LEFT INVERTER (PS5007) SUPPLY PWR PN SN-UNKNOWN REF: AMM 33-20-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
331401-6	NO. 3 RIGHT INVERTER (PS5005) SUPPLY PWR PN SN-UNKNOWN REF: AMM 33-20-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
331401-7	NO. 4 LEFT INVERTER (PS5006) SUPPLY PWR PN SN-UNKNOWN REF: AMM 33-20-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
331401-8	NO. 4 RIGHT INVERTER (PS5010) LAV SUPPLY PWR PN SN-UNKNOWN REF: AMM 33-20-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
331401-9	NO. 5 LEFT INVERTER (PS5011) LAV SUPPLY PWR PN SN-UNKNOWN REF: AMM 33-20-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
332001	RH FWD LIGHTING CONTROL (A5038) UNIT SP-45-53-2 050800311 REF: AMM 33-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
332002	RH MID FWD LIGHTING CONTROL (A5039) UNIT SP-45-53-2 050800787 REF: AMM 33-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
332003	RH MID AFT LIGHTING CONTROL (A5040) UNIT SP-45-53-2 050800261 REF: AMM 33-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
332004	RH AFT LIGHTING CONTROL (A5041) UNIT SP-45-53-2 050800260 REF: AMM 33-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
332005	L/H FWD LIGHTING CONTROL (A5045) UNIT SP-45-53-2 050800312 REF: AMM 33-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
332006	LH MID FWD LIGHTING CONTROL (A5044) UNIT SP-45-53-2 050800980 REF: AMM 33-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
332007	LH MID AFT LIGHTING CONTROL (A5043) UNIT SP-45-53-2 050800408 REF: AMM 33-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
332008	LH AFT LIGHTING CONTROL (A5042) UNIT PN SN-UNKNOWN REF: AMM 33-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
332030	LAVATORY NO SMOKING / RETURN TO SEAT SIGN (DS138) CONTROL UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
332068	COPILOT LIGHTING CONTROL MODULE SP-45-01-6767 040800177 REF: AMM 33-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
332404	ENTRYWAY CONTROL LIGHT PANEL SP-45-32 050800619 REF: AMM 33-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
333004	TAIL CONE MAINTENANCE LIGHT CHANGE PN SN-UNKNOWN REF: AMM 33-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
334011	LANDING/TAXI, LEFT LIGHT PN SN-UNKNOWN REF: AMM 33-40-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
334012	LANDING/TAXI, RIGHT LIGHT PN SN-UNKNOWN REF: AMM 33-40-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
334021	LEFT NAVIGATION (DS37) LIGHT PN SN-UNKNOWN REF: AMM 33-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
334022	RIGHT NAVIGATION (DS38) LIGHT PN SN-UNKNOWN REF: AMM 33-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
334023	TAIL NAVIGATION (DS39) LIGHT PN SN-UNKNOWN REF: AMM 33-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
334041	COPILOT REVERSION PANEL (DS56) OVERLAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
334175	RELAY OPTIONS PANEL ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
334332	UPPER ANTI-COLLISION LIGHT PN SN-UNKNOWN REF: AMM 33-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
334333	LOWER ANTI-COLLISION LIGHT PN SN-UNKNOWN REF: AMM 33-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
335005	FWD ELS ACTIVATION ASSEMBLY (A81) MODULE PN SN-UNKNOWN REF: AMM 33-50-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
335006	AFT ELS ACTIVATION ASSEMBLY (A82) MODULE PN SN-UNKNOWN REF: AMM 33-50-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
336001	PILOT CHART HOLDER 10-62-01 5796 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
336002	COPILOT CHART HOLDER 10-62-01 5802 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
336003	PILOT MAP LIGHT 0204327-001 841627 REF: AMM 33-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
336004	COPILOT MAP LIGHT 0204327-001 541626 REF: AMM 33-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
03310000 (s)	FLIGHT COMPARTMENT LIGHTING - PERFORM OPERATION OF THE FOLLOWING: A. MAP LIGHTS. B. INSTRUMENT PANEL FLUORESCENT LIGHTS. C. INSTRUMENT/INDICATOR LIGHTS. D. LIGHT DIMMING SWITCHES. E. CREW WARNING PANEL. F. PANEL OVERLAYS. PKG 1 REF: AMM 33-10-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			29-AUG-2018 2621.3 2079		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
03320000 (s)	PASSENGER COMPARTMENT LIGHTING - PERFORM OPERATION OF THE FOLLOWING: A. SEAT LIGHTS. B. OVERHEAD LIGHTS. C. READING LIGHTS. D. LAVATORY LIGHTS. E. WARNING LIGHTS.						PKG		
	PKG 1	MOS	12	+14d/-14d			29-AUG-2018		
		HRS/MSC	300	+25/-25			2621.3		
	REF:	AFL					2079		
03340000 (s)	EXTERIOR LIGHTING SYSTEMS - PERFORM OPERATION OF THE FOLLOWING: A. TAXI LIGHTS. B. ANTI-COLLISION BEACONS. C. NAVIGATION LIGHTS. D. STROBE LIGHTS. E. LANDING/RECOGNITION LIGHTS. F. WING ICE INSPECTION LIGHTS. G. EMERGENCY DOOR EGRESS LIGHTS.						PKG		
	PKG 2	MOS	12	+14d/-14d			29-AUG-2018		
		HRS/MSC	300	+25/-25			2621.3		
	REF: See Workcard	AFL					2079		
CHAPTER 34 NAVIGATION									
34-00-FAR-91.171 (s)	CHECK VOR EQUIPMENT FOR IFR OPERATIONS FAR 91.171								
		MOS					11-AUG-2008		
		HRS/MSC	N/A				0		
FAA	REF: FAR FAR 91.171	AFL					0		
34-CUS-01	PERFORM EGPWS DATABASE UPDATE								
		MOS							
		HRS/MSC	A/R						
	REF:	AFL							
34-CUS-02	PERFORM FMS NAV DATABASE UPDATE								
		MOS				-2	04-FEB-2017		
		HRS/MSC	DUE				2023.9		
CUSTOMER CODE	REF:	AFL					1658		
341001	NO. 1 AIR DATA DISPLAY UNIT								
	7030700-71704	MOS					23-APR-2014		
	08041867	HRS/MSC	O/C		TSN:68		1345.4		
	REF: AMM 34-17-01	AFL			TSN:1345.4		1094		
					TSN:1094				
341001A	TEST/INSPECT NO. 1 AIR DATA COMPUTER FAR 91.411								
	7030700-71704	MOS	24				13-APR-2018		13-APR-2020
	08041867	HRS/MSC							
GERMAN LBA NFL	REF: See Workcard	AFL							

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341002	NO. 2 AIR DATA DISPLAY UNIT 7030700-71704 08041868 REF: AMM 34-17-01	MOS HRS/MSC AFL	O/C	TSN:68 TSN:1345.4 TSN:1094			23-APR-2014 1345.4 1094		
341002A	TEST/INSPECT NO. 2 AIR DATA COMPUTER FAR 91.411 7030700-71704 08041868 REF: See Workcard	MOS HRS/MSC AFL	24				13-APR-2018	13-APR-2020	
	GERMAN LBA NFL								
341013	STANDBY AIRSPEED INDICATOR 26240-1129 283093 REF: AMM 34-18-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
341025	STANDBY ALTIMETER 16650-1142 177294B REF: AMM 34-15-01	MOS HRS/MSC AFL	O/C				14-MAY-2018 2469.9 1969		
341025A	TEST/INSPECT STANDBY ALTIMETER FAR 91.411 16650-1142 177294B REF: See Workcard	MOS HRS/MSC AFL	24				10-MAY-2018	10-MAY-2020	
	GERMAN LBA NFL								
341037	LEFT PRIMARY PITOT/STATIC (P/N 0856TJ1 OR P/N 6634100000-001) (IRN P3411053) PROBE 0856TJ1 250487 REF: AMM 34-11-01	MOS HRS/MSC AFL	15000	+25/-25 TSN:2469.9			14-MAY-2018 2469.9 1969	15000	15025
	LIFE LIMIT								
341037A	TEST/INSPECT LEFT PRIMARY PITOT/STATIC (P/N 0856TJ1 OR P/N 6634100000-001) (IRN P3411053) PROBE PITOT/STATIC SYSTEM - FAR 91.411 0856TJ1 250487 REF: See Workcard	MOS HRS/MSC AFL	24				10-MAY-2018	10-MAY-2020	
341038	RIGHT PRIMARY PITOT/STATIC (P/N 0856TJ2 OR P/N 6634100000-003) (IRN P3411054) PROBE 0856TJ2 251069 REF: AMM 34-11-01	MOS HRS/MSC AFL	15000	+25/-25 TSN:2469.9			14-MAY-2018 2469.9 1969	15000	15025
	LIFE LIMIT								

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 341038A	RIGHT PRIMARY PITOT/STATIC (P/N 0856TJ2 OR P/N 6634100000-003) (IRN P3411054) PROBE 0856TJ2 251069 REF: See Workcard	MOS HRS/MSC AFL	24				10-MAY-2018	10-MAY-2020	
341049	PITOT/STATIC, STANDBY PROBE 0856TJ4 251072 REF: AMM 34-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
341061	RADAR ALTIMETER RECEIVER 7001840-936 0803E541 REF: AMM 34-14-01	MOS HRS/MSC AFL	O/C	TSN:66 TSN:1345.4 TSN:1094			20-FEB-2014 1345.4 1094		
341073	FORWARD RADAR ALTIMETER ANTENNA S67-2002-4 552-15131 REF: AMM 34-14-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
341074	AFT RADAR ALTIMETER ANTENNA S67-2002-4 552-15124 REF: AMM 34-14-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
3413-RVSM (s)	FLIGHT CHECK ALTITUDE ALERTER FUNCTION. RVSM COMPLIANT AIRCRAFT. REF: GENERIC CUSTOM	MOS HRS/MSC AFL	N/R				11-AUG-2008 0 0		
341901	(TAT) TOTAL AIR TEMPERATURE PROBE 102AU1AG A78188 REF: AMM 34-17-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
342001	(AHRS) NO. 1 ATTITUDE HEADING REFERENCE DISPLAY UNIT 142185-1102 1640 REF: AMM 34-26-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342002	(AHR) NO. 2 ATTITUDE HEADING REFERENCE DISPLAY UNIT 142185-1102 1642 REF: AMM 34-26-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
342003	(AHR) NO. 1 ATTITUDE HEADING REFERENCE COMPUTER FAN 140691-0000 4809 REF: AMM 34-26-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
342004	(AHR) NO. 2 ATTITUDE HEADING REFERENCE COMPUTER FAN 140691-0000 4802 REF: AMM 34-26-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
342037	LEFT FLUX VALVE 7010133 0711H754 REF: AMM 34-26-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
342038	RIGHT FLUX VALVE 7010133 0712H771 REF: AMM 34-26-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
342101	DUAL ANGLE OF ATTACK INDICATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
342103	STANDBY COMPASS PAI700-5V 66826 REF: AMM 34-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
342103A	CALIBRATION CHECK STANDBY COMPASS PAI700-5V 66826 REF: GENERIC CUSTOM	MOS HRS/MSC AFL	24	+14d/-14d	-16		28-APR-2017 2080.2 1694	12-APR-2019	26-APR-2019

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342701	LEFT ATTITUDE HEADING REFERENCE SYSTEM (AHRS) MEMORY MODULE PN SN-UNKNOWN REF: AMM 34-26-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
342702	RIGHT ATTITUDE HEADING REFERENCE SYSTEM (AHRS) MEMORY MODULE PN SN-UNKNOWN REF: AMM 34-26-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
342801	STANDBY ATTITUDE INDICATOR 501-1648-02 1692 REF: AMM 34-23-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			29-SEP-2014 1452.8 1197		
343005	MARKER BEACON ANTENNA DMN27-3 16667 REF: AMM 34-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
343008	UPPER GLIDESCOPE (E11) ANTENNA PN SN-UNKNOWN REF: AMM 34-30-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
343009	LOWER GLIDESCOPE (E12) ANTENNA PN SN-UNKNOWN REF: AMM 34-30-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
343030	MARKER BEACON ANTENNA SPLITTER DMH21-1 36005 REF: AMM 34-30-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
344111	UPPER TCAS ANTENNA 7514081-913 ANE28993 REF: AMM 34-43-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
344112	LOWER TCAS ANTENNA 7514081-913 ANE28777 REF: AMM 34-43-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
344143	TCAS PROCESSOR 7517900-55020 20007207 REF: AMM 34-43-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			08-NOV-2016 1975.3 1619		
344155	TCAS RELAY BOX ASSEMBLY PN SN-UNKNOWN REF: AMM 34-43-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
344167	TCAS CONFIGURATION MODULE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
344171	NO. 1 TCAS UPPER ANTENNA CABLE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
344172	NO. 2 TCAS UPPER ANTENNA CABLE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
344173	NO. 3 TCAS UPPER ANTENNA CABLE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
344174	NO. 4 TCAS UPPER ANTENNA CABLE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
344176	UPPER TCAS ADAPTER ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
344177	LOWER TCAS ADAPTER ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
344181	NO. 1 TCAS LOWER ANTENNA CABLE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
344182	NO. 2 TCAS LOWER ANTENNA CABLE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
344183	NO. 3 TCAS LOWER ANTENNA CABLE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
344184	NO. 4 TCAS LOWER ANTENNA CABLE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
344205	WEATHER RADAR RECEIVER/TRANSMITTER/ANTENNA 7021450-601 08048372 REF: AMM 34-42-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
344207	WEATHER RADAR TRANSCEIVER PN SN-UNKNOWN REF: AMM 34-42-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
344209	WEATHER RADAR LIGHTNING SENSOR ANTENNA PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
344221	WEATHER RADAR CONTROLLER 7008471-667 0803A275 REF: AMM 34-42-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
344223	LIGHTNING DETECTION PROCESSOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
344513	TERRAIN AWARENESS WARNING (TAWS) DISPLAY UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
344514	TERRAIN AWARENESS WARNING (TAWS) CONFIGURATION MODULE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
344515	TAWS RELAY BOX PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
345001	NO. 1 INTEGRATED NAVIGATION UNIT 7510100-631 0804B652 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
345002	NO. 2 INTEGRATED NAVIGATION UNIT 7510100-631 0711B458 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345011	NO. 1 NAVIGATION RECEIVER MODULE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
345012	NO. 2 NAVIGATION RECEIVER MODULE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
345013	NO. 1 ADF ANTENNA 7510300-901 0801E213 REF: AMM 34-57-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
345014	NO. 2 ADF ANTENNA 7510300-901 0801E215 REF: AMM 34-57-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
345024	GPWS CONTROL PANEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
345025	EHANCED GROUND PROXIMITY WARNING (EGPWS) 965-0976-040-218-218 EMK5-27403 REF: AMM 34-45-01	MOS HRS/MSC AFL	O/C	TSN:32			20-APR-2011 803.6 653		
345037	FORWARD ATC ANTENNA DMN150-2-2 118873 REF: AMM 34-55-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
345038	AFT ATC ANTENNA DMN150-2-2 118888 REF: AMM 34-55-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345049	AFT (NO. 1) DME ANTENNA DMN150-2-2 118852 REF: AMM 34-55-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
345050	FORWARD (NO. 2) DME ANTENNA DMN150-9-2 10533 REF: AMM 34-55-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
345083	LEFT VOR/LOCALIZER ANTENNA DMN4-17-1/N 25501 REF: AMM 34-51-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
345084	RIGHT VOR/LOCALIZER ANTENNA DMN4-17-1/N 25503 REF: AMM 34-51-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
345201	NAV VHF (A42) DUPLEXER PN SN-UNKNOWN REF: AMM 34-51-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
345260	PHASING COUPLER DMN4-17-2 20734 REF: AMM 34-51-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
345501	DME INDICATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
345605	LEFT UPPER MODE S ATC ANTENNA DMN150-2-2 117006 REF: AMM 34-55-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345606	RIGHT UPPER MODE S ATC ANTENNA DMN150-2-2 118875 REF: AMM 34-55-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
346001	PILOT FLIGHT MANAGEMENT CONTROL DISPLAY CDU 2017-41-201 1701 REF: AMM 34-60-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			18-FEB-2013 1267.22 1008		
346002	COPILOT FLIGHT MANAGEMENT CONTROL DISPLAY CDU 2017-41-201 1627 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			18-FEB-2013 1267.22 1008		
346021	FMS DATA (DTU) TRANSFER UNIT 1406-01-1 4971 REF: AMM 34-60-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
346025	NO. 1 FLIGHT MANAGEMENT CONFIGURATION MODULE 10171 5243 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
346026	NO. 2 FLIGHT MANAGEMENT CONFIGURATION MODULE 10171 4858 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
346031	NO. 1 FMS ANTENNA PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
346032	NO. 2 FMS ANTENNA PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
346090	AFIS DATA MANAGEMENT UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
347510	NO. 1 GPS ANTENNA 10706 13256 REF: AMM 34-53-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
347511	NO. 2 GPS ANTENNA 10706 13255 REF: AMM 34-53-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
5-19-02-RVSM-M3411052	VERIFY PITCH, ROLL, AND YAW ALIGNMENT OF THE PRIMARY PITOT-STATIC PROBES RVSM COMPLIANT AIRCRAFT (IRN # M3411052)	MOS HRS/MSC AFL	24	+14d/-14d		-16	14-MAY-2018 2469.9 1969	28-APR-2020	12-MAY-2020
RVSM	REF: AMM 34-11-01								
5-19-02-RVSM-U3411060	PERFORM FUNCTIONAL TEST - AIR DATA SYSTEM (EFFECTIVE ON AIRCRAFT CERTIFIED & MAINTAINED FOR RVSM) (REFER TO 34-17-00) (IRN U3411060)	MOS HRS/MSC AFL	24	+14d/-14d		-16	14-MAY-2018 2469.9 1969	28-APR-2020	12-MAY-2020
RVSM	REF: AMM 34-17-00								
A3400000 (s)	** NAVIGATION SYSTEMS - PERFORM OPERATIONAL CHECK PKG 7	MOS HRS/MSC AFL	24	+14d/-14d			30-NOV-2017 2313.6 1848		
AIRWORTHINESS	REF: AMM 34-00-00		600	+25/-25					
T3411000 (s)	PITOT-STATIC PROBE - PERFORM VISUAL INSPECTION. ENSURE DRAIN HOLES ARE CLEAR OF OBSTRUCTIONS PKG 7	MOS HRS/MSC AFL	24	+14d/-14d			30-NOV-2017 2313.6 1848		
	REF: See Workcard		600	+25/-25					
CHAPTER 34-00		NAVIGATION							



Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340003	FMS INTERNAL BATTERY (UNIVERSAL)	MOS	24	+6m			12-OCT-2018	12-OCT-2020	12-APR-2021
SERVICE LIFE LIMIT	REF:	HRS/MSC AFL							
CHAPTER 35 OXYGEN									
350001	OXYGEN - (IRN O3510007 - COMPOSITE) (IRN Q3510018 INCREASED CAPACITY)	MOS	180	+14d/-14d	TSN:5		28-APR-2017	28-NOV-2031	12-DEC-2031
LIFE LIMIT	REF: AMM 35-00-01	HRS/MSC AFL					2080.2 1694		
+ 350001A	OXYGEN - (IRN O3510007 - COMPOSITE) (IRN Q3510018 INCREASED CAPACITY)	MOS	60	+14d/-14d			06-JAN-2017	06-JAN-2022	20-JAN-2022
	806385-14	HRS/MSC	5000	+25/-25			2080.2	7080.2	7105.2
	REF: GENERIC NO REF	AFL							
+ 350001C	OXYGEN - (IRN O3510007 - COMPOSITE) (IRN Q3510018 INCREASED CAPACITY)	MOS	60	+14d/-14d			06-JAN-2017	06-JAN-2022	20-JAN-2022
	806385-14	HRS/MSC	5000	+25/-25			2080.2	7080.2	7105.2
	REF: GENERIC NO REF	AFL							
350013	OXYGEN CYLINDER LOW PRESSURE RELIEF VALVE	MOS			TSN:0		11-AUG-2008		
	PN	HRS/MSC	O/C		TSN:0		0		
	REF: GENERIC NO REF	AFL			TSN:0		0		
350201	TEMP/PRESSURE TRANSDUCER	MOS			TSN:0		11-AUG-2008		
	PN	HRS/MSC	O/C		TSN:0		0		
	REF: AMM 35-00-03	AFL			TSN:0		0		
350225	OXYGEN FILL (POST SB 45-12-1) VALVE	MOS			TSN:0		11-AUG-2008		
	PN	HRS/MSC	O/C		TSN:0		0		
	REF: GENERIC NO REF	AFL			TSN:0		0		
350230	REMOTE OXYGEN PRESSURE INDICATOR	MOS			TSN:0		11-AUG-2008		
	PN	HRS/MSC	O/C		TSN:0		0		
	REF: AMM 35-00-05	AFL			TSN:0		0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
351001	PILOT OXYGEN MASK MC10-15-166 116914 REF: AMM 35-10-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			21-MAR-2014 1332.5 1077		
351001A	OVERHAUL PILOT OXYGEN MASK PER MANUFACTURER'S INSTRUCTIONS (IRN # L3510016/O3510006) MC10-15-166 116914 REF: GENERIC NO REF	MOS HRS/MSC AFL	72	+14d/-14d			21-MAR-2014 1332.5 1077	21-MAR-2020	04-APR-2020
351002	COPILOT OXYGEN MASK MC10-15-166 SE17288 REF: AMM 35-10-01	MOS HRS/MSC AFL	O/C	TSN:64 TSO:0 TSN:1323.8 TSO:0 TSN:1061 TSO:0			02-DEC-2013 1323.8 1061		
351002A	OVERHAUL COPILOT OXYGEN MASK PER MANUFACTURER'S INSTRUCTIONS (IRN # L3510016/O3510006) MC10-15-166 SE17288 REF: GENERIC NO REF	MOS HRS/MSC AFL	72	+14d/-14d		-63	02-DEC-2013 1323.8 1061	30-SEP-2019	14-OCT-2019
351003	PASSENGER OXYGEN MASK (OVHL/SCRAP) - 289 SERIES PAX OXYGEN MASK (REFER ZODIAC / AVOX MANUAL 833-35-01) REPLACE 289-601-228 NSN REF: SI 833-35-01	MOS HRS/MSC AFL	72	+14d/-14d	TSN:9 TSN:0 TSN:0	-1207	30-NOV-2017 2313.6 1848	11-NOV-2019	25-NOV-2019
351005	PILOT CREW OXYGEN OUTLET PN SN-UNKNOWN REF: AMM 35-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
351006	COPILOT CREW-OXYGEN OUTLET PN SN-UNKNOWN REF: AMM 35-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
352002	ALTITUDE COMPENSATING REGULATOR PN SN-UNKNOWN REF: AMM 35-20-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
352011	OXYGEN CONTROL VALVE P21081 0561 REF: AMM 35-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
353001	PORTABLE OXYGEN CYLINDER PN SN-UNKNOWN REF: AMM 35-00-01	MOS HRS/MSC AFL	O/C						
355111	OXYGEN PRESSURE INDICATOR P24071-3 545 REF: AMM 35-00-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
+ 5-19-00-K3500021	OXYGEN SYSTEM LOW PRESSURE SUPPLY HOSES. ENSURE THAT HOSES ARE FREE OF OBSTRUCTIONS. (REFER TO 35-00-00.) (EFFECTIVE ON AIRCRAFT 45-033, 45-035, 45-195, AND 45-207) (ZONE/ACCESS 200 **IRN # K3500021).	MOS HRS/MSC AFL	N/A				11-AUG-2008 0 0		
+ 5-19-00-N3510013	PERIODIC CHECK OF OXYGEN CYLINDER AND REMOTE OXYGEN FILL VALVES (IRN N3510013). EFFECTIVE ON AIRCRAFT 45 005 THRU 45 244 MODIFIED PER SB 45-12-1. AND AIRCRAFT 45-245 AND SUBSEQUENT.	MOS HRS/MSC AFL	1500	+25/-25	24.1		27-NOV-2014 1475.9 1218	3000	3025
INSPECT	REF: AMM 35-00-01								
5-19-00-N3510019	PERIODIC CHECK OF THE OXYGEN CYLINDER AND REMOTE FILL VALVES, (ZONE/ACCESS 230) (IRN N3510019) , EFFECTIVE ON AIRCRAFT EQUIPPED WITH INCREASED CAPACITY OXYGEN SYSTEM.	MOS HRS/MSC AFL	N/A				11-AUG-2008 0 0		
N/A EQUIPMENT NOT INSTALLED	REF: AMM 35-00-01								
5-19-00-Q3510018	PERFORM OXYGEN CYLINDER (COMPOSITE) AND LOW PRESSURE RELIEF VALVE - PERFORM ICC HYDROSTATIC TEST ON CYLINDER (PER DOT EXEMPTION E8162) AND FUNCTIONALY TEST OXYGEN CYLINDER LOW PRESSURE RELIEF VALVE. EFFECTIVE ON AIRCRAFT EQUIPPED WITH INCREASED CAPACITY OXYGEN SYSTEM. ZONE 230. IRN Q3510018	MOS HRS/MSC AFL	-				11-AUG-2008 0 0		
REF:									

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-00-Q3510023	OXYGEN CYLINDER REGULATOR - PERFORM OVERHAUL, NOTE: ON AIRCRAFT THAT HVE ALREADY PERFORMED OXYGEN CYLINDER HYDROSTATIC TEST, PERFORM OVERHAUL AT NEXT SCHEDULED HYDROSTATIC TEST (EFFECTIVE ON AIRCRAFT EQUIPPED WITH INCREASED CAPACITY OXYGEN SYSTEM)	MOS HRS/MSC AFL	60 5000	+14d/-14d +25/-25		5	28-APR-2017 2080.2 1694	03-MAY-2022 7080.2	17-MAY-2022 7105.2
	REF: AMM 35-00-01								
N3510017 (s)	OXYGEN CYLINDER INSTALLATION - PERFORM VISUAL INSPECTION. CHECK PLUMBING FOR ROUTING, SECURITY,AND CONDITION. (EFFECTIVE ON AIRCRAFT EQUIPPED WITH INCREASED CAPACITY OXYGEN SYSTEM.)	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			30-NOV-2017 2313.6 1848	PKG	
	PKG 7								
	REF: AMM 05-10-00								
O3510001 (s)	CREW SEAT OXYGEN HOSES - PERFORM VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO AREA WHERE OXYGEN HOSES ENTER CREW SEATS ABOVE COCKPIT FLOOR	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			29-AUG-2018 2621.3 2079	PKG	
	PKG 1								
	REF: AMM 05-10-00								
O3510003 (s)	** CABIN LOW PRESSURE OXYGEN DISTRIBUTION FLEX HOSES - PERFORM FUNCTIONAL TEST.	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			30-NOV-2017 2313.6 1848	PKG	
	PKG 7								
AIRWORTHINESS	REF: AMM 35-20-00								
S3510014 (s)	** OXYGEN SYSTEM ALTITUDE COMPENSATING REGULATOR - PERFORM FUNCTIONAL TEST. (EFFECTIVE ON AIRCRAFT 45-170 AND SUBSEQUENT AND PRIOR AIRCRAFT MODIFIED BY SB 45-35-1)	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			30-NOV-2017 2313.6 1848	PKG	
	PKG 7								
AIRWORTHINESS	REF: AMM 35-20-00								

CHAPTER	36	PNEUMATIC
361001		LEFT ASSEMBLY, HP TAILCONE OUTBOARD MANIFOLD
	PN	MOS
	SN-UNKNOWN	HRS/MSC O/C
	REF: GENERIC NO REF	AFL
		TSN:0
		TSN:0
		TSN:0
		11-AUG-2008
		0
		0
361002		LEFT ASSEMBLY, ANTI-ICE OUTBOARD MANIFOLD
	PN	MOS
	SN-UNKNOWN	HRS/MSC O/C
	REF: AMM 30-10-07	AFL
		TSN:0
		TSN:0
		TSN:0
		11-AUG-2008
		0
		0

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
361004	LEFT INBOARD HPBA MANIFOLD ASSEMBLY PN SN-UNKNOWN REF: AMM 36-10-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
361005	RIGHT INBOARD HPBA MANIFOLD ASSEMBLY PN SN-UNKNOWN REF: AMM 36-10-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
361016	RIGHT ASSEMBLY, ANTI-ICE OUTBOARD MANIFOLD PN SN-UNKNOWN REF: AMM 30-10-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
361017	RIGHT ASSEMBLY, HP TAILCONE OUTBOARD MANIFOLD PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
361020	LEFT HP OVER-TEMP SWITCH PN SN-UNKNOWN REF: AMM 36-20-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
361021	RIGHT HP OVER-TEMP SWITCH PN SN-UNKNOWN REF: AMM 36-20-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
361031	ECS CONTROLLER 1165-1-6 207520002 REF: AMM 36-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
361040	VALVE, APU BLEED AIR CHECK REPLACE 4011-14 0305 REF: AMM 36-10-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
361050	LOAD CONTROL (SHUTOFF (L5003) VALVE PN SN-UNKNOWN REF: AMM 36-10-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
361053	NO. 1 ECS SHUTOFF (L37) VALVE 3215468-1 1089 REF: AMM 36-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
361054	NO. 2 ECS SHUTOFF (L38) VALVE 3215468-1 1093 REF: AMM 36-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
361065	LEFT TAILCONE HIGH PRESSURE SHUT-OFF (L39) VALVE 3291216-2 1082 REF: AMM 36-10-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
361066	RIGHT TAILCONE HIGH PRESSURE SHUT-OFF (L40) VALVE 3291216-3 1202C REF: AMM 36-10-02	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0		07/04/2016	04-JUL-2014 1404.3 1142		
361120	NO. 1 PRESSURE (S79) SWITCH 642019-5 0474 REF: AMM 36-10-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
361121	NO. 2 PRESSURE (S88) SWITCH 642019-5 0487 REF: AMM 36-10-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
361125	LEFT PYLON LOW PRESSURE TEMPERATURE SENSOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
361126	RIGHT PYLON LOW PRESSURE TEMPERATURE SENSOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
361127	LEFT TAILCONE LOW PRESSURE (2.0 DIAMETER) CHECK VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
361128	RIGHT TAILCONE LOW PRESSURE (2.0 DIAMETER) CHECK VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
361215	ASSEMBLY, HP LEFT NACELLE BLEED AIR MANIFOLD LJ01212-001 170408-004 REF: AMM 36-10-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
361215A	BORESCOPE ASSEMBLY, HP LEFT NACELLE BLEED AIR MANIFOLD BRACKET LJ01212-001 170408-004 REF: AMM 36-10-07	MOS HRS/MSC AFL	O/C				11-AUG-2008 0 0		
361216	ASSEMBLY, HP RIGHT NACELLE BLEED AIR MANIFOLD LJ01212-002 181207-002 REF: AMM 36-10-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
361216A	BORESCOPE ASSEMBLY, HP RIGHT NACELLE BLEED AIR MANIFOLD BRACKET LJ01212-002 181207-002 REF: AMM 36-10-07	MOS HRS/MSC AFL	O/C				11-AUG-2008 0 0		
361301	APU SERVO AIR CHECK VALVE. EFFECTIVE ON CHECK VALVE S/N 001 THRU 1486. (IRN # K3610013) REPLACE 6C1005 3225 REF: AMM 36-15-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
361302	LEFT ENGINE SERVO AIR CHECK - IRN K3610012 VALVE 6C1005 3192 REF: AMM 36-15-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
361303	RIGHT ENGINE SERVO AIR CHECK - IRN K3610012 VALVE 6C1005 3201 REF: AMM 36-15-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
362005	LEFT FORWARD PYLON OVERHEAT THERMOSTAT (S145) SWITCH PN SN-UNKNOWN REF: AMM 36-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
362006	LEFT AFT PYLON OVERHEAT THERMOSTAT (S146) SWITCH PN SN-UNKNOWN REF: AMM 36-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
362007	RIGHT FORWARD PYLON OVERHEAT THERMOSTAT (S147) SWITCH PN SN-UNKNOWN REF: AMM 36-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
362008	RIGHT AFT PYLON OVERHEAT THERMOSTAT (S148) SWITCH PN SN-UNKNOWN REF: AMM 36-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
+ 5-19-00-D3610002	BORESCOPE INSPECTION HP BLEED AIR MANIFOLD ASSEMBLY ATTACH BRACKET ASSEMBLY FOR CRACKS AT WELD. (EFFECTIVE ON AIRCRAFT 45-001 THRU 45-036 NOT MODIFIED BY SB 45-36-2, REF: AMM 36-10-07	MOS HRS/MSC AFL	N/A				11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 5-19-00-P3610048-LEFT	PERFORM VISUAL INSPECTION OF HP BLEED MANIFOLD ASSEMBLY (REFER TO 5-10-00.) EFFECTIVE ON AIRCRAFT 45-037 AND SUBSEQUENT, AND PREVIOUS AIRCRAFT MODIFIED PER SB 45-36-2, "PNEUMATIC-REPLACEMENT OF HIGH PRESSURE AIR MANIFOLD ASSEMBLY".	MOS					11-AUG-2008		
		HRS/MSC	3000	+100/-100			0	3000	3100
	REF: AMM 36-10-07	AFL					0		
+ 5-19-00-P3610048-RIGHT	PERFORM VISUAL INSPECTION OF HP BLEED MANIFOLD ASSEMBLY (REFER TO 5-10-00.) EFFECTIVE ON AIRCRAFT 45-037 AND SUBSEQUENT, AND PREVIOUS AIRCRAFT MODIFIED PER SB 45-36-2, "PNEUMATIC-REPLACEMENT OF HIGH PRESSURE AIR MANIFOLD ASSEMBLY".	MOS					11-AUG-2008		
		HRS/MSC	3000	+100/-100			0	3000	3100
	REF: AMM 36-10-07	AFL					0		
5-19-01-K3610013	REPLACE APU SERVO CHECK VALVE (6608295-3). EFFECTIVE ON CHECK VALVE S/N 001 THRU 1486. (ZONE/ACCESS 310HL, 310JL, 310QR, 310RR IRN # K3610013)	MOS					04-SEP-2012		
		HRS/MSC	A/R				1170.8		
	REF:	AFL					924		
A3610000 (s)	** BLEED AIR SYSTEM - PERFORM FUNCTIONAL TEST						PKG		
	PKG 7	MOS	24	+14d/-14d			30-NOV-2017		
AIRWORTHINESS	REF: AMM 36-10-00	HRS/MSC	600	+25/-25			2313.6		
		AFL					1848		
A3610001 (s)	** PYLON OVERHEAT THERMOSTAT AND ELECTRICAL SYSTEM - PERFORM FUNCTIONAL TEST						PKG		
	PKG 8	MOS	24	+14d/-14d			30-NOV-2017		
AIRWORTHINESS	REF: AMM 36-20-01	HRS/MSC	600	+25/-25			2313.6		
		AFL					1848		
R3610061 (s)	HIGH PRESSURE BLEED AIR SHUT-OFF VALVE IN-LINE FILTER - PERFORM CLEANING PROCEDURES. (EFFECTIVE ON AIRCRAFT 45-418 AND SUBSEQUENT AND PREVIOUS AIRCRAFT MODIFIED PER SB 45-36-06) NOTE: THE FILTER CAN EITHER BE CLEANED OR REPLACED AT THIS TIME.						PKG		
	PKG 8	MOS	24	+14d/-14d			30-NOV-2017		
	REF: AMM 36-10-02	HRS/MSC	600	+25/-25			2313.6		
		AFL					1848		
CHAPTER 38	WATER/WASTE								
380001	TOILET SERVICE PANEL								
	PN	MOS					11-AUG-2008		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF: AMM 38-30-05	AFL					0		
							TSN:0		
							TSN:0		
							TSN:0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
381009	TOILET HEATED DRAIN MAST ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
383001	ASSEMBLY TOILET 9600-1B U3786 REF: AMM 38-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
383002	TOILET TIMER 9600-12D T5813 REF: AMM 38-30-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
383005	WATER TANK ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
383010	TANK FLOAT SWITCH, TOILET REPLACE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
383011	LAVATORY SINK SHUT OFF VALVE 73310-3 1010667 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-MAY-2010 619.22 493		
384025	TOILET PUMP PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:12 TSN:391.27 TSN:317			25-AUG-2009 391.27 317		
384051	TOILET MACERATOR 5300-1 M3741 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			12-SEP-2011 881.25 721		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
389050	TOILET CLEAN WATER PUMP PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:12 TSN:391.27 TSN:317			25-AUG-2009 391.27 317		
CHAPTER 49 AIRBORNE AUXILIARY POWER									
490060	ELECTRONIC CONTROL, APU ECU 2119560-3 28-M0051 REF: AMM 49-60-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
491011	MAINTENANCE CONTROL, APU PANEL 7088001-2 DC393 REF: AMM 49-60-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
491020	APU, COCKPIT CONTROL PANEL 7088000-1 DB361 REF: AMM 49-60-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
494050	IGNITION, APU UNIT 3888000-7 080218085994 REF: AMM 49-40-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
495001	COOLING, TAILCONE APU (B31) FAN 011809500 107451871 REF: AMM 49-50-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
495002	TAILCONE ACCESS DOOR COOLING (B30) FAN 011809500 107451874 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
495040	APU THERMOSTAT (S175) SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
495041	APU THERMOSTAT (S176) SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
495201	STRUT SUPPORT ASSEMBLY 7630102001-001 0031 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
495202	STRUT SUPPORT ASSEMBLY 7630102001-001 0012 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
497001	APU BITE INDICATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
49APU1 49.APU1	APU 3800726-1 P-410 REF: GENERIC NO REF	MOS HRS/MSC AFL	E/C						
5-19-01-N4900039	APU FUEL LINE (P/N 4549058032-001) REPLACE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	4800	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0	4800	
A4900012 (s)	APU INLET SCREEN AND OPENING - PERFORM VISUAL INSPECTION PKG 2 REF: AMM 05-10-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 29-AUG-2018 2621.3 2079		
F4900013 (s)	APU EXHAUST DUCT AREA, INCLUDING FORWARD AND AFT APU EXHAUST FAIRINGS - PERFORM VISUAL INSPECTION PKG 2 REF: AMM 05-10-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 29-AUG-2018 2621.3 2079		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
H4900011 (s)	PERFORM **APU GENERATOR - OVERVOLTAGE PROTECTION CHECK. PKG 13	MOS	48	+14d/-14d			PKG 20-MAY-2016 1821.7		
AIRWORTHINESS	REF: AMM 49-40-01	HRS/MSC AFL	1200	+25/-25			1492		
O4900000 (s)	AUXILIARY POWER UNIT - PERFORM VISUAL INSPECTION OF EXTERNAL FIREBOX INSTALLATION AND ATTACHING COMPONENTS PKG 2	MOS	12	+14d/-14d			PKG 29-AUG-2018 2621.3		
	REF: AMM 05-10-00	HRS/MSC AFL	300	+25/-25			2079		
O4900002 (s)	AUXILIARY POWER UNIT - FIRE EXTINGUISHER CONTAINER - PERFORM FUNCTIONAL TEST OF WIRING. PKG 7	MOS	24	+14d/-14d			PKG 30-NOV-2017 2313.6		
	REF: AMM 26-22-00	HRS/MSC AFL	600	+25/-25			1848		
O4900010 (s)	APU ENGINE FIRE EXTINGUISHER CONTAINER - CHECK CONTAINER PRESSURE GAUGE FOR PROPER PRESSURE. PKG 2	MOS	12	+14d/-14d			PKG 29-AUG-2018 2621.3		
	REF: AMM 26-22-00	HRS/MSC AFL	300	+25/-25			2079		
APU Model : RE100 (CIMMS) Serial # P-410 Part # 3800726-1									
+ 491000	APU - DOWNLOAD APU ECU (TIMES/CYCLES)	MOS					04-JAN-2013 476.25		
	REF:	HRS/MSC APUS	A/R				1034		
492001	APU - APU COMPRESSOR ROTOR. (P/N 3822523-2 - IRN H4900019) (P/N 3822523-003 - IRN H4900020) ROTOR 3822523-003	MOS					26-OCT-2013 521		
LIFE LIMIT	REF: AMM 49-10-01	HRS/MSC APUS	12000		TSN:0 TSN:0		1127		13127
492005	APU - APU TURBINE ROTOR (P/N 3842340 - IRN H4900018) CHANGE 3842340-2	MOS					26-OCT-2013 521		
LIFE LIMIT	REF: AMM 49-10-01	HRS/MSC APUS	4000		TSN:0 TSN:0		1127		5127
493011	APU - APU PRESSURIZING VALVE PN	MOS					20-MAR-2008 0		
	REF:	HRS/MSC APUS	O/C		TSN:0 TSN:0		0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
493021	APU - APU FILTER BYPASS VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			20-MAR-2008 0 0		
493031	APU - APU PRESSURE RELIEF VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			20-MAR-2008 0 0		
493041	APU - APU DIFFERENTIAL PRESSURE VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			20-MAR-2008 0 0		
493051	APU - APU FUEL PUMP PN SN-UNKNOWN REF: AMM 49-30-04	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			20-MAR-2008 0 0		
493061	APU - APU DIFFERENTIAL PRESSURE INDICATOR PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			20-MAR-2008 0 0		
493071	APU - APU ASSEMBLY, FUEL CONTROL 3883900-1 0601318 REF: AMM 49-30-04	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			20-MAR-2008 0 0		
494011	APU - APU IGNITION EXCITER PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			20-MAR-2008 0 0		
494021	APU - APU LOW VOLTAGE IGNITER PLUG PN SN-UNKNOWN REF: AMM 49-40-02	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			20-MAR-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
494031	APU - APU IGNITION LEAD PN SN-UNKNOWN REF: AMM 49-40-03	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			20-MAR-2008 0 0		
495001	APU - APU ISOLATION VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			20-MAR-2008 0 0		
496001	APU - APU REMOTELY LOCATED (ECU) CONTROLLER 2119560-3 28-M0051 REF: AMM 49-60-04	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			20-MAR-2008 0 0		
496011	APU - APU FUEL SHUTOFF VALVE 3876322-1 0372 REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			20-MAR-2008 0 0		
496021	APU - APU FLOW DIVIDER VALVE PN SN-UNKNOWN REF: AMM 49-30-06	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			20-MAR-2008 0 0		
496031	APU - APU FUEL SOLENOID VALVE PN SN-UNKNOWN REF: AMM 49-30-01	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			20-MAR-2008 0 0		
497001	APU - APU SPEED SENSOR PN SN-UNKNOWN REF: AMM 49-70-04	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			20-MAR-2008 0 0		
497011	APU - APU EGT THERMOCOUPLE PN SN-UNKNOWN REF: AMM 49-70-07	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			20-MAR-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
499025	APU - APU ASSEMBLY, LUBE OIL-PUMP 3881825-1 P-1449 REF: AMM 49-90-03	MOS HRS/MSC APUS	O/C	TSO:0 TSO:0			26-OCT-2013 521 1127		
499037	APU - APU LOW OIL PRESSURE SENSOR PN SN-UNKNOWN REF: AMM 49-90-02	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			20-MAR-2008 0 0		
499049	APU - APU OIL TEMPERATURE BULB PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			20-MAR-2008 0 0		
499061	APU - APU OIL LEVEL SENSOR PN SN-UNKNOWN REF: AMM 49-90-01	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			20-MAR-2008 0 0		
499071	APU - APU ULTIMATE RELIEF VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			20-MAR-2008 0 0		
499081	APU - APU MANIFOLD AND PRIMARY ATOMIZER PN SN-UNKNOWN REF: AMM 49-30-05	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			20-MAR-2008 0 0		
499082	APU - APU MANIFOLD AND SECONDARY ATOMIZER PN SN-UNKNOWN REF: AMM 49-30-05	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			20-MAR-2008 0 0		
5-19-00-O4900008	APU - INSPECT APU CHIP DETECTOR - FOR CONTAMINATION. (ZONE/ACCESS 310JL, 310RR IRN # O4900008) REF: AMM 49-90-05	MOS HRS/MSC APUS	750				26-OCT-2013 521 1127	1271	

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-00-P4900009	APU - CHANGE APU OIL. (ZONE/ACCESS 310JL, 310RR). (IRN # P4900009). (REFER TO 12-10-10.) NOTE: THIS REQUIREMENT IS NOT APPLICABLE FOR OPERATORS ENROLLED IN THE SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) SYSTEM PER HONEYWELL SIL# APU-49).	MOS HRS/MSC APUS	750				26-OCT-2013 521 1127	1271	
	REF: AMM 12-10-10								
5-19-01-K4900005	APU - REPLACE APU ENGINE FUEL FILTER. IRN # K4900005	MOS HRS/MSC APUS	750				26-OCT-2013 521 1127	1271	
	REF: AMM 49-30-03								
5-19-01-T4900004	APU - REPLACE APU OIL FILTER. THIS REQUIREMENT IS NOT APPLICABLE FOR OPERATORS ENROLLED IN THE SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) SYSTEM PER HONEYWELL SIL# APU-49 (ZONE/ACCESS 310JR, 310QR) (IRN # T4900004)	MOS HRS/MSC APUS	750				26-OCT-2013 521 1127	1271	
	REF: AMM 49-90-04								

CHAPTER 52 DOORS

5-19-02-RVSM-M5240004	INSPECT AVIONIC ACCESS DOOR GAP AND MISMATCH FOR RVSM COMPLIANT AIRCRAFT (IRN # M5240004)	MOS HRS/MSC AFL	24	+14d/-14d		-16	14-MAY-2018 2469.9 1969	28-APR-2020	12-MAY-2020
	RVSM REF: AMM 52-40-01								
521001	ASSEMBLY, UPPER CABIN DOOR	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		11-AUG-2008 0 0		
	4552101000-003 W479 REF: AMM 52-10-01								
521002	ASSEMBLY, LOWER CABIN DOOR	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		11-AUG-2008 0 0		
	4552100050V107-001 W466 REF: AMM 52-10-01								
521010	FWD GAS, LOWER ENTRY DOOR DAMPER ASSEMBLY REPLACE	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		11-AUG-2008 0 0		
	PN SN-UNKNOWN REF: AMM 52-10-11								

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
521011	AFT GAS, LOWER ENTRY DOOR DAMPER ASSEMBLY. REPLACE PN SN-UNKNOWN REF: AMM 52-10-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
522001	EMERGENCY EXIT DOOR ASSEMBLY 4552200076-V43-001 L372 REF: AMM 52-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
522010	DOOR ASSY PN SN-UNKNOWN REF: AMM 52-20-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
523001	TAILCONE BAGGAGE DOOR ASSEMBLY 12045-558V2-001 L499 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
524001	TAILCONE ACCESS DOOR 4552405151-009 505 REF: AMM 52-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
524010	SPPR DOOR ASSY PN SN-UNKNOWN REF: AMM 52-40-03	MOS HRS/MSC AFL	O/C						
05210006 (s)	UPPER PASSENGER/CREW DOOR VENT DOOR SPRINGS - PERFORM VISUAL INSPECTION PKG 12 REF: AMM 05-10-00	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 30-NOV-2017 2313.6 1848		
05210008 (s)	EMERGENCY EXIT DOOR INTERNAL AND EXTERNAL HANDLE LATCHING MECHANISM - PERFORM OPERATIONAL CHECK PKG 12 REF: AMM 52-20-07	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 30-NOV-2017 2313.6 1848		



Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
T5210001 (s)	TAILCONE ACCESS DOOR AND SEAL - PERFORM VISUAL INSPECTION OF DOOR, SEALS, AND LATCHES PKG 12	MOS	24	+14d/-14d			PKG 30-NOV-2017		
	REF: AMM 05-10-00	HRS/MSC AFL	600	+25/-25			2313.6 1848		
T5210002 (s)	BAGGAGE COMPARTMENT DOOR - PERFORM VISUAL INSPECTION OF DOORS, SEALS, AND LATCHES PKG 12	MOS	24	+14d/-14d			PKG 30-NOV-2017		
	REF: AMM 05-10-00	HRS/MSC AFL	600	+25/-25			2313.6 1848		
T5210003 (s)	PERFORM EXTERNAL LOWER PASSENGER/CREW DOOR CABLES - VISUAL INSPECTION OF VISIBLE PORTION OF CABLES AND HANDLE AREA PKG 18	MOS	48	+14d/-14d			PKG 20-MAY-2016		
	REF: AMM 05-10-00	HRS/MSC AFL	1200	+25/-25			1821.7 1492		

CHAPTER 53 FUSELAGE

+ 5-19-00-H5323032	EXTERIOR CABIN WINDOW COAMING (UNPAINTED)(ZONE/ACCESS 230 *IRN # H5323032)	MOS	24				14-MAY-2018	14-MAY-2020	
AIRWORTHINESS	REF: NDT PART 6/56-20-01	HRS/MSC AFL	2400				2469.9 1969	4869.9	
5-19-00-H5323092	EXTERIOR CABIN WINDOW COAMING (PAINTED)(ZONE/ACCESS 230 *IRN # H5323092)	MOS	N/A				11-AUG-2008		
	REF: NDT PART 6/56-20-01	HRS/MSC AFL					0 0		
5-19-00-M5310023	DETAILED VISUAL INSPECTION FORWARD AND AFT FUEL CELL BAY STRUCTURE, ANGLE REINFORCEMENT, STRINGER 1, LH & RH HI-LITE COLLARS. EFFECTIVE 45-005 THRU 45-031 NOT MODIFIED PER SB45-53-27. (ZONE/ACCESS 300 IRN M5310023)	MOS	N/A				11-AUG-2008		
53-108 AIRWORTHINESS	REF:	HRS/MSC AFL					0 0		
5-19-00-M5310025	DETAILED VISUAL INSPECTION AFT FUSELAGE KEELBEAM LONGERON (LH & RH, BL 5.15, FS 466.30-495.12) AND AFT FUSELAGE KEELBEAM LOWER FRAME (FS 466.30, BL9.55 LH THRU BL 9.55 RH) OF HI-LITE COLLARS. EFFECTIVE 45-005 THRU 45-031 NOT MODIFIED PER SB 45-53-28. (ZONE/ACCESS 200 IRN M5310025)	MOS	N/A				11-AUG-2008		
53.102 AIRWORTHINESS	REF:	HRS/MSC AFL					0 0		



Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-00-T5323166	EXTERNAL SKIN CUT-OUTS/PENETRATIONS (PRESSURE CABIN) - PERFORM DETAILED VISUAL INSPECTION. INSPECT SKIN AND DOUBLERS AT ANTENNAS, ELECTRICAL COMPONENTS, AND ACCESS PANELS (EXCLUDING PITOT/STATIC PROBES, AOA STALL VANES AND WING INSPECTION LIGHT. (REFER TO 5-10-00.) IRN T5323166	MOS	144				11-AUG-2008	11-AUG-2020	
MANDATORY	REF: GENERIC NO REF	HRS/MSC	9600				0	9600	
		AFL					0		
5-19-00-V5323168	EDDY CURRENT INSPECTION * LOWER COUPE RAIL RADIUS/WINDSCREEN RETAINER ATTACH (P/N'S 4553130001-802 THRU 4553130001-809)	MOS							
AIRWORTHINESS	REF: See Workcard	HRS/MSC	5000					5000	
		AFL							
5-19-01-U5323167-LEFT	REPLACE LEFT COUPE RAIL (P/N 4553002003V7000-001, 4553002003V7001-002) (IRN U5323167)	PN		TSN:0					
N/A BY PART NUMBER	REF: AMM 53-10-04	SN-UNKNOWN		TSN:0					
		AFL		TSN:0					
5-19-01-U5323167-RIGHT	REPLACE RIGHT COUPE RAIL (4553002003V7000-001, 4553002003V7001-002) (IRN U5323167)	PN		TSN:0					
N/A BY PART NUMBER	REF: AMM 53-10-04	SN-UNKNOWN		TSN:0					
		AFL		TSN:0					
5-19-02-RVSM-M5313001	PERFORM PITOT-STATIC PROBE ZONE SKIN CONTOUR CHECK OF THE FORWARD FUSELAGE SKIN FOR RVSM COMPLIANT AIRCRAFT (IRN # M5313001)	MOS	24	+14d/-14d		-16	14-MAY-2018	28-APR-2020	12-MAY-2020
RVSM	REF: AMM 53-00-01	HRS/MSC					2469.9		
		AFL					1969		
530001	FUSELAGE ASSEMBLY	MOS		TSN:0			11-AUG-2008		
	4553000010-001	HRS/MSC	O/C	TSN:0			0		
	L372	AFL		TSN:0			0		
	REF: GENERIC NO REF								
531042	LEFT COUPE RAIL	PN		TSN:0			11-AUG-2008		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 53-10-04	AFL		TSN:0			0		



Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
531043	RIGHT COUPE RAIL PN SN-UNKNOWN REF: AMM 53-10-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
535001	RADOME H0601-5 0550 REF: AMM 53-50-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
535601	DELTA, LEFT FIN 4555501000-015 S7549/A0249 REF: AMM 53-56-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
535602	DELTA, RIGHT FIN 4555501000-016 S7549/A0255 REF: AMM 53-56-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
O5320000 (s)	CENTER PEDESTAL - PERFORM VISUAL INSPECTION PKG 1 REF: AMM 05-10-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 29-AUG-2018 2621.3 2079		
T5321089 (s)	SEAT RAILS - PERFORM DETAILED INSPECTION OF SEAT RAIL (TRACK) SHEAR WEBS FOR CRACKING. (EFFECTIVE ON AIRCRAFT 45-005 THRU 45-394 NOT MODIFIED PER SB 45-53-14) PKG 7 REF: AMM 53-20-01	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 30-NOV-2017 2313.6 1848		
V5321010	FLOORBOARDS AROUND GALLEY, LAVATORY, AND WATER TANK - PERFORM VISUAL INSPECTION REF: AMM 53-20-01	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25		-7.7	29-AUG-2018 2621.3 2079	29-AUG-2019 2913.6	12-SEP-2019 2938.6
V5323172	*SKIN CUT-OUT FOR IRIIDIUM ANTENNAS FS283.88 TO FS308.39 - PERFORM EDDY CURRENT INSPECTION. (EFFECTIVE ON AIRCRAFT 45-445, 45-447, 45-448, 45-449, 45-451, AND 45-452 ONLY) REF: AMM NO REF	MOS HRS/MSC AFL	N/A				11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 54	NACELLES/PYLONS								
+ 5-19-00-Q5450013	VISUAL INSPECTION FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM INSPECTION, PAYING PARTICULAR ATTENTION OF THE FOLLOWING: A. UPPER CAPPING PLATE AT ASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLES. B. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE. (REFER TO 5-10-00.) EFFECTIVE ON AIRCRAFT WITH 5,000 HOUR CZI MODIFIED ENGINES.	MOS					11-AUG-2008		
	REF:	HRS/MSC -					0		
		AFL					0		
5-19-00-Q5450013-LEFT	INSPECTION FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION OF THE FOLLOWING: A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLES. B. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE. (REFER TO 5-10-00.) EFFECTIVE ON AIRCRAFT WITH 5000 HOUR CZI MODIFIED ENGINES. IRN Q5450013	MOS					11-AUG-2008		
	REF: AMM 05-10-00	HRS/MSC N/A					0		
		AFL					0		
5-19-00-Q5450013-RIGHT	INSPECTION INSPECTION FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION OF THE FOLLOWING: A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLES. B. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE. (REFER TO 5-10-00.) EFFECTIVE ON AIRCRAFT WITH 5000 HOUR CZI MODIFIED ENGINES. IRN Q5450013	MOS					11-AUG-2008		
	REF: AMM 05-10-00	HRS/MSC N/A					0		
		AFL					0		
5-19-00-Q5450054	VISUAL INSPECTION FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM INSPECTION, PAYING PARTICULAR ATTENTION OF THE FOLLOWING: A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLES. B. BOLT HOLS, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE. (REFER TO 5-10-00.) EFFECTIVE ON AIRCRAFT WITH 6,000 HOUR CZI MODIFIED ENGINES.	MOS					11-AUG-2008		
	REF:	HRS/MSC 6000					0		6000
		AFL					0		
5-19-00-Q5450054-LEFT	INSPECTION FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION OF THE FOLLOWING: A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLES. B. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE. (REFER TO 5-10-00.) EFFECTIVE ON AIRCRAFT WITH 6,000 HOUR CZI MODIFIED ENGINES. IRN Q5450054	MOS					11-AUG-2008		
	REF: AMM 05-10-00	HRS/MSC 6000					0		6000
		AFL					0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-00-Q5450054-RIGHT	INSPECTION FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION OF THE FOLLOWING: A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLES. B. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE. (REFER TO 5-10-00.) EFFECTIVE ON AIRCRAFT WITH 6,000 HOUR CZI MODIFIED ENGINES. IRN Q5450054	MOS					11-AUG-2008		
	REF: AMM 05-10-00	HRS/MSC	6000				0		6000
		AFL					0		
+ 5-19-01-A5450022	REPLACEMENT AFT ENGINE MOUNT TO END FITTING ATTACH BOLT. (*IRN # A5450022)	MOS					11-AUG-2008		
		HRS/MSC	9600				0		9600
	REF:	AFL					0		
5-19-01-A5450022-LEFT	LEFT AFT ENGINE MOUNT TO END FITTING ATTACH BOLT. IRN A5450022 CHANGE	MOS		TSN:0			11-AUG-2008		
	PN	HRS/MSC	9600	TSN:0			0		9600
	SN-UNKNOWN	AFL		TSN:0			0		
	REF:								
5-19-01-A5450022-RIGHT	RIGHT AFT ENGINE MOUNT TO END FITTING ATTACH BOLT. IRN A5450022 CHANGE	MOS		TSN:0			11-AUG-2008		
	PN	HRS/MSC	9600	TSN:0			0		9600
	SN-UNKNOWN	AFL		TSN:0			0		
	REF:								
5-19-01-A5450028	REPLACE AFT ENGINE BEAM ASSEMBLY END FITTINGS (P/N 4553500201-001/-002) EFFECTIVE AIRCRAFT 45-002 THRU 45-025 (ZONE/ACCESS 450/460 IRN # A5450028)	MOS					11-AUG-2008		
		HRS/MSC	N/A				0		
	REF: AMM 53-40-02	AFL					0		
5-19-01-M5450027	REPLACE FORWARD ENGINE BEAM ASSEMBLY END FITTINGS (P/N 4553500101-003/-004) EFFECTIVE AIRCRAFT 45-002 THRU 45-029 (ZONE/ACCESS 450/460 IRN # M5450027)	MOS					11-AUG-2008		
		HRS/MSC	N/A				0		
	REF: AMM 53-40-02	AFL					0		
5-19-01-P5450020-LEFT	LEFT AFT ENGINE BEAM TO FRAME ATTACHMENT BOLT. IRN P5450020 REPLACE	MOS		TSN:0			11-AUG-2008		
	PN	HRS/MSC	9600	TSN:0			0		9600
	SN-UNKNOWN	AFL		TSN:0			0		
	REF:								

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-01-P5450020-RIGHT	RIGHT AFT ENGINE BEAM TO FRAME ATTACHMENT BOLT. IRN P5450020 REPLACEMENT								
	PN	MOS		TSN:0			11-AUG-2008		
MANDATORY	SN-UNKNOWN	HRS/MSC	9600	TSN:0			0		9600
	REF:	AFL		TSN:0			0		
5-19-01-P5450023-LEFT	LEFT ENGINE TO AFT ENGINE MOUNT ATTACH BOLT. IRN P5450023 CHANGE								
	PN	MOS		TSN:0			11-AUG-2008		
MANDATORY	SN-UNKNOWN	HRS/MSC	9600	TSN:0			0		9600
	REF:	AFL		TSN:0			0		
5-19-01-P5450023-RIGHT	RIGHT ENGINE TO AFT ENGINE MOUNT ATTACH BOLT. IRN P5450023 CHANGE								
	PN	MOS		TSN:0			11-AUG-2008		
MANDATORY	SN-UNKNOWN	HRS/MSC	9600	TSN:0			0		9600
	REF:	AFL		TSN:0			0		
CHAPTER 55 STABILIZERS									
+ 5-19-00-M5510010	EDDY CURRENT INSPECTION HORIZONTAL STABILIZER AFT ROOT RIB. INSPECT AFT ROOT RIB INTERNAL BETWEEN MID SPAR AND AFT SPAR AND UPPER AND LOWER SKINS EXTERNAL AT ATTACHMENT FASTENERS. (REFER TO NDI MANUAL {NDI-104}, PART 6, 55-10-03.)								
		MOS					11-AUG-2008		
AIRWORTHINESS	REF: NDT PART 6/55-10-03	HRS/MSC	4800				0		4800
		AFL					0		
5-19-00-N5510088	DETAILED VISUAL INSPECTION UPPER VERTICAL STABILIZER, PIVOT FITTING STRUCTURE HI-LITE COLLARS. EFFECTIVE 45-005 THRU 45-031 NOT MODIFIED PER SB 45-55-15. (ZONE/ACCESS 300 IRN N5510088)								
55.106		MOS					11-AUG-2008		
AIRWORTHINESS	REF:	HRS/MSC	N/A				0		
		AFL					0		
5-19-00-Q5510091	PERFORM HORIZONTAL STABILIZER HINGE PRIMARY AND SECONDARY PIVOT PIN INSTALLATION AND ATTACHING HARDWARE - PERFORM DETAILED VISUAL INSPECTION. (REFER TO 55-10-00.)								
		MOS					17-OCT-2018		
MANDATORY	REF: AMM 55-10-00	HRS/MSC	625				2699		3324
		AFL					2148		
551005	HORIZONTAL STABILIZER ASSEMBLY								
	4555101001V46-001	MOS		TSN:0			11-AUG-2008		
	S7549A0224	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-40-01	AFL		TSN:0			0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
552031	LEFT ELEVATOR ASSEMBLY 4555201005-007 S7549A0230 REF: AMM 27-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
552032	RIGHT ELEVATOR ASSEMBLY 4555201005-008 S7549A0230 REF: AMM 27-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
553000	TAILCONE/VERTICAL STABILIZER ASSEMBLY 4555301001-001 A0221 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
554005	RUDDER ASSEMBLY 4555401000-021 S7549A0235 REF: AMM 27-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
M5540012	RUDDER TORQUE TUBE - LOOSEN TORQUE TUBE BONDING CLAMP AND PERFORM DETAILED VISUAL INSPECTION OF AREA AROUND BONDING CLAMP FOR CORROSION. NOTE: PERFORM BONDING CHECK OF CLAMP AND BONDING JUMPERS AFTER REINSTALLATION OF CLAMP (EFFECTIVE ON AIRCRAFT 45-005 THRU 45-290 PRE SB 45-27-17)	MOS HRS/MSC AFL	N/A				28-APR-2017 2080.2 1694		
NOT APPLICABLE	REF: AMM 27-20-01								
CHAPTER 56 WINDOWS									
+ 5-19-00-Q5600002	WINDSHIELD RAIN REMOVAL COATING EFFECTIVENESS TEST. (ZONE/ACCESS 220 **IRN # Q5600002). REFER TO 56-10-01	MOS HRS/MSC AFL	300	+25/-25		-7.7	29-AUG-2018 2621.3 2079	2913.6	2938.6
AIRWORTHINESS	REF: See Workcard								
561001	LEFT WINDSHIELD ASSY, (LH) 6656100001-003 2657 REF: See Workcard	MOS HRS/MSC AFL	O/C				07-OCT-2015 1718.9 1414		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 561001A	ULTRASONIC-INSPECTION LEFT WINDSHIELD ASSY, (LH) STRUCTURAL PLIES (IRN N5600003) 6656100001-003 2657 REF: NDT PART 4/56-10-01	MOS HRS/MSC AFL	N/A						
AIRWORTHINESS									
561001B	PERFORM INSPECTION LEFT WINDSHIELD ASSY, (LH) BOLT HOLES (IRN N5600012) 6656100001-003 2657 REF: AMM 56-10-01	MOS HRS/MSC AFL	4800					4800	
AIRWORTHINESS									
561002	RIGHT WINDSHIELD ASSY, (LH) 6656100001-004 2598 REF: See Workcard	MOS HRS/MSC AFL	O/C				07-OCT-2015 1718.9 1414		
+ 561002A	ULTRASONIC-INSPECTION RIGHT WINDSHIELD ASSY, (LH) STRUCTURAL PLIES (IRN N5600003) 6656100001-004 2598 REF: NDT PART 4/56-10-01	MOS HRS/MSC AFL	N/A						
AIRWORTHINESS									
561002B	PERFORM INSPECTION RIGHT WINDSHIELD ASSY, (LH) BOLT HOLE (IRN N5600012) 6656100001-004 2598 REF: AMM 56-10-01	MOS HRS/MSC AFL	4800					4800	
AIRWORTHINESS									
562010-1	LEFT NO.1 WINDOW CABIN PN SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
562010-10	RIGHT NO.5 WINDOW CABIN PN SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
562010-11	LEFT NO.6 WINDOW CABIN PN SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
562010-12	RIGHT NO.6 EMERGENCY EXIT WINDOW PN SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
562010-13	LEFT NO.7 WINDOW CABIN PN SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
562010-14	RIGHT NO.7 WINDOW CABIN PN SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
562010-15	LEFT NO.8 WINDOW CABIN PN SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
562010-16	EMERGENCY EXIT WINDOW CABIN PN SN-UNKNOWN REF: AMM 52-20-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
562010-2	RIGHT NO.1 WINDOW CABIN PN SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
562010-3	LEFT NO.2 WINDOW CABIN PN SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
562010-4	RIGHT NO.2 WINDOW CABIN PN SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
562010-5	LEFT NO.3 WINDOW CABIN PN SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
562010-6	RIGHT NO.3 WINDOW CABIN PN SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
562010-7	LEFT NO.4 WINDOW CABIN PN SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
562010-8	RIGHT NO.4 WINDOW CABIN PN SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
562010-9	LEFT NO.5 WINDOW CABIN PN SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
O5600000 (s)	WINDSHIELDS - PERFORM VISUAL INSPECTION (INTERIOR AND EXTERIOR) PKG 1 REF: AMM 05-10-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 29-AUG-2018 2621.3 2079		
R5600013 (s)	WINDSHIELDS - PERFORM VISUAL INSPECTION OF THE AERODYNAMIC SEAL. IF REPAIRS TO THE SEAL ARE NEEDED, REFER TO 56-10-01. PKG 1 REF: See Workcard	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 29-AUG-2018 2621.3 2079		
T5600001 (s)	CABIN WINDOWS - PERFORM VISUAL INSPECTION PKG 7 REF: AMM 05-10-00	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 30-NOV-2017 2313.6 1848		

CHAPTER 57 WINGS

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 5-19-00-E5750051	VISUALLY INSPECT FLAP MAIN TRACK ROLLERS WITH FLAPS REMOVED. (ZONE/ACCESS 540BL, 540CL, 540JL, AND 540KL *IRN # E5750051)	MOS					11-AUG-2008		
AIRWORTHINESS	REF: AMM 05-10-00	HRS/MSC AFL	10000				0 0		10000
+ 5-19-00-E5750052	VISUALLY INSPECT FLAP NOSE ROLLERS WITH FLAPS REMOVED. (ZONE/ACCESS 540BL, 540, CL 540JL, AND 540KL *IRN # E5750052)	MOS					11-AUG-2008		
AIRWORTHINESS	REF: AMM 05-10-00	HRS/MSC AFL	7200				0 0		7200
+ 5-19-00-N5710002	WING BOX MID SPAR LOWER CAP, OUTBOARD OF JOINT AT WS 137 BETWEEN RIBS 7 AND 8. (ZONE/ACCESS 510/610 *IRN # N5710002)	MOS					11-AUG-2008		
NOT APPLICABLE	REF: AMM 05-10-00	HRS/MSC AFL	N/A				0 0		
+ 5-19-00-N5710008	WING BOX SPAR LOWER CAP - PERFORM NDI INSPECTION. (ZONE/ACCESS 510/610 *IRN # N5710008)	MOS					11-AUG-2008		
NOT APPLICABLE	REF: NDT PART 4/57-30-03	HRS/MSC AFL	N/A				0 0		
+ 5-19-00-N5710009	WING BOX MID SPAR LOWER CAP JOINT AT WS 137 - PERFORM NDI INSPECTION. (ZONE/ACCESS 510/610 *IRN # N5710009)	MOS					11-AUG-2008		
NOT APPLICABLE	REF: NDT PART 2/57-10-02	HRS/MSC AFL	N/A				0 0		
+ 5-19-00-N5710010	WING BOX REAR SPAR LOWER CAP INBOARD OF JOINT WS 81 - PERFORM NDI INSPECTION. (ZONE/ACCESS 510/610 *IRN # N5710010)	MOS					11-AUG-2008		
NOT APPLICABLE	REF: NDT PART 4/57-30-01	HRS/MSC AFL	N/A				0 0		
+ 5-19-00-N5710012	WING BOX REAR SPAR LOWER CAP OUTBOARD OF JOINT AT WS 81 TO RIB 6 - PERFORM NDI INSPECTION. (ZONE/ACCESS 510/610 *IRN # N5710012)	MOS					11-AUG-2008		
NOT APPLICABLE	REF: AMM 05-10-00	HRS/MSC AFL	N/A				0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 5-19-00-N5710013	WING BOX REAR SPAR LWR CAP SKIN TERMINATION AT MS 48 - PERFORM NDI INSPECTION. (ZONE/ACCESS 510/610 *IRN # N5710013)	MOS						11-AUG-2008	
NOT APPLICABLE	REF: NDT PART 6/57-20-04	HRS/MSC	N/A				0		
		AFL					0		
+ 5-19-00-N5710026	WING BOX SPAR LOWER CAP - PERFORM NDI INSPECTION. INSPECT MID SPAR LOWER CAP OUTBOARD OF ROOT RIB AT WS 33 TO WS 99. (ZONE/ACCESS 510/610 *IRN # N5710026)	MOS							
NOT APPLICABLE	REF: NDT PART 4/57-30-03	HRS/MSC	N/A				0		
		AFL					0		
+ 5-19-00-N5710123	WING BOX MID SPAR LOWER CAP AT TRUNNION FITTING - PERFORM EDDY CURRENT INSPECTION AT TRUNNION FITTING. (ZONE/ACCESS 520/620 *IRN # N5710123)	MOS						11-AUG-2008	
NOT APPLICABLE	REF: NDT PART 6/57-10-01	HRS/MSC	N/A				0		
		AFL					0		
5-19-00-N5710148	WING CENTER SECTION REAR SPAR - PERFORM EDDY CURRENT INSPECTION, INSPECT REAR SPAR LOWER CAP FROM CENTERLINE TO WS 33 (ZONE/ACCESS 250CC,250FL,250GR,510BC, IRN # N5710148)	MOS						11-AUG-2008	
AIRWORTHINESS	REF: NDT PART 6/57-20-02	HRS/MSC	9500				0		9500
		AFL					0		
5-19-00-N5710149	WING CENTER SECTION FORWARD AND AFT RIBS AT WS6 AND FORWARD RIBS AT WS 17 - PERFORM EDDY CURRENT INSPECTION. (ZONE ACCESS 510AC,510AL,610AR,510BC, REMOVE AIR DUCTS INSIDE KEELBEAM, IRN # N5710149)	MOS						11-AUG-2008	
AIRWORTHINESS	REF: NDT PART 6/57-10-06	HRS/MSC	10000				0		10000
		AFL					0		
5-19-00-N5710150	WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION, INSPECT MID SPAR LOWER CAP AND LOWER SKIN PANELS BETWEEN WS99 AND WS137. (ZONE/ACCESS 520EL,520GL,620ER,620GR, IRN # N5710150)	MOS						11-AUG-2008	
AIRWORTHINESS	REF: NDT PART 4/57-30-03	HRS/MSC	6500				0		6500
		AFL					0		
5-19-00-N5710151	WING BOX MID SPAR LOWER CAP JOINT AT WS137 - PERFORM X-RAY INSPECTION. INSPECT MID SPAR CENTER/OUTER JOINT. (ZONE/ACCESS 520FL,520GL,620FR,620GR, IRN # N5710151)	MOS						11-AUG-2008	
AIRWORTHINESS	REF: NDT PART 2/57-10-02	HRS/MSC	6500				0		6500
		AFL					0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-00-N5710152	WING BOX REAR SPAR LOWER CAP INBOARD OF JOINT AT WS81 - PERFORM ULTRASONIC INSPECTION, INSPECT REAR SPAR LOWER CAP BETWEEN SKIN TERMINATION AT WS 48 CLOSING RIB AT WS 60. (ZONE/ACCESS REMOVE FLAPS, IRN # N5710152)	MOS					11-AUG-2008		
AIRWORTHINESS	REF: NDT PART 4/57-30-01	HRS/MSC AFL	6500				0 0		6500
5-19-00-N5710153	WING BOX REAR SPAR LOWER CAP JOINT AT WS 81 - PERFORM X-RAY INSPECTION. INSPECT CENTER AND OUTER REAR SPARS, LOWER SPLICE PLATE, AND LOWER SKIN BETWEEN WS 60 AND WS 90. (IRN # N5710153)	MOS					11-AUG-2008		
AIRWORTHINESS	REF: NDT PART 2/57-10-03	HRS/MSC AFL	10000				0 0		10000
5-19-00-N5710155	WING BOX REAR SPAR LOWER CAP TERMINATION AT MS 48 - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR REAR SPAR LOWER CAP BETWEEN WS33 AND WS 48. (ZONE/ACCESS 510/610, IRN # N5710155)	MOS					11-AUG-2008		
AIRWORTHINESS	REF: NDT PART 6/57-20-04	HRS/MSC AFL	6900				0 0		6900
5-19-00-N5710158	CENTER SECTION FRONT SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION. INSPECT CENTER WING FRONT SPAR LOWER CAP BETWEEN SKIN TERMINATIONS (WS31 LEFT TO WS31 RIGHT). (ZONE/ACCESS 250BC,250BL,510AC,520AL,520BL,620AR,620BR, IRN # N5710158)	MOS					11-AUG-2008		
AIRWORTHINESS	REF: NDT PART 6/57-10-03	HRS/MSC AFL	10000				0 0		10000
5-19-00-N5710159	WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION. INSPECT MID SPAR LOWER CAP OUTBOARD OF ROOT RIB AT WS33 TO WS99. (ZONE/ACCESS 520AL THRU 520DL THRU 620AR THRU 620DR, IRN # N5710159)	MOS					11-AUG-2008		
AIRWORTHINESS	REF: NDT PART 4/57-30-03	HRS/MSC AFL	6800				0 0		6800
5-19-00-N5710160	WING BOX MID SPAR LOWER CAP, SKIN TERMINATION AT WS 33 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION. INSPECT MID SPAR LOWER CAP UNDERNEATH ROOT RIB (WS 33) AT POINT OF SKIN TERMINATION. (ZONE/ACCESS 520AL,620AR, IRN # N5710160)	MOS					11-AUG-2008		
AIRWORTHINESS	REF: NDT PART 6/57-10-11	HRS/MSC AFL	6800				0 0		6800



Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-00-N5710163	CENTER SECTION MID SPAR CENTERLINE JOINT - PERFORM EDDY CURRENT INSPECTION. INSPECT CENTER MID SPAR (CENTERLINE TO WS 17), LOWER SPLICE PLATE, AND CENTER MID SPAR JOINT FITTING LOWER CAP. (REFER TO NDI MANUAL (NDI-104) PART 6, 57-10-08 AND 57-10-10.) EFFECTIVE ON A/C MODIFIED PER SB 45-11-5	MOS					11-AUG-2008		
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	6800				0 0		6800
5-19-00-N5710164	CENTER SECTION MID SPAR LOWER CAP - PEFORM EDDY CURRENT INSPECTION. INSPECT MID SPAR FROM CENTERLINE SPLICE PLATE TO SKIN TERMINATION AT MS 33. (ZONE/ACCESS 520AL,520BL,520CL,620AR,620BR OPEN INBOARD MLG DOORS, IRN # N5710164)	MOS					11-AUG-2008		
AIRWORTHINESS	REF: NDT PART 6/57-10-02	HRS/MSC AFL	10000				0 0		10000
5-19-00-N5710165	WING BOX REAR SPAR FLAP TRACK CUT-OUTS - PERFORM EDDY CURRENT INSPECTION. INSPECT FLAP TRACK CUT-OUTS AT WS65, WS 126 AND WS184 ON REAR SPAR. (ZONE/ACCESS REMOVE FLAPS, IRN # N5710165)	MOS					11-AUG-2008		
AIRWORTHINESS	REF: NDT PART 6/57-20-01	HRS/MSC AFL	9300				0 0		9300
5-19-00-N5710168	WING BOX MID SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION AT TRUNNION FITTING. (ZONE/ACCESS 520/620, IRN # N5710168)	MOS					11-AUG-2008		
AIRWORTHINESS	REF: NDT PART 6/57-10-01	HRS/MSC AFL	6500				0 0		6500
5-19-00-N5710169	MID SPAR AT RIB #2 NEAR WS48 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION. (ZONE/ACCESS 520BL,620BR, IRN # N5710169)	MOS					11-AUG-2008		
AIRWORTHINESS	REF: NDT PART 6/57-10-11	HRS/MSC AFL	7700				0 0		7700
5-19-00-N5710170	MID SPAR AT RIB #3 NEAR WS60 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION.(ZONE/ACCESS 520CL,620CR, IRN # N5710170)	MOS					11-AUG-2008		
AIRWORTHINESS	REF: NDT PART 6/57-10-11	HRS/MSC AFL	7700				0 0		7700
5-19-00-N5710171	FORWARD FLANGE FASTENERS AT REAR SPAR BETWEEN WS 52 AND WS 60 - PEROFRM BOLT HOLE EDDY CURRENT INSPECTION. (ZONE/ACCESS 510AZ,610AZ REMOVE MLG, IRN # N5710171)	MOS					11-AUG-2008		
AIRWORTHINESS	REF: NDT PART 6/57-20-03	HRS/MSC AFL	6500				0 0		6500

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-00-N5710172	WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION AT TRUNNION FITTING. (ZONE/ACCESS 520/620, IRN # N5710172)	MOS					11-AUG-2008		
NOT APPLICABLE	REF: NDT PART 4/57-10-00	HRS/MSC AFL	N/A				0 0		
5-19-00-N5710173	WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION AT TRUNNION FITTING. (ZONE/ACCESS 520/620, IRN # N5710173)	MOS					11-AUG-2008		
AIRWORTHINESS	REF: NDT PART 4/57-10-00	HRS/MSC AFL	6500				0 0	6500	
5-19-00-N5710174	WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT MS 48 - PEFORM ULTRASONIC INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS 33 AND WS 48. (ZONE/ACCESS 510/610, IRN # N5710174)	MOS					11-AUG-2008		
NOT APPLICABLE	REF: NDT PART 4/57-30-04	HRS/MSC AFL	N/A				0 0		
5-19-00-N5710175	WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT MS 48 - PERFORM ULTRASONIC INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS 33 AND WS 48. (ZONE/ACCESS 510/610, IRN # N5710175)	MOS					11-AUG-2008		
AIRWORTHINESS	REF: NDT PART 4/57-30-04	HRS/MSC AFL	6900				0 0	6900	
5-19-00-N5710177	WING MID SPAR (CENTER SECTION) LOWER CAP AND CENTER JOINT FITTING - PERFORM ULTRASONIC INSPECTION. (ZONE/ACCESS 520AL,520BL,520CL,620AR,620BR, IRN # N5710177)	MOS					11-AUG-2008		
AIRWORTHINESS	REF: NDT PART 4/57-30-05	HRS/MSC AFL	6800				0 0	6800	
571001	WING ASSEMBLY 4557000004-001 499082800479 REF: AMM 57-10-00	MOS		TSN:0			11-AUG-2008		
		HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
573001	LEFT WINGLET FILLER PN SN-UNKNOWN REF: GENERIC NO REF	MOS		TSN:0			11-AUG-2008		
		HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
573002	RIGHT WINGLET FILLER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
573090	LEFT WING WINGLET 4557300006-001/00 276335600479 REF: AMM 57-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
573091	LEFT WINGLET LEADING EDGE ASSEMBLY PN SN-UNKNOWN REF: AMM 57-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
573092	RIGHT WING WINGLET 4557300006-002/00 290099000479 REF: AMM 57-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
573093	RIGHT WINGLET LEADING EDGE ASSEMBLY PN SN-UNKNOWN REF: AMM 57-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
574005	LEFT INBOARD LEADING EDGE 4557400005-039 684222900479 REF: AMM 57-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
574007	RIGHT INBOARD LEADING EDGE 4557400005-040 791425900481 REF: AMM 57-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
574011	LEFT INBOARD LEADING EDGE ACCESS SECTION 4557400005-037 319721400479 REF: AMM 57-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
574013	RIGHT INBOARD LEADING EDGE ACCESS SECTION 4557400005-038 011809400481 REF: AMM 57-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
574033	LEFT CENTER LEADING EDGE 4557400005-041 700090800458 REF: AMM 57-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
574035	RIGHT CENTER LEADING EDGE 4557400005-042 786922900479 REF: AMM 57-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
574039	LEFT OUTBOARD LEADING EDGE ACCESS SECTION 4557400005-045 011817100479 REF: AMM 57-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
574041	RIGHT OUTBOARD LEADING EDGE ACCESS SECTION 4557400005-044 229554700481 REF: AMM 57-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
574050	LEFT OUTBOARD LEADING EDGE 4557400005-043 011815000478 REF: AMM 57-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
574051	RIGHT OUTBOARD LEADING EDGE 4557400005-046 933360600479 REF: AMM 57-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
575001	LEFT FLAP ASSEMBLY 4557500006-009 984468600479 REF: AMM 27-50-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
575002	RIGHT FLAP ASSEMBLY 4557500006-010 917181800479 REF: AMM 27-50-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
576001	LEFTAILERON 4557600003-001 015223300479 REF: AMM 27-10-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
576002	RIGHTAILERON 4557600003-002 499102200479 REF: AMM 27-10-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
576003	UPPERAILERON QUADRANT ASSEMBLY PN SN-UNKNOWN REF: AMM 27-10-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
576004	LOWERAILERON QUADRANT ASSEMBLY PN SN-UNKNOWN REF: AMM 27-10-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
+ 576037	REPLACE LEFTAILERON (ZONE/ACCESS 540/640 *IRN # A5760004) BOLTS PN SN-UNKNOWN REF: AMM 27-10-02	MOS HRS/MSC AFL	9600	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0	9600	
+ 576038	REPLACE RIGHTAILERON (ZONE/ACCESS 540/640 *IRN # A5760004) BOLTS PN SN-UNKNOWN REF: AMM 27-10-02	MOS HRS/MSC AFL	9600	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0	9600	
577001	ASSEMBLY, LEFT SPOILER 4557700003-043 381630100470 REF: AMM 27-60-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
577002	ASSEMBLY, RIGHT SPOILER 4557700003-044 381632300470 REF: AMM 27-60-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
G5730013 (s)	AILERON BRUSH SEALS - PERFORM DETAILED INSPECTION. PKG 4 REF: AMM 57-60-01	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 29-AUG-2018 2621.3 2079		
P5700001 (s)	WINGLET - PERFORM VISUAL INSPECTION PKG 4 REF: AMM 05-10-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 29-AUG-2018 2621.3 2079		
P5710180 (s)	EXTERNAL LOWER WING SKIN - PERFORM VISUAL INSPECTION. PKG 10 REF: AMM 05-10-00	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 30-NOV-2017 2313.6 1848		
Q5710156 (s)	PERFORM **WING BOX BASIC SKIN/STRINGER, LOWER SKIN - VISUAL INSPECTION. INSPECT OUTBOARD WING FORWARD AND AFT LOWER SKIN PANELS AND STRINGERS. (POST SB 45-11-5) PKG 22 REF: GENERIC NO REF	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 20-MAY-2016 1821.7 1492		
R5750069 (s)	FLAPS - PERFORM VISUAL INSPECTION OF FLAP NOSE ROLLERS, FLAP TRACKS, FLAP NOSE ROLLER TRACKS, AND FLAP MAIN TRACK ROLLERS. PKG 4 REF: AMM 05-10-00	MOS HRS/MSC AFL	12 300	+14d/-14d +25/-25			PKG 29-AUG-2018 2621.3 2079		
U5710147 (s)	** WING BOX MID SPAR LOWER CAP, OUTBOARD OF JOINT AT WS 137 BETWEEN RIB #7 AND #8 - PERFORM DETAILED VISUAL INSPECTION. INSPECT MID SPAR LOWER CAP AND LOWER SKIN PANELS. (EFFECTIVE ON AIRCRAFT POST SB 45-11-5) PKG 10 REF: AMM 05-10-00	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 30-NOV-2017 2313.6 1848		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
U5710154 (s)	** WING BOX REAR SPAR LOWER CAP, OUTBOARD OF JOINT AT WS 81 TO RIB #6 - PERFORM DETAILED VISUAL INSPECTION. INSPECT OUTER REAR SPAR LOWER CAP AND AFT LOWER SKIN PANEL OUTBOARD OF REAR SPLICE AT WS 90. (EFFECTIVE ON AIRCRAFT POST SB 45-11-5)						PKG		
	PKG 10	MOS	24	+14d/-14d			30-NOV-2017		
AIRWORTHINESS	REF: AMM 05-10-00	HRS/MSC	600	+25/-25			2313.6		
		AFL					1848		

CHAPTER 71 POWER PLANT

+ 5-19-00-P7120069-LEFT	PERFORM VISUAL INSPECTION - ENGINE MOUNT ISOLATORS, FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS. (REFER TO 71-20-00.)								
		MOS					11-AUG-2008		
	REF: AMM 71-20-00	HRS/MSC	3000				0		3000
		AFL					0		
+ 5-19-00-P7120069-RIGHT	PERFORM VISUAL INSPECTION ENGINE MOUNT ISOLATORS - FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS. (REFER TO 71-20-00.)								
		MOS					11-AUG-2008		
	REF: AMM 71-20-00	HRS/MSC	3000				0		3000
		AFL					0		
+ 5-19-00-Q7110004-LEFT	TAP TEST NO. 1 ENGINE NACELLE INLET (ZONE/ACCESS 430/440 IRN Q7110004). (REFER TO 71-10-01.)								
		MOS					04-SEP-2012		
	REF: AMM 71-10-01	HRS/MSC	3000				1170.8		4170.8
		AFL					924		
+ 5-19-00-Q7110004-RIGHT	TAP TEST NO. 2 ENGINE NACELLE INLET (ZONE/ACCESS 430/440 IRN Q7110004). (REFER TO 71-10-01.)								
		MOS					04-SEP-2012		
	REF: AMM 71-10-01	HRS/MSC	3000				1170.8		4170.8
		AFL					924		
+ 5-19-00-Q7120002-LEFT	DETAILED VISUAL INSPECTION NO. 1 ENGINE ENGINE MOUNT ISOLATORS - PERFORM DETAILED INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS. (REFER TO 71-20-00.) EFFECTIVE ON AIRCRAFT WITH 5,000 HOUR CZI MODIFIED ENGINES.								
		MOS					11-AUG-2008		
	REF: AMM 71-20-00	HRS/MSC	N/A				0		
		AFL					0		
+ 5-19-00-Q7120002-RIGHT	DETAILED VISUAL INSPECTION NO. 2 ENGINE ENGINE MOUNT ISOLATORS - PERFORM DETAILED INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS. (REFER TO 71-20-00.) EFFECTIVE ON AIRCRAFT WITH 5,000 HOUR CZI MODIFIED ENGINES.								
		MOS					11-AUG-2008		
	REF: AMM 71-20-00	HRS/MSC	N/A				0		
		AFL					0		



Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-00-Q7120073-LEFT	VISUAL INSPECTION NO. 1 ENGINE ENGINE MOUNT ISOLATORS - PERFORM DETAILED INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS. (REFER TO 71-20-00.) EFFECTIVE ON AIRCRAFT WITH 6,000 HOUR CZI MODIFIED ENGINES.	MOS HRS/MSC AFL	6000				11-AUG-2008 0 0	6000	
	REF: AMM 71-20-00								
5-19-00-Q7120073-RIGHT	VISUAL INSPECTION NO. 2 ENGINE ENGINE MOUNT ISOLATORS - PERFORM DETAILED INSPECTION OF FORWARD AND AFT ISOLATORS AND ASSOCIATED PARTS. (REFER TO 71-20-00). EFFECTIVE ON AIRCRAFT WITH 6,000 HOUR CZI MODIFIED ENGINES.	MOS HRS/MSC AFL	6000				11-AUG-2008 0 0	6000	
	REF: AMM 71-20-00								
5-19-00-R7100032	DETAIL VISUAL INSPECTION L/H ENGINE NACELLE TUBES - PERFORM DETAILED VISUAL INSPECTION. (REFER TO 71-10-03.)	MOS HRS/MSC AFL	N/A				10-FEB-2011 803.6 653		
NOT APPLICABLE	REF: AMM 71-10-03								
5-19-01-K7120004	REPLACE FORWARD AND AFT ENGINE MOUNT ISOLATOR HOUSING. (ZONE/ACCESS 450/460 IRN # K7120004)	MOS HRS/MSC AFL	15000/C/ C	+25/-25			11-AUG-2008 0 0	15000	15025
LIFE LIMIT	REF: AMM 71-20-00								
5-19-01-Q7120005-LEFT	REPLACE ENGINE MOUNT ISOLATOR FORWARD BONDED MOUNTING AND AFT MOUNT METAL MESH ELEMENTS (REFER TO LORD CORPORATION COMPONENT MAINTENANCE MANUAL APE97-008) EFFECTIVE ON AIRCRAFT WITH 5,000 HOUR CZI MODIFIED ENGINES.	MOS HRS/MSC AFL	N/A				11-AUG-2008 0 0		
	REF: AMM 71-20-00								
5-19-01-Q7120005-RIGHT	REPLACE ENGINE MOUNT ISOLATOR FORWARD BONDED MOUNTING AND AFT MOUNT METAL MESH ELEMENTS. (REFER TO LORD CORPORATION COMPONENT MAINTENANCE MANUAL APE97-008.) EFFECTIVE ON AIRCRAFT WITH 5,000 HOUR CZI MODIFIED ENGINES.	MOS HRS/MSC AFL	N/A				11-AUG-2008 0 0		
	REF: AMM 71-20-00								

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-19-01-Q7120070-LEFT	REPLACE ENGINE MOUNT ISOLATOR FORWARD BONDED MOUNTING AND AFT MOUNT METAL MESH ELEMENTS. (REFER TO LORD CORPORATION COMPONENT MAINTENANCE MANUAL APE97-008.) EFFECTIVE ON AIRCRAFT WITH 6,000 HOUR CZI MODIFIED ENGINES.	MOS					11-AUG-2008		
LIFE LIMIT	REF: AMM 71-20-00	HRS/MSC AFL	6000				0 0		6000
5-19-01-Q7120070-RIGHT	ENGINE MOUNT ISOLATOR FORWRD BONDED MOUNTING AND AFT MOUNT METAL MESH ELEMENTS. (REFER TO LORD CORPORATION COMPONENT MAINTENANCE MANUAL APE97-008.) EFFECTIVE ON AIRCRAFT WITH 6,000 HOUR CZI MODIFIED ENGINES.	MOS					11-AUG-2008		
LIFE LIMIT	REF: AMM 71-20-00	HRS/MSC AFL	6000				0 0		6000
5-19-01-V7120074L	LEFT ENGINE *REPLACE AFT ENGINE MOUNT BOLT (P/N 4571408525-001) (REFER TO 71-00-01.)	MOS					11-AUG-2008		
AIRWORTHINESS	REF: AMM 71-20-00	PN SN-UNKNOWN AFL	E/C	TSN:0 TSN:0 TSN:0			0 0 0		
5-19-01-V7120074R	RIGHT ENGINE *REPLACE AFT ENGINE MOUNT BOLT (P/N 4571408525-001) (REFER TO 71-00-01.)	MOS					11-AUG-2008		
AIRWORTHINESS	REF: AMM 71-20-00	PN SN-UNKNOWN AFL	E/C	TSN:0 TSN:0 TSN:0			0 0 0		
710001	NO. 1 ASSEMBLY ENGINE	MOS					11-AUG-2008		
	REF: AMM 71-20-00	PN SN-UNKNOWN AFL	O/C	TSN:0 TSN:0 TSN:0			0 0 0		
710002	NO. 2 ASSEMBLY ENGINE	MOS					11-AUG-2008		
	REF: AMM 71-20-00	PN SN-UNKNOWN AFL	O/C	TSN:0 TSN:0 TSN:0			0 0 0		
711001	NO. 1 ENGINE FORWARD MOUNT	MOS					11-AUG-2008		
	REF: AMM 71-20-00	PN SN-UNKNOWN AFL	O/C	TSN:0 TSN:0 TSN:0			0 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
711002	NO. 2 ENGINE FORWARD MOUNT PN SN-UNKNOWN REF: AMM 71-20-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
712005	NO. 1 ENGINE AFT MOUNT ISOLATOR ASSEMBLY LM-833-SA18 LK1707 REF: AMM 71-20-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
712006	NO. 2 ENGINE AFT MOUNT ISOLATOR ASSEMBLY LM-833-SA18 LK1706 REF: AMM 71-20-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
712007	NO. 1 ENGINE FORWARD UPPER MOUNT ISOLATOR ASSEMBLY LM-833-45 LK6171 REF: AMM 71-20-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
712008	NO. 2 ENGINE FORWARD UPPER MOUNT ISOLATOR ASSEMBLY LM-833-45 LK6129 REF: AMM 71-20-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
712009	NO. 1 ENGINE FORWARD LOWER MOUNT ISOLATOR ASSEMBLY LM-833-45 LK6158 REF: AMM 71-20-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
712010	NO. 2 ENGINE FORWARD LOWER MOUNT ISOLATOR ASSEMBLY LM-833-45 LK6160 REF: AMM 71-20-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
712045	NO. 1 MOUNT, ENGINE AFT ARM 4571200011-003 CDF1110 REF: AMM 71-20-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
712046	NO. 2 MOUNT, ENGINE AFT ARM 4571200011-003 CDF1115 REF: AMM 71-20-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
716005	NO. 1 ENGINE INLET NACELLE PN SN-UNKNOWN REF: AMM 71-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
716006	NO. 2 ENGINE INLET NACELLE PN SN-UNKNOWN REF: AMM 71-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
71EN1 71.EN1	NO. 1 ENGINE 3060084-1 P-116969C REF: AMM 71-00-01	MOS HRS/MSC AFL	E/C						
71EN2 71.EN2	NO. 2 ENGINE 3060084-1 P-116968C REF: AMM 71-00-01	MOS HRS/MSC AFL	E/C						
G7100002 (s)	LOWER ENGINE COWLING - VISUALLY INSPECT LATCH CHANNELS FOR CHAFING. PKG 9 REF: AMM 05-10-00	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 30-NOV-2017 2313.6 1848		
G7110000 (s)	ENGINE NACELLE - PERFORM VISUAL INSPECTION. INSPECT INLET BULKHEAD, STRUCTURE, PLUMBING, SKIN SPOT WELDS, ANTI-ICE OUTLET SCREEN, AND FASTENERS FOR SECURITY, CRACKS, AND GENERAL CONDITION. PKG 9 REF: AMM 05-10-00	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 30-NOV-2017 2313.6 1848		
G7110001 (s)	ENGINE INLET LIP AND DUCT - PERFORM VISUAL INSPECTION. PKG 9 REF: AMM 05-10-00	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			PKG 30-NOV-2017 2313.6 1848		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
G7110002 (s)	ENGINE STARTER/GENERATOR INLET AND EXHAUST DUCT AND SEALS - PERFORM VISUAL INSPECTION. PKG 9	MOS	24	+14d/-14d			PKG 30-NOV-2017 2313.6		
	REF: AMM 05-10-00	HRS/MSC AFL	600	+25/-25			1848		
G7110003 (s)	ENGINE ALTERNATOR EXHAUST DUCT AND SEALS - PERFORM VISUAL INSPECTION. PKG 9	MOS	24	+14d/-14d			PKG 30-NOV-2017 2313.6		
	REF: AMM 05-10-00	HRS/MSC AFL	600	+25/-25			1848		
O7120000 (s)	FORWARD ENGINE MOUNTS - PERFORM VISUAL INSPECTION. PKG 3	MOS	12	+14d/-14d			PKG 29-AUG-2018 2621.3		
	REF: AMM 05-10-00	HRS/MSC AFL	300	+25/-25			2079		

ENGINE NO. 1 Model : TFE731-20BR-1 B Serial # P-116969C Part # 3060084-1

710100	NO. 1 ENGINE - MAIN ENGINE WIRING HARNESS ASSEMBLY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
+ 710130 (s)	NO. 1 ENGINE - INSPECT TAILPIPE/LPT3 ROTOR ASSEMBLY-VISUALLY INSPECT FOR FOREIGN OBJECT DAMAGE, THERMAL DISTRESS, AND LEAKS. REF: LMM 72-00-00	MOS HRS/MSC ENC	800	+50/-300			16-FEB-2018 2383.6 1854		
+ 710140 (s)	NO. 1 ENGINE - INSPECT INLET/FAN AREA? INSPECT FOR FOREIGN OBJECT DAMAGE AND LEAKAGE (REFER TO PARAGRAPH 4.B) REF: See Workcard	MOS HRS/MSC ENC	800	+50/-300			16-FEB-2018 2383.6 1854		
+ 714010 (s)	NO. 1 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS? VISUALLY INSPECT FOR SECURITY AND DAMAGE REF: LMM 72-00-00	MOS HRS/MSC ENC	800	+50/-300			16-FEB-2018 2383.6 1854		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 715010 (s)	NO. 1 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS? VISUALLY INSPECT FOR SECURITY, LOOSE OR BROKEN CLAMPS OR BRACKETS, LEAKS, CRACKS, CUTS, OR RUBBING	MOS					16-FEB-2018		
	REF: LMM 72-00-00	HRS/MSC ENC	800	+50/-300			2383.6 1854		
ENGINE NO. 2 Model : TFE731-20BR-1B Serial # P-116968C Part # 3060084-1									
710100	NO. 2 ENGINE - MAIN ENGINE WIRING HARNESS ASSEMBLY	PN			TSN:0		07-MAY-2008		
	REF: See Workcard	SN-UNKNOWN ENC	O/C		TSN:0		0 0		
+ 710130 (s)	NO. 2 ENGINE - INSPECT TAILPIPE/LPT3 ROTOR ASSEMBLY-VISUALLY INSPECT FOR FOREIGN OBJECT DAMAGE, THERMAL DISTRESS, AND LEAKS.	MOS					16-FEB-2018		
	REF: LMM 72-00-00	HRS/MSC ENC	800	+50/-300			2383.6 1854		
+ 710140 (s)	NO. 2 ENGINE - INSPECT INLET/FAN AREA? INSPECT FOR FOREIGN OBJECT DAMAGE AND LEAKAGE (REFER TO PARAGRAPH 4.B)	MOS					16-FEB-2018		
	REF: See Workcard	HRS/MSC ENC	800	+50/-300			2383.6 1854		
+ 714010 (s)	NO. 2 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS? VISUALLY INSPECT FOR SECURITY AND DAMAGE	MOS					16-FEB-2018		
	REF: LMM 72-00-00	HRS/MSC ENC	800	+50/-300			2383.6 1854		
+ 715010 (s)	NO. 2 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS? VISUALLY INSPECT FOR SECURITY, LOOSE OR BROKEN CLAMPS OR BRACKETS, LEAKS, CRACKS, CUTS, OR RUBBING	MOS					16-FEB-2018		
	REF: LMM 72-00-00	HRS/MSC ENC	800	+50/-300			2383.6 1854		
CHAPTER 72 ENGINE									
ENGINE NO. 1 Model : TFE731-20BR-1 B Serial # P-116969C Part # 3060084-1									
72-AS-720005	NO. 1 ENGINE - INSPECT MAJOR PERIODIC PER MANUFACTURERS INSTRUCTIONS	MOS					07-MAY-2008		
	REF: LMM 72-00-00	HRS/MSC ENC	3000	+100/-100			0 0	(3000) 3000	3100

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-AS-720006 (s)	NO. 1 ENGINE - INSPECT COMB CHAMBER PLENUM CASE INSP PER MANUFACTURERS INSTRUCTIONS	MOS					07-MAY-2008		
	REF: GENERIC NO REF	HRS/MSC ENC	3000	+100/-100			0 0		
72-AS-720007	NO. 1 ENGINE - INSPECT COMPRESSOR ZONE PER MANUFACTURERS INSTRUCTIONS	MOS					07-MAY-2008		
	REF: LMM 72-00-00	HRS/MSC ENC	6000	+200/-200			0 0	(6000) 6000	6200
72-AS-720008 (s)	NO. 1 ENGINE - INSPECT AGB PER MANUFACTURERS INSTRUCTIONS	MOS					07-MAY-2008		
	REF: See Workcard	HRS/MSC ENC	6000	+200/-200			0 0		
72-AS-720010	NO. 1 ENGINE - ANALYSIS OIL AND FILTER (BASELINE/SPECIAL REQUIREMENT)	MOS					12-AUG-2008		
	REF: LMM 72-00-00	HRS/MSC ENC	A/R				11.9 10		
72-AS-720011	NO. 1 ENGINE - REPLACE FUEL FILTER ELEMENT (25-HR INITIAL)	MOS					12-AUG-2008		
	REF: LMM 73-21-02	HRS/MSC ENC	A/R				11.9 10		
720110	NO. 1 ENGINE - ACCESSORY GEARBOX	MOS					07-MAY-2008		
	3060827-2	HRS/MSC	O/C	TSN:0			0		
	S-3035	ENC		TSN:0			0		
	REF: LMM 72-60-02			TSN:0			0		
720244	NO. 1 ENGINE - NO. 6 CARBON SEAL ASSEMBLY	MOS					07-MAY-2008		
	PN	HRS/MSC	O/C	TSN:0			0		
	SN-UNKNOWN	ENC		TSN:0			0		
	REF: GENERIC NO REF			TSN:0			0		
720245	NO. 1 ENGINE - NO. 6 BEARING ASSEMBLY	MOS					07-MAY-2008		
	PN	HRS/MSC	O/C	TSN:0			0		
	SN-UNKNOWN	ENC		TSN:0			0		
	REF: GENERIC NO REF			TSN:0			0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
722001	NO. 1 ENGINE - FAN INLET HOUSING ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
723002	NO. 1 ENGINE - NO. 3 CARBON SEAL ASSEMBLY PN SN-UNKNOWN REF: LMM 72-30-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
+ 723010 (s)	NO. 1 ENGINE - CHECK CARBON SEAL HEALTH REF: LMM 72-00-00	MOS HRS/MSC ENC	1600	+50/-100			29-JUN-2015 1602.9 1293		
723011	NO. 1 ENGINE - NO. 4 CARBON SEAL RUNNER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
723012	NO. 1 ENGINE - NO. 4 CARBON SEAL ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
723013	NO. 1 ENGINE - NO. 5 CARBON SEAL RUNNER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
723014	NO. 1 ENGINE - NO. 5 CARBON SEAL ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
723081	NO. 1 ENGINE - ROTATING, AIR 2ND STAGE SEAL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725007	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) NOZZLE ASSEMBLY								
72.500	PN SN-UNKNOWN REF: LMM 72-50-07	MOS HRS/MSC ENC	A/R	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
725010	NO. 1 ENGINE - 1ST-STAGE LOW PRESSURE TURBINE (LPT) DISC								
LIFE LIMIT	3060625-1 070322903012 REF: LMM 72-50-04	MOS HRS/MSC ENC	12000	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0	(12000) 12045	
725020	NO. 1 ENGINE - 2ND-STAGE LOW PRESSURE TURBINE (LPT) DISC								
LIFE LIMIT	3060611-1 070322903142 REF: LMM 72-50-04	MOS HRS/MSC ENC	12000	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0	(12000) 12045	
725030	NO. 1 ENGINE - 3RD-STAGE LOW PRESSURE TURBINE (LPT) DISC								
LIFE LIMIT	3060671-2 070322902966 REF: LMM 72-50-04	MOS HRS/MSC ENC	12000	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0	(12000) 12045	
725040	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) DISC								
LIFE LIMIT	3060841-1 071217200548 REF: LMM 72-50-07	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0	(10000) 10045	
725045	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) ASSY								
	PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
725050	NO. 1 ENGINE - FAN DISC								
LIFE LIMIT	3060287-2 08-13651-00545 REF: GENERIC NO REF	MOS HRS/MSC ENC	12000	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0	(12000) 12045	
725060	NO. 1 ENGINE - 1ST-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC								
LIFE LIMIT	3060372-1 070316004778 REF: LMM 72-30-04	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0	(10000) 10045	

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725070	NO. 1 ENGINE - 2ND-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC 3075839-1 070316001327 REF: LMM 72-30-04	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0	(10000) 10045	
LIFE LIMIT									
725071	NO. 1 ENGINE - COMBUSTION LINER PN SN-UNKNOWN REF: LMM 72-40-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
725080	NO. 1 ENGINE - 3RD-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC 3060374-1 070316004577 REF: LMM 72-30-04	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0	(10000) 10045	
LIFE LIMIT									
725081	NO. 1 ENGINE - OUTER TRANSITION LINER PN SN-UNKNOWN REF: LMM 72-40-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
725090	NO. 1 ENGINE - 4TH-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC 3075326-5 060350106563 REF: LMM 72-30-04	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0	(10000) 10045	
LIFE LIMIT									
725110	NO. 1 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD 3074744-1 08P06316 REF: LMM 72-30-10	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
725120	NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR IMPELLER 3060371-1 070322905846 REF: LMM 72-50-06	MOS HRS/MSC ENC	8000	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0	(8000) 8045	
LIFE LIMIT									
725130	NO. 1 ENGINE - FAN SPINNER 3060156-2 072784300331 REF: LMM 72-70-01	MOS HRS/MSC ENC	12000	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0	(12000) 12045	
LIFE LIMIT									



Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725140	NO. 1 ENGINE - FAN DRIVE SHAFT 3060180-2 070339001996 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
725160	NO. 1 ENGINE - FORWARD ROTOR HIGH PRESSURE SEAL 3060698-1 07-03501-11887 REF: LMM 72-70-03	MOS HRS/MSC ENC	7000	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0	(7000) 7045	
725170	NO. 1 ENGINE - HIGH PRESSURE SHOULDERED SHAFT 3060366-3 08P04395 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
725180	NO. 1 ENGINE - COMBUSTION PLENUM CASE 3060534-4 08P05038 REF: LMM 72-40-04	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
725210	NO. 1 ENGINE - HIGH PRESSURE TURBINE FORWARD SEAL PLATE 3060514-1 08-03229-00889 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0	(10000) 10045	
725220	NO. 1 ENGINE - TRANSITION DUCT 3060694-6 08P01973 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
725230	NO. 1 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE SEAL SUPPORT 3060693-1 081756503217 REF: LMM 72-50-04	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
725240	NO. 1 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE ASSEMBLY 3060666-7 08P07930 REF: LMM 72-50-04	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725250	NO. 1 ENGINE - FORWARD SHAFT HIGH PRESSURE TURBINE (HPT) COUPLING 3060502-2 08P07076 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
725260	NO. 1 ENGINE - AFT HIGH PRESSURE TURBINE (HPT) SHAFT COUPLING 3060599-2 08P09414 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
725270	NO. 1 ENGINE - NOZZLE LOW PRESSURE TURBINE (LPT) (A5) SEAL 3073765-12 081756503469 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
726005	NO. 1 ENGINE - TRANSFER GEARBOX ASSEMBLY 3070093-16 08P11026 REF: LMM 72-60-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
726010	NO. 1 ENGINE - OIL PUMP SPUR ANNUAL BALL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
726011	NO. 1 ENGINE - AFT OIL PUMP SPUR ANNULAR BALL BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
726012	NO. 1 ENGINE - FORWARD ALTERNATOR SPU ANNULAR BALL BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
726013	NO. 1 ENGINE - AFT ALTERNATOR SPU ANNULAR BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
726014	NO. 1 ENGINE - AIR-OIL SEPERATOR ANNULAR BALL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
726015	NO. 1 ENGINE - AIR-OIL SEPERATOR ANNULAR BALL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
726016	NO. 1 ENGINE - FORWARD STARTER/GENERATOR SPU ANNULAR BALL BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
726017	NO. 1 ENGINE - AFT STARTER/GENERATOR SPU ANNULAR BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
727001	NO. 1 ENGINE - BYPASS FAN STATOR PN SN-UNKNOWN REF: LMM 72-70-04	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
727005	NO. 1 ENGINE - UPPER FAN DUCT ASSEMBLY PN SN-UNKNOWN REF: LMM 72-70-05	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
727006	NO. 1 ENGINE - LOWER FAN DUCT ASSEMBLY PN SN-UNKNOWN REF: LMM 72-70-05	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			(EBT)		
727010 (s)	NO. 1 ENGINE - INSPECT BYPASS STATOR VANE ASSEMBLY. REF: See Workcard	MOS HRS/MSC ENC	1200	+100/-200			30-NOV-2017 2313.6 1803		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
727101	NO. 1 ENGINE - NO. 1 CARBON SEAL ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
727102	NO. 1 ENGINE - NO. 1 CARBON SEAL RUNNER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
727103	NO. 1 ENGINE - NO. 1 BEARING ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
727105	NO. 1 ENGINE - RING GEAR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
727203	NO. 1 ENGINE - NO. 3 BALL BEARING PN SN-UNKNOWN REF: LMM 72-30-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
727210	NO. 1 ENGINE - PLANET HOUSING ASSEMBLY PN SN-UNKNOWN REF: LMM 72-72-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
727210-1	NO. 1 ENGINE - NO. 1 PLANET GEAR ASSEMBLY PN SN-UNKNOWN REF: LMM 72-72-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
727210-2	NO. 1 ENGINE - NO. 2 PLANET GEAR ASSEMBLY PN SN-UNKNOWN REF: LMM 72-72-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
727210-3	NO. 1 ENGINE - NO. 3 PLANET GEAR ASSEMBLY PN SN-UNKNOWN REF: LMM 72-72-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
727210-4	NO. 1 ENGINE - NO. 4 PLANET GEAR ASSEMBLY PN SN-UNKNOWN REF: LMM 72-72-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
727210-5	NO. 1 ENGINE - NO. 5 PLANET GEAR ASSEMBLY PN SN-UNKNOWN REF: LMM 72-72-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
ENGINE NO. 2 Model : TFE731-20BR-1B Serial # P-116968C Part # 3060084-1									
72-AS-720005	NO. 2 ENGINE - INSPECT MAJOR PERIODIC PER MANUFACTURERS INSTRUCTIONS REF: LMM 72-00-00	MOS HRS/MSC ENC	3000	+100/-100			07-MAY-2008 0 0	(3000) 3000	3100
72-AS-720006 (s)	NO. 2 ENGINE - INSPECT COMB CHAMBER PLENUM CASE INSP PER MANUFACTURERS INSTRUCTIONS REF: GENERIC NO REF	MOS HRS/MSC ENC	3000	+100/-100			07-MAY-2008 0 0		
72-AS-720007	NO. 2 ENGINE - INSPECT COMPRESSOR ZONE PER MANUFACTURERS INSTRUCTIONS REF: LMM 72-00-00	MOS HRS/MSC ENC	6000	+200/-200			07-MAY-2008 0 0	(6000) 6000	6200
72-AS-720008 (s)	NO. 2 ENGINE - INSPECT AGB PER MANUFACTURERS INSTRUCTIONS REF: See Workcard	MOS HRS/MSC ENC	6000	+200/-200			07-MAY-2008 0 0		
72-AS-720010	NO. 2 ENGINE - ANALYSIS OIL AND FILTER (BASELINE/SPECIAL REQUIREMENT) REF: LMM 72-00-00	MOS HRS/MSC ENC	A/R				12-AUG-2008 11.9 10		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-AS-720011	NO. 2 ENGINE - REPLACE FUEL FILTER ELEMENT (25-HR INITIAL)	MOS HRS/MSC ENC	A/R				12-AUG-2008 11.9 10		
	REF: LMM 73-21-02								
720110	NO. 2 ENGINE - ACCESSORY GEARBOX 3060827-2 S-3041	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
	REF: LMM 72-60-02								
720244	NO. 2 ENGINE - NO. 6 CARBON SEAL ASSEMBLY PN SN-UNKNOWN	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
	REF: GENERIC NO REF								
720245	NO. 2 ENGINE - NO. 6 BEARING ASSEMBLY PN SN-UNKNOWN	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
	REF: GENERIC NO REF								
722001	NO. 2 ENGINE - FAN INLET HOUSING ASSEMBLY PN SN-UNKNOWN	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
	REF: GENERIC NO REF								
723002	NO. 2 ENGINE - NO. 3 CARBON SEAL ASSEMBLY PN SN-UNKNOWN	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
	REF: LMM 72-30-01								
+ 723010 (s)	NO. 2 ENGINE - CHECK CARBON SEAL HEALTH	MOS HRS/MSC ENC	1600	+50/-100			29-JUN-2015 1602.9 1293		
	REF: LMM 72-00-00								
723011	NO. 2 ENGINE - NO. 4 CARBON SEAL RUNNER PN SN-UNKNOWN	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
	REF: GENERIC NO REF								

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723012	NO. 2 ENGINE - NO. 4 CARBON SEAL ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
723013	NO. 2 ENGINE - NO. 5 CARBON SEAL RUNNER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
723014	NO. 2 ENGINE - NO. 5 CARBON SEAL ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
723081	NO. 2 ENGINE - ROTATING, AIR 2ND STAGE SEAL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
725007 72.500	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) NOZZLE ASSEMBLY PN SN-UNKNOWN REF: LMM 72-50-07	MOS HRS/MSC ENC	A/R	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
725010 LIFE LIMIT	NO. 2 ENGINE - 1ST-STAGE LOW PRESSURE TURBINE (LPT) DISC 3060625-1 070322903028 REF: LMM 72-50-04	MOS HRS/MSC ENC	12000	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		(12000) 12045
725020 LIFE LIMIT	NO. 2 ENGINE - 2ND-STAGE LOW PRESSURE TURBINE (LPT) DISC 3060611-1 070322904179 REF: LMM 72-50-04	MOS HRS/MSC ENC	12000	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		(12000) 12045
725030 LIFE LIMIT	NO. 2 ENGINE - 3RD-STAGE LOW PRESSURE TURBINE (LPT) DISC 3060671-2 070322902936 REF: LMM 72-50-04	MOS HRS/MSC ENC	12000	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		(12000) 12045

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725040	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) DISC 3060841-1 071217200955 REF: LMM 72-50-07	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0	(10000) 10045	
725045	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) ASSY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
725050	NO. 2 ENGINE - FAN DISC 3060287-2 08-13651-00112 REF: GENERIC NO REF	MOS HRS/MSC ENC	12000	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0	(12000) 12045	
725060	NO. 2 ENGINE - 1ST-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC 3060372-1 070316004773 REF: LMM 72-30-04	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0	(10000) 10045	
725070	NO. 2 ENGINE - 2ND-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC 3075839-1 07316001287 REF: LMM 72-30-04	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0	(10000) 10045	
725071	NO. 2 ENGINE - COMBUSTION LINER PN SN-UNKNOWN REF: LMM 72-40-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
725080	NO. 2 ENGINE - 3RD-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC 3060374-1 070316005023 REF: LMM 72-30-04	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0	(10000) 10045	
725081	NO. 2 ENGINE - OUTER TRANSITION LINER PN SN-UNKNOWN REF: LMM 72-40-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725090	NO. 2 ENGINE - 4TH-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC 3075326-5 070350109481 REF: LMM 72-30-04	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0	(10000) 10045	
LIFE LIMIT									
725110	NO. 2 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD 3074744-1 08P06310 REF: LMM 72-30-10	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
725120	NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR IMPELLER 3060371-1 070322905851 REF: LMM 72-50-06	MOS HRS/MSC ENC	8000	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0	(8000) 8045	
LIFE LIMIT									
725130	NO. 2 ENGINE - FAN SPINNER 3060156-2 072784300563 REF: LMM 72-70-01	MOS HRS/MSC ENC	12000	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0	(12000) 12045	
LIFE LIMIT									
725140	NO. 2 ENGINE - FAN DRIVE SHAFT 3060180-2 070339002000 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
725160	NO. 2 ENGINE - FORWARD ROTOR HIGH PRESSURE SEAL 3060698-1 07-03501-11890 REF: LMM 72-70-03	MOS HRS/MSC ENC	7000	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0	(7000) 7045	
LIFE LIMIT									
725170	NO. 2 ENGINE - HIGH PRESSURE SHOULDERED SHAFT 3060366-3 08P04402 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
725180	NO. 2 ENGINE - COMBUSTION PLENUM CASE 3060534-4 08P04163 REF: LMM 72-40-04	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725210	NO. 2 ENGINE - HIGH PRESSURE TURBINE FORWARD SEAL PLATE 3060514-1 08-03229-00878 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0	(10000) 10045	
725220	NO. 2 ENGINE - TRANSITION DUCT 3060694-6 08P00546 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
725230	NO. 2 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE SEAL SUPPORT 3060693-1 081756503439 REF: LMM 72-50-04	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
725240	NO. 2 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE ASSEMBLY 3060666-7 08P07932 REF: LMM 72-50-04	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
725250	NO. 2 ENGINE - FORWARD SHAFT HIGH PRESSURE TURBINE (HPT) COUPLING 3060502-2 08P06992 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
725260	NO. 2 ENGINE - AFT HIGH PRESSURE TURBINE (HPT) SHAFT COUPLING 3060599-2 08P09415 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
725270	NO. 2 ENGINE - NOZZLE LOW PRESSURE TURBINE (LPT) (A5) SEAL 3073765-12 081756503472 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
726005	NO. 2 ENGINE - TRANSFER GEARBOX ASSEMBLY 3070093-16 08P11025 REF: LMM 72-60-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
726010	NO. 2 ENGINE - OIL PUMP SPUR ANNUAL BALL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
726011	NO. 2 ENGINE - AFT OIL PUMP SPUR ANNULAR BALL BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
726012	NO. 2 ENGINE - FORWARD ALTERNATOR SPU ANNULAR BALL BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
726013	NO. 2 ENGINE - AFT ALTERNATOR SPU ANNULAR BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
726014	NO. 2 ENGINE - AIR-OIL SEPERATOR ANNULAR BALL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
726015	NO. 2 ENGINE - AIR-OIL SEPERATOR ANNULAR BALL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
726016	NO. 2 ENGINE - FORWARD STARTER/GENERATOR SPU ANNULAR BALL BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
726017	NO. 2 ENGINE - AFT STARTER/GENERATOR SPU ANNULAR BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
727001	NO. 2 ENGINE - BYPASS FAN STATOR PN SN-UNKNOWN REF: LMM 72-70-04	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
727005	NO. 2 ENGINE - UPPER FAN DUCT ASSEMBLY PN SN-UNKNOWN REF: LMM 72-70-05	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
727006	NO. 2 ENGINE - LOWER FAN DUCT ASSEMBLY PN SN-UNKNOWN REF: LMM 72-70-05	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			(EBT)		
727010 (s)	NO. 2 ENGINE - INSPECT BYPASS STATOR VANE ASSEMBLY. REF: See Workcard	MOS HRS/MSC ENC	1200	+100/-200			30-NOV-2017 2313.6 1803		
727101	NO. 2 ENGINE - NO. 1 CARBON SEAL ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
727102	NO. 2 ENGINE - NO. 1 CARBON SEAL RUNNER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
727103	NO. 2 ENGINE - NO. 1 BEARING ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
727105	NO. 2 ENGINE - RING GEAR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
727203	NO. 2 ENGINE - NO. 3 BALL BEARING PN SN-UNKNOWN REF: LMM 72-30-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
727210	NO. 2 ENGINE - PLANET HOUSING ASSEMBLY PN SN-UNKNOWN REF: LMM 72-72-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
727210-1	NO. 2 ENGINE - NO. 1 PLANET GEAR ASSEMBLY PN SN-UNKNOWN REF: LMM 72-72-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
727210-2	NO. 2 ENGINE - NO. 2 PLANET GEAR ASSEMBLY PN SN-UNKNOWN REF: LMM 72-72-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
727210-3	NO. 2 ENGINE - NO. 3 PLANET GEAR ASSEMBLY PN SN-UNKNOWN REF: LMM 72-72-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
727210-4	NO. 2 ENGINE - NO. 4 PLANET GEAR ASSEMBLY PN SN-UNKNOWN REF: LMM 72-72-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
727210-5	NO. 2 ENGINE - NO. 5 PLANET GEAR ASSEMBLY PN SN-UNKNOWN REF: LMM 72-72-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
CHAPTER 73	ENGINE FUEL AND CONTROL								
733001	NO. 1 ENGINE FUEL FLOW TRANSDUCER PN SN-UNKNOWN REF: AMM 73-31-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
733002	NO. 2 ENGINE FUEL FLOW TRANSDUCER PN SN-UNKNOWN REF: AMM 73-31-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
733013	DUAL FUEL FLOW (DFFC) CONVERTER 10540B08F07 08031107A REF: AMM 73-31-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
733031	LEFT ENGINE FUEL TEMPERATURE BULB MS28034-3 T0624 REF: AMM 73-31-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
733032	RIGHT ENGINE FUEL TEMPERATURE BULB MS28034-3 T0004 REF: AMM 73-31-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
ENGINE NO. 1 Model : TFE731-20BR-1 B Serial # P-116969C Part # 3060084-1									
730110	NO. 1 ENGINE - FUEL CONTROL UNIT 3070800-37 19230 REF: LMM 73-20-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
730120 (s)	NO. 1 ENGINE - REPLACE FUEL FILTER ELEMENT REF: LMM 73-21-02	MOS HRS/MSC ENC	600	+50/-100			30-NOV-2017 2313.6 1803		
730130	NO. 1 ENGINE - ENGINE FUEL PUMP ASSEMBLY 3060760-4 2619 REF: LMM 73-20-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
731001	NO. 1 ENGINE - MOTIVE FLOW FUEL PUMP ASSEMBLY 3060759-1 1475 REF: LMM 73-21-02	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731005-1	NO. 1 ENGINE - NO. 1 FUEL MANIFOLD NOZZLE ASSEMBLY PN SN-UNKNOWN REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
731005-10	NO. 1 ENGINE - NO. 10 FUEL MANIFOLD NOZZLE ASSEMBLY PN SN-UNKNOWN REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
731005-11	NO. 1 ENGINE - NO. 11 FUEL MANIFOLD NOZZLE ASSEMBLY PN SN-UNKNOWN REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
731005-12	NO. 1 ENGINE - NO. 12 FUEL MANIFOLD NOZZLE ASSEMBLY PN SN-UNKNOWN REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
731005-2	NO. 1 ENGINE - NO. 2 FUEL MANIFOLD NOZZLE ASSEMBLY PN SN-UNKNOWN REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
731005-3	NO. 1 ENGINE - NO. 3 FUEL MANIFOLD NOZZLE ASSEMBLY PN SN-UNKNOWN REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
731005-4	NO. 1 ENGINE - NO. 4 FUEL MANIFOLD NOZZLE ASSEMBLY PN SN-UNKNOWN REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
731005-5	NO. 1 ENGINE - NO. 5 FUEL MANIFOLD NOZZLE ASSEMBLY PN SN-UNKNOWN REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731005-6	NO. 1 ENGINE - NO. 6 FUEL MANIFOLD NOZZLE ASSEMBLY PN SN-UNKNOWN REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
731005-7	NO. 1 ENGINE - NO. 7 FUEL MANIFOLD NOZZLE ASSEMBLY PN SN-UNKNOWN REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
731005-8	NO. 1 ENGINE - NO. 8 FUEL MANIFOLD NOZZLE ASSEMBLY PN SN-UNKNOWN REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
731005-9	NO. 1 ENGINE - NO. 9 FUEL MANIFOLD NOZZLE ASSEMBLY PN SN-UNKNOWN REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
731015	NO. 1 ENGINE - FUEL PUMP PRESSURE DIFFERENTIAL INDICATOR PN SN-UNKNOWN REF: LMM 73-20-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
731110	NO. 1 ENGINE - PRESSURE LIMITER (PCD) VALVE 3070685-11 17806 REF: LMM 73-20-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
731120	NO. 1 ENGINE - FUEL FLOW DIVIDER/DRAIN VALVE 394476-2 2816 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
732102	NO. 1 ENGINE - RELIEF VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
732120 (s)	NO. 1 ENGINE - INSPECT MOTIVE FLOW FUEL PUMP DRIVE SPLINE	MOS					30-NOV-2017		
	REF: See Workcard	HRS/MSC ENC	600	+50/-100			2313.6 1803		
ENGINE NO. 2 Model : TFE731-20BR-1B Serial # P-116968C Part # 3060084-1									
730110	NO. 2 ENGINE - FUEL CONTROL UNIT	MOS					07-MAY-2008		
	3070800-37	HRS/MSC	O/C	TSN:0			0		
	19233	ENC		TSN:0			0		
	REF: LMM 73-20-01			TSN:0					
730120 (s)	NO. 2 ENGINE - REPLACE FUEL FILTER ELEMENT	MOS					30-NOV-2017		
	REF: LMM 73-21-02	HRS/MSC ENC	600	+50/-100			2313.6 1803		
730130	NO. 2 ENGINE - ENGINE FUEL PUMP ASSEMBLY	MOS					07-MAY-2008		
	3060760-4	HRS/MSC	O/C	TSN:0			0		
	2633	ENC		TSN:0			0		
	REF: LMM 73-20-01			TSN:0					
731001	NO. 2 ENGINE - MOTIVE FLOW FUEL PUMP ASSEMBLY	MOS					07-MAY-2008		
	3060759-1	HRS/MSC	O/C	TSN:0			0		
	1461	ENC		TSN:0			0		
	REF: LMM 73-21-02			TSN:0					
731005-1	NO. 2 ENGINE - NO. 1 FUEL MANIFOLD NOZZLE ASSEMBLY	MOS					07-MAY-2008		
	PN	HRS/MSC	O/C	TSN:0			0		
	SN-UNKNOWN	ENC		TSN:0			0		
	REF: LMM 73-10-01			TSN:0					
731005-10	NO. 2 ENGINE - NO. 10 FUEL MANIFOLD NOZZLE ASSEMBLY	MOS					07-MAY-2008		
	PN	HRS/MSC	O/C	TSN:0			0		
	SN-UNKNOWN	ENC		TSN:0			0		
	REF: LMM 73-10-01			TSN:0					
731005-11	NO. 2 ENGINE - NO. 11 FUEL MANIFOLD NOZZLE ASSEMBLY	MOS					07-MAY-2008		
	PN	HRS/MSC	O/C	TSN:0			0		
	SN-UNKNOWN	ENC		TSN:0			0		
	REF: LMM 73-10-01			TSN:0					



Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731005-12	NO. 2 ENGINE - NO. 12 FUEL MANIFOLD NOZZLE ASSEMBLY PN SN-UNKNOWN REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
731005-2	NO. 2 ENGINE - NO. 2 FUEL MANIFOLD NOZZLE ASSEMBLY PN SN-UNKNOWN REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
731005-3	NO. 2 ENGINE - NO. 3 FUEL MANIFOLD NOZZLE ASSEMBLY PN SN-UNKNOWN REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
731005-4	NO. 2 ENGINE - NO. 4 FUEL MANIFOLD NOZZLE ASSEMBLY PN SN-UNKNOWN REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
731005-5	NO. 2 ENGINE - NO. 5 FUEL MANIFOLD NOZZLE ASSEMBLY PN SN-UNKNOWN REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
731005-6	NO. 2 ENGINE - NO. 6 FUEL MANIFOLD NOZZLE ASSEMBLY PN SN-UNKNOWN REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
731005-7	NO. 2 ENGINE - NO. 7 FUEL MANIFOLD NOZZLE ASSEMBLY PN SN-UNKNOWN REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
731005-8	NO. 2 ENGINE - NO. 8 FUEL MANIFOLD NOZZLE ASSEMBLY PN SN-UNKNOWN REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731005-9	NO. 2 ENGINE - NO. 9 FUEL MANIFOLD NOZZLE ASSEMBLY PN SN-UNKNOWN REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
731015	NO. 2 ENGINE - FUEL PUMP PRESSURE DIFFERENTIAL INDICATOR PN SN-UNKNOWN REF: LMM 73-20-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
731110	NO. 2 ENGINE - PRESSURE LIMITER (PCD) VALVE 3070685-11 17816 REF: LMM 73-20-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
731120	NO. 2 ENGINE - FUEL FLOW DIVIDER/DRAIN VALVE 394476-2 2866 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
732102	NO. 2 ENGINE - RELIEF VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
732120 (s)	NO. 2 ENGINE - INSPECT MOTIVE FLOW FUEL PUMP DRIVE SPLINE REF: See Workcard	MOS HRS/MSC ENC	600	+50/-100			30-NOV-2017 2313.6 1803		
CHAPTER 74 IGNITION									
743001	TAIL CONE RELAY (P13) PANEL PN SN-UNKNOWN REF: AMM 74-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
743001-1	EMERGENCY LIGHTING (P-51) RELAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
743005-1	K22 RELAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
743005-2	K61 RELAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
ENGINE NO. 1 Model : TFE731-20BR-1 B Serial # P-116969C Part # 3060084-1									
740110	NO. 1 ENGINE - IGNITION UNIT PN SN-UNKNOWN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
740130	NO. 1 ENGINE - 5 O'CLOCK IGNITER (#1 POSITION) PLUG PN SN-UNKNOWN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
+ 740140 (s)	NO. 1 ENGINE - REMOVE AND INSPECT 5 O'CLOCK IGNITER PLUG AND LEAD REF: LMM 74-00-01	MOS HRS/MSC ENC	1600	+50/-100			29-JUN-2015 1602.9 1293		
740150	NO. 1 ENGINE - 7 O'CLOCK IGNITER (#2 POSITION) PLUG PN SN-UNKNOWN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
+ 740160 (s)	NO. 1 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEAD REF: LMM 74-00-01	MOS HRS/MSC ENC	1600	+50/-100			29-JUN-2015 1602.9 1293		
742011	NO. 1 ENGINE - NO. 1 IGNITION (IPC 20 REFERENCE) LEAD PN SN-UNKNOWN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
742012	NO. 1 ENGINE - NO. 2 IGNITION (IPC 25 REFERENCE) LEAD PN SN-UNKNOWN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
ENGINE NO. 2 Model : TFE731-20BR-1B Serial # P-116968C Part # 3060084-1									
740110	NO. 2 ENGINE - IGNITION UNIT PN SN-UNKNOWN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
740130	NO. 2 ENGINE - 5 O'CLOCK IGNITER (#1 POSITION) PLUG PN SN-UNKNOWN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
+ 740140 (s)	NO. 2 ENGINE - REMOVE AND INSPECT 5 O'CLOCK IGNITER PLUG AND LEAD REF: LMM 74-00-01	MOS HRS/MSC ENC	1600	+50/-100			29-JUN-2015 1602.9 1293		
740150	NO. 2 ENGINE - 7 O'CLOCK IGNITER (#2 POSITION) PLUG PN SN-UNKNOWN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
+ 740160 (s)	NO. 2 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEAD REF: LMM 74-00-01	MOS HRS/MSC ENC	1600	+50/-100			29-JUN-2015 1602.9 1293		
742011	NO. 2 ENGINE - NO. 1 IGNITION (IPC 20 REFERENCE) LEAD PN SN-UNKNOWN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
742012	NO. 2 ENGINE - NO. 2 IGNITION (IPC 25 REFERENCE) LEAD PN SN-UNKNOWN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 75 AIR									
ENGINE NO. 1 Model : TFE731-20BR-1 B Serial # P-116969C Part # 3060084-1									
754210	NO. 1 ENGINE - PT2 PROBE								
	PN	MOS		TSN:0			07-MAY-2008		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: LMM 75-40-01	ENC		TSN:0			0		
761310	NO. 1 ENGINE - SURGE BLEED VALVE								
	978812-7-1	MOS		TSN:0			07-MAY-2008		
	13593	HRS/MSC	O/C	TSN:0			0		
	REF: LMM 76-10-01	ENC		TSN:0			0		
ENGINE NO. 2 Model : TFE731-20BR-1B Serial # P-116968C Part # 3060084-1									
754210	NO. 2 ENGINE - PT2 PROBE								
	PN	MOS		TSN:0			07-MAY-2008		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: LMM 75-40-01	ENC		TSN:0			0		
761310	NO. 2 ENGINE - SURGE BLEED VALVE								
	978812-7-1	MOS		TSN:0			07-MAY-2008		
	13656	HRS/MSC	O/C	TSN:0			0		
	REF: LMM 76-10-01	ENC		TSN:0			0		
CHAPTER 76 ENGINE CONTROLS									
761013	THROTTLE CONTROL MODULE								
	69011-17	MOS		TSN:0			11-AUG-2008		
	607	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 76-10-02	AFL		TSN:0			0		
761201	AFT LEFT THROTTLE CABLE								
	PN	MOS		TSN:0			11-AUG-2008		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 76-10-01	AFL		TSN:0			0		
761202	AFT RIGHT THROTTLE CABLE								
	PN	MOS		TSN:0			11-AUG-2008		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 76-10-01	AFL		TSN:0			0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
761203	LEFT FORWARD THROTTLE CABLE PN SN-UNKNOWN REF: AMM 76-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
761204	RIGHT FORWARD THROTTLE CABLE PN SN-UNKNOWN REF: AMM 76-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

ENGINE NO. 1 Model : TFE731-20BR-1 B Serial # P-116969C Part # 3060084-1

761320	NO. 1 ENGINE - SOLENOID CONTROLLER VALVE 109696-6-1 13151 REF: LMM 76-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
761330	NO. 1 ENGINE - ENGINE (DEEC) DISPLAY UNIT 2118882-1008 38-AW0451 REF: LMM 76-10-02	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
761330A	NO. 1 ENGINE - DOWNLOAD ENGINE (DEEC) DISPLAY UNIT ECTM 2118882-1008 38-AW0451 REF: See Workcard	MOS HRS/MSC ENC	50				14-FEB-2019 2789.1 2173	(2839.1) 2839.1	
CUSTOMER CODE									

ENGINE NO. 2 Model : TFE731-20BR-1B Serial # P-116968C Part # 3060084-1

761320	NO. 2 ENGINE - SOLENOID CONTROLLER VALVE 109696-6-1 13149 REF: LMM 76-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
761330	NO. 2 ENGINE - ENGINE (DEEC) DISPLAY UNIT 2118882-1008 38-AW0450 REF: LMM 76-10-02	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		



Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
761330A	NO. 2 ENGINE - DOWNLOAD 2118882-1008	ENGINE (DEEC)	DISPLAY UNIT	ECTM			14-FEB-2019		
CUSTOMER CODE	38-AW0450 REF: See Workcard	MOS HRS/MSC ENC	50				2789.1 2173	(2839.1)	2839.1
CHAPTER 77 ENGINE INDICATING									
5-19-00-F7720002	PERFORM ENGINE TEMPERATURE INDICATING SYSTEM - PERFORM ITT MARGIN CHECK. (EFFECTIVE ON AIRCRAFT 45-080 THRU 45-169 NOT MODIFIED BY SB 45-22-4.) (ZONE/ACCESS 410/420 **IRN # F7720002)								
		MOS					11-AUG-2008		
	REF:	HRS/MSC AFL	N/A				0 0		
+ 5-19-00-F7720003	PERFORM ENGINE TEMPERATURE INDICATING SYSTEM - PERFORM HARDWARE VALIDATION CHECK. (EFFECTIVE ON AIRCRAFT 45-080 THRU 45-169 NOT MODIFIED BY SB 45-22-4.) (ZONE/ACCESS 410/420 IRN # F7720003)								
		MOS					11-AUG-2008		
	REF:	HRS/MSC AFL	N/A				0 0		
774001	ENGINE VIBRATION MONITOR BOX 241-241-000-501	MOS			TSN:0		11-AUG-2008		
	AD06150	HRS/MSC	O/C		TSN:0		0		
	REF: AMM 77-41-01	AFL			TSN:0		0		
774010	P36 RELAY BOX PN	MOS			TSN:0		11-AUG-2008		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0		0		
	REF: AMM 77-41-03	AFL			TSN:0		0		
774011	LEFT ENGINE VIBRATION ACCELEROMETER PN	MOS			TSN:0		11-AUG-2008		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0		0		
	REF: AMM 77-41-02	AFL			TSN:0		0		
774012	RIGHT ENGINE VIBRATION ACCELEROMETER PN	MOS			TSN:0		11-AUG-2008		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0		0		
	REF: AMM 77-41-02	AFL			TSN:0		0		

ENGINE NO. 1 Model : TFE731-20BR-1 B Serial # P-116969C Part # 3060084-1

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
770101	NO. 1 ENGINE - N1 MONOPOLE PN SN-UNKNOWN REF: LMM 77-10-02	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
771210	NO. 1 ENGINE - N1 COMPENSATOR 3060735-4 071309700553 REF: LMM 77-10-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
771220	NO. 1 ENGINE - N2 MONOPOLE PN SN-UNKNOWN REF: LMM 77-10-05	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
772210	NO. 1 ENGINE - ITT HARNESS ASSEMBLY PN SN-UNKNOWN REF: LMM 77-20-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
ENGINE NO. 2 Model : TFE731-20BR-1B Serial # P-116968C Part # 3060084-1									
770101	NO. 2 ENGINE - N1 MONOPOLE PN SN-UNKNOWN REF: LMM 77-10-02	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
771210	NO. 2 ENGINE - N1 COMPENSATOR 3060735-4 071309700567 REF: LMM 77-10-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
771220	NO. 2 ENGINE - N2 MONOPOLE PN SN-UNKNOWN REF: LMM 77-10-05	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
772210	NO. 2 ENGINE - ITT HARNESS ASSEMBLY PN SN-UNKNOWN REF: LMM 77-20-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 78	EXHAUST								
5-19-00-R7830007	PERFORM - THRUST REVERSER - PERFORM CONDUCTIVITY CHECK OF RH THRUST REVERSER DOOR SKIN AND COWL ADJACENT TO APU EXHAUST								
	REF: NDT PART 6/78-30-01	MOS HRS/MSC AFL APH	1200				11-AUG-2008 0 0 0	1200	
783001	LEFT THRUST REVERSER								
	LJ7830101-5 A30040489 REF: AMM 78-31-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
783002	RIGHT THRUST REVERSER								
	LJ7830101-6 A30042489 REF: AMM 78-31-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
783025	TRANSFORMER/RECTIFIER ELECTRONIC CONTROL UNIT								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
783037	NO. 1 GPM HYDRAULIC CONTROL VALVE								
	PN SN-UNKNOWN REF: AMM 78-32-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
783038	NO. 2 GPM HYDRAULIC CONTROL VALVE								
	PN SN-UNKNOWN REF: AMM 78-32-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
783051	LEFT OUTBOARD THRUST REVERSER ACTUATOR								
	PN SN-UNKNOWN REF: AMM 78-32-20	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
783052	LEFT INBOARD THRUST REVERSER ACTUATOR PN SN-UNKNOWN REF: AMM 78-32-20	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
783053	RIGHT INBOARD THRUST REVERSER ACTUATOR PN SN-UNKNOWN REF: AMM 78-32-20	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
783054	RIGHT OUTBOARD THRUST REVERSER ACTUATOR PN SN-UNKNOWN REF: AMM 78-32-20	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
783061	NO. 1 CONTROL, THRUST REVERSER HYDRAULIC VALVE PN SN-UNKNOWN REF: AMM 78-32-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
783062	NO. 2 CONTROL, THRUST REVERSER HYDRAULIC VALVE PN SN-UNKNOWN REF: AMM 78-32-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
783101	LEFT THRUST REVERSER HYDRAULIC ISOLATION VALVE R-9045-9 1122 REF: AMM 78-30-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
783102	RIGHT THRUST REVERSER HYDRAULIC ISOLATION VALVE R-9045-9 1123 REF: AMM 78-30-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
783150	LEFT HAND INBOARD LATCHBOX ACTUATOR PN SN-UNKNOWN REF: AMM 78-32-30	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
783151	RIGHT HAND INBOARD LATCHBOX ACTUATOR PN SN-UNKNOWN REF: AMM 78-32-30	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
783210	LEFT THRUST REVERSER CONTROL VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
783211	RIGHT THRUST REVERSER CONTROL VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
783220	NO. 1 ENGINE THROTTLE RETARD ACTUATOR PN SN-UNKNOWN REF: AMM 78-32-40	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
783221	NO. 2 ENGINE THROTTLE RETARD ACTUATOR PN SN-UNKNOWN REF: AMM 78-32-40	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
783301	LEFT THRUST REVERSER CONTROL BOX 78367006-3 00619 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				29-JUN-2015 1602.9 1327		
783302	RIGHT THRUST REVERSER CONTROL BOX 78367006-3 00634 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				29-JUN-2015 1602.9 1327		
783320	LEFT OUTBOARD THRUST REVERSER WIRE HARNESS PN SN-UNKNOWN REF: AMM 78-33-20	MOS HRS/MSC AFL	C/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
783321	LEFT INBOARD THRUST REVERSER WIRE HARNESS PN SN-UNKNOWN REF: AMM 78-33-20	MOS HRS/MSC AFL	C/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
783322	RIGHT INBOARD THRUST REVERSER WIRE HARNESS PN SN-UNKNOWN REF: AMM 78-33-20	MOS HRS/MSC AFL	C/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
783323	RIGHT OUTBOARD THRUST REVERSER WIRE HARNESS LJ7836701-5 NSN REF: AMM 78-33-20	MOS HRS/MSC AFL	C/C				05-AUG-2015 1656.2 1364		
D7830078 (s)	PERFORM ** THRUST REVERSER SYSTEM THROTTLE RETARD ACTUATOR - OPERATIONAL CHECK PKG 21 REF: AMM 78-32-40	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 20-MAY-2016 1821.7 1492		
H7830081 (s)	PERFORM THRUST REVERSERS - REMOVE LINK ROD ASSEMBLIES AND PERFORM MAGNETIC PARTICLE INSPECTION. PKG 21 REF: NDT PART 7/78-30-01	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 20-MAY-2016 1821.7 1492		
H7830082 (s)	PERFORM THRUST REVERSERS - REMOVE THRUST REVERSER DOOR ASSEMBLIES AND PERFORM EDDY CURRENT INSPECTION OF PIVOT FITTING AND DOOR HINGES. PKG 21 REF: See Workcard	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			PKG 20-MAY-2016 1821.7 1492		
CHAPTER 79	OIL								
792037	NO. 1 OIL PRESSURE SWITCH PN SN-UNKNOWN REF: AMM 79-30-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
792038	NO. 2 OIL PRESSURE SWITCH PN SN-UNKNOWN REF: AMM 79-30-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
793001	NO. 1 ENGINE OIL PRESSURE TRANSDUCER PN SN-UNKNOWN REF: AMM 79-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
793002	NO. 2 ENGINE OIL PRESSURE TRANSDUCER PN SN-UNKNOWN REF: AMM 79-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
793011	LEFT TEMPERATURE OIL BULB MS28034-3 T0615 REF: AMM 79-30-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
793012	RIGHT TEMPERATURE OIL BULB MS28034-3 R9996 REF: AMM 79-30-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
793013	APU TEMPERATURE OIL BULB PN SN-UNKNOWN REF: AMM 49-70-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-AUG-2008 0 0		
ENGINE NO. 1 Model : TFE731-20BR-1 B Serial # P-116969C Part # 3060084-1									
790110	NO. 1 ENGINE - OIL PUMP 3060785-3 031405700513 REF: LMM 79-20-03	MOS HRS/MSC ENC	O/C	TSO:0 TSO:0 TSO:0			16-OCT-2014 1459.3 1176		
790130 (s)	NO. 1 ENGINE - ANALYSIS OIL AND FILTER (SOAP) REF: LMM 72-00-00	MOS HRS/MSC ENC	150	+100			29-AUG-2018 2621.3 2034		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
790140 (s)	NO. 1 ENGINE - PERFORM OIL CHANGE REF: LMM 72-00-00	MOS HRS/MSC ENC	1200	+100/-200			30-NOV-2017 2313.6 1803		
790150 (s)	NO. 1 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION AND PERFORM RESISTANCE CHECK REF: See Workcard	MOS HRS/MSC ENC	600	+50/-100			30-NOV-2017 2313.6 1803		
790160 (s)	NO. 1 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION REF: See Workcard	MOS HRS/MSC ENC	150	+100			29-AUG-2018 2621.3 2034		
791001	NO. 1 ENGINE - ENGINE OIL CHIP DETECTOR PN SN-UNKNOWN REF: LMM 79-10-01	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		07-MAY-2008 0 0		
792008	NO. 1 ENGINE - OIL FLOW REDUCTION VALVE 3060769-1 08-06451-08524 REF: LMM 79-20-08	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		07-MAY-2008 0 0		
792011	NO. 1 ENGINE - FUEL/OIL VALVE PN SN-UNKNOWN REF: LMM 79-30-01	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		07-MAY-2008 0 0		
792012	NO. 1 ENGINE - OIL TEMPERATURE REGULATOR PN SN-UNKNOWN REF: LMM 79-20-03	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		07-MAY-2008 0 0		
792220	NO. 1 ENGINE - UPPER OIL COOLER ASSEMBLY 160552-3 1837 REF: LMM 79-20-10	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		07-MAY-2008 0 0		



Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
792230	NO. 1 ENGINE - LOWER LEFT OIL COOLER ASSEMBLY 160554-5 2759 REF: LMM 79-20-10	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
792240	NO. 1 ENGINE - LOWER RIGHT OIL COOLER ASSEMBLY 160554-6 2773 REF: LMM 79-20-10	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
792250	NO. 1 ENGINE - PRESSURE BREATHER VALVE PN SN-UNKNOWN REF: LMM 79-20-02	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
792260	NO. 1 ENGINE - OIL TEMPERATURE CONTROL VALVE 158465-6 13072 REF: LMM 79-30-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
793064	NO. 1 ENGINE - TEMP BULB PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
793310	NO. 1 ENGINE - OIL FILTER BYPASS VALVE PN SN-UNKNOWN REF: LMM 79-30-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
+ 793315 (s)	NO. 1 ENGINE - CHECK OIL FILTER BYPASS VALVE CIRCUIT/THERMAL LOCKOUT SWITCH REF: LMM 79-30-01	MOS HRS/MSC ENC	600	+50/-100			30-NOV-2017 2313.6 1803		
793320	NO. 1 ENGINE - FUEL HEATER / OIL COOLER ASSEMBLY 3060709-4 2869 REF: LMM 79-20-07	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		

ENGINE NO. 2 Model : TFE731-20BR-1B Serial # P-116968C Part # 3060084-1

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
790110	NO. 2 ENGINE - OIL PUMP 3060785-2 081405700353 REF: LMM 79-20-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
790130 (s)	NO. 2 ENGINE - ANALYSIS OIL AND FILTER (SOAP) REF: LMM 72-00-00	MOS HRS/MSC ENC	150	+100			29-AUG-2018 2621.3 2034		
790140 (s)	NO. 2 ENGINE - PERFORM OIL CHANGE REF: LMM 72-00-00	MOS HRS/MSC ENC	1200	+100/-200			30-NOV-2017 2313.6 1803		
790150 (s)	NO. 2 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION AND PERFORM RESISTANCE CHECK REF: See Workcard	MOS HRS/MSC ENC	600	+50/-100			30-NOV-2017 2313.6 1803		
790160 (s)	NO. 2 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION REF: See Workcard	MOS HRS/MSC ENC	150	+100			29-AUG-2018 2621.3 2034		
791001	NO. 2 ENGINE - ENGINE OIL CHIP DETECTOR PN SN-UNKNOWN REF: LMM 79-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
792008	NO. 2 ENGINE - OIL FLOW REDUCTION VALVE 3060769-1 08-06451-08523 REF: LMM 79-20-08	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
792011	NO. 2 ENGINE - FUEL/OIL VALVE PN SN-UNKNOWN REF: LMM 79-30-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
792012	NO. 2 ENGINE - OIL TEMPERATURE REGULATOR PN SN-UNKNOWN REF: LMM 79-20-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
792220	NO. 2 ENGINE - UPPER OIL COOLER ASSEMBLY 160552-3 1834 REF: LMM 79-20-10	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
792230	NO. 2 ENGINE - LOWER LEFT OIL COOLER ASSEMBLY 160554-5 2840 REF: LMM 79-20-10	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
792240	NO. 2 ENGINE - LOWER RIGHT OIL COOLER ASSEMBLY 160554-6 2774 REF: LMM 79-20-10	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
792250	NO. 2 ENGINE - PRESSURE BREATHER VALVE PN SN-UNKNOWN REF: LMM 79-20-02	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
792260	NO. 2 ENGINE - OIL TEMPERATURE CONTROL VALVE 158465-6 13068 REF: LMM 79-30-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
793064	NO. 2 ENGINE - TEMP BULB PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		
793310	NO. 2 ENGINE - OIL FILTER BYPASS VALVE PN SN-UNKNOWN REF: LMM 79-30-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			07-MAY-2008 0 0		

Status Report

LEARJET 45 S/N 45-372 (SE-RMO): 2792.6 HRS, 2223 AFL as of 25-Feb-2019

Owner/Operator: HUMMINGBIRD AVIATION SERVICES

Report Date: 28-FEB-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 793315 (s)	NO. 2 ENGINE - CHECK OIL FILTER BYPASS VALVE CIRCUIT/THERMAL LOCKOUT SWITCH	MOS						30-NOV-2017	
	REF: LMM 79-30-01	HRS/MSC ENC	600	+50/-100				2313.6 1803	
793320	NO. 2 ENGINE - FUEL HEATER / OIL COOLER ASSEMBLY	MOS						07-MAY-2008	
	3060709-4	HRS/MSC	O/C	TSN:0				0	
	2819	ENC		TSN:0				0	
	REF: LMM 79-20-07			TSN:0					
CHAPTER 85	FUEL CELL SYSTEMS								
859000	SUBMIT LOGBOOK ENTRIES FOR ELOGBOOK	MOS						11-AUG-2008	
	REF: GENERIC CUSTOM	HRS/MSC AFL	A/R					0 0	